

Steve

Ref: NT4C NS/INC19011960/6sd3 sv

ASSIGNMENT

From: Date:
Estimated Cost:
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No:
at Workshop no:
at:
Insured: FBM 6006C
Policy No: 5103047197 (06/07/2018 - 07/07/2019)
Claims No: MT/1051903-002
Sum Insured: Excess:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:
IOAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

Veh No: SHB 5685K Vi Regn: 30/11/17
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover:
Truck / Trailer or:
Make: Toyota Prius c.v. 1798
Colour: Maroon A/C Insured / Std
Sp. Reading: 292175 T/Ratio: Insured / Std
Eng/No:
C/No: JTD KB3FU 603575779
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SU
TOYO / YOKO or Westlake
Front: Rear:
R/Bal. 5 - mm R/Bal. 5
L/Bal. 5 - mm L/Bal. 5
D.O.A. 3/7/19 D.O.A. 5/7/19
Survey held at SMRT
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooltop
Rear LH
The UIC / Chassis frame / Body Structure affected due

Date / Time Action / Instruction
SHB 5685K NS/INC18004826/5Vbe2, D.O.A: 07/03/2018
FBM 6006C X

17/07/19 Confirmed P/P \$ 2,535.59 @ 3 days with Steve
(\$ 2,397.59 - Red - 49%)

RECEIVED 22 JUL 2019

07/19/2012
FBM 6006C
19/7/2019

Date/Time File Pass to:
22/07/19
Typist
Date/Time File Return to:
21

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 3
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Report Format:
Lump Sum I.B. 2,535.59 p/p

Survey Fee:
Transportation
3 - R.R. 34
3 - P.R. 34
3 - Fuel 34

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1051903-002	SMRT TAXIS PTE LTD	SHB 5685K	FBM 6006C	03/07/2019	22:30	\$ 4,933.18	\$ 2,535.59
2	MT/1049479-002	COMFORT TRANSPORTATION PTE LTD	SHD 344Sp	SGJ 6827G	16/06/2019	00:50	\$ 11,440.74	\$ 4,400.00

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="03/07/2019 09:03"/>
Vehicle No.(For Motor)	<input type="text" value="FBM6006C"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5102047197		ONG LEONG HENG	S1760733B	GMC	Comprehensive	FBM6006C	FBM6006C	06/07/2018	05/07/2019

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 17 July 2019 9:10 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team; Shirley Hiew (LKK Auto); Shirley Hiew (LKK Auto)
Subject: RE: SHB5685K

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Wednesday, 17 July 2019 8:52 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: SUR; CS A Team; Shirley Hiew (LKK Auto); Shirley Hiew (LKK Auto)
Subject: SHB5685K

Dear Poh Suan,

We confirm the finalize \$2,535.59 (P/P, before GST). 3 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, July 15, 2019 3:57 PM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5685K

Hi Steve,

Attached herewith the repair estimate of SHB 5685K having Case No: TAX/07/19/2012.

There is no change to the approved amount of \$2,535.59 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Monday, 15 July 2019 3:49 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 11:35
Date Of Accident	03/07/2019 22:30
Exact Location Of Accident	KJE TOWARDS PIE CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5685K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	N MOHANASUNDERN
NRIC No	S1258458Z
Date Of Birth	23/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	448
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS I WAS TRAVELLING AT KJE TOWARDS PIE CHANGI WITH ONE MALE CHINESE PASSENGER ON BOARD, SUDDENLY I FELT AN IMPACT ON MY REAR OF MY TAXI . I ALIGHT AND I REALISE THAT THERE WAS A MOTORCYCLE FBM6006C HAD HIT ONTO MY REAR PORTION OF MY TAXI.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM6006C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ONG LEONG HENG
NRIC/Passport Number	S1760733B
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper. In the bottom left corner, there is a small, faint circular stamp or mark.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

W

uph 02/7/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5685K
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS110364
Chassis No.:	JTDKB3FU603575779
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00

COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$26,876.00
Total Rebate Amount:	\$30,626.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Case Details

Case Reference Number :
TAX/07/19/2012

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5685K

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7573-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 03/07/2019 02:30 PM

Vehicle Age(In Months) : 20

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92 ¹³	Replace ▾	✓ ON
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	✓ RPS
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	1	89.93	Replace ▾	✓ RR
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72 ¹³	Replace ▾	✓ CUT
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give ▾	X NAI

Total Spare Part Cost 3,130.18

Surveyor Total 1,635.57

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,130.18

Final Sur Total 1,635.57

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Give	X NM
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/ RR
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	25.00	328.58	Replace	0	0	Not Give	X NM
One Time Key In	Main			SEAL, RR BUMPER, LH	1	63.90	63.90	25.00	63.90	Replace	1	63.90	Replace	/ CUT
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	1	175.73	Replace	/ RR
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	15.00	15.00	25.00	11.25	Replace	10	11.25	Replace	/ RR
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	X NM
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	RX
Total Spare Part Cost									3,130.18	Surveyor Total 1,635.57				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									3,130.18	Final Sur Total 1,635.57				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER LH	378.00	200	
3	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
Total:			936.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	20.00	

5779.20#

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,130.18	1,635.57
Total Labour Cost	507.00	400.00
Total Spray Painting	936.00	480.00
Other	360.00	20.00
Overall Total	4,933.18	2,535.57
Lump Sum Repair Option		
Lump Sum Total	0.00	2,535.57
Surveyor Approved Amount		2,535.57
No of Repair Days*	4	3
Remarks	-	P/P, take before spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		

Save

Clear

Survey Date

05/07/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Date:


9/7/19

Section A - Accident Details

Registration Number	SHB5685K
Case Reference Number	TAX/07/19/2012
Registration Date	30/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	N MOHANA SUNDERN
Type of Accident	Side Swipe
Accident Date and Time	3/7/2019 10:30 PM
Accident Reported Date and Time	4/7/2019 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102277
Special Instruction to ARC, if any	SIDE
Prepared Date and Time	5/7/2019 2:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$936.00	\$480.00
Total Spare Part Cost	\$3,130.18	\$1,635.59
Total Other Cost	\$360.00	\$20.00
TOTAL COST	\$4,933.18	\$2,535.59 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	05/07/2019 3:12 PM	05/07/2019 3:20 PM
Signature		
Remarks	P/P, take before spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0205	Invoice Number	
Quotation Date	11.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$400.00
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$936.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 20	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52462470 10	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given
		81591470 10	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace
		81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given
		52592470 40	SEAL, RR BUMPER, LH	1.00	\$85.20	25.00	\$63.90	Replace	Replace
		58399470 30	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	25.00	\$175.73	Replace	Replace

		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		61602471 60	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	R
Total					\$3,880.30		\$1,635.59			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1635.59
 + 400.00
 + 500.00

 2535.59



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19011960/Esd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 22-07-2019
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 6006C	Veh. Inspected	SHB 5685K
Policy No.	5102047197	Coverage (\$)	0.00
Claim No.	MT/1051903-002	Excess (\$)	0.00
Assign From		Assign Date	05/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603575779	Colour	MAROON
Odometer	292175	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	5 mm
L/H Front Tyre	195/65R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2019	Inspection Date	05/07/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5685K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, RR BUMPER ASSY (DISC 25%)	DENTED	423.90	317.93
1	FILLER, RR BUMPER, LH (DISC 25%)	BROKEN	119.90	89.93
1	GUARD, RR BUMPER, LOWER (DISC 25%)	CUT	558.30	418.73
1	SEAL, RR BUMPER, LH (DISC 25%)	CUT	85.20	63.90
1	COVER, RR FLOOR UNDER, LH (DISC 25%)	BROKEN	234.30	175.73
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	BROKEN	486.80	438.12
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD, RR BUMPER, RH & LH, 1 @ \$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @ \$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @ \$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @ \$11.00	NOT NECESSARY	22.00	-
1	RETAINER, RR BUMPER, LH	NOT NECESSARY	111.50	-
1	COVER, GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	LENS & BODY, REAR COMBINATION LAMP, LH	NOT NECESSARY	438.10	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	PANEL SUB-ASSY, FENDER REAR LH	TO REPAIR SEE LABOUR	824.80	-
			3,976.20	1,635.59
	<u>LABOUR</u>			
	PANEL BEATING & BODYWORKS. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FENDER REAR LH.		507.00	400.00
	SPRAY PAINT.		936.00	480.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,803.00	900.00
	GRAND TOTAL		5,779.20	2,535.59

Report Ref No. NS/INC19011960/Esd3s2

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,535.59
--------------------------------------------	--	--	----------

Report Ref No. NS/INC19011960/Esd3s2

CHEN TSUE YEE
Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.