

REF: NTUC

Hwee Jie

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SHB860D Yr Regn: 12 Dec 2017

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To Inspect Vehicle No: \_\_\_\_\_

Make: Toyota Prius C.C. 1798

at Workshop m/s \_\_\_\_\_

Colour: maroon A/C:  Insured /  Std /  NI / NA

of \_\_\_\_\_

Sp. Reading: - T/Radio:  Insured /  Std /  NI / NA

Insured: SMK 1978K

Eng/No: -

Policy No. \_\_\_\_\_

C/No: JTDKB3FU503576079

Claims No. MT/1045879-003

Gen. Cond:  Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering:  In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake:  In order / Jammed / Leaked / Burnt or

Make of Veh: \_\_\_\_\_

Modi: Nil /  Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: 195/65 R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Bal. or Market Value: \_\_\_\_\_

Front Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 24/5/19 D.O.I. 27/5/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at Sumit

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear /  O/S / UIC / Rooftop or

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 860D - CC3/ATG/1013551 / R/1/192 <u>Sum: 9/7/2011</u> 05/19/2108
	SMK 1978K - X
	Part by Part \$1876.88 (Red: 6666.32; 78%) <u>SMK1978K</u>
	RECEIVED 11 JUL 2019
	<u>[Signature]</u> 11/7/2019

Date/Time. File Pass to?  : Preli. Report

Days Of Repair: 4

1) 11/7 Typist  : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time. File Return to?

Survey Fee:	160
Transportation:	
) S + PS. SI	
) Photos	
) Others	
TOTAL	160

2) Add Fee:  : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Report Format :  
Lump Sum / 1876.88

## Denise Tay (LKKAuto)

**From:** MTCL@income.com.sg  
**Sent:** Thursday, 11 July 2019 9:15 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

**Samsia**  
Senior Admin Assistant,  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with you

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Wednesday, 10 July 2019 9:32 AM  
**To:** MTCL@income.com.sg  
**Subject:** REQUEST CLAIM NUMBER

Dear Sir/Madam,

Request claim number

Date : 10/7/2019

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1045879-003	SMRT	SHB860D	SMK 1978K	24/5/2019	10:35	7272.94	1876.88

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

#### Vehicle Details

Vehicle No.:	SHB860D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS111395
Chassis No.:	JTDKB3FU503576079
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

#### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00

#### Intended COE Rebate Details

COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,916.00
<b>Total Rebate Amount:</b>	<b>\$31,666.00</b>

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/05/2019 09:39
Date Of Accident	24/05/2019 10:35
Exact Location Of Accident	ROBINSON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB860D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

### Driver

Name of Driver	NEO YEW SING
NRIC No	S1715075H
Date Of Birth	02/12/1965
Occupation	OUTDOOR
Date Of Driving Pass	22/04/1983
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 51  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - RELIEF  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : UNKNOWN  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS TRAVELLING STRAIGHT ALONG ROBINSON ROAD WITH A PASSENGER ON BOARD WHEN THE VEHICLE SMK1978K ABRUPTLY DASHED OUT FROM THE RIGHT MOST LANE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO BIG  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SMK1978K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver LOH JUN YONG THOMAS  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

 24/5/19  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Case Details

**Case Reference Number :**  
TAX/05/19/2108

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**  
SHB860D

**Company Type :** SMRT Taxis Pte Ltd

**Estimation ID :** EST-7021-ID

**Assigned By :** Taxi Claims Manager  
Team

**Insurance Company Name :** NTUC Income Insurance Co-operative Ltd

**Accident Date and Time :** 24/05/2019 02:35 AM

**Vehicle Age(In Months) :** 17

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	XR
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.68	Replace	1	0.00	Replace	acc /
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	0	Repair	R X
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	937.20	Replace	BUC /
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Not Give	nn X
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	82.10	25.00	61.57	Replace	0	0	Not Give	nn X
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	nn X
One Time Key In	Main			DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	nn X

Total Spare Part Cost 4,631.94

Surveyor Total 997.20

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,631.94

Final Sur Total 997.20

SMRT Recommendation											Surveyor Approval				
BOI Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	768.60	768.60	10.00	691.74	Replace	0	0	Not Give	nn X	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	nee /	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0	Not Give	} nn	
One Time Key In	Main			HINGE ASSY, REAR DOOR , UPPER RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give		
One Time Key In	Main			HINGE ASSY, REAR DOOR , LOWER RH	1	73.30	73.30	25.00	54.97	Replace	0	0	Not Give		
One Time Key In	Main			CHECK ASSY, REAR DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Not Give		
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	0	0	Not Give		
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	Rx	
Total Spare Part Cost									4,631.94	Surveyor Total		997.20			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0			
Final Spare Part Cost									4,631.94	Final Sur Total		997.20			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	50	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
Total:			1,116.00	350.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY REAR DOOR RH	378.00	0	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
<b>Total:</b>			<b>1,116.00</b>	<b>350.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
3	Main	TO TRANSFER DOOR MECHANISM	240.00	50	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
<b>Total:</b>			<b>680.00</b>	<b>90.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,631.94	997.20
Total Labour Cost	845.00	400.00
Total Spray Painting	1,116.00	350.00
Other	680.00	90.00
Overall Total	7,272.94	1,837.20
Lump Sum Repair Option		
Lump Sum Total	0.00	1,837.20
Surveyor Approved Amount		1,837.20
No of Repair Days*	5	4
Remarks		p/p repair, photo before paint.
Surveyor Name		Hwee jie

2603-20

Signature

Estimator Assesment(\$)

Surveyor Assesment(\$)



Save

Clear

Survey Date

27/05/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company




Acknowledged by Repairer

Signature:

Date:

**Section A - Accident Details**

Registration Number	SHB860D
Case Reference Number	TAX/05/19/2108
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NEO YEW SING
Type of Accident	Side Swipe
Accident Date and Time	24/5/2019 10:35 AM
Accident Reported Date and Time	24/5/2019 2:03 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	24/5/2019 10:52 AM
Replacement Vehicle Issued?	No
Job Card Number	24101649
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	25/5/2019 9:36 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,116.00	\$350.00
Total Spare Part Cost	\$4,631.94	\$1,036.88
Total Other Cost	\$680.00	\$90.00
<b>TOTAL COST</b>	<b>\$7,272.94</b> <i>2543.20</i>	<b>\$1,876.88 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	25/05/2019 9:54 AM	27/05/2019 2:34 PM
Signature	<i>[Signature]</i>	<i>[Signature]</i>
Remarks		p/p repair, photo before paint.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 50 Woodlands Industrial Park E4, Singapore  
 FAX Number : 63955592  
 Estimator Telephone Number : 65002023  
 Accident Reporting Number : 88962672

Date Generated : 07/07/2019  
 User ID : PehSuan

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1906-0484	Invoice Number	
Quotation Date	28.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$400.00 /
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$400.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESpray MIRROR COVER RH	\$180.00	\$50.00 /
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 /
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,116.00</b>	<b>\$350.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00 /
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$680.00</b>	<b>\$90.00</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	100.00	\$0.00	Replace	Repair
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
		6871012151	HINGE ASSY, FRONT DOOR, UPPER RH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given
		6873012120	HINGE ASSY, FRONT DOOR, LOWER RH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given
		6980121020	DOOR FRONT WINDOW REGULATOR SUB-ASSY	0.00	\$230.80	0.00	\$0.00	Replace	Not Given
		8571047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Not Given
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	0.00	\$1,243.90	0.00	\$0.00	Replace	Not Given
		6875020122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		6877052031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Not Given
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
<b>Total</b>					<b>\$5,902.20</b>		<b>\$1,036.88</b>		

1036.88  
 + 400.00  
 + 440.00  
 -----  
 1876.88

### Enquire Transaction History

Transaction History Details

Log Date/Time:	25 May 2019 / 09:22:14	Transaction Amount:	\$7.49
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	SMK1978K	Business Transaction Reference No.:	20190525092214710235
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ESASBAHD - BALQISH BINTE ABDUL HALIL		

Search Date / Time: 24 May 2019 10:35:00  
Insurance Company: NTUC INCOME INS CO-OP LTD  
Information displayed is correct as at the log date and time.

Enquire Related Logs      OK



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19011963/Jtf3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 17-07-2019	
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMK 1978K	Veh. Inspected	SHB 860D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1045879-003	Excess (\$)	0.00
Assign From		Assign Date	27/05/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU503576079	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	6 mm
L/H Front Tyre	195/65 R15	SAILUN	6 mm
R/H Rear Tyre	195/65 R15	SAILUN	6 mm
L/H Rear Tyre	195/65 R15	SAILUN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	24/05/2019	Inspection Date	27/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 860D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	PANEL SUB-ASSY, FRONT DOOR RH (DISC 25%)	BUCKLED	1,249.60	937.20
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	CHECK ASSY, FRONT DOOR	NOT NECESSARY	153.50	-
1	HINGE ASSY, FRONT DOOR, UPPER RH	NOT NECESSARY	82.10	-
1	HINGE ASSY, FRONT DOOR, LOWER RH	NOT NECESSARY	92.10	-
1	DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	NOT NECESSARY	230.80	-
1	DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, RH	NOT NECESSARY	768.60	-
1	PANEL SUB-ASSY, REAR DOOR, RH	NOT NECESSARY	1,243.90	-
1	HINGE ASSY, REAR DOOR, UPPER RH	NOT NECESSARY	83.30	-
1	HINGE ASSY, REAR DOOR, LOWER RH	NOT NECESSARY	73.30	-
1	CHECK ASSY, REAR DOOR	NOT NECESSARY	153.50	-
2	PIXEL STICKER @\$60.00	NOT NECESSARY	120.00	-
1	FENDER SUB-ASSY, FR, RH	TO REPAIR SEE LABOUR	933.10	-
1	COVER, OUTER MIRROR, RH	TO REPAIR SEE LABOUR	89.50	-
1	MOULDING ASSY, BODY ROCKER PANEL, RH	TO REPAIR SEE LABOUR	576.00	-
			5,962.20	1,036.88
<b>LABOUR</b>				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FR, RH, COVER, OUTER MIRROR, RH AND MOULDING ASSY, BODY ROCKER PANEL, RH.			845.00	400.00
SPRAY PAINT.			1,116.00	350.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			200.00	20.00
TO TRANSFER DOOR MECHANISM.			240.00	50.00
TO REPLACE SUNDRY PARTS.			100.00	-

Report Ref No. NS/INC19011963/Jtf3e2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,641.00	840.00
<b>GRAND TOTAL</b>			<b>8,603.20</b>	<b>1,876.88</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>1,876.88</b>

Report Ref No. NS/INC19011963/Jtf3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.