

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2019 14:58 Sendback Est	09 Jul 2019 17:41 S\$1,182.00	05 Jul 2019 16:46 Edit Adj Rpt	S\$834.00 Edit Estimates	S\$834.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BOON MENG EQUIPMENT PTE LTD , Co. Reg. No.: 198302276E, Email: FELICIACHUA@BOONMENG.COM.SG		
Main Claimant:	BOON MENG EQUIPMENT PTE LTD , Co. Reg. No.: 198302276E		
Vehicle Reg. No.:	GBF3041G	Date of Loss:	04/07/2019 09:00 - :59 [33 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMPC1900175H/DL	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SKW1987P	Policy No. (Claimant):	5093849412-01
		Excess:	
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 / 6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ECICS (08/07/2019): Alert - Adj Mandate Approved (S\$0.00) - GBF3041G - Claim Handler: Desmond Lee
- ECICS (08/07/2019): Alert - Adj Mandate Approved (S\$0.00) - GBF3041G - Claim Handler: Desmond Lee

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBF3041G (DMPC1900175H/DL)
[SKW1987P]
TP
BOON MENG EQUIPMENT PTE LTD
Jul 4 2019 9:00AM
[BOON MENG EQUIPMENT PTE LTD]
Kan Fook Sing Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	09/07/19 17:41	Repairer Estimates	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 09:22	General View	Load JPG ☒	☒
2	27/08/19 09:22	General View	Load JPG ☒	☒
3	27/08/19 09:22	General View	Load JPG ☒	☒
4	27/08/19 09:22	General View	Load JPG ☒	☒
5	27/08/19 09:22	General View	Load JPG ☒	☒
6	27/08/19 09:22	General View	Load JPG ☒	☒
7	27/08/19 09:22	General View	Load JPG ☒	☒
8	27/08/19 09:22	General View	Load JPG ☒	☒
9	27/08/19 09:22	General View	Load JPG ☒	☒
10	27/08/19 09:22	General View	Load JPG ☒	☒
11	27/08/19 09:22	General View	Load JPG ☒	☒
12	27/08/19 09:22	General View	Load JPG ☒	☒
13	27/08/19 09:22	General View	Load JPG ☒	☒
14	27/08/19 09:22	General View	Load JPG ☒	☒
15	27/08/19 09:22	General View	Load JPG ☒	☒
16	27/08/19 09:22	General View	Load JPG ☒	☒
17	27/08/19 09:22	General View	Load JPG ☒	☒
18	27/08/19 09:22	General View	Load JPG ☒	☒
19	27/08/19 09:22	General View	Load JPG ☒	☒
20	27/08/19 09:22	General View	Load JPG ☒	☒
21	27/08/19 09:22	General View	Load JPG ☒	☒
22	27/08/19 09:22	General View	Load JPG ☒	☒
23	27/08/19 09:22	General View	Load JPG ☒	☒
24	27/08/19 09:22	General View	Load JPG ☒	☒
25	27/08/19 09:22	General View	Load JPG ☒	☒
26	27/08/19 09:22	General View	Load JPG ☒	☒
27	27/08/19 09:22	General View	Load JPG ☒	☒
28	27/08/19 09:22	General View	Load JPG ☒	☒
29	27/08/19 09:22	General View	Load JPG ☒	☒
30	27/08/19 09:22	General View	Load JPG ☒	☒
31	27/08/19 09:22	General View	Load JPG ☒	☒
32	27/08/19 09:28	Reinspection Photo	Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
33	27/08/19 09:28	Reinspection Photo	Load JPG	☒
34	27/08/19 09:28	Reinspection Photo	Load JPG	☒
35	27/08/19 09:28	Reinspection Photo	Load JPG	☒
36	27/08/19 09:28	Reinspection Photo	Load JPG	☒
37	27/08/19 09:34	Reinspection Photo	Load JPG	☒
38	27/08/19 09:34	Reinspection Photo	Load JPG	☒
39	27/08/19 09:34	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	04/07/19 14:59	E-filed GIA report	Load PDF	

Linked Accident Report Documents

Photos/Images			View	View in Browser
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	04/07/19 11:19	Accident Photo	Load JPG	☒
2	04/07/19 11:19	Accident Photo	Load JPG	☒
3	04/07/19 11:19	Accident Photo	Load JPG	☒
4	04/07/19 11:19	Accident Photo	Load JPG	☒
5	04/07/19 11:19	Accident Photo	Load JPG	☒
6	04/07/19 11:19	Accident Photo	Load JPG	☒
7	04/07/19 11:19	Accident Photo	Load JPG	☒
8	04/07/19 11:19	Accident Photo	Load JPG	☒
9	04/07/19 11:19	Accident Photo	Load JPG	☒
10	04/07/19 11:19	Accident Photo	Load JPG	☒
11	04/07/19 11:19	Accident Photo	Load JPG	☒
12	04/07/19 11:19	Accident Photo	Load JPG	☒
13	04/07/19 11:19	Accident Photo	Load JPG	☒
14	04/07/19 11:19	Accident Photo	Load JPG	☒
15	04/07/19 11:19	Accident Photo	Load JPG	☒
16	04/07/19 11:19	Accident Photo	Load JPG	☒
17	04/07/19 11:19	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	04/07/19 11:21	Accident Sketch Plan	Load TIF	
2	04/07/19 11:21	Accident Sketch Plan	Load TIF	
3	04/07/19 11:21	certificate of insurance	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19011966/UTD3S2

Date: 06/09/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No:
 Claimant Vehicle No: GBF3041G Insured Vehicle No: SKW1987P
 Date of Loss: 04/07/2019 Nature of Claim: TP Claim No: DMPC1900175H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3041G**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2638027
 Reg. Date: 06/09/2016 (Man. Year: 2016) Chassis No: JTFAT35Y60K206799
 Colour: Silver Odometer: 47900 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15 Rear Tyre Size: 155 R12 (D)
 Front Left Side: HIFLY 6 mm Rear Left Side: HIFLY 6/6 mm
 Front Right Side: HIFLY 6 mm Rear Right Side: HIFLY 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	242.00	99.00	143.00	59.09
Miscellaneous Items	30.00	15.00	15.00	50.00
Labour	510.00	420.00	90.00	17.65
Paintwork Labour	400.00	300.00	100.00	25.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,182.00	834.00	348.00	29.44
+ GST 7.00/7.00% (S\$)	82.74	58.38	24.36	29.44
Nett Amount (S\$)	1,264.74	892.38	372.36	29.44

INSPECTION

Date of Assignment: 05/07/2019 Present Location: Kan Fook Sing Motor Workshop (Defu)
 Date Inspected: 22/07/2019 Inspected At: Kan Fook Sing Motor Workshop (Defu)
 Estimated Period of Repair: 3.0 days No. 61 Defu Lane 12
 Singapore 539147

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3041G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LAMP RH (WCP)	Cracked	75.00 F	*75.00 F
2	1		*REAR LAMP PANEL RH (WCP)	Repair	50.00 F	*- F
3	1		*REAR TAILGATE BRACKET RH (WCP)	Repair	80.00 F	*- F
4	1		*REAR BRACKET STOPPER RH (WCP)	Cut	15.00 F	*15.00 F

F=Franchise part.

Sub Total (\$\$)	220.00	90.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	22.00	9.00
Total Parts (\$\$)	242.00	99.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	REAR NUMBER PLATE (BENT)	30.00	15.00
Sub Total (S\$)			30.00	15.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	400.00	300.00
<u>Labour Items</u>				
2	TO CHECK WIRING SYSTEM	New	30.00	20.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	480.00	400.00
Gross Labour Cost (S\$)			910.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >