

ASS. REC. BY:

Surveyor: Adrian

REF: CS/III19011968/Arf302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Cubiel Wee

of III

Date/Time: 5/7/19 @ 5.30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 838M

Insured:

SHC 2334M

at Workshop m/s

Yap Lee Motor

Tel:

6844 1555

of

1 Kabi Bukit Ave 6 #01-26

Policy No:

Claim No:

MCT19070080

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 4/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.24am 8/7/19

Person Contacted:

Shirley

Vehicle IN / OUT

Date/Time

Action/Instruction

Inspected ✓

SHC 2334M: CS3/III1900108/Gsd3e2-1 D.O.A: 29/12/2018

SKF 838M: X

16/7/19

Adrian confirmed LS \$3100 (Red 5928.23, 66%)

ASS. REC. BY:

REF:

III

ASSIGNMENT

From:

Date: 8/7/2019

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SKF838M

at Workshop m/s

Yap Lee Motor

of

1 Kaki Bukit Ave 6 #01-26

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKF838M

Yr Regn: 2016, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Fielder

c.c

1496

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

84123

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NRE1618001511

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

08/07/19

Survey held at

Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear A/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 11

RECEIVED 10 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

16/7 - typist

Report Format:

Merimen

Lump Sum / LBJ: (\$

3100/2

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

250

11

261

Veron Chen (LKKAuto)

From: Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Sent: Tuesday, 16 July 2019 10:21 AM
To: Veron Chen (LKKAuto); Motor Claim - III
Cc: SUR
Subject: III Ref: MCT19070080 RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Veron,

Claim number is MCT19070080. Accident involving SHC2334M(III) & SKF838M on 04/07/2019

Daniel Pooi

**Motor Claims Department
India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 16 July, 2019 9:50 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Pooi Chin Han Daniel <danielpooi@iii.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Gabriel,

Please provide claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 8 July 2019 9:27 AM
To: 'Motor Claim - III' <motorclaim@iii.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Pooi Chin Han Daniel' <danielpooi@iii.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Friday, 5 July 2019 5:30 PM

To: Ruby Ong <ruby@htapartners.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Pooi Chin Han Daniel <danielpooi@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKF838M and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: 05 July, 2019 2:25 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our client is agreeable to appoint **Adrian Ling, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SKF 838M**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)

Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Friday, 5 July 2019 9:02 AM

To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: 04 July, 2019 5:34 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Importance: High

Your ref: SHC 2334M

Our ref: TCL.MH.ro.50426.19.ylm

WITHOUT PREJUDICE

1 March 2019

URGENT

India International Insurance Pte Ltd

64 Cecil Street
#04-00 IOB Building
Singapore 049711

Attn: Motor Claims Dept

By Email only

Dear Sirs

CLAIMANT: LECCA CAR LEASING

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKF 838M & SHC 2334M ALONG AYE TOWARDS TUAS ON 4 JULY 2019 @ 1025HRS

We are instructed by Lecca Car Leasing to notify you of a road traffic accident on 4 July 2019 at about 1025hrs along AYE towards Tuas involving our client's vehicle registration number SKF 838M and vehicle registration number SHC 2334M driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or

responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.


If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by AVG antivirus software.
www.avg.com

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 5 July 2019 5:30 PM
To: Ruby Ong; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Pooi Chin Han Daniel
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKF838M and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: 05 July, 2019 2:25 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our client is agreeable to appoint **Adrian Ling, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SKF 838M**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6

Contact Person : Mrs Chua / Shirley : 6844 1555

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Friday, 5 July 2019 9:02 AM

To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext + 248

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: 04 July, 2019 5:34 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKF 838M [OUR REF. TCL.GCN.RO.50426.19.YLM]

Importance: High

Your ref: SHC 2334M
Our ref: TCL.MH.ro.50426.19.ylm

WITHOUT PREJUDICE

1 March 2019

URGENT

India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711
Attn: Motor Claims Dept

By Email only

Dear Sirs

CLAIMANT: LECCA CAR LEASING

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SKF 838M & SHC 2334M ALONG AYE TOWARDS TUAS ON 4 JULY 2019 @ 1025HRS

We are instructed by Lecca Car Leasing to notify you of a road traffic accident on 4 July 2019 at about 1025hrs along AYE towards Tuas involving our client's vehicle registration number SKF 838M and vehicle registration number SHC 2334M driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/07/2019 15:01
Date Of Accident	04/07/2019 10:25
Exact Location Of Accident	AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKF838M
Insured/Policyholder	
Name Of Registered Owner	LECCA CAR LEASING
Co Reg No	53247626C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65333312
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA FIELDER-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN866064
Cover Note Number	
Driver	
Name of Driver	QUEK SENG INN
NRIC No	S8018091H
Date Of Birth	26/06/1980
Occupation	INDOOR
Date Of Driving Pass	18/05/2007
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90881024
Fax Number	
Contact Number	
Email Address	ALEX.QUEK@OCTOPUSGROUP.COM.SG

Address BLK 131B KIM TIAN ROAD #10-177
SINGAPORE
Postcode 162131
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : DUONG THUY LIEN
GENDER: : FEMALE
Passenger 2 NAME: : AIDEN QUEK
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC2334M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver LAY TEO KOO
NRIC/Passport Number S0208673E
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

Driver's Signature: _____
 (if driver is not the policyholder)
 Date & Time: 4/11

Sketch Plan #2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

(/We declare the foregoing particulars are true in every respect.

[illegible]

Policyholder's Signature _____

Date & Time

Driver's Signature _____

(I driver is not the policyholder)

Date & Time:

Reporting Centre Person(s) Signature: _____

YAP LEE MOTOR

No 1 Kaki Bukit Avenue 6 #01-26 AutoBay @ Kaki Bukit

Singapore 417883

Tel : 6844 1555 Fax : 6844 1311

8 July 2019

REG NO. : SKF 838 M
MAKE/MODEL : TOYOTA FIELDER

7P11
Veron.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear tailgate <i>Repair</i>	\$ 986.10 <i>x</i>
1	Rear tailgate lamp	\$ 425.00 <i>x</i>
1	Rear tailgate lock	\$ 144.20 <i>r</i>
1	Rear tailgate rubber	\$ 222.10 <i>x</i>
1	Rear tailgate "X" emblem	\$ 63.10 <i>-</i>
1	Rear tailgate "FIELDER" emblem	\$ 54.20 <i>-</i>
1	Rear tailgate "COROLLA" emblem	\$ 55.20 <i>-</i>
1	Rear taillamp -L/H <i>cracked.</i>	\$ 534.70 <i>-</i>
1	Rear end panel <i>Dented.</i>	\$ 645.70 <i>-</i>
1	Rear end panel inner garnish <i>Not New</i>	\$ 155.90 <i>x</i>
1	Rear bumper <i>Distorted</i>	\$ 889.20 <i>✓</i>
1	Rear bumper bracket <i>Not New</i>	\$ 72.10 <i>x</i>
1	Rear bumper clip (1 set) <i>New</i>	\$ 50.00 <i>30</i>
1	Rear bumper inner sponge <i>Not New</i>	\$ 121.50 <i>x</i>
1	Rear bumper reflector <i>cracked</i>	\$ 88.90 <i>✓</i>
1	Rear bumper side retainer <i>New</i>	\$ 69.20 <i>-</i>
1	Rear fender -L/H <i>Repair</i>	\$ 1,435.00 <i>x</i>
1	Rear fender inner shield <i>Deformed</i>	\$ 162.20 <i>✓</i>
1	Rear fender inner shield clip (1 set) <i>New</i>	\$ 50.00 <i>10</i>
		\$ 6,224.30
	Less 25%	\$ 1,556.08
		\$ 4,668.23

2602.40

1951.80

SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>Not New</i>	\$ 80.00 <i>x</i>
1	Rear reverse sensor (1 set) <i>Damaged.</i>	\$ 350.00 <i>200</i>
1	Rear fender quarter glass sealant <i>Not New</i>	\$ 80.00 <i>x</i>
		\$ 510.00

200

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$ 150.00 <i>60</i>
3	To remove and refit rear reverse sensor.	\$ 150.00 <i>50</i>
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 120.00 <i>x</i>
5	To remove and refit rear windscreen glass.	\$ 180.00 <i>x</i>
6	To remove and refit quarter glass.	\$ 120.00 <i>x</i>
7	To apply undercoating.	\$ 150.00 <i>80</i>
8	Panel beating.	\$ 1,500.00 <i>700</i>
9	To re-spray painting on the affected areas.	\$ 1,400.00 <i>800</i>
		\$ 3,850.00

1720

total: 3871.80

1/5 3.1K

06 Days

GRAND TOTAL :

PAGE 1 OF 1

\$ 9,028.23

3.1K

LKK Auto Consultancy
the Repairer of the vehicle
To remove and refit rear reverse sensor.
To transfer rear tailgate mechanism and wiring assembly.
To remove and refit rear windscreen glass.
To remove and refit quarter glass.
To apply undercoating.
Panel beating.
To re-spray painting on the affected areas.
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(Date)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19011968/AVF3N2

Date: 23/07/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SKF838M	Insured Vehicle No :	SHC2334M
Date of Loss:	04/07/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF838M	Engine No:	2NR8503522
Make & Model:	TOYOTA COROLLA FIELDER, 1.5 (A)	Chassis No:	NRE1618001511
Reg. Date:	15/01/2016 (Man. Year: 2015)	Odometer:	84123 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,178.22	2,151.80	3,026.42	58.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,720.00	2,130.00	55.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,028.22	3,871.80	5,156.42	57.11
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	9,028.22	3,100.00	5,928.22	65.66

INSPECTION

Date of Assignment:	05/07/2019	
Date Inspected:	08/07/2019	Inspected At:
		Yap Lee Motor (HQ)
		1 Kaki Bukit Avenue 6, #01-26 Autobay
		@ Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jul 2019)	
Parts:	N/A	TOYOTA COROLLA FIELDER 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF838M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	986.10 FL	*- FL
2	1		*REAR TAILGATE LAMP	Not Necessary	425.00 FL	*- FL
3	1		*REAR TAILGATE LOCK	Not Necessary	144.20 FL	*- FL
4	1		*REAR TAILGATE RUBBER	Not Necessary	222.10 FL	*- FL
5	1		*REAR TAILGATE X EMBLEM	Necessary	63.10 FL	*63.10 FL
6	1		*REAR TAILGATE FIELDER EMBLEM	Necessary	54.20 FL	*54.20 FL
7	1		*REAR TAILGATE COROLLA EMBLEM	Necessary	55.20 FL	*55.20 FL
8	1		*REAR TAILLAMP-L/H	Cracked	534.70 FL	*534.70 FL
9	1		*REAR END PANEL	Dented	645.70 FL	*645.70 FL
10	1		*REAR END PANEL INNER GARNISH	Not Necessary	155.90 FL	*- FL
11	1		*REAR BUMPER	Distorted	889.20 FL	*889.20 FL
12	1		*REAR BUMPER BRACKET	Not Necessary	72.10 FL	*- FL
13	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
14	1		*REAR BUMPER INNER SPONGE	Not Necessary	121.50 FL	*- FL
15	1		*REAR BUMPER REFLECTOR	Cracked	88.90 FL	*88.90 FL
16	1		*REAR BUMPER SIDE RETAINER	Necessary	69.20 FL	*69.20 FL
17	1		*REAR FENDER-L/H	Repair	1,435.00 FL	*- FL
18	1		*REAR FENDER INNER SHIELD	Deformed	162.20 FL	*162.20 FL
19	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*10.00 FL
20	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
22	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,734.30	2,802.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,556.08	650.60
Total Parts (\$\$)	5,178.22	2,151.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE AND REFIT QUARTER GLASS	New	120.00	0.00
7	TO APPLY UNDERCOATING	New	150.00	80.00
8	PANEL BEATING	New	1,500.00	700.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	800.00
Gross Labour Cost (\$\$)			3,850.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >