



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
MR PHUA HUA SENG 22 Begonia Dr Singapore 809880 809880 Contact No	Cust No/Name	/MR PHUA HUA SENG
	Reg No/Reg Date	/
	Date In/Mileage	/ 0
	Chassis No	
	Engine No	
	Make/Model	/
	Colour/Trim	/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00001	Cash	05/07/2019/ 16:26		323 / ChrisBulaclac	27852			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088							350.00
	TO PERFORM COMPUTER DIAGNOSTIC , COMPUTER RESET & PROGRAMMING							
S	MIPNT88088							100 150.00
	TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS							
S	MIPNT88088							50.00
	TO SUPPLY FRONT NUMBER PLATE WITH CASING							
S	MIPNT88088							800 2400.00
	TO REPLACE FRONT BUMPER, REINFORCEMENT, BRACKETS RADIATOR GRILLE ETC.							
S	MIPNT98088							600 1200.00
	SPRAY PAINTING FRONT BUMPER & ACCIDENT REPAIRED AREAS							
S	MIPNT88088							1800.00
	FRONT BUMPER							
S	MIPNT88088							660.00
	FRONT BUMPER REINFORCEMENT							
S	MIPNT88088							224.00
	FRONT BUMPER SPONGE							
S	MIPNT88088							60.00
	FRONT BUMPER CLIPS SET							
S	MIPNT88088							60.00
	FRONT BUMPER RIVET SET							
S	MIPNT88088							114.00
	PLATE NUMBER BASE GARNISH							
S	MIPNT88088							180.00
	LOWER BUMPER CENTRE GRILLE							
S	MIPNT88088							720.00
	RADIATOR GRILLE ASSY							
S	MIPNT88088							340.00
	FRONT SENSOR BUMPER CTR @ 2 PCS							
Z	NOTES							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MR PHUA HUA SENG 22 Begonia Dr Singapore 809880 809880 Contact No	Cust No/Name	/MR PHUA HUA SENG
	Reg No/Reg Date	/
	Date In/Mileage	/ 0
	Chassis No	
	Engine No	
	Make/Model	/
	Colour/Trim	/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	05/07/2019/ 16:26		323 / ChrisBulaciac	27852

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
MR PHUA HUA SENG MERCEDES BENZ S400 HYBRID 3.5 (A) EM30K Z NOTES ACCIDENT ON 04/07/2019 ALONG UPPER THOMSON ROAD OWNER CLAIMING THIRD PARTY TP # SJX1545T TP INSURER : EQ INSURANCE				
<p>the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				

Estimate

Steve CLKK
8322 8813

wh AM/L 8/7/19, 12.11pm
3 days
P/P
Ry Beh spy

Confirm & accepted by

Parts	0.00
Labour	0.00
Standard Menu	0.00
Specialist Job	8,308.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	8,308.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.