

CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 Contact No	Cust No/Name	/MR PHUA HUA SENG
	Reg No/Reg Date	/
	Date In/Mileage	/ 0
	Chassis No	
	Engine No	
	Make/Model	/
	Colour/Trim	/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000061	Credit	17/07/2019/ 09:42	DS	303 / Renemer	27852		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
S	MIPNT88088						350.00
	TO PERFORM COMPUTER DIAGNOSTIC , COMPUTER RESET & PROGRAMMING						
S	MIPNT88088						100.00
	TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088						50.00
	TO SUPPLY FRONT NUMBER PLATE WITH CASING						
S	MIPNT88088						800.00
	TO REPLACE FRONT BUMPER,RADIATOR GRILLE,SPONGE,BRACKETS, PLATE NO. GARNISH,LOWER GRILLE,ETC. STRAIGHTE,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT98088						600.00
	SPRAY PAINTING FRONT BUMPER & ACCIDENT REPAIRED AREAS						
S	MIPNT88088						1800.00
	FRONT BUMPER						
S	MIPNT88088						224.00
	FRONT BUMPER SPONGE						
S	MIPNT88088						60.00
	FRONT BUMPER CLIPS SET						
S	MIPNT88088						60.00
	FRONT BUMPER RIVET SET						
S	MIPNT88088						114.00
	PLATE NUMBER BASE GARNISH						
S	MIPNT88088						180.00
	LOWER BUMPER CENTRE GRILLE						
S	MIPNT88088						720.00
	RADIATOR GRILLE ASSY						
S	MIPNT88088						340.00
	FRONT SENSOR BUMPER CTR @ 2 PCS						
Z	NOTES						


Confirm & accepted by

ATTN: STEVE

FINALIZATION 17/7

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 Contact No	Cust No/Name	/MR PHUA HUA SENG
	Reg No/Reg Date	/
	Date In/Mileage	/ 0
	Chassis No	
	Engine No	
	Make/Model	/
	Colour/Trim	/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	17/07/2019/ 09:42	DS	303 / Renemer	27852


Description of Goods / Services	Qty	Unit Price	Disc%	Amount
MR PHUA HUA SENG MERCEDES BENZ S400 HYBRID 3.5 (A) EM30K Z NOTES ACCIDENT ON 04/07/2019 ALONG UPPER THOMSON ROAD OWNER CLAIMING THIRD PARTY TP # SJX1545T TP INSURER : EQ INSURANCE				
<h1>Estimate</h1>				

Confirm & accepted by

Parts	0.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,398.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	5,398.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**


Invoice Name & Address	Owner Name & Vehicle Info	
MR PHUA HUA SENG 22 Begonia Dr Singapore 809880 809880 Contact No	Cust No/Name	/MR PHUA HUA SENG
	Reg No/Reg Date	/
	Date In/Mileage	/ 0
	Chassis No	
	Engine No	
	Make/Model	/
	Colour/Trim	/

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00001	Cash	05/07/2019/ 16:26		323 / ChrisBulaclac	27852		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
S	MIPNT88088						350.00
	TO PERFORM COMPUTER DIAGNOSTIC , COMPUTER RESET & PROGRAMMING						
S	MIPNT88088					100	150.00
	TO CHECK LIGHTING & WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088						50.00
	TO SUPPLY FRONT NUMBER PLATE WITH CASING						
S	MIPNT88088					800	2400.00
	TO REPLACE FRONT BUMPER, REINFORCEMENT, BRACKETS 800 RADIATOR GRILLE ETC.						
S	MIPNT98088					600	1200.00
	SPRAY PAINTING FRONT BUMPER & ACCIDENT REPAIRED 600 AREAS						
S	MIPNT88088						1800.00
	FRONT BUMPER ? / CRU						
S	MIPNT88088						660.00
	FRONT BUMPER REINFORCEMENT ? X NAI						
S	MIPNT88088						224.00
	FRONT BUMPER SPONGE ? / BR						
S	MIPNT88088						60.00
	FRONT BUMPER CLIPS SET / MC						
S	MIPNT88088						60.00
	FRONT BUMPER RIVET SET / MC						
S	MIPNT88088						114.00
	PLATE NUMBER BASE GARNISH / CRU						
S	MIPNT88088						180.00
	LOWER BUMPER CENTRE GRILLE ? / BR						
S	MIPNT88088						720.00
	RADIATOR GRILLE ASSY / BR						
S	MIPNT88088						340.00
	FRONT SENSOR BUMPER CTR @ 2 PCS / MC						
Z	NOTES						

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MR PHUA HUA SENG 22 Begonia Dr Singapore 809880 809880 Contact No	Cust No/Name /MR PHUA HUA SENG Reg No/Reg Date / Date In/Mileage / 0 Chassis No Engine No Make/Model / Colour/Trim /

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	05/07/2019/ 16:26		323 / ChrisBulaclac	27852

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
MR PHUA HUA SENG MERCEDES BENZ S400 HYBRID 3.5 (A) EM30K Z NOTES ACCIDENT ON 04/07/2019 ALONG UPPER THOMSON ROAD OWNER CLAIMING THIRD PARTY TP # SJX1545T TP INSURER : EQ INSURANCE				
<p>the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>				

Estimate

Steve (CLKK)
8322 8813wh M/L 8/7/19, 12.11pm
3 days
PIP
Ry Beh spy

Confirm & accepted by

Parts	0.00
Labour	0.00
Standard Menu	0.00
Specialist Job	8,308.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	8,308.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.