

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUIRENS RENTAL PTE LTD
 c/o 46 Lenton Plain
 Singapore 786548

Not Authorized
11 Days @
Monday After Rain
8 days

Date: 06/07/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA COROLLA AXIO/ SLE 7886 X		
1 pc	rear boot lid	br 796.40 ✓
1 pc	rear boot emblem logo	na 69.20 ✓
1 pc	rear boot emblem ' AXIO '	na 55.70 ✓
1 pc	rear boot emblem ' COROLLA '	na 54.10 ✓
2 pcs	rear boot hinge @ 195.20	R 390.40 X
1 pc	rear boot lock	nd 220.10 ✓
1 pc	rear boot lock catch	R 68.40 X
1 pc	rear boot weatherstrip 211.60	cr 237.60 ✓
1 pc	rear boot outer chrome moulding	br 196.70 X
1 pc	rear bumper	br 565.70 ✓
2 pcs	rear bumper side retainer <i>MSS</i> @ 78.60	ols dis 157.20 ✓
2 pcs	rear bumper side reflector @ 196.30	su 392.60 X
2 pcs	rear bumper bracket @ 197.20	R 394.40 ✓
1 pc	rear end panel	br 576.20 ✓
1 pc	rear end panel garnish 205.30	cm 375.30 ✓
2 pcs	rear tail lamp @ 452 <i>MSS</i> <i>ols urgent</i> @ 577.60	904 1,155.20 ✓
2 pcs	rear tail lamp housing panel @ 314.20	R 628.40 X
2 pcs	rear tail lamp side clip @ 3.60	na 7.20 ✓
2 pcs	rear tail rubber pad @ 18.60	su 37.20 X
	258 sub-total(a)	6,378.00
1 pc	front bonnet 808.70	br 956.10 ✓
1 pc	front bonnet lock	R 78.60 X
1 pc	front bumper 552.25	br/crm 667.10 ✓
1 pc	front bumper reinforcement 340	br 357.10 ✓
1 pc	front bumper reinforcement sponge pad 98.80	cm 316.50 ✓
1 pc	front bumper centre grille	cm 295.60 ✓
1 pc	front bumper centre grille cover	dis 76.10 ✓
2 pcs	front bumper fog lamp side cover @ 96.30	su 192.60 X
2 pcs	front head lamp assy @ 805.40 <i>ols urgent</i> @ 974.40	1,948.80 ✓
2 pcs	front head lamp panel @ 274.20	R 548.40 X
1 pc	front centre top panel	br 265.60 ✓
1 pc	front centre panel cover	R 295.40 X
1 pc	front centre brace panel	R 197.60 X
	258 sub-total(b1)	6,195.50

	(a) + (b1)		12,573.50
12 pcs	front bumper clip	@ 3.60	<i>mc</i> 43.20 ✓
1 pc	front grille pad		<i>nsp</i> 195.60 X
1 pc	front grille top chrome		<i>nsp</i> 196.10 X
2 pcs	front grille lower chrome	@ 117.30	<i>nsp</i> 234.60 X
1 pc	front grille emblem logo		<i>mc</i> 79.60 ✓
		sub-total(b2)	749.10
	(a) + (b1) + (b2)	sub-total	13,322.60
		less 25%	3,330.65
		sub-total	9,991.95
	number plate	s.nett	<i>nc</i> 35.00 } 45.50
	number plate casing	s.nett	35.00
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,650.00 <i>1000</i>
	To check wiring system.		50.00 <i>40</i>
	To apply putty and spray painting on affected areas.		1,450.00 <i>1200</i>
	To apply rust proofing on affected areas.		150.00 <i>90</i>
	To apply waterproof sealant on affected areas.		120.00 <i>30</i>
		Total	13,481.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 6452 8211 FAX: 6451 7423

ESTIMATE

MCQUEEN RENTALS PTE LTD

c/o 46 Lentor Plain
 Singapore 786548

Date : 26/2/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SUPPLEMENTARY FORTOYOTA AXIO / SLE 7886 X	
1 pc	air-con condensor	✓ 1,086.10
1 pc	radiator	X 1,175.70
	puncture	
	serviceable	
	sub-total	2,261.80
	less 25%	565.45
	sub-total	1,696.35
1 pc	radiator coolant	X 38.00
	<input type="checkbox"/> ot Necessary	
	s.nett @ 38.00	
	total	1,734.35