

Kp

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

*Not Authorized*  
*11 Sep 8?*  
*Prermy After Paint*

MCQUIRENS RENTAL PTE LTD  
c/o 46 Lenton Plain  
Singapore 786548

Date: 06/07/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA COROLLA AXIO/ SLE 7886 X</b>		
1 pc	rear boot lid	Bur 796.40
1 pc	rear boot emblem logo	na 69.20
1 pc	rear boot emblem ' AXIO '	na 55.70
1 pc	rear boot emblem ' COROLLA '	na 54.10
2 pcs	rear boot hinge @ 195.20	na 390.40
1 pc	rear boot lock	na 220.10
1 pc	rear boot lock catch	na 68.40
1 pc	rear boot weatherstrip	115-SU na 237.60
1 pc	rear boot outer chrome moulding	na 196.70
1 pc	rear bumper	Bu 565.70
2 pcs	rear bumper side retainer @ 78.60	olst 157.20
2 pcs	rear bumper side reflector @ 196.30	na 392.60
2 pcs	rear bumper bracket @ 197.20	na 394.40
1 pc	rear end panel	na 576.20
1 pc	rear end panel garnish	dit 375.30
2 pcs	rear tail lamp <i>olst cm</i> @ 577.60	1,155.20
2 pcs	rear tail lamp housing panel @ 314.20	na 628.40
2 pcs	rear tail lamp side clip @ 3.60	na 7.20
2 pcs	rear tail rubber pad @ 18.60	na 37.20
sub-total(a)		6,378.00
1 pc	front bonnet	na 956.10
1 pc	front bonnet lock	na 78.60
1 pc	front bumper	Bu/na 667.10
1 pc	front bumper reinforcement	Bu 357.10
1 pc	front bumper reinforcement sponge pad	cm 316.50
1 pc	front bumper centre grille	cm 295.60
1 pc	front bumper centre grille cover	na 76.10
2 pcs	front bumper fog lamp side cover @ 96.30	na 192.60
2 pcs	front head lamp assy @ 974.40	na 1,948.80
2 pcs	front head lamp panel @ 274.20	na 548.40
1 pc	front centre top panel	na 265.60
1 pc	front centre panel cover	na 295.40
1 pc	front centre brace panel	na 197.60
sub-total(b1)		6,195.50

	(a) + (b1)		12,573.50	
12 pcs	front bumper clip	@ 3.60	<i>Mr</i> 43.20	<i>✓</i>
1 pc	front grille pad		<i>Red</i> 195.60	<i>✓</i>
1 pc	front grille top chrome		<i>CM</i> 196.10	<i>✓</i>
2 pcs	front grille lower chrome	@ 117.30	<i>NIP</i> 234.60	<i>X</i>
1 pc	front grille emblem logo		<i>Mr</i> 79.60	<i>✓</i>
		sub-total(b2)	749.10	
	(a) + (b1) + (b2)	sub-total	13,322.60	
		less 25%	3,330.65	
		sub-total	9,991.95	
	number plate	s.nett	<i>Red</i> 35.00	} 45.00
	number plate casing	s.nett	35.00	
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,650.00	<i>1100l</i>
	To check wiring system.		50.00	<i>40l</i>
	To apply putty and spray painting on affected areas.		1,450.00	<i>1200l</i>
	To apply rust proofing on affected areas.		150.00	<i>90l</i>
	To apply waterproof sealant on affected areas.		120.00	<i>30l</i>
		Total	13,481.95	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_