COMFORTDELGRO

Our Ref: 305309096

Date: 05.07.2019

Time of Fax: (815kg)

Via Fax: emil

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Your Insured: SLP 3504S

Date of Acc: 04 07. 2019

Company Registration No: 199506048W

Workshop

Attn: Motor Claims Dept.

Dear Sirs

59 Loyang Drive Singapore 508969

Fax no. 6546 8156

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Tel no. 62148355 or Hp no. 98240811 Lim Kwok Eng. Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305 Lim Tien Siong Tel no. 62148398 or Hp no. 96358546 Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006

Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

Larry Ng Tel: 6214 8316

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

L . S Larry Ng

for Vice President Crash Repairs & Claims Recovery











COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

MAKE

VEHICLE NO : SHD3054J

: HYUNDAI

MODEL : i40 DOA: 4. Jul. 2019

5. Jul. 2019

<u>AXA</u>

DATE:

Qty Parts Descrip	Parts Description/ Labour		Unit Price	Amount	
1 Front Door – RH				\$1,403.00	-
1 Rear Door – RH				\$1,351.10	
1 Rear Fender – RH				\$566.30	
1 Rocker Panel Garnish —	RH			\$483.60	
1 Rear Bumper				\$553.00	
10 Rear Bumper Clips			\$2.20	\$22.00	
1 Rear Wheel Cover – RH				\$107.10	
	SUB TOTAL			\$4,486.10	
	LESS 20%			\$897.22	
	DISCOUNTED TOTAL			\$3,588.88	
			1 4		
1 Front Door Comfort Log	0			\$75.00	
1 Rear Door APP Sticker				\$80.00	
1 Rear Bumper Rubber M	at			\$50.00	Nett
				\$205.00	
Labour Charge					
1 Panel Beating				\$750.00	1
1 Spray Painting Charge				\$1,000.00	
1 Wiring Charge				\$100.00	
1 Tuff Kote				\$100.00	
2 Transfer of Door			\$150.00	\$300.00	
	TOTAL LABOUR	₹		\$2,250.00	
	ESTIMATE TOTA	4		\$6,043.88	
			5		
			, , , , , , , , , , , , , , , , , , ,		_
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will					
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					