

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Muhammad Razi Bin Ahmad

Accident Date : 16-Mar-19

Vehicle No : FBM 4088 D

Vehicle Model : Honda CB400

## Estimated Repair Costs

| Qty | Description             | Amount S(\$) |
|-----|-------------------------|--------------|
|     | <u>List Items</u>       |              |
| 1   | Front side cowling -L/H | \$ 320.00    |
| 1   | Front fender            | \$ 196.00    |
| 1   | Front cowling           | \$ 280.00    |
| 1   | Headlamp                | \$ 380.00    |
| 2   | Fork inner tubes        | \$ 620.00    |
| 2   | Fork outer tubes        | \$ 640.00    |
| 1   | Fork under bracket      | \$ 335.00    |
| 1   | Front brake disc        | \$ 560.00    |
| 1   | Front rim shaft         | \$ 68.00     |
| 1   | Front sport rim         | \$ 1,100.00  |
| 1   | Handle-bar              | \$ 145.00    |
| 2   | Handle-bar ends         | \$ 60.00     |
| 1   | Hand-grip, (1 set)      | \$ 80.00     |
| 2   | Side mirrors            | \$ 240.00    |
| 1   | Clutch lever            | \$ 58.00     |
| 1   | Brake lever             | \$ 65.00     |
| 1   | Front signal            | \$ 176.00    |
| 1   | Front footrest          | \$ 75.00     |
| 1   | Front footrest bracket  | \$ 245.00    |
| 1   | Gear pedal              | \$ 95.00     |
| 1   | Rear footrest           | \$ 70.00     |
| 1   | Rear footrest bracket   | \$ 110.00    |
| 1   | Main stand              | \$ 145.00    |
| 1   | Side stand              | \$ 80.00     |
| 1   | Rear signal -L/H        | \$ 176.00    |
|     |                         | \$ 6,319.00  |
|     |                         | \$ 631.90    |
|     |                         | \$ 5,687.10  |

Less 10%

Final total \$1200

4406  
3965.40

Special Nett Items

|   |                         |        |          |     |
|---|-------------------------|--------|----------|-----|
| 1 | Number plate ( 1 set )  | \$ 17  | 28.00    | X   |
| 2 | Fork oils               | \$ net | 30.00    | 176 |
| 2 | Fork oil seals          | \$ net | 56.00    | 176 |
| 1 | Steering cone ( 1 set ) | \$ net | 80.00    | 7   |
| 1 | Lever guard ( 1 set )   | \$ 176 | 300.00   | —   |
| 1 | Rear box                | \$ 176 | 250.00   | —   |
| 1 | Rear box bracket        | \$ 176 | 180.00   | —   |
| 1 | Crash bar ( 1 set )     | \$ 176 | 480.00   | —   |
|   |                         | \$     | 1,404.00 |     |

| <u>S/No.</u> | <u>Labour</u>                               |        |        |
|--------------|---------------------------------------------|--------|--------|
| 1            | To provide towing service.                  | \$ 35  | 50.00  |
| 2            | To check wiring and reset headlamp focusing | \$ 176 | 80.00  |
| 3            | To provide labour.                          | \$ 300 | 480.00 |
|              |                                             | \$     | 610.00 |

Grand Total \$ 7,701.10

1733.4  
4506.72



EROFIA MOTOR TRADING PTE LTD

LiK Auto Consultants hereby notify the Repairer of the following:

- To remove belowwater spray painting
- To check damaged parts during recovery
- Parts prices are subject to confirmation
- This policy covers it with "Without Franchise" items
- No Franchise is allowed
- Supplementary work must be authorized and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: