

EK 52 AUTO PTE LTD (HQ)
1 KAKI BUKIT AVE 6
#01-53 (417883)

VEHICLE No:GBJ 5825C

1PC REAR BODY PANEL N/S
1PC REAR BUMPER
1PC TAILLAMP N/S
1PC TAILLAMP LOWER GARNISH N/S

(102) $\begin{matrix} \sim \\ \sim \\ \sim \\ \sim \end{matrix}$ $\begin{matrix} \$1,499.10 \\ \$654.10 \\ \$386.00 \\ \$105.00 \end{matrix}$ $\begin{matrix} \times \\ \times \\ \times \\ \times \end{matrix}$
\$2,644.20

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO DISMANTLE & REFIX REVERSE SENSOR
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

$\begin{matrix} \$50.00 \\ \$50.00 \\ \$50.00 \\ \$880.00 \\ \$850.00 \end{matrix}$ $\begin{matrix} 20 \\ \times \\ \times \\ 550 \\ 550 \end{matrix}$
TOTAL \$4,524.20 $\begin{matrix} 550 \\ 1120 \end{matrix}$

not Attached
LKK

$\frac{P/P \$ 1120}{=}$

3 day.

12/2/19

Whose Approval

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: