


Cecilia



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Quotation

DATE: 04/07/19
VEHICLE NO: PC6031R
DRIVER: PEH SAN LENG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/07/1039
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 01/07/19
REF No: JW-0719-404

S/N	Description	Qty	Cost per Unit	Amount S\$
Labour Costs				
1	TO PANEL BEAT RHS REAR PANEL.	1	400	400.00 300
2	TO REMOVE AND REPLACE RHS REAR PANEL STICKER,	1	1200	1,200.00 950
Spray Paint				
1	Spray Painting	1	600	600.00 450
	TO PUTTY AND SPRAY PAINTING RHS REAR PANEL.			
TOTAL:				2,200.00
Total Amount				SGD 2,200.00

Remarks:

Signature of Workshop Dpt


Signature of Department Head

Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Surveyor Sign: 
Surveyor Name: RASUL
Date: 09/07/19 @ 1400hrs

3 days

P/P

Ready after repair

LKK

67418434

Summer