

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKE2911B
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991743/YISHUN

Date: 15 Jul 2019

Policy No: A29006255QMX

Veh Reg No: SKE2911B

Make/Model: TOYOTA HARRIER
PREMIUM 2.0 A

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 02/07/2019

TP Veh Reg No: SKT2920X

Not Authorised

61 Lyr @ 2100

Running After Paim

Chassis No: ZSU600068907

Engine No: 3ZRB703424

Reg. Date: 12/08/2017

4 days

Estimate Repair Cost to Vehicle No :SKE2911B

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	1,450.40	1 PC	1,450.40	✓
2 FRONT BUMPER LH SIDE RETAINER	90.66	1 PC	90.66	✓
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 FRONT LH FENDER	1,012.00	1 PC	1,012.00	✓
			2,574.06	
	Less 25%		643.52	1,930.55
Labour				
5 PANEL BEATING	400.00	1 LA	400.00	3800
6 PUTTY & RESPRAY PAINT	500.00	1 LA	500.00	4200
7 RUSTPROOFING	30.00	1 LA	30.00	✓
			930.00	930.00
			Total	S\$ 2,860.55
			Add GST @ 7%	200.24
			Total Amount Payable	S\$ 3,060.79

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE