

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8954J

DATE 4/7/2019 16:44

MAKE :

MODEL : HYUNDAI i40

LKK/kalwa

H/Sun

Lee

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Under Cover			\$ 228.00
	Rear Bumper			\$ 2174.90
	SUB TOTAL			\$ 874.20
	LESS 20%			\$ 174.84
	DISCOUNTED TOTAL			\$ 699.36
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 830.00
	ESTIMATE TOTAL			\$ 1,965.06

276.00

Nett

Nett

Nett

Nett

400

X 1.2

20

Kalwa LKK

M 5/7/19

2 Dgs

L/S

After Repair photo

LKK Auto Cons. Station to notify the Repairer of the following:

- To resurvey the damaged part
- To dispute the repair cost
- Parts used are not original
- Third party survey is allowed
- No illegal modification

Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.