

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

*Not Adul
work
5 day.
2/5 # 1700*

09-08-19

Date of accident : 04-07-2019

OUR REF : SMH 8057M/T/19

Tay Su Yin

Blk 298 Compassvale Street

#03-19

Singapore 541298

- LKK Auto Consultants hence notify the Repairer of the following:

 - To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date of Acknowledgement: 09/07/19 to 13/07/19

Acknowledged by Repairer
Signature: _____
Date: _____

ESTIMATE BILL ON VEH. NO. : SMH 8057M

MODEL : HONDA FIT HYBRID 1.5

CHASSIS NO : GP51339521

LIST ITEM

Rear Door Assy LH	1		799.20 X
Rear Door Frame Black Sticker	11		30.30 X
Rear Fender LH		<i>300gms</i>	695.20
Rear Fender Glass Moulding		<i>1m</i>	148.20
Rear Fender Glass Inner Seal		<i>1m</i>	38.10
Rear Fender Glass Clips		8pcs @ 6.00	48.00 X
Rear Sport Rim Assy LH		<i>1pc cur</i>	863.20 X
			2,622.20
		Less Discount 20%:	524.44
			2,097.76

SPECIAL NETT ITEM

Rear Fender Glass Sealant			40
		<i>1m</i>	60.00

LABOUR CHARGE

To remove & refix interior upholstery			80.00
To remove & refix rear LH fender glass		<i>100</i>	150.00
To check & adjust computer wheel alignment		<i>11</i>	120.00 X
To respray affeted areas		<i>600</i>	680.00

To renew damaged parts, straighten & repair and aligned all parts

600.00 ✓

To remove & refix rear LH sport rim & contact wheel balancing

✓ ✓ 130.00 X

3,917.76

GST 7%: 274.24

AMOUNT DUE: 4,192.00