

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : LONPAC INSURANCE BHD
 300, Beach Road, #17-04/07
 THE CONCOURSE
 Singapore 199555
 TEL: 62507388 FAX: 62963767
 ATTN: Motor Claim Department
 Your Ref No: 19/LP/TP-132(07)
 Claim Type: Third Party

Estimate No: EST0004936
Date: 05 Jul 2019
Policy No: D19MTPV01007989
Veh Reg No: SKN5568S
Make/Model: MAZDA 3

Reg. Date:

Estimate Repair Cost to Vehicle No :SKN5568S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Parts				
1 FRT BONNET		1 PC	450.00	
2 FRT BONNET RUBBER		1 PC	35.00	
3 FRT BUMPER		1 PC	750.00	
4 FRT BUMPER RETAINER RH		1 PC	15.00	
5 FRT BUMPER CLIPS		10 PC	25.00	
6 FRT BUMPER BEAM (BELOW HEADLAMP)		1 PC	15.00	
7 FOG LAMP GARNISH RH		1 PC	50.00	
8 HEADLAMP RH		1 PC	920.00	
9 HEADLAMP PANEL RH		1 PC	220.00	
10 FRT FENDER RH		1 PC	160.00	
11 FENDER COWLING CLIPS		10 PC	20.00	
			2,660.00	
	Add 20%		532.00	3,192.00
Labour				
12 WIRE CHECKING		1 UNIT	20.00	
13 LABOUR CHARGE		1 UNIT	600.00	
14 SPRAY PAINTING		1 UNIT	650.00	
				1,270.00

Amount Before Excess	S\$ 4,462.00
Add GST @ 7%	312.34
Total Amount payable	S\$ 4,774.34

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS THIRTY FOUR ONLY

For SME Motor Pte Ltd



 AUTHORISED SIGNATURE