

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
 TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg  
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

**M/S :** SEOW CHOEN FRANCIS  
 22 SARACA ROAD

SINGAPORE 807368  
 TEL: 92265206  
 ATTN:

Your Ref No: SJY3959P  
 Claim Type: Third Party  
 Accident Date: 03/07/2019  
 TP Veh Reg No: SKW9016U

**Estimate No:** MC1900508  
**Date:** 05 Jul 2019  
**Policy No:** GA013720  
**Veh Reg No:** SJY3959P  
**Make/Model:** SUZUKI SX4 SEDAN 1.6  
 AT

*AG*  
*10-12*

*Not Notarised*  
*11 Sep 2019*  
*Repair After Paint*  
*3days*

**Estimate Repair Cost to Vehicle No :SJY3959P**

Description	Quantity	List Price S\$	Amount S\$
<b>SPARE PARTS</b>			
1 REAR BUMPER	1 PC	<i>Ben</i> 675.25	✓
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	<i>Sen</i> 60.00	X
3 REAR BUMPER CLIPS	12 PC	<i>Sen</i> 36.00	✓
4 REAR BUMPER LOWER SPOILER	1 PC	<i>Not Mi</i> 748.55	✓
5 REAR BUMPER REFLECTOR	1 PC	<i>Sen</i> 20.00	X
6 REAR BUMPER REINFORCEMENT	1 PC	227.20	?
		1,767.00	
	Less 15%	265.05	1,501.95
<b>Special Nett</b>			
7 REVERSE SENSOR	1 SET	200.00	?
		200.00	200.00
<b>LABOUR</b>			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>500</i>
10 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>300</i>
11 TO SPRAY REAR BUMPER, REAR BOOT, REAR BUMPER LOWER SPOILER.	1 PC	500.00	<i>400</i>
		1,100.00	1,100.00
		Total	S\$ 2,801.95
		Add GST @ 7%	196.14
		Total Amount Payable	S\$ 2,998.09

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY EIGHT AND CENTS NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.  
 Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE