

KF

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SEOW CHOEN FRANCIS
22 SARACA ROAD

SINGAPORE 807368

TEL: 92265206

ATTN:

Claim No: MC1900508
No: MF1900554
Date: 09 Sep 2019
Policy No: GA013720
Veh Reg No: SJY3959P
Make/Model: SUZUKI SX4 SEDAN 1.6
AT

Your Ref No: SJY3959P
Claim Type: Third Party
Accident Date: 03/07/2019
TP Veh Reg No: SKW9016U

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJY3959P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BUMPER	1 PC	675.25	
2 REAR BUMPER CLIPS	12 PC	36.00	
3 REAR BUMPER LOWER SPOILER	1 PC	748.55	
		1,459.80	
	Less 15%	218.97	1,240.83
LABOUR			
4 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	10.00	
5 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	
7 TO SPRAY REAR BUMPER,REAR BOOT,REAR BUMPER LOWER SPOILER.	1 PC	400.00	
		760.00	760.00
	Total		S\$ 2,000.83
	Lump Sum Less 20%		-400.17
	Sub Total		S\$ 1,600.66
	Less Rounding		-0.66
	Lum Sum Repair		S\$ 1,600.00 ✓dk
	Less Excess		S\$ 0.00
	Amount Before GST		S\$ 1,600.00
	Add GST @ 7%		112.00
	Total Amount Payable		S\$ 1,712.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED TWELVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 08/07/2019

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SEOW CHOEN FRANCIS
 22 SARACA ROAD

SINGAPORE 807368

TEL: 92265206

ATTN:

Your Ref No: SJY3959P
 Claim Type: Third Party
 Accident Date: 03/07/2019
 TP Veh Reg No: SKW9016U

Estimate No: MC1900508
 Date: 05 Jul 2019
 Policy No: GA013720
 Veh Reg No: SJY3959P
 Make/Model: SUZUKI SX4 SEDAN 1.6
 AT

MC
10-12

Not Authorized
6/1/19 @ 7
Recovery After Paint 3days

Estimate Repair Cost to Vehicle No :SJY3959P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>Ben</i> 675.25	—
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	<i>Sen</i> 60.00	X
3 REAR BUMPER CLIPS	12 PC	<i>Sen</i> 36.00	—
4 REAR BUMPER LOWER SPOILER	1 PC	<i>McMi</i> 748.55	—
5 REAR BUMPER REFLECTOR	1 PC	<i>Sen</i> 20.00	X
6 REAR BUMPER REINFORCEMENT	1 PC	<i>R</i> 227.20	X
		1,767.00	
	Less 15%	265.05	1,501.95
Special Nett			
7 REVERSE SENSOR	1 SET	<i>Sen</i> 200.00	X
		200.00	200.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>50</i>
10 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD, TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>300</i>
11 TO SPRAY REAR BUMPER, REAR BOOT, REAR BUMPER LOWER SPOILER.	1 PC	500.00	<i>400</i>
		1,100.00	1,100.00
	Total	S\$ 2,801.95	
	Add GST @ 7%	196.14	
	Total Amount Payable	S\$ 2,998.09	

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY EIGHT AND CENTS NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE