

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJR 432 Z
TP/MG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 20/06/2019

TP Veh Reg No: SMD2207H

Estimate No: ES1991747/YISHUN

Date: 15 Jul 2019

Policy No: MT110383

Veh Reg No: SJR432Z

Make/Model: TOYOTA ALLION 1.5 A

Chassis No: NZT2603038241

Engine No: 1NZD297434

Reg. Date: 05/06/2009

Estimate Repair Cost to Vehicle No :SJR432Z

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	927.50	1 PC	927.50	
2 FRONT BUMPER REINFORCEMENT	421.70	1 PC	421.70	
3 FRONT BUMPER CENTRE LOWER GRILLE	150.70	1 PC	150.70	
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	
5 FRONT GRILLE	411.50	1 PC	411.50	
6 RH HEADLAMP	627.50	1 PC	627.50	
			2,559.90	
	Less 25%		639.98	1,919.93
Labour				
7 PANEL BEATING	500.00	1 LA	500.00	
8 PUTTY & RESPRAY PAINT	500.00	1 LA	500.00	
			1,000.00	1,000.00
Total				S\$ 2,919.93
Add GST @ 7%				204.40
Total Amount Payable				S\$ 3,124.33

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: