



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:

India International Insurance Pte Ltd (HQ)

UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/06/2019
Vehicle Reg. No.:	SBR6206R	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	SKODA SUPERB, 1.8 ELEGANCE (A)	Vehicle Reg. Date:	30/07/2009
Vehicle Colour:	DARK GREY	Chassis No:	TMBBB93T399038280
Engine No:	CDA037232		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	4,667.63
Miscellaneous Items	11.00
Labour	1,260.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,938.63
+ GST 7.00% (S\$)	415.70
Nett Amount (S\$)	6,354.33

This claim is handled by: AH WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2019)
Parts:	143	SKODA SUPERB 1.8 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBR6206R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER RETAINER LH <i>acc</i>	10.00	0.00	*58.95 FL
2	1		*REAR TAIL LAMP LOWER BRACKET LH <i>?</i>	10.00	0.00	*65.80 FL
3	10		*REAR BUMPER CLIPS <i>acc</i>	10.00	0.00	*38.00 FL
4	1		*REAR BUMPER <i>de</i>	10.00	0.00	*1,465.51 FL
5	1		*REAR NUMBER PLATE <i>sch</i>	0	0.00	*45.00 FS
6	1		*REAR SKIRTING <i>de</i>	10.00	0.00	*423.00 FL
7	1		*REAR PARKING SENSOR <i>acc</i>	10.00	0.00	*234.75 FL
8	1		*REAR EXHAUST SILENCER <i>?</i>	10.00	0.00	*1,856.75 FL
9	2		*REAR EXHAUST OUTER CHROME <i>?</i>	10.00	0.00	*993.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,181.26
- List Item Discount on L Items (S\$)	513.63
Total Parts (S\$)	4,667.63

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)		11.00

Estimates on Labour

Particulars	Lab.Type	Amount
<u>Labour Items</u>		
TO REPAIR REAR END PANEL & OTHER ATTACHMENT PARTS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN & REALIGN ALL ACCIDENT DAMAGED PARTS	New	300 400.00
TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	300 450.00
TO REMOVE & REFIX REAR PARKING SENSOR	New	60 80.00
TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	X 40.00
TO REMOVE & REFIX REAR EXHAUST SILENCER	New	80 250.00
TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST	New	20 40.00
Gross Labour Cost (\$\$)		1,260.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasm
Hp 90010068
4
2/3 days
4/8
12/07/19 @ 1055
Ready after repair