

7/8/2019

## Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 169419  
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

Mova Spray Centre  
2K Oven Spray Painting System

Power-M Automotive Pte Ltd  
Specialise in Car Air-con Services,  
Car Audio & Hi-Fi System.

Hilton Car Rental Centre  
Hilton Auto Trading  
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:  
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

## PARTICULARS OF CLAIM

|                               |                                       |                    |                   |
|-------------------------------|---------------------------------------|--------------------|-------------------|
| Claim Type:                   | THIRD PARTY                           | Ref. No:           |                   |
| Policy No:                    |                                       | Date of Loss:      | 29/06/2019        |
| Vehicle Reg. No.:             | SBR6206R                              | Driveable?         |                   |
| Party At Fault:               | UNKNOWN                               |                    |                   |
| Make/Model:                   | SKODA SUPERB, 1.8 ELEGANCE (A)        | Vehicle Reg. Date: | 30/07/2009        |
| Vehicle Colour:               | DARK GREY                             | Chassis No:        | TMBBB93T399038280 |
| Engine No:                    | CDA037232                             |                    |                   |
| Odometer:                     | 0 KM                                  |                    |                   |
| Paint Type:                   |                                       |                    |                   |
| List Item Discount:           | 10.00 %                               |                    |                   |
| Total Loss?                   | NO                                    |                    |                   |
| Est. Duration of Repair (day) | 4                                     |                    |                   |
| Present Location:             | MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) |                    |                   |

| COST OF CLAIMS      | Amount   |
|---------------------|----------|
| Parts               | 4,667.63 |
| Miscellaneous Items | 11.00    |
| Labour              | 1,260.00 |
| Paintwork Labour    | 0.00     |
| Towing              | 0.00     |
| Gross Total (S\$)   | 5,938.63 |
| + GST 7.00% (S\$)   | 415.70   |
| Nett Amount (S\$)   | 6,354.33 |

This claim is handled by: AH WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jul 2019)  
 Parts: 143 SKODA SUPERB 1.8 Elegance (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SBR6206R)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No.                                   | Qty | Part No. | Particulars                               | %Disc | %Depr | Amount               |
|---------------------------------------|-----|----------|-------------------------------------------|-------|-------|----------------------|
| 1                                     | 1   |          | *REAR BUMPER RETAINER LH <i>nc</i>        | 10.00 | 0.00  | *58.95 FL            |
| 2                                     | 1   |          | *REAR TAIL LAMP LOWER BRACKET LH <i>?</i> | 10.00 | 0.00  | *66.00 FL            |
| 3                                     | 10  |          | *REAR BUMPER CLIPS <i>nc</i>              | 10.00 | 0.00  | *38.00 FL            |
| 4                                     | 1   |          | *REAR BUMPER <i>de</i>                    | 10.00 | 0.00  | *1,465.51 FL         |
| 5                                     | 1   |          | *REAR NUMBER PLATE <i>sc</i>              | 0     | 0.00  | *45.00 FS <i>sla</i> |
| 6                                     | 1   |          | *REAR SKIRTING <i>de</i>                  | 10.00 | 0.00  | *423.00 FL           |
| 7                                     | 1   |          | *REAR PARKING SENSOR <i>nc</i>            | 10.00 | 0.00  | *234.75 FL           |
| 8                                     | 1   |          | *REAR EXHAUST SILENCER <i>?</i>           | 10.00 | 0.00  | *1,856.75 FL         |
| 9                                     | 2   |          | *REAR EXHAUST OUTER CHROME <i>?</i>       | 10.00 | 0.00  | *993.50 FL           |
| Sub Total (S\$)                       |     |          |                                           |       |       | 5,181.26             |
| - List Item Discount on L Items (S\$) |     |          |                                           |       |       | 513.63               |
| Total Parts (S\$)                     |     |          |                                           |       |       | 4,667.63             |

F=Franchise part, S=SpcNelt, L=ListItemDisc.

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

Parts \$ 2220.21 - 10%  
 \$ 1998.18  
 SN \$ 45.  
 Labour \$ 766  
 + Labour \$ 150  
 Total \$ 2953.18 - 20%  
 \$ 2350 4 DAYS

2716.96  
 10%  
 P - 2445.26  
 s/w - 45.00  
 L - 910.00  
 T - 3400.26  
 20%  
 2720.20  
 45 - 2700  
 4 days

7/8/2019

## Estimate Report

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO REPAIR REAR END PANEL &amp; OTHER ATTACHMENT PARTS. TO REMOVE &amp; REPLACE ALL ACCIDENT DAMAGED PARTS. TO STRAIGHTEN &amp; REALIGN ALL ACCIDENT DAMAGED PARTS

New

300 ~~400.00~~

2 TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

New

300 ~~450.00~~

3 TO REMOVE &amp; REFIX REAR PARKING SENSOR

New

60 ~~80.00~~

4 TO RUST PROOF ON ACCIDENT DAMAGED PARTS

New

X ~~40.00~~

5 TO REMOVE &amp; REFIX REAR EXHAUST SILENCER

New

80 ~~250.00~~

6 TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST

New

20 ~~40.00~~

Repair Rear exhaust silencer \$150.00-

Gross Labour Cost (\$\$)

1,260.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Rasul

Hp 90010068

4  
3/4 days

L/S

12/07/19 @ 1055

Reay after repair