

1550010

INS. CASE OWNER:

Ce3/AIG1400

7791

Leaser-1
Krosz 2

LKK:
IDAC:

25-4-14

ASSIGNMENT

Surveyor: Kenneth

DOI: 23-04-14

Date/Time: 23-04-14

Registered in Meritmen: 23/4/14

Pre-assign / CCU / FTE



Insured Vehicle No.: STC 9747K

Claim No.: 30262646186

Name of Insured: Yee Suk Tiao

Policy No.: 2003 1313

Insured Tel No.: HP:

Make/Model: Nissan

Excess Sec II :SS D.O.A: 19-04-14

Place of Accident: Road / Accident / Incident

Is driver the owner? (YES / NO) Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age: Yee Yee Koo

(V/L: YES / NO Insured Liability: % Final? Yes / No

Driver Tel No.: 96616813

STH 5065P



INSRS:
WSP: Trans. Cab
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	FOR CSO ONLY:	
	Is driver the owner? (YES / NO)	Finalisation:
	If NO, Driver Name / Age :	Email AIG for OI GIA:
	Driver's Own Vehicle Number: Insurance Company:	Apt letter to OI:
		Call OI:
		After call ltr to OI:
		Type Report:
		Prepare Invoice:
		Others:
		Documentation Check List: Handler Typist
		OI Apt Ltr: <input type="checkbox"/>
		Authorisation To Act: <input type="checkbox"/>
		Release Voucher: <input type="checkbox"/>
		Final Repair Bill: <input type="checkbox"/>
		Car Rental Invoice: <input type="checkbox"/>
		LTA / GIA : <input type="checkbox"/>
		Medical Bill: <input type="checkbox"/>
		Approval Email: <input type="checkbox"/>
		Payment Breakdown Form: <input type="checkbox"/>
		Others: <input type="checkbox"/>
22-05-13	called 000 not available. 2 times.	
21/5/14 3:06	called 000. but spoke to PH. Mr Yee. Inform about the claim. confirm the accident. Mr Yee mentioned it was a amber light while he was driving. TP came from the right and entered into his backdoor. no witnesses. no video. Inform as we were passed to settle the claim Mr Yee will be affected letter out.	
	need to review the case..	
	CONFLICTING VERSION AS TO THE POSITION OF TRAFFIC LIGHT PERHAPS (UN)WITNESSING THE 10 SECOND LIGHT TO AMBER	
	100. AMBER TRAFFIC LIGHT WAS AMBER HE STILL PROCEEDED TO DRIVE AHEAD. THIS PERHAPS BEING THE 100 POSITION ON THE CHANGE OF TRAFFIC LIGHT RESULTED IN THE COLLISION. PLEASE NOTE THAT TP HAS ONE WITNESS AS TO THE 100 P/R TO DETERMINE LIABILITY.	

FINALIZATION	Date/Time:	Confirm with:	Confirm by: KSL
Repair Cost: 45	SS 14,500	(16 days) Reduction: 87 %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 24.09.14	Confirm with: Wai Yan	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: 100%	% 50	(Agreed / Assessed) BOLA S/N No. : Nil	If NO or B 28, Ass. Lia :
Repair Cost: w/loy: +15,515.00	SS 7,757.50		
Loss of Rental (LOR): +934.89	SS 911.45	(21 days) x +93.09	
Loss of Use (LOU): -	SS -	(\$ x days)	
Loss of Income (LOI): +1,090	SS 525.10	(\$ 50 x 21 days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input checked="" type="checkbox"/>	[Tick only one]	
GIA/LTA Search +6.00	SS 6.00		
Medical: -	SS -		
Disbursement: -	SS -	(e.g. Tow/ Independent)	
Legal Cost -	SS -		
Total: +18,525.89	SS 9,265.95	Global Sum SS: 9,300.00	
FINAL PAYMENT	Date/Time: 24.09.14	Confirm with: Wai Yan	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 9,300.00	Name 1: TRADE-CAB AUTO SERVICES PTE LTD	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT

ASS. REC. BY:

REF: A16/

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S140 50657 Yr Regn: 09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AD

Make: Toy wish c.c. 1799

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 544322 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W 903 00 3075

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front R/Bal. 2 mm Rear R/Bal. 6 mm

L/Bal. 2 mm L/Bal. 6 mm

D.O.A. 19/4/14 D.O.I. 23/4/14

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/3/15</u>	<u>1/1 Rpt B 19,500 Confirmed Damage (1075 X)</u>
<u>18/03/15</u>	<u>wait for BI claim. Rpt L \$ 97829.96, 57% since TP failed to cover for BI claim. To monitor the progress of this case. Once BI is settled, our file can be closed.</u>
	<u>As per A16, BI settled 50%. Maintain 50 offer to TP. Follow up with OI. Their claim was settled 50% by TP insurance.</u>

Date/Time, File Pass to? : Prel. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/04/2014 15:03
Date Of Accident	19/04/2014 11:50
Exact Location Of Accident	Changi Airport T3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5065P
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

Insurance Company


Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/2149
Cover Note Number	

Driver

Name of Driver	LYE KOON LEONG PETER
NRIC No	S0288134I
Date Of Birth	22/10/1942
Occupation	Outdoor
Date Of Driving Pass	04/09/2007
Driving Experience	6 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-96681346
Fax Number	
Contact Number	
EEmail Address	NOEMAIL
Address	BLK 52 COMMONWEALTH DRIVE #16-544
Postcode	142052

Address
Postcode

Accident Sketch Plan Pg.1



Police Report Pg.1

Police Station Of Origin:
 Toa Payoh N.P.C
 93 Toa Payoh Central #01-02 Toa Payoh
 Community Building SINGAPORE 319194
 Tel No: 1800-2519999



T/20140421/4011

2 of 3

Report No. T/20140421/4011

CONTINUATION OF REPORT

Driver			
Name	LYE KOON LEONG PETER	ID No.	S02881341
Related Vehicle	SHD5065P (Car)	Contact No.	96681346
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/04/2014	Date Discharge	19/04/2014
No. of Days granted Medical Leave (MC)	04	Degree of Injury	Slight
Driver			
Name	PANG YICK KAN	ID No.	S8970819B
Related Vehicle	SJC9747K (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details.

On 19/04/2014 at about 1150hrs, I was driving my Transcab Taxi, registration plate number SHD5065P at Changi Airport Terminal 3. After I dropped my passenger at the Changi Airport Terminal 3 Departure Hall, I drove my Taxi and head towards the Taxi Holding area at Changi Airport Terminal 3. When I turned my Taxi and head towards the Taxi Holding area, there was a Cross-Traffic Junction. When I was driving towards the Cross-Traffic Junction, I observed that the traffic light was green for me to continue driving forward. When I drove forward, a Nissan Latio, registration plate number SJC9747K, which was driving towards the Changi Airport Terminal 3 Departure Hall, suddenly the car came in-front of me. As I could not react in time, I knocked onto the right side of the Nissan Latio. Subsequently both my car and the other party car came to a stop along the road towards Changi Airport Terminal 3 Departure Hall. After which, we both driver came out of our vehicle and exchanged particulars. At that point of time, I felt pain at my chest area. As such Ambulance was called and I was conveyed to Changi General Hospital.

Peter Lye
 S-02881341-1

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 200303878K

Vehicle Details

Vehicle No.: SHD5065P
 Vehicle to be Exported: Yes
 Intended De-registration Date: 21 Apr 2014
 Vehicle Make: TOYOTA
 Vehicle Model: WISH 1.8 BI-FUEL AUTO
 Primary Colour: Red
 Manufacturing Year: 2009
 Engine No.: 1ZZ3239640
 Chassis No.: JTDER12W903003075
 Maximum Power Output: 97.0 kW (130 bhp)
 Open Market Value: \$22,392.00
 Original Registration Date: 30 Sep 2009
 First Registration Date: 30 Sep 2009
 Transfer Count: 0
 Actual ARF Paid: \$13,436.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 29 Sep 2017
 PARF Rebate Amount: \$10,077.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2017
 COE Category: A - Car (1600cc & below)
 COE Period (Years): 8
 QP Paid: \$12,016.00
 COE Rebate Amount: \$5,165.00
Total Rebate Amount: \$15,242.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Apr 2014



Please read through the Privacy Statement, Terms of Use and Disclaimer
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
 Copyright © 2014 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/04/2014 11:10
Date Of Accident	19/04/2014 11:50
Exact Location Of Accident	ALONG RD 1 AIRPORT BOULEVARD NEAR T3 DEPARTURE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC9747K
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	YEO SIK TUA
NRIC No	S1832403B

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO-1.5 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? Yes

If No, Please state action to be taken

Vehicle Category	Private Car
------------------	-------------

Insurance Company

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100331713-01000
Cover Note Number	

Driver

Name of Driver	PANG YICK KAN
Passport No/FIN	S8970819B
Date Of Birth	14/01/1989
Occupation	Indoor
Date Of Driving Pass	22/12/2008
Driving Experience	5 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-96616817
Fax Number	
Contact Number	
EMail Address	tsz_ning@yahoo.com
Address	BLK 876 WOODLANDS AVE 9 #07-254
Postcode	2573
Was driver an employee of the Insured's Company	No

Postcode

POLICE REPORT Pg.1

Police Station Of Origin:
 Bishan N.P.C
 20 Bishan Street 23 SINGAPORE 579757
 Tel No: 1800-5529999



T/20140419/4080

1 of 3

Report No. T/20140419/4080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/04/2014 18:10		Vide Report No.: P/20140419/0021	Station Diary No.: 51
Name of Informant: PANG YICK KAN		Address: 31 BISHAN STREET 11 #23-02 SINGAPORE 579819	
ID Type / ID No.: NRIC NO / S8970819B		Contact No.: Home/Office:	Mobile: 94592580
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 25	Date of Birth: 14/01/1989	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Student		Driving Licence Information: Class: 3A	Date of Expiry:

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/04/2014 11:50	Type of Location: -
Location: Along Road 1 AIRPORT BOULEVARD near to Terminal 3 departure				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Plate No.	Make	Model	Color	Damage	Count
SHD5065P	taxi			Seriously Damaged	0
SJC9747K	Car			Seriously Damaged	2

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg.1

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999



T/20140419/4080

3 of 3


Report No. T/20140419/4080


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / RIDUAN RAJATMARICAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/04/2014 18:10
Officer In Charge Of Case: TP / GIT / MD ABDILLAH BIN PALIL Contact No.: 65476246	Classification Of Case:



TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5065P - AIG

ROEL

*Hand
 Not Authorised
 Prepared on 14/5/04
 Bank Value??*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 5065P - ROEL
 JTDER12W903003075
 TOYOTA
 WISH 1.8
 19.04.2014
AIG

PART		LIST	
1	1	Front Bumper Cover	\$ Nil 487.80 ✓
2	1	Front Bumper Lower Absorber	\$ Nil 108.33 ✓
3	1	Front Bumper Reinforcement	\$ Nil 265.09 ✓
4	1	Front Bumper Side Support LH	\$ Nil 63.50 ✓
5	1	Front Bumper Side Support RH	\$ Nil 63.50 ✓
6	1	Front Bumper Retainer RH	\$ CA 68.50 ✓
7	1	Front Bumper Retainer LH	\$ Mis 68.50 ✓
8	1	Front Bumper Bracket RH	\$ Mis 49.00 ✓
9	1	Front Bumper Bracket LH	\$ Mis 49.00 ✓
10	1	Front Bumper Centre Grille	\$ Nil 349.80 ✓
11	1	Front Bumper Lower Grille	\$ Nil 215.60 ✓
12	1	Front Bumper Fog Lamp Cover RH	\$ Mis 17.60 ✓
13	1	Front bumper Fog Lamp Cover LH	\$ Mis 17.60 ✓
14	1	Front Tow Hook	\$ R 200.00 X
15	1	Bonnet	\$ Bt 849.30 ✓
16	1	Bonnet Insulator	\$ 213.36 ✓ Deform 436.72 50% ✓
17	1	Bonnet TOYOTA Badge	\$ Acc 189.00 ✓
18	1	Bonnet Hinge RH	\$ Bt 68.00 ✓
19	1	Bonnet Hinge LH	\$ Bt 68.00 ✓
20	1	Bonnet Lock	\$ Bt 75.02 ✓
21	1	Bonnet Lock Cable	\$ In 44.43 ✓
22	1	Bonnet moulding	\$ Nil 161.97 ✓
23	1	Bonnet damper stay RH	\$ Nil 199.21 X
24	1	Bonnet damper stay LH	\$ Nil 199.21 X
25	1	Bonnet insulator	\$ Reported 436.72 X
26	1	Bonnet Under Weatherstrip Seal	\$ Tr 59.99 ✓
27	1	Front Support Panel	\$ Bt 1,018.60 ✓
28	1	Front support panel side garnish RH	\$ Mis 28.50 ✓
29	1	Front support panel side garnish LH	\$ Mis 28.50 ✓
30	1	Front Brace Panel	\$ Nil 79.57 ✓
31	1	Front Fender RH	\$ Bt 698.00 ✓
32	1	Front Fender Liner RH	\$ CA 307.62 ✓
33	1	Front Fender Indicator Lamp RH	\$ Sve 79.83 X
34	1	Front Fender Inner Wheel House Panel RH	\$ Bt 595.72 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO 201019626G
SHD 5065P - AIG

ROEL

Item No	Quantity	Description	Unit Price	Total Price
35	1	Front Fender LH	\$ 698.00	698.00 ✓
36	1	Front Fender Liner LH	\$ 307.62	307.62 ✓
37	1	Front Fender Indicator Lamp LH	\$ 79.83	79.83 ✓
38	1	Front Fender Inner Wheel House Panel LH	\$ 595.72	595.72 ✓
39	1	Front Headlamp RH	\$ 800.02	800.02 ✓
40	1	Headlamp RH inner panel RH	\$ 732.00	732.00 ✗
41	1	Front Headlamp LH	\$ 800.02	800.02 ✓
42	1	Headlamp RH inner panel LH	\$ 732.00	732.00 ✗
43	1	Radiator Assembly	\$ 1,890.20	1,890.20 ✓
44	1	Radiator Grille	\$ 169.80	169.80 ✓
45	1	Radiator Fan Blade	\$ 186.62	186.62 ✓
46	1	Radiator Fan Motor	\$ 310.63	310.63 ✓
47	1	Radiator Fan Cowling	\$ 190.40	190.40 ✓
48	1	Radiator Upper Hose	\$ 31.44	31.44 ✓
49	1	Radiator Lower Hose	\$ 46.67	46.67 ✗
50	1	Radiator Expansion Tank	\$ 150.63	150.63 ✓
51	1	Radiator Expansion Tank Bracket	\$ 100.00	100.00 ✗
52	1	Radiator Overflow Pipe	\$ 150.00	150.00 ✗
53	1	Aircon Condenser	\$ 1,488.00	1,488.00 ✓
54	1	Aircon Condenser Pipe (HIGH)	\$ 213.41	213.41 ✗
55	1	Aircon Condenser Pipe (LOW)	\$ 336.19	336.19 ✗
56	1	Air Cleaner Assembly	\$ 863.70	863.70 ✓
57	1	Air-cleaner Intake Duct	\$ 84.64	84.64 ✓
58	1	Air-cleaner Intake Duct Hose (top)	\$ 61.83	61.83 ✓
59	1	Air-cleaner Intake Hose	\$ 166.18	166.18 ✗
60	1	Front Fuse Box - Top Cover	\$ 72.14	72.14 ✗
61	1	Front Fuse Box Lower Cover	\$ 125.23	125.23 ✗
62	1	Front Fuse Box Centre Junction	\$ 163.44	163.44 ✗
63	1	Front Fuse Box Centre Cover	\$ 40.00	40.00 ✗
64	1	Gear box assy	\$ 16,629.60	16,629.60 ✗
65	1	Gear box cross member	\$ 1,211.90	1,211.90 ✗
66	1	Gear box cross member bracket	\$ 239.76	239.76 ✗
67	1	Engine block	\$ 7,927.34	7,927.34 ✗
68	1	ABS pump	\$ 4,733.00	4,733.00 ✓
69	1	ABS pump pipe	\$ 68.40	68.40 ✗
70	1	ABS pump switch	\$ 2,140.00	2,140.00 ✗
71	1	MANIFOLD, INTAKE	\$ 506.25	506.25 ✗
72	1	Engine Splash Cover RH	\$ 148.50	148.50 ✓
73	1	Engine Splash Cover LH	\$ 148.50	148.50 ✓
74	1	Front Seat Belt RH	\$ 718.50	718.50 ✓
75	1	Front safety belt cover garnish LH	\$ 211.40	211.40 ✗
76	1	Front safety belt cover garnish RH	\$ 211.40	211.40 ✗

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5065P - AIG

ROEL

Item No	Qty	Description	Unit	Price	Total
77	1	Front Seat Belt tension RH	\$	105.01	105.01
78	1	Front Seat Belt LH	\$	718.50	718.50
79	1	Front Seat Belt tension LH	\$	105.01	105.01
80	1	Battery	\$	200.00	200.00
81	1	Battery tray	\$	52.90	52.90
82	1	Battery fastener bracket	\$	31.05	31.05
83	1	Front Seat Belt LH	\$	718.50	718.50
84	1	Steering rack & pinion assy	\$	2,639.44	2,639.44
85	1	Steering rack end	\$	205.21	205.21
86	1	Steering rack & pinion bushing	\$	25.00	25.00
87	1	Steering tie-rod end LH	\$	210.90	210.90
88	1	Steering tie-rod end RH	\$	210.90	210.90
89	1	Steering Wheel	\$	1,399.80	1,399.80
90	1	Steering Wheel assy	\$	1,601.10	1,601.10
91	1	Front shock absorber assy LH	\$	465.00	465.00
92	1	Front shock absorber top mounting LH	\$	132.63	132.63
93	1	Front shock absorber assy RH	\$	465.00	465.00
94	1	Front shock absorber top mounting RH	\$	132.63	132.63
95	1	Front lower arm RH	\$	517.14	517.14
96	1	Front lower arm LH	\$	517.14	517.14
97	1	Front knuckle arm RH	\$	408.95	408.95
98	1	Front knuckle arm LH	\$	408.95	408.95
99	1	Front Drive Shaft RH	\$	800.00	800.00
100	1	Front Drive Shaft LH	\$	900.00	900.00
101	1	Front spindle arm	\$	124.00	124.00
102	1	Front wheel bearing with hub	\$	268.00	268.00
103	1	Front strut bar	\$	100.79	100.79
104	1	Front strut bar bracket	\$	231.58	231.58
105	1	Front wheel bearing cone	\$	150.50	150.50
106	1	Front wheel bearing oil seal	\$	100.79	100.79
107	1	Front wheel bearing	\$	40.00	40.00
108	1	Front stabilizer bar	\$	367.60	367.60
109	1	Front stabilizer bar link	\$	155.50	155.50
110	1	Front stabilizer bar bracket	\$	138.00	138.00
111	1	Front stabilizer bar bush	\$	117.27	117.27
112	1	Front Gear Box Mounting LH	\$	135.00	135.00
113	1	Front Engine Mounting	\$	81.00	81.00
114	1	Gear Box mounting RR	\$	291.40	291.40
115	1	Front Engine Mounting RH	\$	174.65	174.65
116	1	Member Sub Assy Engine Mouting centre	\$	503.61	503.61
117	1	Front Windscreen	\$	1,406.64	1,406.64
118	1	Front Windscreen Moulding	\$	86.40	86.40

ROEL

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGAI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5065P - AIG

119	1	Windscreen washer tank - filler neck	\$	100.63
120	1	Windscreen washer tank	\$	138.33
121	1	Windscreen washer tank motor	\$	222.38 X
122	1	Front Door RH	\$	1,554.00 X
123	1	Front Door LH	\$	1,554.00 X
124	1	Alternator assembly	\$	2,214.70 X
125	1	Aircon compressor - pump	\$	3,000.00 X
126	1	ECU assy	\$	3,820.20 X
127	1	V-belt	\$	121.70 X
128	1	Power steering pump	\$	4,720.80 X

TOTAL	\$	89,018.87
25%	\$	22,254.72
	\$	66,764.15

Specical Nett

1	Front Licence Plate	\$	80.00
1	Front CNG Sticker	\$	15.00
1Set	Front Bumper Fastener Clip	\$	12.00
2	Front Bonnet Stopper	\$	8.00
1Set	Bonnet insulator clip	\$	35.00
1Set	Bonnet Under Weatherstrip Seal Clips	\$	18.00
2 Set	Front Fender Liner clip	\$	24.00
1Set	Radiator Grille Clip	\$	18.00
2	Radiator Bracket	\$	45.60 X
2	Radiator Bracket Mounting	\$	28.20 X
2	Radiator Lower Mounting Bushing	\$	14.17 X
2	Radiator Coolant	\$	60.00 2CSN
1	Horn High Pitch	\$	101.92 X
1	Horn Low Pitch	\$	101.92 X
1Set	Engine Splash Cover Clip RH	\$	12.00
1Set	Engine Splash Cover Clip LH	\$	12.00
1	Front Fender Advertisement Sticker LH	\$	250.00 X
1	Front Fender Advertisement Sticker RH	\$	250.00 X
2	Front windscreen sealant	\$	80.00 4CSN
1	Front windscreen inner sponge seal	\$	60.00 3CSN
2	Front ERP Sticker	\$	40.00 X
1	Front tyre RH	\$	180.00 X
1	Front tyre rim RH	\$	120.00 X
1	Front tyre rim hub cap RH	\$	50.00 X
1	Front tyre LH	\$	180.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGAI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 COI/GST REG NO.201019626G
SHD 5065P - AIG

ROEL

	\$	120.00 X
1 Front tyre rim LH	\$	50.00 X
1 Front tyre rim hub cap LH		

TOTAL \$ 1,965.81

TOTAL PARTS \$ 68,729.96

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	16,800.00 2400
Putty And Spray Painting Of The Affected Portion.	\$	16,200.00 1400
To Rust-proofing Of The Affected Areas.	\$	220.00 1800
To Check Electrical Lighting Concerned.	\$	120.00 400
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X
To transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 380.00 X
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	na 270.00 X
To Reseal Sealant On Gap	\$	120.00 600
Labour Charge To Mount And Dismount Vehicle On Car-O-Liner Bench, To Facilitate Repair.	\$	380.00 2500
To Check Steering Geometry And Computer Wheel Alianment.	\$	220.00 600

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5065P - AIG

ROEL

To Transfer Of Tire, Rim And On Wheel Balancing.	\$	<i>na</i> 170.00 X
To Replace, Refix And Top Up Coolant For Radiator	\$	120.00 <i>50%</i>
To Dismantle And Refit Front End Suspension, Undercarriage Parts, Final Checking And Testing.	\$	270.00 <i>240%</i>
To Pull And Jack Out Chassis Frame And Correct It To Symmetrical Position With The Aid Of Hydraulic Pneumatic Jack.	\$	<i>Repair</i> 380.00 X
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	380.00 <i>100%</i>
To Dismantle And Refit Front End Suspension, Undercarriage Parts, Final Checking And Testing.	\$	<i>Repair</i> 380.00 X
To Remove And Renew Engine And Gear Box Mounting.	\$	380.00
To Dismantle And Refit Engine Cross-member And Engine Mounting.	\$	380.00
		} <i>230%</i>
To Lift-up Engine With Gear Box And Refit.	\$	<i>Repair</i> 400.00 X
Putty And Spray Painting Of The Affected Portion.	\$	<i>Repair</i> 4,050.00 X
To check ABS brake efficiency, final checking and testing.	\$	380.00
To remove and refit ABS pump relay to enable repair.	\$	380.00
		} <i>100%</i>

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHD 5065P - AIG

ROEL

To vacuum, replace, refix and recharge air condenser	\$	380.00	} x
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	
To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00	12cl
Towing Fees	\$	120.00	5cl

TOTAL \$ 43,600.00

Over all total \$ 112,329.96

REPAIRE DAYS

60 DAYS

16 days

Proposed 11 days @ 14,500/pc

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Zayyer

From: Zayyer
Sent: Thursday, 29 October, 2015 8:25 PM
To: 'Singh, Charan'
Cc: 'PRDSG.DFILE'; CS A Team; Olivia Lau
Subject: RE: #3026264460SG004#027#

Dear Charan,

We refer to the above matter and updates.

Kindly be informed that our surveyor had finalised above matter with TP's repairer since 4 March 2015.

TP's repairer did not submit the LOD until now. In view of no further development, we will proceed to temporarily close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Best Regards,

Zayer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayyer@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Singh, Charan [<mailto:Charan.Singh@aig.com>]
Sent: Wednesday, 30 September, 2015 11:12 AM
To: Zayyer <zayyer@lkkauto.com>
Cc: PRDSG.DFILE <PRDSG.DFILE@aig.com>
Subject: #3026264460SG004#027#

Dear Zayer,

As per my last email to settle the matter at 50/50.

Kindly advise if the matter had been settled with the third party workshop.

Regards,

Charan Singh
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1637 | Fax +(65) 6835 7416
charan.singh@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Zayyer [<mailto:zayyer@lkkauto.com>]
Sent: Monday, May 25, 2015 2:02 PM
To: Singh, Charan
Cc: Hsiao Tong; Zayyer
Subject: RE: #3026264460SG004#023#

Dear Charan,

TP sustained BI due to accident.

As per TP repairer, they informed us that they want to wait for PIR and BI settlement.

Therefore, kindly advise us if TP's BI claim has been settled.

Best Regards,

Zayer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayyer@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong
Sent: Monday, 25 May, 2015 11:52 AM
To: Singh, Charan
Cc: Zayyer
Subject: RE: #3026264460SG004#023#

LKK Ref: CC3/AIG14007791/Kza3

Dear Charan,

Please refer to the screenshot below.

Case has been registered in Merimen on 25/04/2014. However there was no claim no. and AIG officer provided by your good office.