

Khanchana

ASS. REC. BY: bx REF: AIG

12062/6(10)


W.S.

ASSIGNMENT

From: _____ Date: 9/7/19
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLG1516T
 at Workshop m/s Motor Image
 of 19 lorong R toa payoh
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLG1516T Yr Regn: 22 Sep 2016
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 2.0
 Make: Subaru Forester C.C. 1995
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 82253 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: IF151SKC5G9076302
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/60R17
 R: 11

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm Rear 6 mm
 D.O.A. _____ D.O.I. 09-07-19
 Survey held at W/S 229pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
<u>15/10</u>	<u>Final Rpt \$4449.3 with Glow hoo;</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Wheel end (\$) _____

Survey Fee:

Transportation:	_____
\$ + RS. SI	_____
Photos	_____
Others	_____
TOTAL	_____



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLG1516T	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0283/2019	YEAR: 22-SEP-2016
ENGINE NO: FB20Y380782	CHASSIS NO: JF1SJ5KC5GG076302
DOA: 22/06/2019	TOA: 1820HRS
TYPE OF CLAIM: 3 RD PARTY	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER,END PANEL & TAILGATE 250	\$1250.00
2.	RESPRAY REAR BUMPER,END PANEL & TAILGATE 200	\$1000.00
3.	REMOVE & REFIX EXHAUST	\$114.00
4.	TRANSFER TAILGATE MECHANISM	\$150.00
5.	FAULT DIAGNOSTIC	\$235.00
6.	REMOVE & INSTALL REAR WINDSCREEN	\$300.00
7.	TO REMOVE & REFIX FUEL TANK	\$171.00
8.	TO CONDUCT REAR LIGHTING TEST	\$28.00
9.	TO CONDUCT PROTECTANT COATING	\$750.00
10.	TO CONDUCT ANTI RUST COATING	\$290.00
11.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	\$300.00
12.	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	\$145.00
13.	SUNDRIES	\$100.00
Total Labour		\$4833.00

750
500
800
NN
NN
NN
NN
NN
20
2455

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Que Qiang
HP / EMAIL:	82880282 QueQiang@kkauto.com
BEFORE PAINT:	before paint photos. (MIE)
DAYS GIVEN:	5

09/7/19.



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel: (65) 6703 8101/8102
 Fax: (65) 6253 5535
www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SG-1516-T

Surveyor: _____

DESCRIPTION

PART NO

AMOUNT

<u>DESCRIPTION</u>	<u>PART NO</u>	<u>AMOUNT</u>
① BACK BEAM COMPLETE REAR / B7	5771SG0219 P	\$288.00
② LETTER-MARK-REAR / 1 piece	93079SG000	⑨ \$39.60
③ LETTER-MARK REAR / 1 piece	93079SG030	⑩ \$64.80
④ COVER-Bumper REAR / 1 pc	5773SG0060	⑧ \$14.40
⑤ COVER HOOK-R / 1 pc	5773SG0104	③ \$10.40
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		

Motor Image
 10/7/19

Estimate

Date 06 / 25 / 2019 001 / 002

Name	QUOTATION FOR SLG1516T	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJKC5GG076302

Part Number	Part Code Name	Part Code	Q'ty	Price
63019SG000	GLASS-REAR GATE <i>? / del</i>	FIG-621 63011	1	799.20
63232SG010	RUBBER-REAR GATE <i>/ del</i>	FIG-621 63232	1	12.60
63232SG000	DAM RUBBER-REAR GATE GLASS <i>/ del</i>	FIG-621 63232C	2	7.20
60809SG0109P	PANEL-REAR GATE <i>/ huc</i>	FIG-620 60810	1	1,072.80
63516SG001	WEATHER STRIP-REAR GATE <i>X</i>	FIG-901 63516	1	111.60
63032FG102	LATCH & ACTUATOR-REAR GATE <i>X</i>	FIG-622 63176A	1	144.00
63264AG100	STRIKER-REAR GATE <i>X</i>	FIG-622 63264	1	21.60
94026SG000VH	TRIM PANEL-REAR SKIRT <i>X</i>	FIG-940 94046	1	36.00
57704SG012	BUMPER-FACE,REAR <i>/ re</i>	FIG-591 57704A	1	540.00
57711SG0219P	BACK BEAM COMPLETE-REAR <i>? / BT</i>	FIG-591 57711D	1	288.00
57707SG080	BRACKET-REAR BUMPER SIDE,RIGHT <i>X</i>	FIG-591 57707H	1	14.40
57707SG090	BRACKET-REAR BUMPER SIDE,LEFT <i>X</i>	FIG-591 57707I	1	14.40
57707SG060	BRACKET-REAR BUMPER CORNER,RIG HT <i>X</i>	FIG-591 57707AC	1	18.00
57707SG070	BRACKET-REAR BUMPER CORNER,LEF T <i>X</i>	FIG-591 57707AD	1	18.00
Page-Total				3,097.80

①
②
③
④
⑤

⑥
⑦

Memo

Grand Total
3,097.80

2848.7 2849

Tel

*-30%: 1718.5
1994.073*

4449.073