



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLG1516T	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0283/2019	YEAR: 22-SEP-2016
ENGINE NO: FB20Y380782	CHASSIS NO: JF1SJ5KC5GG076302
DOA: 22/06/2019	TOA: 1820HRS
TYPE OF CLAIM: 3 RD PARTY	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT	
1.	REPAIR/REPLACE REAR BUMPER,END PANEL & TAILGATE 250	\$1250.00	500
2.	RESPRAY REAR BUMPER,END PANEL & TAILGATE 200	\$1000.00	400
3.	REMOVE & REFIX EXHAUST	\$114.00	X
4.	TRANSFER TAILGATE MECHANISM	\$150.00	✓
5.	FAULT DIAGNOSTIC	\$235.00	X
6.	REMOVE & INSTALL REAR WINDSCREEN	\$300.00	✓
7.	TO REMOVE & REFIX FUEL TANK	\$171.00	X
8.	TO CONDUCT REAR LIGHTING TEST	\$28.00	X
9.	TO CONDUCT PROTECTANT COATING	\$750.00	X
10.	TO CONDUCT ANTI RUST COATING	\$290.00	X
11.	TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES	\$300.00	?
12.	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	\$145.00	✓
13.	SUNDRIES	\$100.00	20
Total Labour		\$4833.00	

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Que Qiang
HP / EMAIL:	82880282 QueQiang@kkauto.com
BEFORE PAINT:	before paint photos. ✓ (MIE)
DAYS GIVEN:	4

09/7/19.

Estimate

Date 06 / 25 / 2019 001 / 002

Name	QUOTATION FOR SLG1516T	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG076302

Part Number	Part Code Name	Part Code	Q'ty	Price
63019SG000	GLASS-REAR GATE ? / del	FIG-621 63011	1	799.20
63232SG010	RUBBER-REAR GATE / del	FIG-621 63232	1	12.60
63232SG000	DAM RUBBER-REAR GATE GLASS / del	FIG-621 63232C	2	7.20
60809SG0109P	PANEL-REAR GATE / huc	FIG-620 60810	1	1,072.80
63516SG001	WEATHER STRIP-REAR GATE ?	FIG-901 63516	1	111.60
63032FG102	LATCH & ACTUATOR-REAR GATE X	FIG-622 63176A	1	144.00
63264AG100	STRIKER-REAR GATE X	FIG-622 63264	1	21.60
94026SG000VH	TRIM PANEL-REAR SKIRT ?	FIG-940 94046	1	36.00
57704SG012	BUMPER-FACE,REAR / be	FIG-591 57704A	1	540.00
57711SG0219P	BACK BEAM COMPLETE-REAR ?	FIG-591 57711D	1	288.00
57707SG080	BRACKET-REAR BUMPER SIDE,RIGHT X	FIG-591 57707H	1	14.40
57707SG090	BRACKET-REAR BUMPER SIDE,LEFT X	FIG-591 57707I	1	14.40
57707SG060	BRACKET-REAR BUMPER CORNER,RIG HT X	FIG-591 57707AC	1	18.00
57707SG070	BRACKET-REAR BUMPER CORNER,LEF T X	FIG-591 57707AD	1	18.00
Page-Total				3,097.80

Memo

Grand Total
3,097.80

Tel	
-----	--