

ASS. REC. BY:

REF: CS/CTI19012063/K/f3n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

8/7/17 05:08pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQL 8636S

Insured:

YJ 168 B

at Workshop m/s

Ah Lim motor

Tek

64831244

of

Blk 10 AMK Ind. Park 2A #01-09

64563637

Policy No:

GA 061210 PMCVSN 19215719000

Claim No:

SNM19D203059 02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:40am 9/7/14

Person Contacted:

Zila

Vehicle IN/OUT

Date/Time

Action/Instruction
--------------------

February ✓

YJ 168B : CC4/AXA1602100A/Gph3g2

D.O.A. 12/10/2016

SGL 86365: X

12/19 \$1959.60 Car loan paid to 250, 11%  
no comp sum.

ASS. REC. BY:

REF:

C721

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

6.3/20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

8/21

Person Contacted:

Vehicle: IN / OUT

Veh No:

PGL 86365

Yr Regn:

OP, 06

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c.

1500

Colour

M. Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

351013

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TM6BK 106270311449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Type Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

3

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

30/6/19

D.O.I.

9/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

RECEIVED 12 SEP 2019

12/9/2019

Date/Time, File Pass to?

☐

: Prel. Report

1) 19/9/2019

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS - St

Fees:

Others

TOTAL

220

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

1959.60

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 8 July 2019 5:08 PM  
**To:** Zila @ Ah Lim Motor Company  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D203059/CHONGBS - TP / OUR CLIENT SGL8636S DOA: 30/06/2019 POLICY NO. GA061210 YOUR INSURED YJ168B

**WITHOUT PREJUDICE**

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Zila @ Ah Lim Motor Company [mailto:zila@ahlimmotor.com.sg]  
**Sent:** Wednesday, 3 July, 2019 10:30 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D203059/CHONGBS - TP / OUR CLIENT SGL8636S DOA: 30/06/2019 POLICY NO. GA061210 YOUR INSURED YJ168B

Hi,

We choose Kenneth Kong to be the surveyor.

Thanks.

*Zila*

*Ah Lim Motor @ AMK*

*No 10 Ang Mo Kio Ind Pk 2A*

*#01-09 AMK Autopoint*

*S 568047*

*Tel: 64831244 Fax: 64836170*

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

**Sent:** Wednesday, July 3, 2019 10:28 AM

**To:** Zila @ Ah Lim Motor Company <zila@ahlimmotor.com.sg>

**Subject:** RE: OUR REF: SNM19D203059/CHONGBS - TP / OUR CLIENT SGL86365 DOA: 30/06/2019 POLICY NO. GA061210 YOUR INSURED YJ168B

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Tuesday, 2 July, 2019 5:31 PM

To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; zila@ahlimmotor.com.sg; Alfred Toh  
<[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>

Subject: OUR REF: SNM19D203059/CHONGBS - TP / OUR CLIENT SGL8636S DOA: 30/06/2019 POLICY NO. GA061210  
YOUR INSURED YJ168B

Dear Boon Sen,

Please conduct PRS for SGL8636S.

\*\*\* Officer-In-Charge – Chong Boon Sen – 63896171 (file with OIC).

Thank you

**Lim Shu Min**

Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

From: Zila @ Ah Lim Motor Company [<mailto:zila@ahlimmotor.com.sg>]

Sent: Tuesday, 2 July, 2019 10:16 AM

To: Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

Cc: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

Subject: TP / OUR CLIENT SGL8636S DOA: 30/06/2019 POLICY NO. GA061210 YOUR INSURED YJ168B

Hi Claims Dept,

Please kindly arrange survey.

Note: Vehicle is not in. – To be arrange

Thanks.

Zila

Ah Lim Motor @ AMK

No 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

S 568047

Tel: 64831244 Fax: 64836170

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 3517A

### Vehicle Details

Vehicle No.: SGL8636S  
Vehicle to be Exported: No  
Intended Deregistration Date: 01 Jul 2019  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA3 SP  
Primary Colour: Purple  
Manufacturing Year: 2006  
Engine No.: Z6488319  
Chassis No.: JM6BK106270311449  
Maximum Power Output: 79.0 kW (105 bhp)  
Open Market Value: \$15,376.00  
Original Registration Date: 29 Sep 2006  
First Registration Date: 29 Sep 2006  
Transfer Count: 1  
Actual ARF Paid: \$16,914.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Aug 2021  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$25,759.00  
COE Rebate Amount: \$11,148.00  
**Total Rebate Amount: \$11,148.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Jul 2019

OK

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

**M/S :** LEE SWEE LIN ALICIA SANDRA  
BLK 682C JURONG WEST CENTRAL 1 #07-130

SINGAPORE 643682

TEL: 94593801

ATTN:

Your Ref No: SGL8636S

Claim Type: Third Party

Accident Date: 30/06/2019

TP Veh Reg No: YJ168B

**Estimate No: MC1900494**

Date: 02 Jul 2019

Policy No: GA061210

Veh Reg No: **SGL8636S**

Make/Model: MAZDA 3 SP

*Like  
2pm*

*Not withash*

*6/1 Sep 87*

*Recovery After Paint*

*4 days*

## Estimate Repair Cost to Vehicle No :SGL8636S

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>SPARE PARTS</b>			
1 FRONT WINDSCREEN	1 PC	<i>CM</i> 1,141.10	<i>✓</i>
2 FRONT WINDSCREEN MOULDING	1 PC	<i>ma</i> 81.90	<i>✓</i>
3 SIDE MIRROR ASSY	1 PC	<i>ma</i> 389.00	<i>✓</i>
		1,612.00	
	Less 20%	322.40	1,289.60
<b>LABOUR</b>			
4 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<i>✓</i>
5 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR PILLAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	<i>250</i>
6 TO SPRAY FRONT DOOR PILLAR,SIDE MIRROR RH.	1 PC	400.00	<i>300</i>
		920.00	920.00
Total			S\$ 2,209.60
Add GST @ 7%			154.67
Total Amount Payable			S\$ 2,364.27

TOTAL: SINGAPORE DOLLAR TWO THOUSAND THREE HUNDRED SIXTY FOUR AND CENTS TWENTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



Kg

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : LEE SWEE LIN ALICIA SANDRA  
BLK 682C JURONG WEST CENTRAL 1 #07-130

Claim No: MC1900494  
No: MF1900553  
Date: 09 Sep 2019  
Policy No: GA061210  
Veh Reg No: SGL8636S  
Make/Model: MAZDA 3 SP

SINGAPORE 643682

TEL: 94593801

ATTN:

Your Ref No: SGL8636S

Claim Type: Third Party

Accident Date: 30/06/2019

TP Veh Reg No: YJ168B

## Repair Cost to Vehicle No (For Finalization):SGL8636S

Description	Quantity	List Price S\$	Amount S\$
<b>SPARE PARTS</b>			
1 FRONT WINDSCREEN	1 PC	1,141.10	
2 FRONT WINDSCREEN MOULDING	1 PC	81.90	
3 SIDE MIRROR ASSY	1 PC	389.00	
		1,612.00	
	Less 20%	322.40	1,289.60
<b>LABOUR</b>			
4 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
5 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT DOOR PILLAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	250.00	
6 TO SPRAY FRONT DOOR PILLAR,SIDE MIRROR RH.	1 PC	300.00	
		670.00	670.00
<b>Total</b>			<b>S\$ 1,959.60</b>
<b>Less Excess</b>			<b>S\$ 0.00</b>
<b>Amount Before GST</b>			<b>S\$ 1,959.60</b>
<b>Add GST @ 7%</b>			<b>137.17</b>
<b>Total Amount Payable</b>			<b>S\$ 2,096.77</b>

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINETY SIX AND CENTS SEVENTY SEVEN ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 09/07/2019

For AH LIM MOTOR COMPANY

**AH LIM MOTOR COMPANY**

No. 10 Ang Mo Kio Ind. Park 2A

#01-09 / AMK Autopoint Singapore 568047

AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19012063/KQF3N2

Date: 20/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19215719000	
Claimant Vehicle No :	SGL8636S	Insured Vehicle No :	YJ168B	
Date of Loss:	30/06/2019	Nature of Claim:	TP	Claim No: SNM19D203059C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGL8636S	Engine No:	Z6488319
Make & Model:	MAZDA 3, 1.6 SP (A)	Chassis No:	JM6BK106270311449
Reg. Date:	29/09/2006 (Man. Year: 2006)	Odometer:	351013 km
Colour:	Metallic Maroon		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 3 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 3 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,289.60	1,289.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	670.00	250.00	27.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,209.60</b>	<b>1,959.60</b>	<b>250.00</b>	<b>11.31</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>154.67</b>	<b>137.17</b>	<b>17.50</b>	<b>11.31</b>
<b>Nett Amount (\$\$)</b>	<b>2,364.27</b>	<b>2,096.77</b>	<b>267.50</b>	<b>11.31</b>

## INSPECTION

Date of Assignment:	19/09/2019	
Date Inspected:	09/07/2019	Inspected At: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2019)
<b>Parts:</b> 143	MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGL8636S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,141.10 FL	*1,141.10 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	81.90 FL	*81.90 FL
3	1		*SIDE MIRROR ASSY	Dented	389.00 FL	*389.00 FL
F=Franchise part. L=ListItemDisc.						
<b>Sub Total (\$\$)</b>					<b>1,612.00</b>	<b>1,612.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>					322.40	322.40
<b>Total Parts (\$\$)</b>					<b>1,289.60</b>	<b>1,289.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN	New	120.00	120.00
2	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD,TO KNOCK & REPAIR FRONT DOOR PILLAR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	400.00	250.00
3	TO SPRAY FRONT DOOR PILLAR,SIDE MIRROR RH	New	400.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>920.00</b>	<b>670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >