

12/12/16

NS CASE OWNER

Finchamere CC 2 / AIG1602 3411, 12/12/16

LKK IDAC

Surveyor

Taufik

DOI

ASSIGNMENT

12/12/16

Date / Time

Registered in Meritmen

12/12/16

Pre-assign / CCU / FTE

SJF 99656

916785767669



Insured Vehicle No.

Name of Insured

MUHAMMAD KIOZHAN BIN RAHMAT

Claim No.

Policy No.

7100420000-0000

Insured Tel No.

HP: 97433041

Make / Model

MITSUBISHI

Excess Sec II :SS

D.O.A: 4/12/16

Place of Accident

PUNOS LINE TMS SELLER

Is driver the owner?

(YES / NO) YES

Nature of Accident

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

If NO, Driver Name / Age

Driver Tel No.

(VA) YES / NO

Insured Liability

Final ? Yes / No

SJC 4229A



INSRS: WSP: Tel: Liability: RMKS:

SMART



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
12/12/16	Non-Reporting In (1st)	
12/12/16	Non-Reporting In (2nd)	
12/12/16	Non-Reporting In (Final)	
	Notification In (if non-pickup):	
	Call Of: 30/12/16	
	After call In to OI	
	Documentation Check List:	Handler Typist
	Notification In (if non-pickup)	<input type="checkbox"/>
	After call In to OI	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

File Reviewed - To RIO of evidence. To get TP evidence since he said travel is straight and not walk U-Turn.

12/12/19 - FILE PAS TO LSP TO CLOSE

PRELIMINARY ADVICE Date/Time: 12/12/16 Sent By: [Signature]

FINALIZATION Date/Time: Confirm with: Confirm by: Email Call

Repair Cost: \$55 days Reduction: %

FINAL SETTLEMENT Date/Time: 10/3/19 Confirm with: Lee Geh Email Call

Final Liability: % 50 (Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost: \$5496.04 \$5 2748.02 PIR against both drivers

Loss of Rental (LOR): \$802.25 401.25 (6 days) x \$133.75

Loss of Use (LOU): \$5 5 days

Loss of Income (LOI): \$5 5 days

LOR only LOU only LOR + LOI LOR + LOI (Tick only one)

GIA/LTA Search: \$5 5.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/Independent)

Legal Cost: \$5 -

Total: \$5 3154.27 **Global Sum \$5: 3150.00**

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 3150.00 Name 1: SMART Taxi Pte Ltd

Payee 2: (Strike if N.A.): \$5 Name 2:

Payee 3: (Strike if N.A.): \$5 Name 3:

COPY SENT 10/3/19 W/S 12

AM 12/12/19

Surveyor Tang M

REF:

ALG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNCG777A Yr Regn: 8/4/2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prime c.c 1798
 Colour Maroon A/C: Insured / Std / NI / NA
 Sp. Reading 79658 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 370KUN364605707795
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 4/10/16 D.O.I. 7/12/16 @ 1550
 Survey held at SMRT
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Dvt M/S / U/C
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$5,496
	\$5,496.04 Red (\$19619.18/64%) LKK
	ALG - 53F99659

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee:	
Transportation:	
S - RS, SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG16023411/T1yb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 08-12-2016	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJF 9965G	Veh. Inspected	SHC 4779A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	08/12/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/12/2016	Inspection Date	07/12/2016
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

13-12-16/12:31
13-12-16/16:31

7-12-11/16:31

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4779A
 Ref. No : TAX/12/18/2025
 Reg. Date : 08/04/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHEW KOK CHENG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 04/12/2016 07:50:00 PM
 Accident Reported Date / Time : 05/12/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Taufikh
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024086452
 Special Instruction to ARC, if any :
 SJF9965G / AIG - LKK
 Before paint photo, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR TAUFIKH, HP 9749 5749/
 EMAIL: taufikh@lkkauto.com
 Prepared Date : 05/12/2016 11:35:09 AM



M.C
14/12
CHEW
S508
A902

15:00 13-12-16 pass

1 1 1 1 1
 1/4 1/2 3/4
 7 9 6 5 8
 7 9 7 2 1

Recording Centers

Radio Antonio

1st witness [Signature] Date 13-12-16

2nd witness [Signature] Date 13-12-16

Supplementary
 - Details in Supplementary photos

13-12-16

14.06.16m

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605767796

Mileage

0

Work Shop :

Repair Completed Date / Time

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,362.00	600.00
Total Spray Painting Charges	: 2,034.00	950.00
Total Material Charges	: 7,294.53	3,616.03
Other Charges	: 1,155.00	540.00
TOTAL	: 11,835.53	5,706.03
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	5.00
Prepared / Adjusted By	:	TAUFIKH (LKK)
Arc / Surveyor Sign Off Date	: 05/12/2016 05:23:25 AM	07/12/2016 04:31:17 AM



Prepared / Adjusted Date :

Remarks

Prepared Date : 05/12/2016 05:23:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

QN-1612-0633

Invoice No

Quotation Date

26/12

Invoice Date

Invoice Amount

Prepared Date

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,352.00	600.00
Total Labour	1,352.00	600.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	200.00
TO RESPRAY VIEW MIRROR	180.00	100.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	150.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY FRONT PILLAR LH	180.00	0.00
TO RESPRAY RIM	180.00	100.00
TO REPSRAY FRONT BUMPER	378.00	200.00 ?
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
Total Spray Painting & Panel Beating	2,034.00	950.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
TO TRANSFER DOOR MECHANISM	120.00	60.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	60.00 ? X
TO REMOVE AND REFIX WING MIRROR	120.00	60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	60.00
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	150.00 ? X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
Total Other Costs	1,155.00	540.00

330-

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
87002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No <input checked="" type="checkbox"/>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <input checked="" type="checkbox"/>
88740-12120			HINGE LOWER LHF. DOOR	1	90.10	25.00	67.58	Replace	Check	No <input checked="" type="checkbox"/>
88720-15151			HINGE UPPER LHF. DOOR	1	80.50	25.00	60.38	Replace	Check	No <input checked="" type="checkbox"/>
88610-47021			CHECK ASSY. FR DOOR	1	150.30	25.00	112.73	Replace	Check	No <input checked="" type="checkbox"/>
89802-52070			DOOR REGULATOR SUB-ASSY. FRT/REAR LH	1	224.80	25.00	168.60	Replace	Check	No <input checked="" type="checkbox"/>
87940-47310		6505599	MIRROR ASSY. LH	1	1,224.90	25.00	918.68	Replace	Replace	No <input checked="" type="checkbox"/>
87961-47150			MIRROR GLASS LH	1	142.50	25.00	106.85	Replace	Check	No <input checked="" type="checkbox"/>
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.27	Replace	Check	No <input checked="" type="checkbox"/>
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
75852-47900			MOULDING BODY, LH	0	673.60	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No <input checked="" type="checkbox"/>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <input checked="" type="checkbox"/>
62120-47021			QUARTER GLASS FRT/LH	0	234.90	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
81132-47030			PILLAR, FR BODY, LH	1	363.10	100.00	0.00	Repair	Repair	No <input checked="" type="checkbox"/>
42611-47140 (Fit)		5505858	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No <input checked="" type="checkbox"/>
48520-80294			SHOCK ABSORBER FRT/LH	1	394.20	25.00	295.85	Replace	Check	No <input checked="" type="checkbox"/>
48069-47050			LOWER ARM FRT/LH	1	625.90	25.00	469.43	Replace	Check	No <input checked="" type="checkbox"/>
43330-49185			JOINT ASSY, LWR BALL	1	195.60	25.00	146.70	Replace	Check	No <input checked="" type="checkbox"/>
43202-47030			STEERING KNUCKLE LH FRT	1	580.80	25.00	435.60	Replace	Check	No <input checked="" type="checkbox"/>
48520-80294			SHOCK ABSORBER FRT/LH	1	394.20	25.00	295.85	Replace	Check	No <input checked="" type="checkbox"/>
48820-47020			STABILIZER BAR LINK FRT/RH/LH	1	195.00	25.00	146.25	Replace	Check	No <input checked="" type="checkbox"/>
43420-47030			DRIVE SHAFT LH	1	1,543.80	25.00	1,157.85	Replace	Check	No <input checked="" type="checkbox"/>
52118-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Repair	Repair	No <input checked="" type="checkbox"/>
52118-47040		6505518	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No <input checked="" type="checkbox"/>
52811-47080		6505518	BUMPER ENERGY ABSORBER FRT	0	78.80	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52021-47023		8505539	BUMPER REINFORCEMENT FRT	0	498.40	25.00	0.00	Replace	Not given	No X
57014-47030			ARM SUB-ASSY, FR BUMPER LH	0	250.40	25.00	0.00	Replace	Not given	No X
53201-47902			SUPPORT SUB-ASSY	0	1,460.40	25.00	0.00	Replace	Not given	No X
81170-47500		8505436	HEAD LAMP LH	0	945.20	10.00	0.00	Replace	Not given	No X
53852-47020			FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	38.98	Replace	Check	No X
53878-47030		8505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No X
45047-49165			TIE ROD END LH	1	159.30	25.00	118.48	Replace	Check	No X
53828-47060			PROTECTOR, FRONT FENDER SIDE PANEL LH (A)	1	114.50	25.00	85.87	Replace	Replace	No X
TOTAL MATERIALS								7,294.55	3,616.04	
TOTAL MATERIALS(Discounted)								7,294.53	3,616.03	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
33928-17060		PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	25.00	85.87	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						85.87			

3616.03 3616.04
 + 600.00 600
 + 1490.00 1490

 5706.03 5476.04
 5 days
 Confirmed with Rich Soren

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg No : SHC4779A
 Ref No : TAX/12/16/2025
 Reg. Date : 08/04/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHEW KOK CHENG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 04/12/2016 07:50:00 PM
 Accident Reported Date / Time : 05/12/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024086452
 Special Instruction to ARC, if any :
 SJF9965G
 Prepared Date : 05/12/2016 11:35:09 AM



*Tanpin 9749 5749
 WP
 4/12/16 @ 1550
 5 days
 Resing before paint
 tanpin @ 1kkantown.*

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605767795

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,352.00	0.00
Total Spray Painting Charges	2,034.00	0.00
Total Material Charges	10,574.22	11,208.04
Other Charges	1,155.00	0.00
TOTAL	15,115.22	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	8.00	0.00
Prepared / Adjusted By		0.00
Arc / Surveyor Sing Off Date	05/12/2016 05:23:25 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date

Remarks

Prepared Date : 05/12/2016 05:23:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,352.00	0.00
Total Labour	1,352.00	0.00 600

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 100
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 150
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT PILLAR LH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 100
TO REPSRAY FRONT BUMPER	378.00	0.00 ?
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 X
Total Spray Painting & Panel Beating	2,034.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO TRANSFER DOOR MECHANISM	120.00	0.00 60
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0.00 60?
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 60
TO REMOVE AND REFIX UNDERCARRIAGE	250.00	0.00 150?
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
Total Other Costs	1,155.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace <i>BT</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>BT</i>	No
68740-12120			HINGE LOWER LHF, DOOR	1	90.10	25.00	67.57	Replace	Replace <i>BT</i>	No
68720-15151			HINGE UPPER LHF, DOOR	1	80.50	25.00	60.37	Replace	Replace <i>BT</i>	No
68610-47021			CHECK ASSY. FR DOOR	1	150.30	25.00	112.72	Replace	Replace <i>BT</i>	No
69802-52070			DOOR REGULATOR SUB-ASSY. FRT/REAR LH	1	224.80	25.00	168.60	Replace	Replace <i>BT</i>	No
87940-47310		6505599	MIRROR ASSY. LH	1	1,224.90	25.00	918.67	Replace	Replace <i>BT</i>	No
87961-47150			MIRROR GLASS LH	1	142.50	25.00	106.87	Replace	Replace <i>BT</i>	No
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace <i>BT</i>	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace <i>BT</i>	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace <i>BT</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>BT</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>BT</i>	No
62120-47021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace <i>BT</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>BT</i>	No
61132-47030			PILLAR, FR BODY, LH	1	363.10	25.00	272.33	Repair	Replace <i>BT</i>	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>BT</i>	No
48520-80294			SHOCK ABSORBER FRT/LH	1	394.20	25.00	295.65	Replace	Replace <i>BT</i>	No
48069-47050			LOWER ARM FRT/LH	1	625.90	25.00	469.42	Replace	Replace <i>BT</i>	No
43330-49185			JOINT ASSY, LWR BALL	1	195.60	25.00	146.70	Replace	Replace <i>BT</i>	No
43202-47030			STEERING KNUCKLE LH FRT	1	580.80	25.00	435.60	Replace	Replace <i>BT</i>	No
48520-80294			SHOCK ABSORBER FRT/LH	1	394.20	25.00	295.65	Replace	Replace <i>BT</i>	No
48820-47020			STABILIZER BAR LINK FRT/RH/LH	1	195.00	25.00	146.25	Replace	Replace <i>BT</i>	No
43420-17030			DRIVE SHAFT LH	1	1,543.80	25.00	1,157.85	Replace	Replace <i>BT</i>	No
12119-7930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Repair	Replace <i>BT</i>	No
2116-7040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>BT</i>	No
2611-7080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>BT</i>	No

Number	Part No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photo Attach
52021-47023	6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No
57014-47030		ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace X	No
53201-47902		SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace X	No
81170-47500	6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace X	No
53852-47020		FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	36.97	Replace	Replace X	No
53876-47030	6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace ?	No
45047-49165		TIE ROD END LH	1	159.30	25.00	119.47	Replace	Replace ?	No
TOTAL MATERIALS									
TOTAL MATERIALS(Discounted)							10,574.28	11,208.05	
Added Spare Parts / Material Usage After Surveyor Signed off							10,574.22	11,208.04	

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Mei Kwan (LKKAuto)

From: Boyogan, Joane <Joane.Boyogan@aig.com>
Sent: Sunday, 7 July, 2019 1:43 PM
To: Mei Kwan (LKKAuto)
Subject: RE: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg) *** AIG REF: TP / 8167853676SG

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: HMK

Dear Mei Kwan,

In view of the PIR, please proceed to negotiate settlement with third party repairer on a 50/50 basis

I've since reopened the corresponding Merimen case and sent back the adjuster report for your further action


Thank you

Regards,

Joane Boyogan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +65 64191898
joane.boyogan@aig.com | www.aig.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Cheok, Lee Wai
Sent: Thursday, July 04, 2019 10:42 AM
To: Boyogan, Joane

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Thursday, 4 July, 2019 10:15 AM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

**URGENT
LAST ATTEMPT – APPEAL**

Dear All,

Please note that:-

1. the final result of police investigation indicated that our driver and your insured were given a warning for making an unauthorised U-turn and inconsiderate driving respectively.
2. we have settled both your insured's TPPD and TPBI claims at 50% each. We attach the proof of settlement for your perusal.
3. Police action is applicable since this accident involved only 2 vehicles.

In view of the above, we would urge your principal to review the matter and let us know by **12th July 2019** if they are prepared to settle our claim at 50%, otherwise we will escalate the matter to GIA for their deliberation. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: 13/02/2017 17:04
To: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA); Jas Khine (LKKAuto)
Cc: Admin A; CS A Team
Subject: RE: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G - AIG (Our Ref: TAX/12/16/2025/lg)
Attachments: TAX 12 16 2025.pdf

Dear Lee Gek,

Thank you for your email.

Please note that :-

LKK ref	Officer in charge
_C3/AIG16023411/T1yb3	Jas

To check availability of the case handler, you may contact the undersigned.

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA) [<mailto:LeeGek@smrt.com.sg>]
Sent: Monday, 13 February, 2017 4:55 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Jas Khine (LKKAuto) <jaskhine@lkkauto.com>
Subject: Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G - AIG (Our Ref: TAX/12/16/2025/lg)

Dear All,

We quantify our own losses as follows:-

Cost of repairs	\$5496.04	6100
Loss of rental	\$1070.00 (\$133.75 x 8 days)	1202.50
LTA search fee	\$ 5.00	5698.54
	\$6571.04	83142.27 (103)
	=====	5.10

We attach the proof of rental, repair bill, laid-up report, police/GIA reports of our taxi and LTA search for your perusal.

Please let us hear from you soon.

Regards
Tan Lee Gek (DID: 6866 2647)
Claims Department

Jia Le (LKK Auto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Wednesday, 10 July 2019 2:52 PM
To: Jia Le (LKK Auto)
Subject: Returned of DV Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)
Attachments: img-710144328-0001.pdf

Dear Carlor,

We attach the duly signed DV and ATA for your necessary action. Please let us have AIG's cheque for \$3,150.00 for our own losses payable to **SMRT TAXIS PTE LTD**. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]
Sent: 10/07/2019 12:22
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Subject: RE: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

'WITHOUT PREJUDICE'

Dear Lee Gek,

DV and ATA attached.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) [mailto:LeeGek@smrt.com.sg]
Sent: Wednesday, 10 July 2019 10:35 AM
To: Jia Le (LKK Auto)
Subject: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

Dear Carlor,

We accept your global offer of \$3,150.00 for our own losses. Please let us have your DV and ATA. Thanks.

Regards
Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]
Sent: 10/07/2019 10:14
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Subject: RE: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

*'WITHOUT PREJUDICE'
SAVE AS TO COSTS*

Dear Sir/Madam,

Accident on 04/12/2016 involving SJF 9965G & SHC 4779A

In view of the PIR, we have our principal instruction to settle at 50/50 liability.

For a quick and amicable settlement, we offer to settle global sum at **SS 3,150.00**

Kindly confirm acceptance.

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) [<mailto:LeeGek@smrt.com.sg>]
Sent: Tuesday, 9 July 2019 5:51 PM
To: Jia Le (LKK Auto)
Subject: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

Dear Carlor,

We have submitted our LOD to your office on 13/2/2017. Nevertheless, we attach our LOD for our own losses and the supporting documents for your perusal.

We are claiming for an additional sum of \$25.68 for the police search fee for obtaining a conclusive result. Please refer to the attached bill from AJAX Adjusters & Surveyors.

Please let us have your offer by **16th July 2019**. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]

Sent: 09/07/2019 12:11

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Subject: RE: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

Without Prejudice

Dear Lee Gek,

Kindly assist to send a copy of LOD for our necessary action.

Thank you.

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Monday, 8 July 2019 12:01 PM

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis); Jia Le (LKK Auto)

Cc: CS A Team; Admin A

Subject: RE: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

‘WITHOUT PREJUDICE’
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Jia Le,

Kindly assist. Our ref: [CC3/AIG16023411/T1db3q2-1](#).

- * To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>

Sent: Thursday, 4 July, 2019 10:15 AM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: URGENT / LAST ATTEMPT Re: Accident on 4/12/2016 involving SHC 4779A & SJF 9965G (Our Ref: TAX/12/16/2025/lg)

URGENT

LAST ATTEMPT – APPEAL

Dear All,

Please note that:-

- 1) the final result of police investigation indicated that our driver and your insured were given a warning for making an unauthorised U-turn and inconsiderate driving respectively.
- 2) we have settled both your insured's TPPD and TPBI claims at 50% each. We attach the proof of settlement for your perusal.
- 3) Police action is applicable since this accident involved only 2 vehicles.

In view of the above, we would urge your principal to review the matter and let us know by **12th July 2019** if they are prepared to settle our claim at 50%, otherwise we will escalate the matter to GIA for their deliberation. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



AJAX

Adjusters & Surveyors

AJAX Adjusters & Surveyors Pte Ltd
120 Lower Delta Road
#08-08 Cendex Centre
Singapore 169208
Tel: (65) 6255 0808
Fax: (65) 6849 9155
info@ajaxadjusters.com

Date : 26 June 2019
To : SMRT Taxis Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705
Attn : Ms Tan Lee Gek

Invoice No – A28981
Company Reg No - 200912520Z
GST Reg No – 200912520Z

TAX INVOICE

YOUR REF / CLAIM NUMBER : TAX/12/16/2025
OUR REF : SC-TP000117173/SMRT
INSURED : SHC4779A
CLAIM TYPE : MOTOR
DATE OF LOSS : 04 February 2017
POLICY NO. : Please Advise



No.	Description	Amount (\$S)
1	Traffic Police Search Fee	14.00
2	Administrative fee	10.00

Subtotal 24.00
GST 7.00% 1.68
Total 25.68

Payment Terms: 30 days from invoice date

Please remit by electronic transfer as follows:
Payee: AJAX Adjusters & Surveyors Pte Ltd
United Overseas Bank Ltd
Swift Code: UOVBSGSG
Singapore Dollar Account No: 393-301-554-6
US Dollar Account No: 393-900-206-3
Email remittance advice to: accounts@ajaxadjusters.com

Checked By : Huan Tan 4/7/19
Verified By : Lee Gek 4/7/19
Approved By : Chong Fei Yuan 5/7/19
Assistant General Manager
Claims & Insurance Agency
Automotive Services

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, SMRT TAXIS PTE LTD (the third party claimant") of BLK 60 WOODLANDS INDUSTRIAL PARK E4 (S) 757705 (address), owner of SHC 4779A (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHC 4779A that was damaged pursuant to the accident which occurred on 04/12/2016 (date) along JALAN EUNOS (location) involving vehicle no/s SJF 9965G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 10 (day) of July (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS3,150.00 (Global Sum) for vehicle no. SHC 4779A that was damaged pursuant to the accident which occurred on 04/12/2016 (date) along JALAN EUNOS (location) involving vehicle no/s SJF 9965G.

This is pursuant to the inspection conducted on 07/12/2016 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 4779A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 4779A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of July (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.



SMRT Automotive Services Pte Ltd
 251 North Bridge Road Singapore 179102
 Tel: 65 63311000 Fax: 65 63340247

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705



Tax Invoice

GST Reg No. : MR-8500001-7
 CRN : 199004280Z
 Invoice No. : IV170100766
 Date : 25.01.2017
 Vehicle No. : SHC4779A
 Your Ref No. : TAX/12/16/2025
 Our Ref No. : 24086452
 Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
DOOR:F/LH, FOR TOYOTA PRIUS TAXI	1.00	\$ 894.40	(25.00)	\$ 223.60	\$ 670.80
STICKER DECAL SMRT (DOOR)	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
HINGE LOWER LHF, DOOR	0.00	\$ 90.10	(25.00)	\$ 0.00	\$ 0.00
HINGE UPPER LHF, DOOR	0.00	\$ 80.50	(25.00)	\$ 0.00	\$ 0.00
CHECK ASSY, FR DOOR,	0.00	\$ 150.30	(25.00)	\$ 0.00	\$ 0.00
DOOR REGULATOR SUB-ASSY, FRT/REAR LH	0.00	\$ 224.80	(25.00)	\$ 0.00	\$ 0.00
MIRROR ASSY, REAR VIEW:LH, TOYOTA PRIUS	1.00	\$1224.91	(25.00)	\$ 306.23	\$ 918.68
MIRROR GLASS LH	0.00	\$ 142.50	(25.00)	\$ 0.00	\$ 0.00
LAMP, SIGNAL:SIDE MIRROR, LH, TOYOTA PRIUS	0.00	\$ 65.30	(10.00)	\$ 0.00	\$ 0.00
MIRROR:OUTER REAR VIEW, LH, TOYOTA PRIUS	1.00	\$ 107.40	(100.00)	\$ 107.40	\$ 0.00
MOULDING BODY, LH	0.00	\$ 673.60	(25.00)	\$ 0.00	\$ 0.00
FENDER, FRONT:LH, FOR TOYOTA PRIUS TAXI	1.00	\$ 723.40	(25.00)	\$ 180.85	\$ 542.55
NAME PLATE (HYBRID)	1.00	\$ 51.90	(25.00)	\$ 12.97	\$ 38.92
QUARTER GLASS FRT/LH	0.00	\$ 234.90	(25.00)	\$ 0.00	\$ 0.00
SEALANT W/SCREEN	0.00	\$ 37.00	0.00	\$ 0.00	\$ 0.00
PILLAR, FR BODY, LH	1.00	\$ 363.10	(100.00)	\$ 363.10	\$ 0.00
RIM, TYRE:FOR TOYOTA PRIUS TAXI	1.00	\$1484.20	(25.00)	\$ 371.05	\$ 1113.15
SHOCK ABSORBER FRT/LH	0.00	\$ 394.20	(25.00)	\$ 0.00	\$ 0.00
LOWER ARM FRT/LH	0.00	\$ 625.90	(25.00)	\$ 0.00	\$ 0.00
JOINT ASSY, LWR BALL	0.00	\$ 195.60	(25.00)	\$ 0.00	\$ 0.00
STEERING KNUCKLE LH FRT	0.00	\$ 580.80	(25.00)	\$ 0.00	\$ 0.00
SHOCK ABSORBER FRT/LH	0.00	\$ 394.20	(25.00)	\$ 0.00	\$ 0.00

Authorized Signature
 for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV170100766
Date : 25.01.2017
Vehicle No. : SHC4779A
Your Ref No. : TAX/12/16/2025
Our Ref No. : 24086452
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
STABILIZER BAR LINK FRT/RH/LH	0.00	\$ 195.00	(25.00)	\$ 0.00	\$ 0.00
DRIVE SHAFT LH	0.00	\$1543.80	(25.00)	\$ 0.00	\$ 0.00
BUMPER, FRONT: FOR TOYOTA PRIUS TAXI	1.00	\$ 482.00	(100.00)	\$ 482.00	\$ 0.00
SUPPORT, BUMPER: F/LH, FOR TOYOTA PRIUS	1.00	\$ 76.40	(25.00)	\$ 19.10	\$ 57.30
ABSORBER, ENERGY: BUMPER, FRT, TOYOTA PRIUS	0.00	\$ 78.80	(25.00)	\$ 0.00	\$ 0.00
REINFORCEMENT, BUMPER: FRT, TOYOTA PRIUS	0.00	\$ 498.40	(25.00)	\$ 0.00	\$ 0.00
ARM SUB-ASSY, FR BUMPER LH	0.00	\$ 250.40	(25.00)	\$ 0.00	\$ 0.00
SUPPORT SUB-ASSY	0.00	\$1460.40	(25.00)	\$ 0.00	\$ 0.00
HEADLAMP: LH, FOR TOYOTA PRIUS TAXI	0.00	\$ 945.20	(10.00)	\$ 0.00	\$ 0.00
FENDER LINER PAD, FR WHEEL. LH	0.00	\$ 49.30	(25.00)	\$ 0.00	\$ 0.00
LINER, FENDER: F/LH, FOR TOYOTA PRIUS TAXI	1.00	\$ 171.70	(25.00)	\$ 42.92	\$ 128.77
TIE ROD END LH	0.00	\$ 159.30	(25.00)	\$ 0.00	\$ 0.00
PROTECTOR, FRONT FENDER SIDE PANEL LH	1.00	\$ 114.50	(25.00)	\$ 28.62	\$ 85.87
Sub-Total					\$ 3616.04

Labour

TO REPAIR LH FRONT PORTION 1.00 \$ 600.00 0.00 \$ 0.00 \$ 600.00

Others

TO CHECK WIRING AND SYSTEM FUNCTION 1.00 \$ 30.00 0.00 \$ 0.00 \$ 30.00

TO APPLY RUST-PROOFING ON AFFECTED AREA 1.00 \$ 40.00 0.00 \$ 0.00 \$ 40.00

TO TRANSFER DOOR MECHANISM 1.00 \$ 60.00 0.00 \$ 0.00 \$ 60.00

Authorized Signature
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV170100766
Date : 25.01.2017
Vehicle No. : SHC4779A
Your Ref No. : TAX/12/16/2025
Our Ref No. : 24086452
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REMOVE AND REFIX WING MIRROR	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	1.00	\$ 60.00	0.00	\$ 0.00	\$ 60.00
TO REMOVE AND REFIX UNDERCARRIAGE	0.00	\$ 250.00	0.00	\$ 0.00	\$ 0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	1.00	\$ 80.00	0.00	\$ 0.00	\$ 80.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	0.00	\$ 125.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY FRONT DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY VIEW MIRROR	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO RESPRAY ROCKER PANEL MOULDING	1.00	\$ 150.00	0.00	\$ 0.00	\$ 150.00
TO RESPRAY FRONT FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT PILLAR LH	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
TO RESPRAY RIM	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT SUPPORT PANEL	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
GRAND TOTAL					\$ 5,496.04

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 04.12.2016

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.


Authorized Signature
for SMRT Automotive Services Pte Ltd



Our Ref : TAX/12/16/2025/LG

Date : 13/12/2016

To : Claims Department

From : SMRT Taxis

ACCIDENT INVOLVING SHC4779A & SJF9965G ON 04/12/2016 ALONG EUNOS LINK

CONFIRMATION OF TAXI RENTAL

This is to confirm the daily taxi rental rate for taxi registration no. SHC4779A is \$133.75/day.

Kindly proceed to recover any rental loss from the third party as a result of this accident.

Thank you.



For Manager
SMRT Taxis Pte Ltd



Accident Vehicle Laid-Up Report

Registration No. : SHC4779A Accident Case No. : TAX/12/16/2025
Make / Model : TOYOTA PRIUS Ref. No. : 24086452

Date and Time Vehicle off-road for Accident Repair : 05.12.2016 10:09:00
Date and Time Repair Completed : 13.12.2016 15:23:48

Remarks :

Generated by : NGSIUCHING

Printed on : 16.12.2016

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	06 Dec 2016 / 09:00:01		
Asset Type:	Vehicle	Transaction Amount:	\$5.35
Asset ID:	SJF9965G		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20161208090001029653

Search Date / Time: 04 Dec 2016 19:50:00

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the [Back](#) or [Forward](#) buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution
Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Dec 2016 Edit Reg		07 Dec 2016 00:00 Edit Adj Rpt	S\$5,496.04 Edit Estimates	S\$5,496.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MUHAMMAD RIDZUAN BIN RAHMAT , ID: 57607372D, Tel: +6597433041								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4779A	Date of Loss:	04/12/2016 19:00 - :59 [7 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8167853676SG	Policy/Cover Note No.:	2100470000						
Vehicle Reg. No. (Insured):	SJF9965G	Policy No. (Claimant):	D-II027591MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (07/07/2019): Report Send Back Alerts - SHC4779A (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4779A (8167853676SG)
 [SJF9965G]
 TP
 SMRT TAXIS PTE LTD
 Dec 4 2016 7:00PM
 [MUHAMMAD RIDZUAN BIN RAHMAT]
 SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	09/12/16 11:50	Accident Statement <small>From: SC - Reg. No: SJF9965G, Claimant: MUHAMMAD RIDZUAN BIN RAHMAT</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/05/17 11:36	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
3	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
4	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
5	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
6	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
7	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
8	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
9	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
10	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
11	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
12	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
13	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
14	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
15	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
16	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
17	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
18	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
19	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
20	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
21	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
22	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
23	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
24	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
25	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
26	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
27	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
28	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
29	24/05/17 11:36	General View							Load JPG	<input checked="" type="checkbox"/>	
30	24/05/17 11:36	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
32	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
33	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
34	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
35	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
36	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
37	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
38	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
39	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
40	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
41	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
42	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
43	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
44	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
45	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
46	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
47	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>
48	24/05/17 11:36	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/12/16 16:08	TP ESTIMATE- MARKED		
2	08/12/16 16:08	TP GIA REPORT		
3	19/04/17 15:11	POLICE INVESTATION RESULT		
4	19/04/17 16:26	EMAIL FROM SMRT		
5	18/05/17 17:16	EMAIL CORRESPONDENCE WITH AIG		
6	18/05/17 17:16	EMAIL TO SMRT THAT WE DENY LIAB		
7	04/07/19 10:17	TPBI settlement		
8	04/07/19 10:17	TPPB settlement		
9	04/07/19 10:17	PIR		
10	04/07/19 10:20	EMAIL FROM SMRT - APPEAL CASE		
11	29/07/19 11:07	WORKSHOP INVOICE		
12	29/07/19 11:07	AUTHORISATION TO ACT FORM		
13	29/07/19 11:07	Release Voucher		
14	29/07/19 11:07	RENTAL MILEAGE		
15	29/07/19 11:07	RENTAL RECEIPT		
16	29/07/19 11:07	LTA SEARCH		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJF9965G (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID CVT (A)
	SHC4779A (TP veh)		
Date of Accident:	04/12/2016		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	19,365.20
Final Repair Cost	:	\$	3,150.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	8 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,150.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 50 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 3,150.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

29 Jul
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG16023411/T1DB3Q2-1
Date: 29/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100470000	
Claimant Vehicle No : SHC4779A	Insured Vehicle No : SJF9965G	
Date of Loss: 04/12/2016	Nature of Claim: TP	Claim No: 8167853676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4779A		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR6589194
Reg. Date:	08/04/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U605767795
Colour:	Maroon	Odometer:	79658 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,949.20	3,616.04	11,333.16	75.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,416.00	1,880.00	2,536.00	57.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	19,365.20	5,496.04	13,869.16	71.62
	+ Car Rental (6.0 x S\$133.75/day) (S\$)	802.50		
	+ Doc/Search Fee (S\$)	5.00		
	Nett Liability (S\$)	6,303.54		
	Global Sum Settlement (S\$)	3,150.00		

INSPECTION

Date of Assignment:	07/12/2016	
Date Inspected:	07/12/2016 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR FRT/LH (DISC 25%)	Bent	894.40 F	*670.80 F
2	1		*MIRROR ASSY ,LH (DISC 25%)	Distorted	1,224.90 F	*918.68 F
3	1		*FENDER FRT/LH (DISC 25%)	Bent	723.40 F	*542.55 F
4	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.92 F
5	1		*WHEEL DISC.FRONT (DISC 25%)	Dented	1,484.20 F	*1,113.15 F
6	1		*BUMPER SUPPORT F/LH (DISC 25%)	Necessary	76.40 F	*57.30 F
7	1		*FENDER LINER FRT/LH (DISC 25%)	Deformed	171.70 F	*128.77 F
8	1		*PROTECTOR ,FRONT FENDER SIDE PANEL LH (DISC 25%)	Deformed	114.50 F	*85.87 F
9	1		*HINGE LOWER LHF ,DOOR	Not Necessary	90.10 F	*- F
10	1		*HINGE UPPER LHF,DOOR	Not Necessary	80.50 F	*- F
11	1		*CHECK ASSY ,FR DOOR	Not Necessary	150.30 F	*- F
12	1		*DOOR REGULATOR SUB-ASSY ,FRT/REAR LH	Not Necessary	224.80 F	*- F
13	1		*MIRROR GLASS LH	Not Necessary	142.50 F	*- F
14	1		*MIRROR LAMP LH	Not Necessary	65.30 F	*- F
15	1		*MOULDING BODY,LH	Not Necessary	673.60 F	*- F
16	1		*QUARTER GLASS FRT/LH	Not Necessary	234.90 F	*- F
17	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
18	1		*SHOCK ABSORBER FRT/LH	Not Necessary	394.20 F	*- F
19	1		*LOWER ARM FRT/LH	Not Necessary	625.90 F	*- F
20	1		*JOINT ASSY ,LWR BALL	Not Necessary	195.60 F	*- F
21	1		*STEERING KNUCKLE LH FRT	Not Necessary	580.80 F	*- F
22	1		*SHOCK ABSORBER FRT/LH	Not Necessary	394.20 F	*- F
23	2		*STABILIZER BAR LINK FRT/RH/LH	Not Necessary	195.00 F	*- F
24	1		*DRIVE SHAFT LH	Not Necessary	1,543.80 F	*- F
25	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
26	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
27	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
28	1		*SUPPORT SUB-ASSY	Not Necessary	1,460.40 F	*- F
29	1		*HEAD LAMP LH	Not Necessary	945.20 F	*- F
30	1		*FENDER LINE PAD ,FR WHEEL LH	Not Necessary	49.30 F	*- F
31	1		*TIE ROD END LH	Not Necessary	159.30 F	*- F
32	1		*SOLAR FILM	Not Necessary	125.00 F	*- F
33	1		*COVER ,OUTER MIRROR ,LH	Repair	107.40 F	*- F
34	1		*PILLAR ,FR BODY LH	Repair	363.10 F	*- F
35	1		*BUMPER FRT	Repair	482.00 F	*- F
36	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F

F=Franchise part.

Total Parts (\$\$) 14,949.20 3,616.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,352.00	600.00
2	SPRAY PAINT	New	2,034.00	950.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
5	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
6	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS	New	120.00	0.00
7	TO REMOVE AND REFIX WING MIRROR	New	120.00	60.00
8	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	60.00
9	TO REMOVE AND REFIX UNDERCARRIAGE	New	250.00	0.00
10	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	80.00
Gross Labour Cost (S\$)			4,416.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >