

Surveyor: Gino Liang

ASSIGNMENT (Office)

From (Person): Tan Kah Leng

of

CTI

Date/Time: 8/7/19 @ 2.21pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SJM 4497L

Insured:

SGH 2855L

at Workshop n/s

Huat Hock Motor

Tel:

9826 3234

of Blk 3012 Bedok North Ave 4 # 01-2054 Bedok Hrd. Park e

Policy No:

Claim No:

3NM19D203169

Sum Insured:

Excess:

Make of Veh:

D.O.A

6/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.43pm @ 8/7/19

Person Contacted:

Mr. Benz

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Notified ✓
	call back tomorrow morning
	SJM 4497L : CS3/CAI12022043/Yqd1 D.O.A: 13/11/2012
	SGH 2855L : CC4/ASM18000153/Wub392 D.O.A: 9/12/2019

ASS. REC. BY:

REF:

CTF

73678

ASSIGNMENT

(2023)

From:

Date:

9/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJM 4497L

at Workshop m/s

Hunt Hock Motor

of

B/K 3012 Bedok North Ave 4 # 01-2054

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$27K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJM4497L

Yr Regn:

03 Jan 2009

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan latia

1.5

c.c

1498

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

85502

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAACU2-0020449

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

09-07-19

Survey held at

w/s

12:30pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/8

COB: 12340

Finalized \$3050 with Boss. (Red: 5023.31' 62%)

RECEIVED 22 AUG 2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

\$ + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.:

30501

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 8 July 2019 2:21 PM
To: Accident@kscgp.com; assignments
Subject: RE: OUR REF: SNM19D203169/TANKL - Notice to conduct pre-repairinspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca
Attachments: 2nd PRS.PDF

Dear LKK,

Please refer to attached workshop details.

Thank you

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Kah Leong
Sent: Monday, 8 July, 2019 2:16 PM
To: 'Accident@kscgp.com' <Accident@kscgp.com>; 'admin' <admin@lbs-auto.com>; assignments <assignments@lkkauto.com>
Subject: RE: OUR REF: SNM19D203169/TANKL - Notice to conduct pre-repairinspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Candice,

We refer to your email of 08.07.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK

Please cancel the below assignment. Sorry for the inconvenience caused.

Aside to LBS,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.chinataiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Kah Leong
Sent: Monday, 8 July, 2019 2:03 PM
To: 'Accident@kscgp.com' <Accident@kscgp.com>; 'admin' <admin@lbs-auto.com>
Subject: RE: OUR REF: SNM19D203169/TANKL - Notice to conduct pre-repair inspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Candice,

We refer to your email of 08.07.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M&A LBS Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LBS,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.chinataiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, 8 July, 2019 12:50 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D203169/TANKL - Notice to conduct pre-repair inspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca

Dear Kah Leong,

Thank you for your swift reply.

We enclose herein the 2nd notice to conduct pre-repair inspection. Our client is not agreeable to appointing your proposed surveyors as a Single Joint Expert.

Thank you.

Regards,

Candice

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Tan Kah Leong [mailto:KahLeong.Tan@sg.cntaiping.com]

To: Accident@kscgp.com

Sent: Mon: 8 Jul 2019 03:40:42 +0000

Subject:

Without Prejudice

Dear Candice,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN TAN

LOW SAIL HUI
SEE CHEE HONG
MOHD FATHILAH BIN OSMAN
XING QUO DIANG
KENNETH FONG
HONG EUNG CHOY
CHUA WEN JI
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized copying, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, 8 July, 2019 11:21 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Accident@kscgp.com
Subject: OUR REF: SNM19D203169/TANKL - Notice to conduct pre-repair inspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca

Dear Kah Leong,

Please conduct PRS for SJM4497L.

Officer in Charge – Kah Leong 63896193 (file with OIC).

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6224 7175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, 8 July, 2019 9:42 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Notice to conduct pre-repair inspection - Your insured vehicle: SGH 2855L / Our ref: SJM4497L/HM/ca

Dear Sirs,

We enclose herein the Notice to conduct pre-repair inspection, for your immediate attention and necessary action.

Thank you.

Regards,

Candice

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Your Ref : SNM19D203169/TANKL

Our Ref : SJM 4497L/HM/ca

Date : 8 July 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

Your Ref : SNM19D203169/TANKL
Our Ref : SJM 4497L/HM/ca
Date : 8 July 2019

Fax : 6538 3708
Tel : 3152 0979
Email : accident@kscgp.com

China Taiping Insurance (Singapore) Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 6 JULY 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	T Thiyagarajan	ST Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Huat Hock Motor Workshop
Blk 3012 Bedok North Avenue 4
#01-2054 Bedok Industrial Park E
Singapore 489978

Contact Person/Tel : Benz Mong (Tel no: 9826 3234)

Yours faithfully,

ca

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2019 13:46
Date Of Accident	06/07/2019 11:40
Exact Location Of Accident	ALONG NEW UPPER CHANGI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM4497L
Insured/Policyholder	
Name Of Registered Owner	NURAINI BINTE ZAINOL
NRIC No	S1127367Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94571023
Alternative Phone No	OTHERS-94571023

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072033441-03
Cover Note Number	03/01/2019 - 02/01/2020

Driver

Name of Driver	NURAINI BINTE ZAINOL
NRIC No	S1127367Z
Date Of Birth	27/09/1955
Occupation	INDOOR
Date Of Driving Pass	21/07/1980
Driving Experience	38 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94571023
Fax Number	
Contact Number	OTHERS-94571023
Email Address	NOEMAIL

Address	BLK 42 CHAI CHEE STREET #03-44
Postcode	461042
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NUR AULA BINTE ZAINOL GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, I WAS TRAVELLING ALONG NEW UPPER CHANGI ROAD. I CAME TO A STOP WHILE WAITING FOR THE VEHICLE IN FRONT OF ME TO PROCEED. SUDDENLY, I HEARD A LOUD BANG AND FELT A JERK I CAME DOWN AND SAW THAT VEHICLE B (SGH2855L), HAS COLLIDED ONTO THE REAR PORTION OF MY VEHICLE. WE TOOK SOME PHOTOS AND EXCHANGED PARTICULARS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH2855L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAVID WEE SOON JIN
NRIC/Passport Number	S8310755C
Contact Number	91737915
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

Location: New Upper Changi Road beside Bedok MRT Taxi Stand(108)

Date/Time: 6.7.19 / 1140am


Veh A: SJM4497L

Veh B: SGH2855L

Dry & Clear

Veh A: 2 people

Veh B: 1 person



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was travelling along New upper Changi Road. I came to a stop while waiting for the vehicle in front of me to proceed.

Suddenly, I heard a loud bang & felt a jerk. I came down & saw that Veh B, SGH2855L, has collided onto the rear portion of my vehicle.

Weh took some photos & exchanged particulars.

Veh B: David Wee Soon Jin
S8310755C
91 73 79 15

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Nuraini Zulfah
Policyholder's Signature

Date & Time:

Nuraini Zulfah
Driver's Signature
(If driver is not the policyholder)

Date & Time:

du

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	7367Z
Vehicle No.:	SJM4497L
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L AT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	HR15038113B
Chassis No.:	JN1BAAC11Z0020449
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,017.00
Original Registration Date:	03 Jan 2009
First Registration Date:	03 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$9,082.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$12,340.00
Total Rebate Amount:	\$12,340.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Jul 2019

OK



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Vehicle No : SJM 4497L	Accident Date : 6.7.19
Mileage :	Make / Model : Nissan Latio
	CHASSIS : JN1BAAC11Z0020449
Date :	Fax No. : 6445 2934

Items				
Rear Bootlid Repair X			\$798.56	X
Rear Bootlid Logo "Latio"	/ MC		\$56.20	/
Rear Bootlid Logo "Nissan"	/ MC		\$45.60	/
Rear Carplate & Casing (set)	/ BT	40(SN)	\$70.00	/
Rear Bootlid Lock Assembly	/ BT	167.9	\$27.90	57.9
Rear Boot Lock Catch X	/ NN		\$50.60	X
Rear Boot Rubber stopper X			\$24.55	X
Rear End Panel	/ MC	442.6	\$498.87	/
Rear End Panel Garnish (Top)	/ RL	53	\$73.10	73.1
Rear End Panel Garnish Clips (1set)	/ MC		\$40.00	20
LH Rear Fender inner trim	/ TN	242.4	\$286.50	/
LH Rear Fender Repair X			\$841.00	X
LH Rear Bumper side retainer	/ RL		\$35.20	/
LH Taillamp	/ GAA	249.3	\$289.54	/
RH Taillamp	/ photos	249.3	\$289.54	/
Rear Bootlid weatherstrip	/ Twi	89.8	\$69.80	59.9
Rear Bumper center Guide X	NN3 @25.00		\$75.00	X
Rear LH Fender inner Panel X	Repair		\$262.10	X
Rear Bumper LH Bracket	/ BT		\$45.90	/
Rear Panel sensor X	NN		\$85.25	X
Rear Parking sensor	/ DM	\$207(SN)	\$280.00	/
Rear Parking sensor Wire harness X	NN		\$120.00	X
Rear Bootlid inner trim	X		\$182.00	X
Rear Bootlid inner Garnish clip (1set)	/ MC		\$40.00	20
Rear Bumper Foam Shock Absorber	/ RL		\$85.60	55
Rear Bootlid hinge (LH) X	NN		\$98.50	X
Rear Bumper	/ TN		\$532	/
	2145	SN: 240		
	10%: 1930.5			



發福摩多車房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Labour to dismantle, replace, cut, weld, knock out dents, straighten parts for repair works & replace parts.	\$1000.00 600 1000
Spray paint to adjacent panels & paint & patching materials.	\$1000.00 800 900
Anti rust on adjacent metal panels	\$200.00 60
Wiring & Bulb replacement & checking	\$100.00 30
Remove & replace reverse sensor & conduct distance safety test	\$120.00 40
Removal of spare tyre, spare tyre board & parts to facilitate repair works	\$60.00 50
Removal & refix/replace rear inner trim to facilitate rear fender repair works	\$120.00 x NN
Waterproofing test	\$100.00 x NN
Estimate Number of days to repair	1680 07 days 5 Days.

Impson repair.

After repair photos.

Impson - 8288 0282

09/7/19.

3850.5

20%: 3050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3073.31

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2019		21 Aug 2019 09:04 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -			
Main Claimant:	NURAINI BINTE ZAINOL, ID: S1127367Z			
Vehicle Reg. No.:	SJM4497L	Date of Loss:	06/07/2019 11:00 - :59 [126 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D203169C02	Policy/Cover Note No.:	DMPCSN30524119033	
Vehicle Reg. No. (Insured):	SGH2855L	Policy No. (Claimant):	5072033441-03	
		Excess:	S\$500.00	
Repairer:	Huat Hock Motor Workshop (HQ) BLK 3012 BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E, 1648 Bedok - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/08/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJM4497L (SNM19D203169C02)**
[SGH2855L]

TP
NURAINI BINTE ZAINOL
Jul 6 2019 11:00AM
[-]
Huat Hock Motor Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 11:37	General View	Load PDF	
2	23/08/19 11:37	Reinspection Photo	Load PDF	

Linked Accident Report Documents

Assessment Reports			View View in Browser	
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/07/19 13:55	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/07/19 13:52	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hock Wah Motor Workshop Pte Ltd (Bedok)	Thumbnail	Print
1	06/07/19 13:52	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012065/GTF3S2
Date: 23/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30524119033
Claimant Vehicle No: SJM4497L Insured Vehicle No: SGH2855L
Date of Loss: 06/07/2019 Nature of Claim: TP Claim No: SNM19D203169C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM4497L Engine No: HR15038113B
Make & Model: NISSAN LATIO, 1.5 (A) Chassis No: JN1BAAC11Z0020449
Reg. Date: 03/01/2009 (Man. Year: 2008) Odometer: 85502 km
Colour: Grey
Engine Capacity: 1498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,373.31	2,170.50	3,202.81	59.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,680.00	1,020.00	37.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,073.31	3,850.50	4,222.81	52.31
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	8,073.31	3,050.00	5,023.31	62.22

INSPECTION

Date of Assignment: 21/08/2019
Date Inspected: 09/07/2019 Inspected At: Huat Hock Motor Workshop (HQ)
INDUSTRIAL PARK E
Singapore 1648
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but
https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=857567&extid=314092&CFID=57955655&C... 1/4

8/23/2019

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2019)
Parts:	144	NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM4497L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	798.56 F	*- FL
2	1		*REAR BOOTLID LOGO LATIO	Necessary	56.20 F	*56.20 FL
3	1		*REAR BOOTLID LOGO NISSAN	Necessary	45.60 F	*45.60 FL
4	1		*REAR BOOTLID LOCK ASSEMBLY	Bent	97.90 F	*97.90 FL
5	1		*REAR BOOT LOCK CATCH	Not Necessary	50.60 F	*- FL
6	1		*REAR BOOT RUBBER STOPPER	Not Necessary	24.55 F	*- FL
7	1		*REAR END PANEL	Buckled	498.87 F	*442.60 FL
8	1		*REAR END PANEL GARNISH (TOP)	Deformed	73.10 F	*73.10 FL
9	1		*SET REAR END PANEL GARNISH CLIPS	Necessary	40.00 F	*20.00 FL
10	1		*LH REAR FENDER INNER TRIM	Torn	286.50 F	*242.40 FL
11	1		*LH REAR FENDER	Repair	841.00 F	*- FL
12	1		*LH REAR BUMPER SIDE RETAINER	Deformed	35.20 F	*35.20 FL
13	1		*LH TAILLAMP	Cracked	289.54 F	*219.30 FL
14	1		*RH TAILLAMP	Cracked	289.54 F	*219.30 FL
15	1		*REAR BOOTLID WEATHERSTRIP	Twisted	69.80 F	*59.90 FL
16	3		*REAR BUMPER CENTER GUIDE	Not Necessary	75.00 F	*- FL
17	1		*REAR LH FENDER INNER PANEL	Repair	262.10 F	*- FL
18	1		*REAR BUMPER LH BRACKET	Bent	45.90 F	*45.90 FL
19	1		*REAR PANEL SENSOR	Not Necessary	85.25 F	*- FL
20	1		*REAR PARKING SENSOR WIRE HARNESS	Not Necessary	120.00 F	*- FL
21	1		*REAR BOOTLID INNER TRIM	Not Necessary	182.00 F	*- FL
22	1		*SET REAR BOOTLID INNER GARNISH CLIP	Necessary	40.00 F	*20.00 FL
23	1		*REAR BUMPER FOAM SHOCK ABSORBER	Deformed	85.60 F	*35.60 FL
24	1		*REAR BOOTLID HINGE (LH)	Not Necessary	98.50 F	*- FL
25	1		*REAR BUMPER	Torn	532.00 F	*532.00 FL
26	1		*SET REAR CARPLATE & CASING	Bent	70.00 FS	*40.00 FS
27	1		*REAR PARKING SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	5,373.31	2,385.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	214.50
Total Parts (\$\$)	5,373.31	2,170.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO DISMANTLE , REPLACE, CUT, WELD, KNOCK OUT DENTS, STRAIGHTEN PARTS FOR REPAIR WORKS & REPLACE PARTS.	New	1,000.00	600.00
2	SPRAY PAINT TO ADJACENT PANELS & PAINT & PATCHING MATERIALS.	New	1,000.00	900.00
3	ANTI RUST ON ADJACENT METAL PANELS.	New	200.00	60.00
4	WIRING & BULB REPLACEMENT & CHECKING.	New	100.00	30.00
5	REMOVE & REPLACE REVERSE SENSOR & CONDUCT DISTANCE SAFETY TEST.	New	120.00	40.00
6	REMOVAL OF SPARE TYRE, SPARE TYRE BOARD & PARTS TO FACILITATE REPAIR WORKS.	New	60.00	50.00
7	REMOVAL & REFIX / REPLACE REAR INNER TRIM TO FACILITATE REAR FENDER REPAIR WORKS.	New	120.00	0.00
8	WATERPROOFING TEST.	New	100.00	0.00
Gross Labour Cost (S\$)			2,700.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >