

ASS. REC. BY:

REF: TM1 / (C3) / TMS 19012067 / KTF3N2

*Kenneth*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

Insured: \_\_\_\_\_

Policy No. MK000641

Claims No. M1905226


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S11D5747E Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius c.c. 1798

Colour M.P. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 3988 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTOKB3F4 703079230

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size: F: 195/55R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 0 mm R/Bal. 0 mm

L/Bal. 0 mm L/Bal. 0 mm

D.O.A. 5/7/19 D.O.I. 8/7/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

S11D 5747E - (S) / FCI 190042492 / Ktd3

ROA - 26/07/2019

SLR 4571E - X

17-1:54pm - sent email to tokiu.

Part by Part \$1717.90 (Red: 24657.30; 93%)

RECEIVED 27 AUG 2019

Date/Time, File Pass to?

: Prell. Report

1) 27/8 Typist

: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trlp: 1

Survey Fee:

Transportation: 250

\_\_\_\_\_ S + RS. \_\_\_\_\_ SI

\_\_\_\_\_ Fares

\_\_\_\_\_ Others

TOTAL

261

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / (L.B.): (\$ 1717.90)

## Denise Tay (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Thursday, 22 August 2019 11:48 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** RE: SHD 5747E / DOA: 5/7/2019 -- AAD1907-067  
**Attachments:** IMG\_0083.JPG; IMG\_0085.JPG; IMG\_0090.JPG

Hi Denise

We submit COR \$ 1,717.90.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



### TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Denise Tay (LKKAuto) [mailto:[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)]  
**Sent:** Thursday, 22 August, 2019 11:12 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** SHD 5747E / DOA: 5/7/2019

Dear Wai Yin,

Can finalise?

Best Regards,

**Denise Tay** | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 9 July 2019 1:54 PM  
**To:** 'Motor Claims'  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - COMFORTDELGRO ENGINEERING PTE LTD, DOA: 5/7/2019, SHD 5747E (TP VEHICLE), SLR 4571E (OI VEHICLE)  
**Attachments:** police report.pdf; SHD 5747E EST.pdf; GIA REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5747E at M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 8/7/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
 Owner ID: 3878K

### Vehicle Details

Vehicle No.: SHD5747E  
 Vehicle to be Exported: Yes  
 Intended Deregistration Date: 05 Jul 2019  
 Vehicle Make: TOYOTA  
 Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)  
 Primary Colour: Red  
 Manufacturing Year: 2018  
 Engine No.: 2ZR2B99716  
 Chassis No.: JTDKB3FU703079230  
 Maximum Power Output: 90.0 kW (120 bhp)  
 Open Market Value: \$26,605.00  
 Original Registration Date: 17 Jan 2019  
 First Registration Date: 17 Jan 2019  
 Transfer Count: 0  
 Actual ARF Paid: \$14,247.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 16 Jan 2027  
 PARF Rebate Amount: \$10,685.00

### Intended COE Rebate Details

COE Expiry Date: 16 Jan 2027  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 8  
 PQP Paid: \$20,838.00  
 COE Rebate Amount: \$16,670.00  
**Total Rebate Amount: \$27,355.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/07/2019 16:34
Date Of Accident	05/07/2019 13:10
Exact Location Of Accident	JURONG GATEWAY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5747E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM,SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	CHUA HAN TECK
NRIC No	S0041748C
Date Of Birth	16/06/1950
Occupation	OUTDOOR
Date Of Driving Pass	04/02/1972
Driving Experience	47 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96546279
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	APT BLK 131 BEDOK NORTH AVENUE 3 #07-106
Postcode	460131
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20190706/2048

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR4571E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH KOK WEE
NRIC/Passport Number	S6903896D
Contact Number	94504434

Page 3 of 15

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SINGAPORE  
POLICE FORCE



T/20190706/2048

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

3 of 3

Report No. T/20190706/2048

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LIM HWEE JIE, SAMUEL	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 06/07/2019 12:13
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOON Contact No.: 65476435	Classification Of Case: SN 061
Authentication Stamp NP168	SIGNATURE

**Trans-cab Auto Services Pte Ltd**

AAD1907-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5747E**

*Not Authored*  
*Resunny B4 paint*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model: 08 JUL 2019  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**SHD 5747E**  
JTDKB3FU703079230  
TOYOTA  
PRIUS  
5.7.19  
**TOKIO MARINE**  
17/1/2019

PART		LIST
1	1 REAR BUMPER	\$ <i>Buc</i> 458.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	\$ <i>R1</i> 318.80 ✓
3	1 REAR BUMPER TOWING COVER	\$ <i>Sn</i> 14.70 X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$ <i>Not in</i> 552.60 ✓
5	1 REAR BUMPER SIDE RETAINER LH	\$ <i>Sn</i> 112.70
6	1 REAR BUMPER SIDE RETAINER RH	\$ <i>Sn</i> 112.70
7	1 REAR TAILGATE	\$ <i>M</i> 1,547.27
8	1 REAR TAILGATE OUTER GARNISH	\$ <i>M</i> 905.10
9	1 COVER, REAR COMBINATION LAMP, RH	\$ <i>Sn</i> 54.70
10	1 COVER, REAR COMBINATION LAMP, RH	\$ <i>Sn</i> 54.70
11	1 GARNISH, BACK DOOR SIDE, LH	\$ <i>Sn</i> 93.60
12	1 GARNISH, BACK DOOR SIDE, RH	\$ <i>Sn</i> 93.60
13	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ <i>Sn</i> 55.40
14	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ <i>Sn</i> 55.40
15	1 BOARD ASSY, BACK DOOR TRIM	\$ <i>Sn</i> 254.40
16	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$ <i>Sn</i> 51.20
17	1 REAR TAILGATE WEATHERSTRIP	\$ <i>Sn</i> 365.20
18	1 REAR END PANEL	\$ <i>M</i> 602.10
19	1 TAILLAMP LOWER RH	\$ <i>Sn</i> 548.40
20	1 TAILLAMP UPPER RH	\$ <i>Sn</i> 557.90
21	1 REAR BUMPER SIDE RH	\$ <i>Sn</i> 232.00
22	1 REAR BUMPER SIDE LH	\$ <i>Sn</i> 232.00
23	1 TAILLAMP LOWER LH	\$ <i>Sn</i> 548.40
24	1 TAILLAMP UPPER LH	\$ <i>Sn</i> 557.90
25	1 REAR FENDER RH	\$ <i>R</i> 817.50
26	1 REAR FENDER LH	\$ <i>M</i> 817.50
27	1 BOARD, BACK DOOR TRIM	\$ <i>Sn</i> 220.70
28	1 PANEL SUB-ASSY, QUARTER, LH	\$ <i>R</i> 836.70
29	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$ <i>M</i> 290.50

X

**Trans-cab Auto Services Pte Ltd**

AAD1907-067

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5747E**

30	1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>12</i>	836.70	X
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	<i>12</i>	290.50	X
<b>TOTAL</b>			<b>\$</b>		<b>12,489.47</b>	
25%			<b>\$</b>		<b>3,122.37</b>	
			<b>\$</b>		<b>9,367.10</b>	

**Special Nett**

1	1SET	PARKING AID	\$	<i>12</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>12</i>	22.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	<i>12</i>	80.00	X
4	1	WINDSCREEN MOULDING	\$	<i>12</i>	100.00	X
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>12</i>	100.00	X
6	1	REAR TAILGATE TOYOTA LOGO	\$	<i>12</i>	47.00	✓
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>12</i>	52.90	✓
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>12</i>	53.50	✓
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>12</i>	80.00	<i>3012</i>
10	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>12</i>	80.00	<i>3012</i>
11	1	REAR BUMPER PROTECTOR	\$	<i>12</i>	100.00	X
12	1	REAR WHEEL RIM	\$	<i>12</i>	1,570.55	X
13	1	REAR WHEEL RIM COVER	\$	<i>12</i>	175.80	X
14	1	SPARE WHEEL RIM	\$	<i>12</i>	1,570.55	X
15	1	SPARE WHEEL RIM COVER	\$	<i>12</i>	175.80	X
<b>TOTAL</b>			<b>\$</b>		<b>4,908.10</b>	

**TOTAL PARTS \$ 14,275.20****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>12</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	<i>2001</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$		170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>2201</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1907-067**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5747E**

To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i>	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>50</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>150</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>12,100.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>26,375.20</b>	

**(PART-BY-PART) Repair Days**

**15 Days**

LKK Auto Consultant is hence notify the Repairer of the following:

- To resurvey before start spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company.

Accepted by: \_\_\_\_\_  
 Date: \_\_\_\_\_  
 Signature: \_\_\_\_\_

*2 days*

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI19012067/KTF3N2

**Date:** 28/08/2019

#### REFERENCE

<b>Handling Insurer:</b>	Tokio Marine Insurance Singapore Ltd	<b>Policy No:</b>	MK000641
<b>Claimant Vehicle No :</b>	SHD5747E	<b>Insured Vehicle No :</b>	SLR4571E
<b>Date of Loss:</b>	05/07/2019	<b>Nature of Claim:</b>	TP
			<b>Claim No:</b> M1905226

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SHD5747E	<b>Engine No:</b>	2ZR2B99716
<b>Make &amp; Model:</b>	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	<b>Chassis No:</b>	JTDKB3FU703079230
<b>Reg. Date:</b>	17/01/2019 (Man. Year: 2018)	<b>Odometer:</b>	39888 km
<b>Colour:</b>	Metallic White/Red		
<b>Engine Capacity:</b>	1798 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	195/65R15	<b>Rear Tyre Size:</b>	195/65R15
<b>Front Left Side:</b>	Yokohama 8 mm	<b>Rear Left Side:</b>	Yokohama 8 mm
<b>Front Right Side:</b>	Yokohama 8 mm	<b>Rear Right Side:</b>	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,275.20	1,232.90	13,042.30	91.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,100.00	485.00	11,615.00	95.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<hr/>				
<b>Gross Total (S\$)</b>	<b>26,375.20</b>	<b>1,717.90</b>	<b>24,657.30</b>	<b>93.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,846.26</b>	<b>120.25</b>	<b>1,726.01</b>	<b>93.49</b>
<hr/>				
<b>Nett Amount (S\$)</b>	<b>28,221.46</b>	<b>1,838.15</b>	<b>26,383.31</b>	<b>93.49</b>

#### INSPECTION

<b>Date of Assignment:</b>	12/07/2019	<b>Inspected At:</b>	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
<b>Date Inspected:</b>	08/07/2019		

**Estimated Period of Repair:** 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD5747E)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented/Cut	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Repair	905.10 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*- FL
13	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	55.40 FL	*- FL
14	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	55.40 FL	*- FL
15	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
16	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*- FL
17	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
18	1		*REAR END PANEL	Repair	602.10 FL	*- FL
19	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
20	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
21	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
22	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
23	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
24	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
25	1		*REAR FENDER RH	Repair	817.50 FL	*- FL
26	1		*REAR FENDER LH	Repair	817.50 FL	*- FL
27	1		*BOARD,BACK DOOR TRIM	Serviceable	220.70 FL	*- FL
28	1		*PANEL SUB-ASSY,QUARTER,LH	Repair	836.70 FL	*- FL
29	1		*PANEL,QUARTER WHEEL HOUSE,OUTER LH	Repair	290.50 FL	*- FL
30	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	836.70 FL	*- FL
31	1		*PANEL,QUARTER WHEEL HOUSE,OUTER RH	Repair	290.50 FL	*- FL
32	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
34	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
36	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
37	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*47.00 FS
38	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
39	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
41	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
42	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS
43	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
44	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
45	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
46	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>17,397.57</b>	<b>1,565.40</b>
- List Item Discount on L Items 25.00/25.00% (\$)	3,122.37	332.50
<b>Total Parts (\$)</b>	<b>14,275.20</b>	<b>1,232.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
3	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
5	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
12	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
14	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,100.00</b>	<b>485.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >