

TOTAL

INC 4/5

Income: Follow-Through Survey

Date : 03/09/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1059369-002	SMRT TAXIS PTE LTD	SHB 956L	SMH 3861R	30/06/2019
2	MT/1059602-002	CITYCAB PTE LTD	SHC 977X	SJU 2825U	24/08/2019

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	30/06/2019 10:29
Vehicle No. (For Motor)	SMH3861R	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5107358757		COVE RENTALS PTE LTD	201626878M	GPC	Third Party	SMH3861R	SMH3861R	31/01/2019	26/10/2019

SHB 956L

$$\text{Depreciation per month} = \$117,754.77 \div 96 \\ = \$1226.61$$

$$\text{Balance @ 30/6/19} = 32 \text{ mths} \times \$1226.61 \\ = \$39,251.$$

$$\begin{aligned} \text{Book Value} &= \$39,251 + 70\% \text{ ARF} \\ &= \$39,251 + \$5,857.60 \\ &= \$45,108.60 \end{aligned}$$

$$\begin{aligned} \text{Repair Margin} &= \$45,108.60 - \$24,730.00 \\ &= \underline{\underline{\$20,378.60}} \end{aligned}$$

$$\text{Repair Limit} = \underline{\underline{\$19K.}}$$

Shiau Chan (LKKAuto)

From: Naz (LKKAuto)
Sent: Friday, 12 July 2019 11:21 AM
To: Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/AR & SC/Taxis); Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/AR & SC/Buses); Shiau Chan (LKKAuto); SUR
Subject: Re: SHB 956L request for purchase value (reminder)

Dear Mr Foo,

The repair limit is \$19,000 based on my calculations. Please update if you will be able to repair this taxi within the limit, otherwise, we will proceed with total loss.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis) <TuckFoo@smrt.com.sg>
Sent: Friday, 12 July 2019 10:36 AM
To: Naz (LKKAuto)
Cc: Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/AR & SC/Taxis); Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/AR & SC/Buses)
Subject: RE: SHB 956L request for purchase value (reminder)

Hi Naz ,

Please let us know your calculation soon as possible.

Thanks ,
Tuck Foo

From: Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis)

Sent: 10 July 2019 13:21

To: 'naz@lkkauto.com'

Cc: Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis); Keith Ang Bang Kien (TPHS/Ops&Maint/FOps/SA/QP); Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Peh Eng Hock (Auto Svcs/ARC/AR & SC/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/AR & SC/Buses)

Subject: SHB 956L request for purchase value

Hi Naz ,

As per requested.

The purchase value for this vehicle is **\$117,754.77.**

Please let us know the repair limit for this vehicle taxi.

Thanks ,
Tuck Foo

RE: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117 - SHB956L (TS)

Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>

Wed 7/8/2019 2:23 PM

To: Lynn Gan Peh Ling (TPHS/Ops&Maint/FOps/Ops) <LynnGanPehLingYanPeiling@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>; Chloe Chin Kua Fong (TPHS/Ops&Maint/CM/C&B) <Kuaifong.Chin@smrt.com.sg>
Cc: TPHS_Ops&Maint_CM <TPHS_Ops-Maint_CM@smrtcorp.onmicrosoft.com>; Damian Chan Wee Siong (TPHS/Ops&Maint/FOps) <DamianChan@smrt.com.sg>; Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops) <samkwok@smrt.com.sg>; Chia Teck Guan (TPHS/Ops&Maint/FOps/Ops) <ChiaTeckGuan@smrt.com.sg>; Yip Shung Chi, Darren (TPHS/Ops&Maint/FOps/Ops) <YipShungChiDarren@smrt.com.sg>; Yip Siu Chung (TPHS/Ops&Maint/FOps/Ops) <yipsiuchun@smrt.com.sg>; Siew Wei Ther (TPHS/Ops&Maint/TS/SA/QP) <SiewWeiTher@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/ARC/ARC/Taxis) <limkachiew@smrtlan.com.sg>; Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis) <ANGBANGKIEN@smrtlan.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>; Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis) <PehEngHock@smrt.com.sg>; Gerald Tan Chwee Hock (Auto Svcs/ARC/ARC/Buses) <tanchweehock@smrt.com.sg>
Hi all,

Job card closed.

Order Edit Goto Extras Environment System Help

Change Road - Accident Repair Maintenance Order 24102293: Central Head

Complete (business)

Order RAJC 24102293 TAX/06/19/2117

Sys.Status TECO NMAT PRC SETC MBLR

HeaderData Operations Components Costs Objects Additional Data Location Planning Control Enhancement

Person responsible

PlannerGrp WL / WBRC BRC Wkshp WL

Mn.wk.ctr XWLSA1 / WBRC Taxi SA 1

Notifctn 1001819791

Costs 0.00 SGD

PMActType AIN WORK DONE BY A.

SystCond.

Dates

Bsc start 05.07.2019 14:39 Priority

Basic fin. 05.07.2019 14:39 Revision

Reference object

Func. Loc. SHB956L SHB956L,07-FEB-14

Malfrctn data Damage Notif. dates

Malfr.start 05.07.2019 14:39:32 Breakdown

MalfrEnd 07.08.2019 14:03:00 Breakdown dur. 0.00 H

First operation

Operation SCRAP VEHICLE APPROVE ON 07-08-2019/14:03 CcKey Calculate number of ca.

WkCtr/Pnt XWLSA1 / WBRC Ctrl key PM01 Acty Type PRT

Work durtn 0.0 H Number 0 Opntr dur. 0.0 H Comp.

Person. no 0

Notification is completed -> can only be displayed

SAP

Thanks,
Tuck Foo

From: Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops)

Sent: 07 August 2019 14:03

To: Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Lim Kha Chiew (Auto Svcs/ARC/AR & SC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/AR & SC/Taxis); Chloe Chin Kua Fong (TPHS/Ops&Maint/CM/C&B)

Cc: TPHS_Ops&Maint_CM; Damian Chan Wee Siong (TPHS/Ops&Maint/FOps); Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops); Chia Teck Guan (TPHS/Ops&Maint/FOps/Ops); Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops); Yip Shung Chi, Darren (TPHS/Ops&Maint/FOps/Ops); Yip Siu Chung (TPHS/Ops&Maint/FOps/Ops); Siew Wei Ther (TPHS/Ops&Maint/TS/SA/QP)

Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117 - SHB956L (TS)

Hi All,

"BER" flag has been raised for SHB956L

Please close job card accordingly

Thank you.

Regards,
Lynn

From: Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops)

Sent: 07 August, 2019 1:57 PM

To: Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/AR & SC/Taxis); Yip Shung Chi, Darren (TPHS/Ops&Maint/FOps/Ops)

Cc: Koo Yew Chung (Auto Svcs/ARC/AR & SC); Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Chong Fei Yuan (Auto Svcs/Claims & IA/Claims & IA); Balqish Binte Abdul Halil (Auto Svcs/Claims & IA/Claims & IA/Buses); Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses); Karenina Lim Swee Kim (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses/Claims); Low Thian Seng (Auto Svcs/Claims & IA/Claims & IA/Buses); Magnaye Ana Margie Marasigan (Auto Svcs/Claims & IA/Claims & IA/Taxis); Selena Tan Lee See (Auto Svcs/Claims & IA/Claims & IA/Taxis); Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis); Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses); Wong Kok Wah (Auto Svcs/Claims & IA/Claims & IA); Claudia Lynn Liu Shujing (Auto Svcs/Taxi Maint/Taxi WS/Admin); Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis); Felix Ng Kia Heong (TPHS/Ops&Maint); Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis); Goh Kok Khoo (Auto Svcs/ARC/AR & SC/Buses); Gan Kwai Leng (Auto Svcs/Claims & IA/Claims & IA/Taxis); Lim Ming Huey (Fin/FBP(NonRail)/Roads/Taxis/Taxis); Eileen Bay Yee Ling (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses); Kee Sook Meng (Auto Svcs/ARC/AR & SC/Taxis); Ong Hua Yen (Auto Svcs/Claims & IA/Claims & IA/Buses); Ashlene Lee Bee Gan (Auto Svcs/Claims & IA/Claims & IA/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/AR & SC/Buses); Shaun Lee Shyue Lern (TPHS/Taxis); Seah June Woei (Auto Svcs/Taxi Maint); Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis); Lim Kha Chiew (Auto Svcs/ARC/AR & SC/Taxis); Eldon Lim Sing Yeow (TPHS/Ops&Maint/TS); TPHS_Ops&Maint_FOps; TPHS_Ops&Maint_EF; TPHS_Ops&Maint_CM

Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117 - SHB956L (TS)

Hi Kim Ming/Tuck Foo/Keith,

Please **Do Not Repair SHB956L**, as recommended that this taxi is "Beyond Economical Repair".

Hi Darren,

Please assist to notify STK and arrange a replacement vehicle.

Thank you.

Best Regards,
Lynn

From: Damian Chan Wee Siong (TPHS/Ops&Maint/FOps)

Sent: 07 August, 2019 12:11 PM

To: Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops)

Cc: Chloe Chin Kua Fong (TPHS/Ops&Maint/CM/C&B); Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops); Timothy Yap Thian Woon (TPHS/Ops&Maint/FOps/SA/QP); Chia Teck Guan (TPHS/Ops&Maint/FOps/Ops)

Subject: RE: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117 - SHB956L (TS)

I'll reject due to BER.

From: Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops)

Sent: 07 August 2019 12:03

To: Damian Chan Wee Siong (TPHS/Ops&Maint/FOps)

Cc: Chloe Chin Kua Fong (TPHS/Ops&Maint/CM/C&B); Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops); Timothy Yap Thian Woon (TPHS/Ops&Maint/FOps/SA/QP); Chia Teck Guan (TPHS/Ops&Maint/FOps/Ops)

Subject: FW: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117 - SHB956L (TS)

Hi Damian,

The total repair cost with additional supplementary parts quoted by the surveyor is \$43,500.00 (as shown in system) for SHB956L (fault code TP). Surveyor has also calculated and informed that the repair limit is \$19,000.00. Please refer to attachment for your reference.

As shown in the financial model, it recommends us to repair **SHB956L** only from the 7th years onwards based on the estimated remaining repair cost of **\$24,500.00 (Repair Cost \$43,500.00 – Repair Limit \$19,000.00)**.

For your **Approval / Rejection** if we should proceed with the repair in **VACS** please.

ESTIMATION - ARC HEAD APPROVAL FORM

EST-7588-ID: [icon]

Company Type

SMRT Taxi Pte Ltd

Total Spare Part Cost: \$73,084.92

Total Labour Cost: \$3,425.00

Total Sublet Cost: \$4,985.00

Total Other Cost: \$4,284.00

Total Cost: \$85,879.92

Lump Sum Repair Option: [icon]

Lump Sum Repair: \$85,879.92

Number of Repair Days: 14.0

Estimator Remarks:

Total number of repair days = 14 days.
SLIP = 4 days.
Based on TP surveyor calculation the vehicle have left \$19,000.00 for the repair.

\$38,302.26

\$2,500.00

\$2,000.00

\$1,620.00

\$42,462.26

[icon]

\$43,500.00

First Number of Repair Days

14.00

Latest Number of Repair Days

10.00

Surveyor Approved Amount

\$43,500.00

Surveyor Remarks:

LUMP SUM REPAIR
10 DAYS
CHECK ITEM SH45756

Input Sheet

Input in highlighter green

Current Date	7-Aug-19
Taxi No	SHB956L
Model	PRIUS
Date registered	7-Feb-14
Age	5 yrs 5 mths

Total Costs	\$24,500
-------------	----------

Cash flows from scrap	
Scrap value of taxi	\$900
COE rebate (LTA website)	\$17,829
PARF rebate (LTA website)	\$5,857
Original COE (SAP cost)	\$58,590
End of life PARF (SAP cost)	\$5,020

Hired out rate	90.00%	Input expected hire out rate going forward
----------------	--------	--

Rental Rate Yr 1	\$	-
Rental Rate Yr 2	\$	-
Rental Rate Yr 3	\$	-
Rental Rate Yr 4	\$	-
Rental Rate Yr 5	\$	112.50
Rental Rate Yr 6	\$	112.50
Rental Rate Yr 7	\$	112.50
Rental Rate Yr 8	\$	112.50

Life expectancy of taxi				
Results	5 years	6 years	7 years	7 years 8 months
PV repair	NA	\$10,822	\$30,127	\$42,441
PV scrap	NA	\$24,486	\$24,486	\$24,486
DECISION	NA	SCRAP	REPAIR	REPAIR

Accident repair cost	\$24,500	\$0	Auto's Profit
Auto's loss/profit on maintenance	\$0		
Price difference (PQP vs COE)	\$0		
Total cost (less Auto's profit)	\$24,500		

Best Regards,
Lynn

From: _vacs-admin

Sent: 06 August, 2019 4:57 PM

To: Chia Teck Guan (TPHS/Ops&Maint/FOps/Ops); Chloe Chin Kuai Fong (TPHS/Ops&Maint/CM/C&B); Lynn Gan Peh Ling (TPHS/Ops/Fleet Ops/Ops); Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops); Timothy Yap Thian Woon (TPHS/Ops&Maint/FOps/SA/QP)

Subject: VACS : Request Estimation Approval for Case Reference Number: TAX/06/19/2117

Hi,

This is to request you to approve the Estimation provided for the case mentioned below:

Case Reference Number: TAX/06/19/2117

Vehicle Registration Number: SHB956L

Make: TOYOTA

Model: PRIUS

Vehicle Registration Date: 07/02/2014

Fault Code: TP

Accident Date and Time: 30/06/2019 05:50 AM

Accident Report Date and Time: 01/07/2019 11:16 AM

Type of Accident: Head To Side

Total Spare Cost: \$73,084.93

Total Labour Cost: \$3,416.00

Total Spray Cost: \$4,986.00

Total Other Cost: \$4,384.00

Total Repair Cost: \$85,870.93

Kindly login to VACS for more details and to approve/reject the estimate.

Thanks
SMRT Auto Services

DISCLAIMER

This electronic mail message and any files transmitted with it are intended exclusively for the individual or entity to which it is addressed. The message, together with any attachment, may contain confidential and/or privileged information. Any unauthorized review, use, printing, saving, copying, disclosure or distribution is strictly prohibited. If you, the reader is not the intended recipient, please do not disclose, disseminate, circulate, copy or use any of the information contained in this e-mail. Please notify us immediately and delete the e-mail and destroy any printed copy.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 01/07/2019 11:01
Date Of Accident 30/06/2019 05:50
Exact Location Of Accident EU TONG SEN STREET/ UPPER CROSS STREET
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB956L
Insured/Policyholder
Name Of Registered Owner SMRT TAXIS PTE LTD
Co Reg No 198905369K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-800000000
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number D-19093197MFSH
Cover Note Number
Driver
Name of Driver LEE XIAO LOONG TERRENCE
NRIC No S7619491B
Date Of Birth 01/07/1976
Occupation OUTDOOR
Date Of Driving Pass 11/03/1996
Driving Experience 23 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-80000000
Fax Number
Contact Number
EMail Address NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ORCHARD NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7359999 - FAX NO: 67331934
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190701/2005

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMH3861R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver UNKNOWN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LEE XIAO LOONG TERRENCE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB956L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMH3861R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMH3861R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan Pg. 1

Date: 30 Jun 19

Time: 5.48 am

Car A: Taxi

Case B: Other party

7.

Yue Hwa
Bldg

OG Taxi
stand

People's
Park
Centre

En Tong Sen Sreey

Divider

New Bridge Road

Divider

Upper → Cross Streets

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190701/2005

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

1 of 3

Report No. T/20190701/2005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/07/2019 02:37		Vide Report No.:		Station Diary No.: 8	
Informant's Particulars					
Name of Informant: LEE XIAO LOONG TERRENCE			Address: 73 TAMPINES AVENUE 1 #01-02 SINGAPORE 529780		
ID Type / ID No.: NRIC NO / S7619491B			Contact No.: Home/Office: Mobile: 88157671		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 43	Date of Birth: 01/07/1976	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/06/2019 05:50	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 EU TONG SEN STREET UPPER CROSS STREET Junction of Eu Tong Sen Street and Upper Cross Street				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB956L	Car	TOYOTA	Prius	Maroon	Seriously Damaged	0
SMH3861R	Car	VOLKSWAGO N	Golf	White	Seriously Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190701/2005

Police Station Of Origin;
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

2 of 3

Report No. T/20190701/2005

CONTINUATION OF REPORT

Driver			
Name	LEE XIAO LOONG TERRENCE	ID No.	S7619491B
Related Vehicle	SHB956L (Car)	Contact No.	88157671
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	30/06/2019	Date Discharge	30/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Goh Hao Xun	ID No.	S9222118J
Related Vehicle	NIL	Contact No.	92333240
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/06/2019 at about 0550hrs, I was driving my taxi (SHB956L) in the center lane along Eu Tong Sen Street towards Victoria street. The traffic junction at Eu Tong Sen Street and Upper Cross street was green light as such I continued to drive when suddenly I felt an impact from the front right side of my taxi. I immediately stepped on the brake and my taxi was pushed onto the pavement which caused my taxi to hit against the wall. My front and front right side airbag was deployed as well. Paramedic made a check on me and I was then brought to Singapore General hospital.

I did check that the road was clear before I drive however the other vehicle (SMH 3861R) had came from Victoria Street and had turned at a fast speed which caused the accident.

The other vehicle had came from Victoria Street direction and had turned right from Eu Tong Sen Street towards Upper Cross street and subsequently hit onto my taxi. I am unsure how much is the cost of repair for my taxi and his car. The front right part of my taxi and the other car is badly damaged. My car was pushed onto the pave and had hit onto the wall which had made some damages to the government property. I was conveyed and I was in a state of shock. I am could not remember what happened at the scene and I was given 3 days of medical leave. I am feeling pain on the left side of my body and have difficulty moving my left side upper body. I have bruises on my right pinky finger, right elbow and right knee.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999



T/20190701/2005

3 of 3

Report No. T/20190701/2005

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
Sgt 3 THONG RAYMOND

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
01/07/2019 02:37

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt MA JUNXIANG

Classification Of Case:

Contact No: 65476251 Authentication Stamp NP158 SIGNATURE	SN 172
---	---------------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB956L
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5935612
Chassis No.:	JTDKN36U005720679
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	07 Feb 2014
First Registration Date:	07 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Feb 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	06 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$58,590.00
COE Rebate Amount:	\$18,873.00
Total Rebate Amount:	\$24,730.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Jul 2019

OK

Case Details

Case Reference Number : TAX/06/19/2117

Type of Repair : Accident Repair

Vehicle Registration Number : SHB956L

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7588-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income

Insurance Co-operative Ltd

Accident Date and Time : 29/06/2019 09:50 PM

Vehicle Age(In Months) : 64

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation					Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.1	1	13.60	13.60	25.00	10.20	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.2	1	13.60	13.60	25.00	10.20	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.3	1	13.60	13.60	25.00	10.20	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO NOZZLE)	1	13.60	13.60	25.00	10.20	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM MOTOR TO JOINT)	1	17.60	17.60	25.00	13.20	Replace	0	0	Check	✓
One Time Key In	Main			TUBE & ACCESSORY	1	631.90	631.90	25.00	473.92	Replace	0	0	Check	✓
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	386.90	386.90	25.00	290.17	Replace	0	0	Check	✓
One Time Key In	Main			A/C CONDENSER	1	1,181.90	1,181.90	25.00	886.43	Replace	0	0	Check	✓
One Time Key In	Main			HOSE SUB-ASSY, SUCTION	1	405.40	405.40	25.00	304.05	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR ASSY, UPPER	1	679.60	679.60	25.00	509.70	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, INVERTER NO.1	1	80.00	80.00	25.00	60.00	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, INVERTER COOLING NO.5	1	125.30	125.30	25.00	93.97	Replace	0	0	Check	✓
One Time Key In	Main			HOSE, INVERTER COOLING, NO.3	1	57.30	57.30	25.00	42.97	Replace	0	0	Check	✓
One Time Key In	Main			BRACKET SUB ASSY, HV WATER PUMP	1	102.60	102.60	25.00	76.95	Replace	0	0	Check	✓
One Time Key In	Main			PUMP ASSY, WATER	1	454.00	454.00	25.00	340.50	Replace	0	0	Check	✓

Total Spare Part Cost 67,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INVERTER BRACKET TRAY	1	251.60	251.60	25.00	188.70	Replace	0	0	Check	▼
One Time Key In	Main			BRACKET, INVERTER, NO.1	1	31.40	31.40	25.00	23.55	Replace	0	0	Check	▼
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	▼
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	▼ / NRC
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.5	Replace	▼ / DEF
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	▼ / NRC
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	15.20	15.20	10.00	13.68	Replace	1	13.68	Replace	▼ / NRC
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	▼
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check	▼
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	▼
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check	▼
One Time Key In	Main			FENDER APRON SUB FRT/LH	1	637.80	637.80	25.00	478.35	Replace	0	0	Check	▼
One Time Key In	Main			FENDER APRON FRT/LH	1	140.80	140.80	25.00	105.60	Replace	0	0	Check	▼
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace	▼ / R/L
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	▼ / NRC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	▼ / B1
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	▼ / B1
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	1	59.10	Replace	▼ / DEF
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	1	373.8	Replace	▼ / DEF
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	1	187.8	Replace	▼ / B1
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	1	187.8	Replace	▼ / B1
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	1	62.63	Replace	▼ / DEF
One Time Key In	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Check	▼
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	▼ / DEF

Total Spare Part Cost 67,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dia(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NUMBER PLATE FRAME	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	/DEF
One Time Key In	Main			NUMBER PLATE	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	/DEF
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	/DEF
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	/DEF
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	/DEF
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	25.00	181.50	Replace	0	0	Check	
One Time Key In	Main			THERMISTOR ASSY	1	107.00	107.00	10.00	96.30	Replace	0	0	Check	
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	1	265.68	Replace	/MLJ
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Check	
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace	/see
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	58.20	58.20	25.00	43.65	Replace	1	43.65	Replace	/BT
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	1	43.65	Replace	/BT
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	1	19.50	Replace	/BT
Standard	Main	ENGINE	6506145	HOSE, INVERTER COOLING NO.6	1	37.40	37.40	10.00	33.66	Replace	0	0	Check	
One Time Key In	Main			FAN SHROUD TOP	1	99.60	99.60	25.00	74.70	Replace	0	0	Check	
One Time Key In	Main			FAN BLADE	1	158.60	158.60	25.00	118.95	Replace	0	0	Check	
One Time Key In	Main			FAN BLADE NO 2	1	204.20	204.20	25.00	153.15	Replace	0	0	Check	
One Time Key In	Main			FAN MOTOR NO 1	1	538.30	538.30	25.00	403.72	Replace	0	0	Check	
One Time Key In	Main			FAN MOTOR NO 2	1	538.30	538.30	25.00	403.72	Replace	0	0	Check	
One Time Key In	Main			INLET ASSY, AIR	1	232.50	232.50	25.00	174.38	Replace	0	0	Check	
One Time Key In	Main			AIR CLEANER ASSY	1	929.90	929.90	25.00	697.42	Replace	0	0	Check	
One Time Key In	Main			WIRE, ENGINE ROOM	1	5,567.10	5,567.10	10.00	5,010.39	Replace	0	0	Check	
One Time Key In	Main			ENGINE MOUNTING BRACKET, FRONT	1	87.10	87.10	25.00	65.32	Replace	0	0	Check	
One Time Key In	Main			ENGINE MOUNTING FRT	1	198.00	198.00	25.00	148.50	Replace	0	0	Check	

Total Spare Part Cost 67,117.66

Surveyor Total 24,892.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SHOCK ABSORBER FRT/RH	1	394.20	394.20	25.00	295.65	Replace	0	0	Check	✓
One Time Key In	Main			SHOCK ABSORBER MOUNTNG FRT, RH/LH	1	193.80	193.80	25.00	145.35	Replace	0	0	Check	✓
One Time Key In	Main			SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	34.00	25.00	25.50	Replace	0	0	Check	✓
One Time Key In	Main			STABILIZER BAR LINK FRT/RH/LH	1	195.00	195.00	25.00	146.25	Replace	0	0	Check	✓
One Time Key In	Main			SIDE CHASSIC FRT/RH	1	173.50	173.50	25.00	130.13	Replace	0	0	Check	✓
One Time Key In	Main			SIDE CHASSIC BRACE FRT/RH	1	103.80	103.80	25.00	77.85	Replace	0	0	Check	✓
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace	✓ MIS
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✓ /DRF
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓ /NEC
One Time Key In	Main			FENDER SEAL TO COWL SIDE RH	1	15.20	15.20	25.00	11.40	Replace	1	11.40	Replace	✓ /NEC
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Check	✓
One Time Key In	Main			FENDER PROTECTOR FRT/RH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	✓
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	✓
One Time Key In	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check	✓
One Time Key In	Main			FENDER APRON SUB FRT/RH	1	637.80	637.80	25.00	478.35	Replace	0	0	Check	✓
One Time Key In	Main			FENDER APRON FRT/RH	1	168.10	168.10	25.00	126.07	Replace	0	0	Check	✓
One Time Key In	Main			WHEEL DISC, FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	1,113.15	Replace	✓ /BT
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ XJVL
One Time Key In	Main			QUARTER GLASS FRT/RH	1	234.90	234.90	25.00	176.18	Replace	1	176.11	Replace	✓ /NEC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ /NEC
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	505.20	Replace	✓ /NEC BT
One Time Key In	Main			SILL MEMBER OUTER RH	1	519.80	519.80	25.00	389.85	Replace	0	0	Check	✓
One Time Key In	Main			PILLAR, FR BODY	1	363.10	363.10	25.00	272.33	Replace	0	0	Check	✓
One Time Key In	Main			REINFORCEMENT SUB ASSY, FRONT PILLAR LOWER RH	1	453.70	453.70	25.00	340.27	Replace	0	0	Check	✓

Total Spare Part Cost 67,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PILLAR SUB-ASSY, FRONT BODY, INNER RH	1	363.10	363.10	25.00	272.33	Replace	0	0	Check	*
One Time Key In	Main			PILLAR, CTR BODY	1	307.70	307.70	25.00	230.77	Replace	0	0	Check	*
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace	* DEF
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	* IN FCL
One Time Key In	Main			DOOR HINGE LOWER FRT/RH	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	*
One Time Key In	Main			DOOR HINGE UPPER FRT/RH	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	*
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check	*
One Time Key In	Main			RUN CHANNEL RHF, DOOR	1	116.90	116.90	25.00	87.68	Replace	0	0	Check	*
One Time Key In	Main			FRAME SUB-ASSY, FRONT DOOR, REAR LOWER RH	1	85.30	85.30	25.00	63.97	Replace	0	0	Check	*
One Time Key In	Main			TAPE OUT WIN FRAME RHF, DOOR	1	45.60	45.60	25.00	34.20	Replace	0	0	Check	*
One Time Key In	Main			MOULDING, FR DOOR WINDOW RH	1	53.70	53.70	25.00	40.28	Replace	1	40.28	Replace	* NEL
One Time Key In	Main			TAPE OUT WIN FRAME RHF, DOOR	1	45.60	45.60	25.00	34.20	Replace	0	0	Check	*
One Time Key In	Main			DOOR INNER HANDLE FRT/RH	1	84.70	84.70	25.00	63.53	Replace	0	0	Check	*
One Time Key In	Main			DOOR OUTER HANDLE FRT/RH	1	370.80	370.80	25.00	278.10	Replace	0	0	Not Give	*
One Time Key In	Main			COVER, FRONT DOOR OUTSIDE HANDLE	1	14.10	14.10	25.00	10.57	Replace	0	0	Not Give	*
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0	Not Give	*
One Time Key In	Main			WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	1	277.80	277.80	25.00	208.35	Replace	1	208.30	Replace	* NEL
One Time Key In	Main			DOOR WEATHER STRIP FRT/RH	1	171.20	171.20	25.00	128.40	Replace	1	128.40	Replace	* NEL
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.32	Replace	1	980.30	Replace	* BR
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace	* CRK
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	715.80	Replace	* BR
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	* NEL
One Time Key In	Main			DASH BOARD	1	906.10	906.10	25.00	679.58	Replace	0	0	Check	*
One Time Key In	Main			SENSOR, AIR BAG, FRT/RH/LH	2	273.30	546.60	10.00	491.94	Replace	2	491.90	Replace	* NEL

Total Spare Part Cost 67,117.66

Surveyor Total 24,892.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			AIR BAG ASSY, INSTR DRIVER	1	1,555.80	1,555.80	10.00	1,400.22	Replace	1	1,400.	Replace	NKE
One Time Key In	Main			AIR BAG ASSY, INSTR/PASSENGER	1	3,177.00	3,177.00	10.00	2,859.30	Replace	1	2,859.	Replace	
One Time Key In	Main			AIR BAG COMPUTER	1	815.20	815.20	10.00	733.68	Replace	1	733.6	Replace	
One Time Key In	Main			AIR BAG SPIRAL CABLE	1	953.70	953.70	10.00	858.33	Replace	1	858.3	Replace	
One Time Key In	Main			AIR BAG STEERING, DRIVER	1	2,360.40	2,360.40	10.00	2,124.36	Replace	1	2,124.	Replace	
One Time Key In	Main			WIRE ASSY, AIR BAG	1	23.60	23.60	10.00	21.24	Replace	1	21.24	Replace	
One Time Key In	Main			SEAT BELT FRT/LH	1	822.60	822.60	25.00	616.95	Replace	0	0	Check	
One Time Key In	Main			SEAT BELT FRT/RH	1	822.60	822.60	25.00	616.95	Replace	0	0	Check	
One Time Key In	Main			AIR BAG ASSY, RH SIDE	1	1,227.90	1,227.90	10.00	1,105.11	Replace	1	1,105.	Replace	NKE
One Time Key In	Main			SENSOR, SIDE AIR BAG RH/LH	2	556.80	1,113.60	10.00	1,002.24	Replace	2	1,002.	Replace	
One Time Key In	Main			ROOF LINING ASSY,	1	1,877.60	1,877.60	25.00	1,408.20	Replace	0	0	Check	
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	460.6	Replace	SUR
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	
One Time Key In	Main			EMBLEM FRONT	1	66.50	66.50	25.00	64.88	Replace	1	64.88	Replace	NKE
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	1	26.63	Replace	BT
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check	
One Time Key In	Main			GRILLE RADIATOR	1	310.60	310.60	25.00	232.95	Replace	1	232.9	Replace	CRK
One Time Key In	Main			GRILLE RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check	
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	1	104.7	Replace	DEF
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	1	95.78	Replace	
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	1	336.2	Replace	
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	561.0	Replace	

Total Spare Part Cost 67,117.66
Lump Sum Discount (%) 0.00

Surveyor Total 24,692.34
Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HOOD PANEL INSULATOR	1	390.50	390.50	25.00	292.88	Replace	0	0	Check	✓
One Time Key In	Main			HOOD HINGE LH	1	55.90	55.90	25.00	41.92	Replace	0	0	Check	✓
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	0	0	Check	✓
One Time Key In	Main			WIPER GARNISH	1	614.00	614.00	25.00	460.50	Replace	0	0	Check	✓
One Time Key In	Main			WIPER GARNISH COVER, LH	1	23.80	23.80	25.00	17.85	Replace	0	0	Check	✓
One Time Key In	Main			WIPER GARNISH COVER, RH	1	23.80	23.80	25.00	17.85	Replace	0	0	Check	✓
One Time Key In	Main			WINDSCREEN FRT	1	1,543.80	1,543.80	25.00	1,157.85	Replace	1	1,157.	Replace	✓
One Time Key In	Main			WINDSCREEN MOULDING FRT	1	57.60	57.60	25.00	43.20	Replace	1	43.20	Replace	✓
One Time Key In	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace	✓
One Time Key In	Main			HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	0	0	Check	✓
One Time Key In	Main			CABLE ASSY, HOOD	1	52.20	52.20	25.00	39.15	Replace	0	0	Check	✓
One Time Key In	Main			HOOD AUXILIARY CATCH	1	8.60	8.60	25.00	6.45	Replace	0	0	Check	✓
One Time Key In	Main			CLAMP, HOOD LOCK	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	✓
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Check	✓
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.61	Replace	✓
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.61	Replace	✓
One Time Key In	Main			WIPER WASHER INLET	1	36.90	36.90	25.00	27.67	Replace	0	0	Check	✓
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	1	135.07	Replace	✓
One Time Key In	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	10.00	215.10	Replace	0	0	Check	✓
One Time Key In	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	10.00	216.00	Replace	0	0	Check	✓
One Time Key In	Main			TRANSAXLE ASSY.	1	10,249.20	10,249.20	25.00	7,686.90	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR ASSY	1	1,495.90	1,496.90	25.00	1,122.68	Replace	0	0	Check	✓
One Time Key In	Main			CUSHION, RADIATOR	2	11.30	22.60	25.00	16.95	Replace	0	0	Check	✓
One Time Key In	Main			SUPPORT, RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Check	✓

Total Spare Part Cost 67,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT, RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Check	✓
One Time Key In	Main			SUPPORT, RADIATOR,	1	18.50	18.50	25.00	13.88	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	876.30	876.30	25.00	657.22	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR HOSE LOWER	1	42.40	42.40	25.00	31.80	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR TOP HOSE NO 1	1	42.40	42.40	25.00	31.80	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.1	1	37.20	37.20	25.00	27.90	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.2	1	29.00	29.00	25.00	21.75	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.3	1	37.20	37.20	25.00	27.90	Replace	0	0	Check	✓
One Time Key In	Main			RADIATOR HOSE, BYPASS NO.4	1	37.20	37.20	25.00	27.90	Replace	0	0	Check	✓
One Time Key In	Main			COOLANT	4	12.32	49.28	0.00	49.28	Replace	0	0	Check	✓
One Time Key In	Main			COOLANT RESERVE TANK	1	395.30	395.30	25.00	296.48	Replace	0	0	Check	✓
One Time Key In	Main			FAN SHROUD	1	244.50	244.50	25.00	183.38	Replace	1	183.38	Replace	✓ ?
One Time Key In	Main			STABILIZER BAR FRT	1	348.80	348.80	25.00	261.60	Replace	1	261.60	Replace	✓ ?
One Time Key In	Main			STEERING KNUCKLE RH FRT	1	580.80	580.80	25.00	435.60	Replace	0	0	Check	✓
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Check	✓
One Time Key In	Main			LOWER ARM FRT/RH	1	625.90	625.90	25.00	469.42	Replace	0	0	Check	✓
One Time Key In	Main			JOINT ASSY.LWR BALL	1	195.60	195.60	25.00	146.70	Replace	0	0	Check	✓
One Time Key In	Main			TIE ROD END RH	1	159.30	159.30	25.00	119.48	Replace	0	0	Check	✓
One Time Key In	Main			BRAKE HOSE FRT, RH	1	46.20	46.20	25.00	34.65	Replace	0	0	Check	✓
One Time Key In	Main			SENSOR, SPEED, FR RH	1	446.50	446.50	25.00	334.88	Replace	0	0	Check	✓
One Time Key In	Main			STEERING RACK ASSY	1	1,597.50	1,597.50	25.00	1,198.13	Replace	0	0	Check	✓
One Time Key In	Main			CROSS MEMBER FRT	1	2,497.50	2,497.50	25.00	1,873.13	Replace	0	0	Check	✓
One Time Key In	Main			DRIVE SHAFT RH	1	1,764.40	1,764.40	25.00	1,323.30	Replace	0	0	Check	✓
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	810.70	810.70	25.00	608.03	Replace	0	0	Check	✓

Total Spare Part Cost 87,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace	✓
One Time Key In	Main			MEMBER FRT, SUB CENTRE	1	65.00	65.00	25.00	48.75	Replace	0	0	Check	✓
One Time Key In	Main			COVER, ENGINE UNDER, NO.2	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	✓
One Time Key In	Main			AIR BAG ASSY, FRONT SEAT, RH	1	834.50	834.50	10.00	751.05	Replace	0	0	Check	✓
One Time Key In	Main			COVER, FRONT SEAT BACK RH	1	1,108.70	1,108.70	25.00	831.53	Replace	0	0	Check	✓
One Time Key In	Main			COVER, FRONT SEAT CUSHION RH	1	110.63	110.63	25.00	82.97	Replace	0	0	Check	✓
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	✓

Total Spare Part Cost 67,117.66

Surveyor Total 24,692.34

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20

Final Spare Part Cost 53,694.13

Final Sur Total 19,753.87

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,890.00	600	
2	Main	TO REPAIR LH PORTION	676.00	400	
Total:			2,366.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	TO RESPRAY APRON PANEL LH	180.00	0	CHECK
4	Main	TO REPSRAY FRONT BUMPER	378.00	200	
5	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	80	
6	Main	TO REPSRAY FRONT HOOD	378.00	200	
7	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	100	
8	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
9	Main	TO RESPRAY APRON PANEL RH	180.00	0	CHECK
10	Main	TO RESPRAY RIM	180.00	50	
11	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	


			Recommendation(\$)	Adjustment(\$)	
12	Main	TO RESPRAY SILL MEMBER PANEL RH	180.00	0	CHECK
13	Main	TO RESPRAY CENTER PILLAR RH	180.00	0	CHECK
14	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
15	Main	TO RESPRAY DOOR HANDLE	180.00	0	NN
16	Main	RESPRAY MIRROR COVER RH	180.00	30	
17	Main	TO RESPRAY REAR DOOR RH	378.00	200	
Total:			4,446.00	1,760.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	84.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	100	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	Main	TO TOP UP A/C GAS	120.00	20	
6	Main	TO REMOVE / REFIT SEAT	120.00	0	CHECK
7	Main	TO REMOVE AND REFIT FRONT SEAT BELT	240.00	0	CHECK
8	Main	TO REMOVE / REFIT WINDSCREEN	0.00	0	
9	Main	TO ALIGN CHASSIS	350.00	150	
10	Main	TO TRANSFER DOOR MECHANISM	360.00	150	
11	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	700.00	700.00	NEC
12	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	
13	Main	TO REMOVE AND REFIT TYRE	120.00	20	
14	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
15	Main	TO REMOVE AND REFIT ROOF LINING	120.00	50	
16	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	0.00	0.00	
17	Main	TO REMOVE AND REFIX ENGINE WIRE HARDNESS	200.00	0	CHECK
18	Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	0	CHECK
19	Main	TO REMOVE AND REFIX WING MIRROR	120.00	20	
20	Main	TO REMOVE AND REFIT FRONT CROSSMEMBER	120.00	0	CHECK

			Recommendation(\$)	Adjustment(\$)	
21	Main		250.00	150	
		TO REMOVE AND REFIX AIR BAG SYSTEM			
22	Main	TO REMOVE AND REFIX DASHBOARD	250.00		CHECK
23	Main	TO WASH AND VACUUM	60.00	0	NN
24	Main	TO REPLACE SUNDRY PARTS	100.00	0	NN
Total:			4,384.00	1,620.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	53,694.13	19,753.87
Total Labour Cost	2,386.00	1,000.00
Total Spray Painting	4,446.00	1,760.00
Other	4,384.00	1,620.00
Overall Total	64,890.13	24,133.87
Lump Sum Repair Option		✓
Lump Sum Total	64,900.00	24,150.00
Surveyor Approved Amount		24,150.00
No of Repair Days*	16	10
Remarks		LUMP SUM REPAIR 10 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS REQUEST PURCHASE PRICE TO CALCULATE NET BOOK VALUE TO DETERMINE REPAIR LIMIT.
Surveyor Name		Naz
Signature		

Survey Date

08/07/2019

Save Clear

NAZ LKK
8/7/19 1600
L / S
10 DAYS

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS
REQUEST PURCHASE PRICE TO
CALCULATE NET BOOK VALUE
TO SET REPAIR MARKET
LIMIT.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer