



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: DM18HO01491

Date: 03<sup>rd</sup> Sep 2019

Our Ref: CS1/EQI19012076/T1sf3e2

**M/s EQ Insurance Company Ltd**

5 Maxwell Road

#17-00 Tower Block

Mnd Complex

Singapore 069110

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SBS 6125K**

**INSURED VEHICLE: GBB 4186L**

**ACCIDENT DATE: 11/06/2018**

We thank you for your instruction on 21/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBS 6125K from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SBS 6125K and GBB 4186L.
- c) Police Report of Vehicles GBB 4186L.
- d) Colour damaged vehicle photographs of SBS 6125K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SBS 6125K
Make & Model	: Mercedes Benz Citaro O530
Chassis Number	: WEB62808323122069
Year of Registration	: 2011
Engine Capacity	: 6374 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.