

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Jul-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8686 M

1 pc	Wheel cover <i>/</i>	\$	346.40
1 pc	Rear bumper <i>X reg</i>	\$	459.40
1 pc	Rear bumper n/s side bracket <i>X</i>	\$	33.10
		\$	838.90
	Less 20%	\$	167.78
		\$	671.12

S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	n/s door stickers <i>/</i>	\$	100.00
1 pc	Rear n/s fender sticker <i>/</i>	\$	60.00

Sundry	\$	50.00 <i>20</i>
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, n/s rocker panel garnish, rear n/s fender	\$	400 950.00
To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender, rear bumper	\$	720 800.00
To apply rustproof on repaired panels	\$	150.00 <i>X</i>
	\$	2,949.12

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahni (LKK)

8/7/19

3 hrs

PIR

Alka Regan pkk

LKK Auto Consultants hereby notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *[Signature]*