

ASS. REC. BY:

REF:

CS/KT2190120821 USF3 n2

Special Instruction:

Surveyor: MARUUS

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 9/7/19 @ 11.16am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLX 486R Insured: ABA 7332S

at Workshop w/k Euro Success Tel: 98289277

of 1 Kaki Bukit Ave 6 # 02-03

Policy No: _____ Claim No: SNM19D203172

Sum Insured: _____ Receipt: _____

Make of Veh: _____ D.O.A. 7/7/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11:36am @ 9/7/19 Person Contacted: Ah hnat H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>11/07/19</u> ✓
	<u>ABA 7332S</u> NA/CT216014839/13 D.O.A 08/08/2014
	<u>SLX 485x</u> : X

108/11/13 wef

REF:

ASS. REC. BY: *M. Arif*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SLX 485R*
 at Workshop m/s *Su cars Ebn*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: *82k*

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: *1* Consistent? : Yes or NoEst. Repairs: *5* days Res.: Yes or NoLum Sum: *10* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

LTAS2105

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLX 485R* Yr Regn: *3, 18*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

*CA*Make: *Toyota sienta Hybrid 1496*Colour: *Blue* A/C: Insured / Std / NI / NASp. Reading: *125/49* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *NHP170 7109471*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *185/60R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *rexen*Front: *6* mm Rear: *6* mmR/Bal: *6* mm L/Bal: *6* mmD.O.A. *7/7/19* D.O.I. *9/7/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Ad 2/5

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/7/19 * *Note new parts replacement*
Confirmed Repair sum 10,300 with AH huof
(13,189.25 Red - 55%)

RECEIVED 23 JUL 2019

Date/Time, File Pass to?

25/07/19

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final ReportDays Of Repair: *5*Resurvey No. of Trip: *4*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) *RS* \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ *10,300/-* *R/S*)

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 9 July 2019 11:16 AM
To: Ruby Ong
Cc: assignments
Subject: RE: OUR REF: SNM19D203172/CHONGBS - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLX 485R [OUR REF. TCL.GCN.RO.50429.19.ESS]

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Tuesday, 9 July, 2019 7:01 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203172/CHONGBS - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLX 485R [OUR REF. TCL.GCN.RO.50429.19.ESS]
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir

We refer to your email dated 8 July 2019.

Our client is agreeable to appoint **Marcus Chua** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SLX 485R**.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : **EURO SUCCESS SERVICES PTE LTD**

1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Monday, 8 July 2019 5:05 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Subject: RE: OUR REF: SNM19D203172/CHONGBS - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLX 485R
[OUR REF. TCL.GCN.RO.50429.19.ESS]

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 8 July, 2019 3:10 PM

To: Ruby Ong <ruby@htapartners.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D203172/CHONGBS - REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLX 485R [OUR REF. TCL.GCN.RO.50429.19.ESS]

Dear Boon Sen,

Please conduct PRS for SLX485R.

Office in charge – Boon Sen 63896171 (file with OIC).

Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Monday, 8 July, 2019 12:28 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLX 485R [OUR REF. TCL.GCN.RO.50429.19.ESS]

Importance: High

Your ref : GBA 7332S

Our ref : TCL.GCN.ro.50429.19.ess

WITHOUT PREJUDICE

8 July 2019

China Taiping Insurance Co (Singapore) Pte Ltd

Motor Claims Department

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

By Email Only

VERY URGENT

Dear Sirs,

CLAIMANT: PROTESINGAPORE

NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SLX 485R & GBA 7332S AT BLOCK 56 HAVELOCK ROAD ON 7 JULY 2019 @ 1342 HRS

We are instructed by Protesingapore to notify you of a road traffic accident on 7 July 2019 at about 1342 hrs at Block 56 Havelock Road involving our clients' vehicle registration number SLX 485R and vehicle registration number GBA 7332S driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Why limit yourself?

Check out our awesome benefits.

FIND OUT MORE

PAY AFTER USE
NO PAYMENT UPFRONT

INSURANCE COVERAGE
FOR UNLIMITED RELAY DRIVERS

NO PRICE HIKE
OVER FUTURE PRICES

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A

3.18% P.A \$0 Admin Fees At GV
Finance. 2 Years Warranty.
Monthly From \$688
GV Credit Pte Ltd StarAd

HIN LUNG AUTO

Ho Bee Group

One Stop Car Hub

Finance, Insurance, Workshop

New and Used Cars

30 years of car sale

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Sienta Hybrid 1.5A G

Advanced Search

Submit

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Sienta Hybrid 1.5A G

Any

Any

2018

Any

Any

Any

Available



Toyota Sienta Hybrid 1.5A G

\$87,000

\$9,070 /yr

26-Jun-2018

1,496 cc

-

MPV

Available

Fuel Type: Petrol-Electric

Elegant Toyota MPV, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financin...

Prime Motor & Leasing

Posted: 29-Jun-2019

Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota



Toyota Sienta Hybrid 1.5A G

\$90,000

\$9,590 /yr

27-Jun-2018

1,496 cc

-

MPV

Available

Fuel Type: Petrol-Electric

Elegant Yellow MPV, Low Fuel Consumption With Hybrid, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 08-May-2019

Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Sienta Hybrid 1.5A G, Sienta Hybrid 1.5A G Singapore, used Sienta Hybrid 1.5A G Singapore, used Sienta Hybrid 1.5A G, used vehicles Singapore or even buy used Sienta Hybrid 1.5A G Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	3305D

Vehicle Details

Vehicle No.:	SLX485R
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	1NZ8391125
Chassis No.:	NHP1707109471
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$23,248.00
Original Registration Date:	14 Mar 2018
First Registration Date:	14 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$24,548.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Mar 2028
PARF Rebate Amount:	\$18,411.00

Intended COE Rebate Details

COE Expiry Date:	13 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,830.00
COE Rebate Amount:	\$33,694.00
Total Rebate Amount:	\$52,105.00

The information contained herein is correct as at 09 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 14:17
Date Of Accident	07/07/2019 13:40
Exact Location Of Accident	SERVICE ROAD OF HAVELOCK ROAD ESTATE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX485R
Insured/Policyholder	
Name Of Registered Owner	PROTESINGAPORE
Co Reg No	53323305D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA HYBRID 1.5G CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105758811 CLASSIC
Cover Note Number	
Driver	
Name of Driver	LIM SWEE TEE
NRIC No	S1798068A
Date Of Birth	10/05/1967
Occupation	OUTDOOR
Date Of Driving Pass	03/12/1999
Driving Experience	19 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91000931
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 127 RIVERVALE STREET #07-836
Postcode	540127
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	G8A7332S
Vehicle Make/Model/Colour	MITSUBISHI FB70BB1SRDEA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMALINGAM MARIMUTHU
NRIC/Passport Number	G8417577W
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM SWEE TEE
Approximate Age	52
Injuries Sustain	CHEST & BACK NECK PAIN
Injured person in which vehicle?	SLX485R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

1

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report

DECLARATION

I/We declare the following contents are true & correct.


 Policyholder's Signature
 Date & Time:

100-110-110-110-110-110


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

- 8 JUL 2019

LINC KAKI BUKIT,
 22 Kaki Bukit Ave 1
 Singapore 415937
 Tel: 67416697 Fax: 674
 Reporting Officer: 5431111111
 Name:
 NRIC No:



**SINGAPORE
POLICE FORCE**



T/20190707/2129

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8989

1 of 4

Report No. T/20190707/2129

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/07/2019 23:13	Video Report No.:	Station Diary No. 144
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: LIM SWEE TEE		Address: APT BLK 127 RIVERVALE STREET #07-838 SINGAPORE 540127	
ID Type / ID No. NRIC NO / S1798065A		Contact No	Mobile: 91000931
Nationality: SINGAPORE CITIZEN		Email	
Sex: Male	Age: 52	Date of Birth: 10/06/1967	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: GOJEK DRIVER		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury: Others:	Drink Drive: No	Date/Time of Accident: 07/07/2019 13:40	Type of Location: SERVICE ROAD
Location: Along Road 1 HAVELOCK ROAD				
Service Road of Havelock Road Estate				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: REAR to HEAD			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBA7332S	Lorry	MITSUBISHI	FB70BB1SR DEA	White		0
SLX485R	Car	TOYOTA	SIENTA HYBRID 1.5G CVT	Blue	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190707/2129

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 4

Report No: T/20190707/2129

CONTINUATION OF REPORT

Driver			
Name	Ramalingam Marimuthu	ID No	G8417577W
Related Vehicle	GBA7332S (Lorry)	Contact No	83469250
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM SWEE TEE	ID No	S1798066A
Related Vehicle	SLX485R (Car)	Contact No	91000931
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE LTD.	Class of Driving Licence & Expiry Date	Class: 2B.3 Date of Expiry: NIL
Date Treatment	07/07/2019	Date Discharge	07/07/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 07/07/19 at about 1342hrs, I was driving one Gojek vehicle bearing SLX485R along the service road proceeding to the pick-up point of Blk 58 Havelock Road.

While was along the service road, one lorry bearing GBA7332S (about 50m ahead) was reversing from CRC (Central Rubbish Chute) of Blk 58 Havelock Road.

I then slow down my vehicle.

After reversing, the said lorry started to drive towards the direction of my pick-up point, however, the lorry was driving against the flow of traffic on the most right.

After which, the lorry stops and start to reverse towards my vehicle without turning on any signal.

I horned at the lorry several times however there was no response from the lorry.

Thus, the lorry collided onto my vehicle on my vehicle's front right area.

I alighted and spoke to the lorry driver who was believed to be an Indian foreigner driver. He claimed that he did not heard the horn.

Driver's details at follows:

- Name: Ramalingam Marimuthu
- Fin: G8417577W



**SINGAPORE
POLICE FORCE**



T/20190707/2129

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
645025
Tel No: 1800-343 8999

3 of 4

Report No. T/20190707/2129

CONTINUATION OF REPORT

- Hp: 83469250

The said driver had called up his boss to inform about the said accident. However, the boss denied of the responsibility and alleged that I was at fault.

I called the Police whom then advised me to call NTUC. NTUC officer then came. The said officer tried to extract the memory card which I had recorded in my front in-car camera. However, unable to extract.

Damages of my vehicle as follows:

- Front bonnet dented
- Front driver door unable to open fully
- Front right headlight

I had already informed the car rental company (PROTESINGAPORE) about the accident.

Later at about 1530hrs, as I returned home I felt pain on my chest and back neck, difficulty in breathing.

As such I went to Sengkang General Hospital and was given 04 days of MC dated from 07/07/19 - 10/07/19.

I managed to extract the whole accident from my memory card as I got home.

This is the first time happened.



**SINGAPORE
POLICE FORCE**



T/20190707/2129

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

of 4

Report No: T/20190707/2129

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 MOHAMAD ADAM BIN ROSLAN

Signature Of Informant

Signature Of Interpreter:

Not applicable

Date/Time

07/07/2019 23:13

Officer In Charge Of Case:

TP / AEIT /

Insp NEO CHENG BEET, CECILIA

Contact No: 65476069

Classification Of Case:

Authentication Stamp
NP158



Signature

Singapore Police Force

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLX485R

Model: TOYOTA SIENTA HYBRID

not Approved
9/7/19
Repair Sum
\$ 10,300 /-
Sdy.

QTY	List Items	Price \$
1	FRONT R/H DOOR	1112.79 X
1	FRONT R/H DOOR MIRROR	1157.70 X
1	FRONT R/H DOOR RUBBER	150.50
1	FRONT R/H DOOR GLASS RUN CHANNEL	112.30 X
1	FRONT BUMPER 1050.00	1231.66
2	FRONT L-R BUMPER RETAINER @48.50	97.00 1pc
1	FRONT BUMPER REINFORCEMENT 425.10	579.95
1	FRONT BUMPER INNER SPONGE 105.00	233.90
1	FRONT BUMPER CENTRE GRILL	425.80
1	FRONT BUMPER CENTRE GRILL CHROME 125.50	312.60
1	FRONT BUMPER LOGO 68.10	86.60
2	FRONT BUMPER L-R FOG LAMP GARNISH @281.2 145	562.40 1pc
1	FRONT BUMPER TOP rubber 75.50	186.60
1	FRONT SUPPORT PANEL	891.60
1	FRONT SUPPORT PANEL INNER GARNISH	187.60 X
1	FRONT BRACE PANEL	100.63 X
1	AIR CON CONDENSER	1899.50 X
1	RADIATOR	950.00
1	RADIATOR FAN MOTOR ASSY	450.00 X
1	AIR CON COMPRESSOR	1600.00 X
1	AIR CON INNER PIPE	180.00 X
1	AIR CON DISCHARGE PIPE	205.00 X
1	FRONT BONNET 991.10	1492.50
2	FRONT BONNET L-R HINGE @89.9	179.80 1pc
1	FRONT BONNET LOCK	189.63
2	FRONT L-R HYBRID HEADLAMP @3045.8 280x2=560	6091.60
1	FRONT R/H HEADLAMP TOP PANEL	155.60
1	FRONT R/H FENDER 655.10	716.90
1	FRONT R/H FENDER 'HYBRID' EMBLEM	68.00
1	FRONT R/H FENDER INNER SHIELD	181.54 X
1	FRONT R/H WHEEL BEARING	297.88 X
1	FRONT R/H LOWER ARM	497.55 X
1	FRONT WIPER TANK 285.30	350.00
1	FRONT WIPER GARNISH	189.20 X
1	FRONT R/H ENGINE MOUNTING	450.00 X
1	FRONT R/H ENGINE MOUNTING BRACKET	200.00 X
1	FUEL BOX	365.20 X

TOTAL

LESS 25%

TOTAL

\$24,139.53

\$6,034.88

\$18,104.65

12484.73
252
9363.54

Special Nett Items

1	FRONT NUMBER PLATE
1	FRONT NUMBER PLATE BRACKET
10	FRONT BUMPER CLIP @4.5
1	FRONT GRILL COVER
1	FRONT DOOR MECHANISM
1	FRONT R/H SPORT RIM
1	FRONT R/H TYRE
1	AIR CON OIL

11	60.00	X
11	60.00	X
me	45.00	✓
NS	45.00	X
11	180.00	X
R	600.00	X
11	300.00	X
me	60.00	30

\$1,350.00Labour Charge

TO CHECK FRONT ELECTRICAL WIRING
TO RESPRAY UNDERCOATING
TO REMOVE, REFIX AIR-CON CONDENSER VACUUM AND TOP UP GAS
PANEL BEATING , CUT , WELD , REMOVE AND REPLACING ABOVE PARTS
TO RESPRAY PAINTING AND ETC
TO CHECK WHEEL ALIGNMENT
TO REMOVE REFIX FRONT DOOR MECHANISM WIRING ETC
TO REMOVE AND REFIX FRONT UNDERCARRIAGE

60.00	30
200.00	90
150.00	100
1200.00	700
1100.00	1000
160.00	60
11	150.00 X
11	180.00 X

\$3,200.00**ESTIMATE PARTS AND LABOUR GRAND TOTAL****\$22,654.65**

11488.54
102
10300

23489.25

EURO SUCCESS SERV PTE. LTD

1 KAKI BUKIT AVENUE 6, #02-03(AUTOBAY) SINGAPORE 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

SUPPLEMENTARY

Vehicle No: SLX485R

<u>QTY</u>	<u>List Items</u>	<u>Price\$</u>
1	HYBRID BATTERY COOLER	17 770.00
2	FRONT CHASIS L-R MOUNTING @95	17 190.00
2	FRONT L/H SUPPORT PANEL INNER GARNISH@38.2	17 76.40
2	FRONT R/H SUPPORT PANEL INNER GARNISH@38.2	17 76.40

Sub-Total	\$1,112.80
Less 25%	\$278.20
Total	\$834.60

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012082/USF3N2

Date: 24/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19161719000
Claimant Vehicle No :	SLX485R	Insured Vehicle No :	GBA7332S
Date of Loss:	07/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203172C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX485R	Engine No:	1NZ8391125
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707109471
Reg. Date:	14/03/2018 (Man. Year: 2017)	Odometer:	125149 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,289.25	9,438.55	10,850.70	53.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	2,060.00	1,140.00	35.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,489.25	11,498.55	11,990.70	51.05
Approved Total (Overridden) (S\$)		10,300.00		
Nett Amount (S\$)	23,489.25	10,300.00	13,189.25	56.15

INSPECTION

Date of Assignment:	23/07/2019	
Date Inspected:	09/07/2019	Inspected At:
		Euro Success Services Pte Ltd (HQ)
		1 KAKI BUKIT AVENUE 6 #02-03
		AUTOBAY
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2019)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX485R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT R/H DOOR	Repair	1,112.79 FL	*- FL
2	1	*FRONT R/H DOOR MIRROR	Not Necessary	1,157.70 FL	*- FL
3	1	*FRONT R/H DOOR RUBBER	Not Necessary	150.50 FL	*- FL
4	1	*FRONT R/H DOOR GLASS RUN CHANNEL	Not Necessary	112.30 FL	*- FL
5	1	*FRONT BUMPER	Distorted	1,231.66 FL	*1,050.00 FL
6	1	*FRONT L/R BUMPER RETAINER	O/s Cracked	97.00 FL	*48.50 FL
7	1	*FRONT BUMPER REINFORCEMENT	Bent	579.95 FL	*425.10 FL
8	1	*FRONT BUMPER INNER SPONGE	Torn	233.90 FL	*105.00 FL
9	1	*FRONT BUMPER CENTRE GRILL	Grazed	425.80 FL	*425.80 FL
10	1	*FRONT BUMPER CENTRE GRILL CHROME	Grazed	312.60 FL	*165.50 FL
11	1	*FRONT BUMPER LOGO	Necessary	86.60 FL	*68.10 FL
12	1	*FRONT BUMPER L-R FOG LAMP GARNISH	O/s Cut	562.40 FL	*145.00 FL
13	1	*FRONT BUMPER TOP RUBBER	Torn	186.60 FL	*75.50 FL
14	1	*FRONT SUPPORT PANEL	Bent/Twisted	891.60 FL	*891.60 FL
15	1	*FRONT SUPPORT PANEL INNER GARNISH	Not Necessary	187.60 FL	*- FL
16	1	*FRONT BRACE PANEL	Not Necessary	100.63 FL	*- FL
17	1	*AIR CON CONDENSER	Serviceable	1,899.50 FL	*- FL
18	1	*RADIATOR	Bent/Punctured	950.00 FL	*950.00 FL
19	1	*RADIATOR FAN MOTOR ASSY	Not Necessary	450.00 FL	*- FL
20	1	*AIR CON COMPRESSOR	Not Necessary	1,600.00 FL	*- FL
21	1	*AIR CON INNER PIPE	Not Necessary	180.00 FL	*- FL
22	1	*AIR CON DISCHARGE PIPE	Not Necessary	205.00 FL	*- FL
23	1	*FRONT BONNET	Buckled	1,492.50 FL	*991.10 FL
24	1	*FRONT BONNET L-R HINGE	O/s Bent	179.80 FL	*89.90 FL
25	1	*FRONT BONNET LOCK	Twisted	189.63 FL	*189.63 FL
26	2	*FRONT L-R HYBRID HEADLAMP	Cracked	6,091.60 FL	*5,700.00 FL
27	1	*FRONT R/H HEADLAMP TOP PANEL	Bent	155.60 FL	*155.60 FL
28	1	*FRONT R/H FENDER	Bent/Buckled	716.90 FL	*655.10 FL
29	1	*FRONT R/H FENDER HYBRID EMBLEM	Necessary	68.00 FL	*68.00 FL
30	1	*FRONT R/H FENDER INNER SHIELD	Not Necessary	181.54 FL	*- FL
31	1	*FRONT R/H WHEEL BEARING	Not Necessary	297.88 FL	*- FL
32	1	*FRONT R/H LOWER ARM	Not Necessary	497.55 FL	*- FL
33	1	*FRONT WIPER TANK	Distorted	350.00 FL	*285.30 FL
34	1	*FRONT WIPER GARNISH	Not Necessary	189.20 FL	*- FL
35	1	*FRONT R/H ENGINE MOUNTING	Not Necessary	450.00 FL	*- FL
36	1	*FRONT R/H ENGINE MOUNTING BRACKET	Not Necessary	200.00 FL	*- FL
37	1	*FUEL BOX	Not Necessary	365.20 FL	*- FL
38	1	*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
39	1	*FRONT NUMBER PLATE BRACKET	Not Necessary	60.00 FS	*- FS
40	10	*FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
41	1	*FRONT GRILL COVER	No such part	45.00 FS	*- FS
42	1	*FRONT DOOR MECHANISM	Not Necessary	180.00 FS	*- FS
43	1	*FRONT R/H SPORT RIM	Repair	600.00 FS	*- FS
44	1	*FRONT R/H TYRE	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*AIR CON OIL	Necessary	60.00 FS	*30.00 FS
46	1		*HYBRID BATTERY COOLER	Not Necessary	770.00 FL	*- FL
47	2		*FRONT CHASIS L-R MOUNTING	Not Necessary	190.00 FL	*- FL
48	2		*FRONT L/H SUPPORT PANEL INNER GARNISH	Not Necessary	76.40 FL	*- FL
49	2		*FRONT R/H SUPPORT PANEL INNER GARNISH	Not Necessary	76.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,602.33	12,559.73
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,313.08	3,121.18
Total Parts (\$\$)	20,289.25	9,438.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	60.00	30.00
2	TO RESPRAY UNDERCOATING	New	200.00	90.00
3	TO REMOVE,REFIX AIR-CON CONDENSER VACUUM AND TOP UP GAS	New	150.00	100.00
4	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	700.00
5	TO RESPRAY PAINTING AND ETC	New	1,100.00	1,080.00
6	TO CHECK WHEEL ALIGNMENT	New	160.00	60.00
7	TO REMOVE,REFIX FRONT DOOR MECHANISM WIRING ETC	New	150.00	0.00
8	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	180.00	0.00
Gross Labour Cost (S\$)			3,200.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >