

ASS. REC. BY:

REF: CS100119012086/A97302

Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): Jenny Lew of UDI Date/Time: 9/7/19 @ 11:33am

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SME 9176L Insured: XE 4572Dat Workshop m/s: CAS GARAGE Tel: 6484 2220of 1 kaki Bukit Ave 6 # 02-22Policy No: _____ Claim No: M11007681907

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 12:03pm @ 9/7/19 Person Contacted: Nicole Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	<u>3/1/2019 ✓</u>
	<u>XE 4572D : X</u>
	<u>SME 9176L : X</u>
	<u>US \$9100, 9 days (led \$14769.60, 62%)</u>

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME 9176L Yr Regn: 2018, Oct.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.C. 1591Colour: Blue AC: Insured / Std / Nil / NASp. Reading 3980 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMH0841CMJU736961Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 09/07/19Survey held at CASDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or205 O/S
The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 24 JUL 2019

Date / Time Action / Instruction

77 uoi

mv:

pv:

Nett:

Date/Time, File Pass to?

1) 24/7 train

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S+RS, SI

Photos

Others

TOTAL

Date: 13x25:325250+32560+8045760

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 9 July 2019 11:33 AM
To: Nicole Chong; SUR; assignments
Cc: LEE KATIE
Subject: RE: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019
Attachments: 9176gia.zip

WITHOUT PREJUDICE

Dear Nicole,

We will arrange LKK as SJE as requested.

Dear Shiau Chan,

Please arrange to survey the vehicle at CAS Garage Pte. Ltd.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Nicole Chong [<mailto:nicolechong.cas@gmail.com>]
Sent: Tuesday, 9 July, 2019 11:20 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: Re: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

Dear Jenny,

We request LKK to survey our client's vehicle.

Regards,
Nicole Chong
CAS Garage Pte. Ltd.
Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)
Hp: 9791 6119
Office: 6484 2220
UEN: 201828067M

On Tue, 9 Jul 2019 at 10:43, LEW JENNY <jennylew@uoi.com.sg> wrote:

WITHOUT PREJUDICE

Dear Nicole,

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s STA Inspection Pte Ltd.

Please revert to the undersigned within **two (2) working days** whether you have any objections to the appointment of any of our Surveyors, failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

Please forward us a copy of the estimated cost of repair.

We reserve all our rights in this matter.

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Nicole Chong [<mailto:nicolechong.cas@gmail.com>]

Sent: Tuesday, 9 July, 2019 9:51 AM

To: LEE KATIE <katielee@uoi.com.sg>

Subject: Fwd: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

Dear Sir/Madam,

Kindly arrange survey our client's vehicle on 08.07.2019

Do let us know when is the available date and time for inspection of the vehicle at:

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Thank you and have a nice day! Hope to hear from you soon

Regards,

Nicole Chong

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

----- Forwarded message -----

From: **Nicole Chong** <nicolechong.cas@gmail.com>

Date: Tue, 9 Jul 2019 at 09:49

Subject: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

To: <claims@uoi.com.sg>

Dear Sir/Madam,

Kindly arrange survey our client's vehicle on 08.07.2019

Do let us know when is the available date and time for inspection of the vehicle at:

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Thank you and have a nice day! Hope to hear from you soon

Regards,

Nicole Chong

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

Shiau Chan (LKKAUTO)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 24 July 2019 11:43 AM
To: Shiau Chan (LKKAUTO); assignments
Cc: LEE KATIE; SUR
Subject: RE: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

Dear Shiau Chan,

Claim no: M11D07681907

Thanks.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 24 July, 2019 11:15 AM
To: LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

Dear Jenny,

Kindly provide us the claim number of above mentioned.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 9 July 2019 12:04 PM
To: 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'LEE KATIE' <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: PRI - SME 9176L AND XE 4572D ALONG CTE BEFORE BRADDELL DOA 07.07.2019

Dear Jenny,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 15:55
Date Of Accident	07/07/2019 12:10
Exact Location Of Accident	CTE BEFORE BRADDELL EXIT 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME9176L
Insured/Policyholder	
Name Of Registered Owner	YIM SHAO PENG
NRIC No	S8808734H
Email Address	PENGPENG_AIRNESS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96373457
Alternative Phone No	OFFICE-96373457

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2221056
Cover Note Number	

Driver

Name of Driver	YIM SHAO PENG
NRIC No	S8808734H
Date Of Birth	13/03/1988
Occupation	INDOOR
Date Of Driving Pass	03/02/2009
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96373457
Fax Number	
Contact Number	OFFICE 96373457

Address 9 JOO SENG ROAD #10-28

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: NG HUIMIN, EVELYN
GENDER: FEMALE

Passenger 2 NAME: YIM XI EN, HAILEY
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE4572D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver MICHELRAJ BENJAMIN BESKI

NRIC/Passport Number

Contact Number 91335400/67915909

Address

10/10/2024

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident

On 1207 hours, I was driving my car, a Hyundai Elantra 1.6S, from Ang Mo Kio Ave 1 towards CTE entrance. I was keeping on the left most lane driving straight. I noticed a rubbish truck coming in from my right, and heard a loud bump. My car, containing my wife and baby, turned 180 degrees. The truck came to a stop and my car was facing the opposite direction at the CTE. Fortunately, the cars along the expressway was slow. No one was injured. The driver of the truck is Michelraj Benjamin Beski, license number G 7939 743 T. The rubbish truck has the name "Teng Long Industries Pte Ltd" printed on it, "Tel: 6 791 5909".

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

 08/07/2019
H. 02 PM.
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: UNITED OVERSEAS INSURANCE LIMITED

Address: NO 3, ANSON ROAD, #28-01
SPRINGLEAF TOWER, S(079909)

Xiao Chen

Telephone: 62227733 Fax: 63273869

Email CLAIM@UOI.COM.SGMake/ Model : HYUNDAI ELANTRA
CMH0841CMSJ0736961

Date: 08.07.2019

Chassis No : 1 11111111111111111111

Vehicle No: SME 9176L

Date/Time of Accide 07.06.2019/ 2100

Year of Reg: 07.11.2018

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	BOOTLID Dented	1	\$ 1,620.40	\$ ✓ 1,620.40
2	BOOTLID SMART KEY ANTENNA 2	1	\$ 236.50	\$ + 236.50
3	BOOT RELEASE ANTENNA	1	\$ 245.80	\$ + 245.80
4	BOOTLID INNER TRIM	1	\$ 356.20	\$ + 356.20
5	BOOTLID REFLECTORS	2	\$ 352.80	\$ + 705.60
6	BOOTLID EMBLEM "ELANTRA" 2	1	\$ 90.30	\$ ✓ 90.30
7	BOOTLID EMBLEM "S" New	1	\$ 60.30	\$ ✓ 60.30
8	BOOTLID LOGO	1	\$ 68.50	\$ ✓ 68.50
9	BOOTLID TOP LOCK	1	\$ 223.60	\$ + 223.60
10	BOOTLID LOWER CATCH	1	\$ 35.80	\$ + 35.80
11	BOOTLID WEATHERSTRIP	1	\$ 202.90	\$ + 202.90
12	REAR BUMPER Distorted	1	\$ 558.20	\$ ✓ 558.20
13	REAR BUMPER RETAINERS RH Dented	2	\$ 58.60	\$ 58.60 117.20
14	REAR BUMPER REFLECTORS Not new	2	\$ 86.50	\$ 173.00
15	REAR BUMPER REINFORCEMENT New	1	\$ 378.10	\$ 378.10
16	REAR REINFORCEMENT BRACKETS New	2	\$ 69.20	\$ 138.40
17	TAILAMPS RH Smashed, LH ok	2	\$ 475.30	\$ 475.30 950.60 ✓
18	TAILAMPS PANEL Repair	2	\$ 482.50	\$ 965.00
19	REAR END PANEL Dented	1	\$ 502.30	\$ 502.30
20	REAR END PANEL TOP GARNISH New	1	\$ 156.80	\$ + 156.80
21	REAR FENDER RH Distorted	1	\$ 1,900.20	\$ ✓ 1,900.20
22	REAR FENDER INNER COWLING RH New	1	\$ 149.70	\$ + 149.70
23	REAR FENDER INNER TRIM RH Not New	1	\$ 156.80	\$ 156.80
24	REAR FENDER AIR DUCT New	1	\$ 103.50	\$ 103.50
25	REAR WINDSCREEN INNER SEAL New	1	\$ 125.80	\$ ✓ 125.80
26	REAR DOOR RH Dented	1	\$ 1,831.10	\$ ✓ 1,831.10 1355
27	REAR DOOR WEATHERSTRIP RH (FRAME)	1	\$ 162.70	\$ + 162.70
28	REAR DOOR WEATHERSTRIP RH (DOOR)	1	\$ 161.30	\$ + 161.30
29	REAR DOOR CHECKER RH	1	\$ 53.60	\$ + 53.60
30	REAR DOOR HINGE UPPER RH	1	\$ 56.80	\$ + 56.80
31	REAR DOOR HINGE LOWER RH	1	\$ 55.60	\$ + 55.60

32	REAR DOOR OUTER HANDLE RH <i>new</i>	1	\$ 185.60		\$ * 185.60
33	REAR DOOR OUTER HANDLE COVER RH <i>new</i>	1	\$ 55.30		\$ * 55.30
34	REAR DOOR OUTER MOLDING RH <i>new</i>	1	\$ 128.60		\$ * 128.60
35	REAR DOOR OUTER STICKER RH(BLACK) <i>new</i>	3	\$ 65.30		\$ 195.90 6060
36	REAR DOOR RUNCHANNEL RH <i>new</i>	1	\$ 176.50		\$ * 176.50
37	REAR DOOR INNERTRIM RH <i>new</i>	1	\$ 823.60		\$ * 823.60
38	FRONT DOOR RH <i>dent</i>	1	\$ 1,831.10		\$ 1,831.10 1350
39	FRONT DOOR STICKER RH (BLACK) <i>new</i>	2	\$ 65.20		\$ 130.40 6060
40	FRONT DOOR WEATHERSTRIP RH (FRAME) <i>new</i>	2	\$ 162.70		\$ * 162.70
41	FRONT DOOR WEATHERSTRIP RH (DOOR) <i>new</i>	1	\$ 161.30		\$ * 161.30
42	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 185.60		\$ ✓ 185.60
43	FRONT DOOR OUTER HANDLE COVER RH <i>new</i>	1	\$ 55.30		\$ ✓ 55.30
44	SIDE ROCKER PANEL RH <i>new</i>	1	\$ 1,823.60		\$ * 1,823.60
45	REAR RIM RH <i>new</i>	1	\$ 685.60		\$ * 685.60
46	REAR ABSORBER RH <i>new</i>	1	\$ 391.50		\$ * 391.50
47	REAR WHEEL HUB BEARING RH <i>new</i>	1	\$ 395.60		\$ * 395.60
48	REAR KNUCKLE ARM RH <i>new</i>	1	\$ 406.20		\$ * 406.20
Total List Price Cost					\$ 20,337.00
PARTS DISCOUNT 20%					\$ 16,269.60

9566.70
7653.36
S.N. 120

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00		\$ 50.00 25
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00
3	REAR LOWER SPOILER(ACCESORIES) <i>new</i>	1	\$ 650.00		\$ 650.00
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00
5	REVERSE SENSOR <i>new</i>	1 SET	\$ 250.00		\$ 250.00
6	REAR FENDER INNER COWLING SET <i>new</i>	1 SET	\$ 30.00		\$ 30.00
7	REAR FENDER INNER TRIM SET <i>new</i>	1 SET	\$ 30.00		\$ 30.00
8	WINDSCREEN SEALANTS <i>new</i>	2	\$ 80.00		\$ 80.00 60
9	END PANEL INSULATOR SEAL <i>new</i>	2	\$ 80.00		\$ 80.00
Total Special Nett Items					\$ 1,230.00

115

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS	\$ 2,400.00
	1700
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,000.00
	1400
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 80 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 60 150.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ 60 150.00
TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT	\$ 120 180.00
TO REMOVE AND INSTALL REAR UNDERCARRIAGE	\$ * 200.00
TO REMOVE/ RESEAL OFF PEAK SEAL FOR BOOTLID REPLACEMENT	\$ 80 120.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT (BEFORE & AFTER)	\$ 80 180.00
TO REMOVE/ REFIT WIRING CHECKS AND SETTLING ON WINDOW MODULE	\$ * 120.00
TO CONDUCT WATER LEAKAGE TEST	\$ * 150.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 50 150.00
TO REMOVE /REFIT AND REPLACE BOOTLID MECHANISM	\$ * 120.00
TO REMOVE /REFIT AND REPLACE DOORS MECHANISM	\$ 160 250.00
Total Others Cost	\$ 1,970.00
GRAND TOTAL	\$ 23,869.60

3490

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

Adrian Lij
 4/3 09/07/19.
 09 Days.
 total: 11381.36
 4/3: 9.1K.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI19012086/Aqf3n2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 25-07-2019



Code : UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 4572D	Veh. Inspected	SME 9176L
Policy No.		Coverage (\$)	0.00
Claim No.	M11D07681907	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	09/07/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU736961	Colour	BLUE
Odometer	3980	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	6 mm
L/H Front Tyre	195/65 R15	NEXEN	6 mm
R/H Rear Tyre	195/65 R15	NEXEN	6 mm
L/H Rear Tyre	195/65 R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2019	Inspection Date	09/07/2019
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 9176L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED	1,620.40	1,620.40
1	BOOTLID SMART KEY ANTENNA	NOT NECESSARY	236.50	-
1	BOOT RELEASE ANTENNA	NOT NECESSARY	245.80	-
1	BOOTLID INNER TRIM	NOT NECESSARY	356.20	-
2	BOOTLID REFLECTORS @\$352.80	NOT NECESSARY	705.60	-
1	BOOTLID EMBLEM "ELANTRA"	NECESSARY	90.30	90.30
1	BOOTLID EMBLEM "S"	NECESSARY	60.30	60.30
1	BOOTLID LOGO	NECESSARY	68.50	68.50
1	BOOTLID TOP LOCK	NOT NECESSARY	223.60	-
1	BOOTLID LOWER CATCH	NOT NECESSARY	35.80	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	202.90	-
1	REAR BUMPER	DISTORTED	558.20	558.20
2	REAR BUMPER RETAINERS @\$58.60	O/S DAMAGED	117.20	58.60
2	REAR BUMPER REFLECTORS @\$86.50	NOT NECESSARY	173.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	378.10	-
2	REAR REINFORCEMENT BRACKETS @\$69.20	NOT NECESSARY	138.40	-
2	TAILLAMPS @\$475.30	O/S SMASHED / N/S CUT	950.60	950.60
2	TAILLAMPS PANEL @\$482.50	TO REPAIR SEE LABOUR	965.00	-
1	REAR END PANEL	DENTED	502.30	502.30
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	156.80	-
1	REAR FENDER RH	DISTORTED	1,900.20	1,900.20
1	REAR FENDER INNER COWLING RH	NOT NECESSARY	149.70	-
1	REAR FENDER INNER TRIM RH	NOT NECESSARY	156.80	-
1	REAR FENDER AIR DUCT	NOT NECESSARY	103.50	-
1	REAR WINDSCREEN INNER SEAL	NECESSARY	125.80	125.80
1	REAR DOOR RH	DENTED	1,831.10	1,355.00
1	REAR DOOR WEATHERSTRIP RH (FRAME)	NOT NECESSARY	162.70	-
1	REAR DOOR WEATHERSTRIP RH (DOOR)	NOT NECESSARY	161.30	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	53.60	-
1	REAR DOOR HINGE UPPER RH	NOT NECESSARY	56.80	-
1	REAR DOOR HINGE LOWER RH	NOT NECESSARY	55.60	-
1	REAR DOOR OUTER HANDLE RH	NOT NECESSARY	185.60	-

Report Ref No. CS/UOI19012086/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR OUTER HANDLE COVER RH	NOT NECESSARY	55.30	-
1	REAR DOOR OUTER MOLDING RH	NOT NECESSARY	128.60	-
1	REAR DOOR RUN CHANNEL RH	NOT NECESSARY	176.50	-
1	REAR DOOR INNER TRIM RH	NOT NECESSARY	823.60	-
1	FRONT DOOR RH	DENTED	1,831.10	1,350.00
1	FRONT DOOR WEATHERSTRIP RH (FRAME)	NOT NECESSARY	162.70	-
1	FRONT DOOR WEATHERSTRIP RH (DOOR)	NOT NECESSARY	161.30	-
1	FRONT DOOR OUTER HANDLE RH	CUT	185.60	185.60
1	FRONT DOOR OUTER HANDLE COVER RH	CUT	55.30	55.30
1	SIDE ROCKER PANEL RH	TO REPAIR SEE LABOUR	1,823.60	-
1	REAR RIM RH	CUT	685.60	685.60
1	REAR ABSORBER RH	NOT NECESSARY	391.50	-
1	REAR WHEEL HUB BEARING RH	NOT NECESSARY	395.60	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	406.20	-
	LESS 20% DISCOUNT		-4,002.14	-1,913.34
			16,008.56	7,653.36
3	REAR DOOR OUTER STICKER RH (BLACK) @\$65.30 (SN)	NECESSARY	195.90	60.00
2	FRONT DOOR STICKER RH (BLACK) @\$65.20 (SN)	NECESSARY	130.40	60.00
	LESS 20% DISCOUNT		-65.26	-
			261.04	120.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR NUMBER PLATE WITH CASING (SN)	NECESSARY	50.00	25.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR LOWER SPOILER (ACCESORIES)(SN)	NOT NECESSARY	650.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	SET REAR FENDER INNER COWLING (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM (SN)	NOT NECESSARY	30.00	-
2	WINDSCREEN SEALANTS (SN)	NECESSARY	80.00	60.00
2	END PANEL INSULATOR SEAL (SN)	NOT NECESSARY	80.00	-
			1,230.00	115.00

Report Ref No. CS/UOI19012086/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMPS PANEL AND SIDE ROCKER PANEL RH.		2,400.00	1,400.00
	TO RESPRAY AFFECTED AREAS.		2,000.00	1,400.00
	TO TUFFCOAT AFFECTED AREA.		200.00	80.00
	TO REMOVE/REFIT INTERIOR UPHOLSTERY.		150.00	60.00
	TO APPLY SEALANT TO THE AFFECTED AREAS.		150.00	60.00
	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE FENDER REPLACEMENT.		180.00	120.00
	TO REMOVE AND INSTALL REAR UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	TO REMOVE/RESEAL OFF PEAK SEAL FOR BOOTLID REPLACEMENT.		120.00	80.00
	TO PERFORM COMPUTERISED WHEEL ALIGNMENT (BEFORE/AFTER).		180.00	80.00
	TO REMOVE/REFIT WIRING CHECKS AND SETTling ON WINDOW MODULE.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTling.		150.00	50.00
	TO REMOVE/REFIT AND REPLACE BOOTLID MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE/REFIT AND REPLACE DOORS MECHANISM.		250.00	160.00
			6,370.00	3,490.00
	GRAND TOTAL		23,869.60	11,378.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,100.00

Report Ref No. CS/UOI19012086/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.