

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOH FOOK SENG
 BLK 133 PASIR RIS GROVE
 #08-23
 SINGAPORE 518131

ATTN: Motor Claim Department

Your Ref No: SGH2832C
 Claim Type: Third Party
 Accident Date: 01/07/2019

Not Notified
61 Day 87
Returning After Repair

M/G LK

2-4

4 days

Estimate No: MC1900506
 Date: 04 Jul 2019
 Policy No: GA345111
 Veh Reg No: SGH2832C
 Make/Model: DAIHATSU TERIOS
 1.5L 4WD

TP1 SMH 2292B

Estimate Repair Cost to Vehicle No :SGH2832C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT GRILLE CHROME MOULDING		1 PC	200.00	X
2 HEADLAMP LH & RH	<i>old my Bro</i>	2 PC	1,120.00	<i>N/S ?</i>
3 FRONT BUMPER		1 PC	240.00	<i>Photo</i>
4 FRONT BUMPER SIDE RETAINER LH & RH		2 PC	64.00	
5 FRONT BUMPER CLIPS		15 PC	45.00	
6 FRONT BUMPER LOWER AIR GRILLE		1 PC	120.00	
7 FRONT BUMPER TOW COVER		1 PC	24.00	
8 FRONT BUMPER REINFORCEMENT		1 PC	280.00	<i>Photo</i>
9 FRONT FENDER LH		1 PC	190.00	
10 FRONT FENDER COWLING		1 PC	58.00	<i>Photo</i>
11 FRONT FENDER COWLING CLIPS		8 PC	24.00	
12 FOGLAMP LH		1 PC	180.00	
13 FRONT BONNET		1 PC	380.00	
			2,925.00	
			Add 20%	585.00
				3,510.00
Special Nett				
14 NUMBER PLATE		1 PC	35.00	X
				35.00
LABOUR				
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	<i>201</i>
16 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	X
17 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR FRONT BONNET,FRONT FENDER RH,FRONT WHEELHOUSE PANEL LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	600.00	<i>4001</i>
18 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH & RH,RADIATOR SUPPORT PANEL.		1 PC	800.00	<i>5401</i>
				1,520.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOH FOOK SENG
BLK 133 PASIR RIS GROVE
#08-23
SINGAPORE 518131

ATTN: Motor Claim Department

Your Ref No: SGH2832C
Claim Type: Third Party
Accident Date: 01/07/2019

Estimate No: MC1900506
Date: 04 Jul 2019
Policy No: GA345111
Veh Reg No: SGH2832C
Make/Model: DAIHATSU TERIOS
1.5L 4WD

Estimate Repair Cost to Vehicle No :SGH2832C

Amount Before Excess	S\$ 5,065.00
Add GST @ 7%	354.55
Total Amount payable	S\$ 5,419.55

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED NINETEEN AND CENTS FIFTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: