

ASS. REC. BY:

REF: CS/MSG1901200/Dtf302

Special Instruction:

Surveyor: Bryan

## ASSIGNMENT (Office)

From (Person): Crystal Ice

of

MSIGDate/Time: 9/7/19 @ 1.40pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 7280X

Insured:

GBH 5339A

at Workshop in/s

Chunni Motor

Tel:

65425119

of

Blk 10 Annk Autopoint #01-05/06

Policy No:

29027313

Claim No:

599644

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2.28pm @ 9/7/19

Person Contacted:

LynnVehicle IN OUT

Date/Time

Action/Instruction

10/7/19GBH 5339A :NA/LIPR003549/24D.O.A. 26/02/2019SHD 7280X :X10/7 @ 4.53 pm - Revised. preli advise via email.

ASS. REC. BY:


## ASSIGNMENT

COE Nov 2026

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 8HD7280X Yr Regn: 2018, Nov  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Prius c.c. 1798  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 51662 T/Radio: Insured / Std / NI / NA  
 Eng/No: 2ZR2B82264  
 C/No: JTDKB3FU703077512  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65 R 15  
 R: — 11 —  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Yokohama  
 Front Rear  
 R/Bal. S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 05/07/2019 D.O.I. 09/07/2019  
 Survey held at Chunni AMK  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Rear O/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG GBH 5339A
08/08/19	pinpoint 2/3 84501- with 8 day repair (Red: 8520.26 : 50%)
RECEIVED 15 AUG 2019	
	14/8/2019

Date/Time, File Pass to?

1) 14/8 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 24501-

200

11

211



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 10/07/2019

Our Ref: CS/MSG19012100/Dtf3

The Motor Claims Department  
MSIG Insurance Singapore Pte Ltd

**Without Prejudice**

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SHD 7280X**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09/07/2019 at the premises of M/s Chun Ni and have the following to report:-

Workshop Estimate Amount	: S\$ 16,407.94
Revised Estimate Amount	: S\$ 10,553.18
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

**Description of Damage:**

The vehicle sustained damages at the rear o/s portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Bryan Ang  
Licensed Appraiser

## Nivitha (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Tuesday, 9 July 2019 1:40 PM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 08072019153216.pdf  
  
**Importance:** High

### Accident involving veh no: SHD 7280X & GBH 5339A on 05.07.19

#### Manual Assigned

Dear LKK,

Refer to the email below and attachment, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,  
Crystal Lee  
Admin Officer, Claims Services (In-House Survey)  
D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Nabilah Rasol  
**Sent:** Tuesday, 9 July, 2019 11:48 AM  
**To:** 'Chunni Motor' <[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)>  
**Cc:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>; Fievel Foo <[Fievel\\_Foo@sg.msig-asia.com](mailto:Fievel_Foo@sg.msig-asia.com)>  
**Subject:** RE: Accident involving veh no: SHD 7280X & GBH 5339A on 05.07.19

Dear Sirs,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]

**Sent:** Tuesday, 9 July, 2019 9:09 AM

**To:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Cc:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>; Fievel Foo <[Fievel\\_Foo@sg.msig-asia.com](mailto:Fievel_Foo@sg.msig-asia.com)>

**Subject:** Re: Accident involving veh no: SHD 7280X & GBH 5339A on 05.07.19

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,

Chunni Motor Work P/L

On Tue, Jul 9, 2019 at 9:06 AM Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)> wrote:

Dear Sirs,

We refer to your email dated 08/07/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

4) STA Inspection Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

(a) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Moving forward, please email your survey request to [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Thank you.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)





A Member of **MS&AD** INSURANCE GROUP

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]  
**Sent:** Monday, 8 July, 2019 3:47 PM  
**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>  
**Cc:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>  
**Subject:** Accident involving veh no: SHD 7280X & GBH 5339A on 05.07.19

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

**Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.**

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

**Please appoint your In house surveyors.**

Thank you for your kind assistance.

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 10 July 2019 4:53 PM  
**To:** Admin-D (LKKAuto); 'Crystal Lee'; assignments  
**Cc:** 'Ong Zi Hui'; SUR  
**Subject:** RE: Survey Request - Manual Assigned  
**Attachments:** PRELI ADVISED SHD 7280X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 7280X**

Meanwhile, please create merimen.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 9 July 2019 2:26 PM  
**To:** 'Crystal Lee' <[crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Ong Zi Hui' <[zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Survey Request - Manual Assigned

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Crystal Lee [[mailto:crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)]  
**Sent:** Tuesday, 9 July 2019 1:40 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)  
**Cc:** Ong Zi Hui <[zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)>  
**Subject:** Survey Request - Manual Assigned  
**Importance:** High



MCDG19080711 / ComfortDelGro Engineering Pte Ltd - Loyal  
 ENTRY DATE & TIME: 09/07/2019 14:48  
 SUBMITTED BY: Huang XiaoYan

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 08/07/2019 14:48  
 Date Of Accident 05/07/2019 17:20  
 Exact Location Of Accident ADAM ROAD TWDS PIE  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD7280X  
 Insured/Policyholder  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@CDGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
 Vehicle Particulars  
 Manufacturer TOYOTA  
 Model PRIUS  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own Insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
 Insurance Company  
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088936MFSH  
 Cover Note Number  
 Driver  
 Name of Driver HENG LYE WATT  
 NRIC No S0230155E  
 Date Of Birth 17/12/1954  
 Occupation OUTDOOR  
 Date Of Driving Pass 15/01/1976  
 Driving Experience 43 YEARS AND 5 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-94485857  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Address BLK 203 BOON LAY DRIVE #07-15  
 Postcode 640203  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : -  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] JURONG WEST N.P.C  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO ATTACHED / POLICE REPORT : T/20190705/2153

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBH5339A  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver MOHD SUPRI PAGI  
 NRIC/Passport Number S7442294B  
 Contact Number 82201107  
 Address  
 Postcode  
 Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 06.07.2019@1000hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: June

## SKETCH PLAN

A- SHD 7280X  
B- GBH 5339A

Along Adam Road twds PIE

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report: T/20190705/2153

veh(B) GBH 5339A lose control and hit onto my vehicle  
rear right portion. *Heng*

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

*Heng*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 06.07.2019@1000hrs

*N.*  
Reporting Centre Personnel's Signature  
Name:

NRIC/FIN No.: June



**SINGAPORE  
POLICE FORCE**



T/20190705/2153

1 of 3

Report No. T/20190705/2153

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/07/2019 19:36		Vide Report No.:		Station Diary No.: 182	
<b>Informant's Particulars</b>					
Name of Informant: HENG LYE WATT			Address: APT BLK 203 BOON LAY DRIVE #07-15 SINGAPORE 640203		
ID Type / ID No.: NRIC NO / S0230155E			Contact No.:		Mobile: 94485857
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 17/12/1954	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 05/07/2019 17:20	Type of Location: Bend
Location: Along Road 1 ADAM ROAD				
Towards PIE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBH5339A	Van					1
SHD7280X	Car					1

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





**SINGAPORE  
POLICE FORCE**



T/20190705/2153

2 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20190705/2153

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	MOHD SUPRI PAGI	ID No.	S7442294B
Related Vehicle	GBH5339A (Van)	Contact No.	82201107
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	HENG LYE WATT	ID No.	S0230155E
Related Vehicle	SHD7280X (Car)	Contact No.	94485857
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 05/07/2019 at about 1718hrs, I was driving my taxi with one passenger along Adam Road towards PIE. When I was at the bend, I slow down my vehicle. However there is a van driving me behind my vehicle had collided on to my right portion of the vehicles. I then exited my vehicle and met up with the van driver. We then exchange particulars. At that point of time there were no one injured thus no ambulance and police were called. We decide to go for insurance claims. There is a in car camera in my vehicle.

**SINGAPORE  
POLICE FORCE**

T/20190705/2153

3 of 3

Report No. T/20190705/2153

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 66474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 MUHAMMAD AQIL BIN MOHAMMAD  
TASRIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Authentication Stamp

NP168

Singapore Police Force

Signature Of Informant:

Date/Time:

05/07/2019 19:36

Classification Of Case:



## CHUNNI MOTOR WORK PTE LTD

## REPAIR ESTIMATE

VEHICLE NO : SHD 7280X

MAKE :

MODEL : TOYOTA PRIUS

DATE : 6.07.2019

TEL NO : 6542 5119

FAX NO : 6542 6039

M16

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>Dented</i>			\$ 1,126.60
REAR TRUNK LID LOCK <i>NH</i>			\$ 447.70
REAR TRUNK LID COVER TRIM BOARD <i>NH</i>			\$ 216.50
REAR TRUNK LID RUBBER <i>Nec</i>			\$ 357.00
REAR TRUNK LID GLASS (BLACK COLOR) <i>broken</i>			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) <i>Nec</i>			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) <i>Nec</i>			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) <i>Nec</i>			\$ 52.90
REAR BUMPER <i>broken</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>Dented</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>punctured</i>			\$ 552.60
REAR BUMPER SIDE RETAINER, RH <i>NH</i>			\$ 112.70
REAR BUMPER UNDER SIDE COVER (RH) <i>Nec</i>			\$ 167.60
REAR BUMPER TOWING COVER <i>chattered / broken</i>			\$ 82.70
REAR BUMPER CLIPS <i>Nec</i>			\$ 22.00
ARM SUB-ASSY, REAR BUMPER, RH <i>NH</i>			\$ 139.60
SEAL, REAR BUMPER SIDE, RH <i>Cut</i>			\$ 148.40
TAIL LAMP ASSY (UPPER) (RH) <i>broken</i>			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) <i>broken</i>			\$ 548.40
REAR END PANEL <i>Dented</i>			\$ 602.10
REAR END PANEL GARNISH <i>minorly dented</i>			\$ 121.60
REAR SPARE TYRE PANEL <i>Dented repair</i>			\$ 667.70
REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE) <i>NH</i>			\$ 101.40
REAR FIBER TOOLS BOX TRAY <i>NH</i>			\$ 450.00
REAR EXHAUST PIPE <i>wt</i>			\$ 1,163.40
REAR EXHAUST PIPE HANGER <i>NH</i>			\$ 40.70
REAR EXHAUST PIPE INSULATOR <i>NH</i>			\$ 314.60
REAR FENDER, RH <i>Dented</i>			\$ 817.50
REAR FENDER SHEILD (RH) <i>NH</i>			\$ 134.20
REAR FENDER SIDE PANEL <i>Dented</i>			\$ 165.00
REAR FENDER AIR DUCT <i>NH</i>			\$ 165.10
REAR WINDSCREEN GLASS <i>Nec photo</i>			\$ 1,555.80
REAR WINDSCREEN GLASS MOULDING <i>NH</i>			\$ 208.60
SPOILER SUB-ASSY, REAR <i>NH</i>			\$ 953.70
SUB TOTAL			\$ 14,507.80
LESS 20% <i>25%</i>			\$ 2,901.56
DISCOUNTED TOTAL			\$ 11,606.24
REAR TRUNK LID APPS STICKER <i>Nec</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Nec</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR <i>Dent</i>			\$ 135.70
REAR BUMPER METAL PLATE <i>wt / Nec</i>			\$ 50.00
REAR WINDSCREEN SEALANT <i>Nec</i>			\$ 46.00
			\$ 331.70

10387.70

7790.77

331.70

NETT

NETT

NETT

NETT

NETT

SHD 7280X

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
<b>LABOUR CHARGE</b>			
Panel Beating			S 1,800.00 800/-
Spray Painting Charge			S 1,500.00 800/-
Wiring Charge			S 50.00 30/-
Tuff Kote			S 100.00 40/-
Remove/Refix Cushion & Upholstery Rear			S 150.00 80/-
Remove/Refix Rear Windscreen Glass			S 120.00 80/-
Remove/Refix Reverse Sensor			S 120.00 40/-
Remove/Refix Exhaust Pipe			S 150.00 60/-
Diagnosis & Resetting To Erase Fault Code			S 480.00 40/-
		1930.00	
<b>TOTAL LABOUR</b>			S 4,470.00
<b>ESTIMATE TOTAL</b>			S 16,407.94
<p>09/07/2019 @ 1630hrs</p> <p>NA Antenna</p> <p>2 items to days.</p> <p>1 Ryan</p> <p>24K Auto</p>			
<p>10052.47</p> <p>Supp 527.17</p> <p>10579.64</p> <p>L/S 8450.00</p> <p>16970.26</p>			

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 7280X (Supplementary)

MAKE :

MODEL : TOYOTA PRIUS

DATE : 10.07.2019

TEL NO : 6542 5119

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
TAIL LAMP ASSY (UPPER) (LH) <i>crack</i>			\$ 557.90 ✓
TAIL LAMP SIDE COVER (RH) <i>crack</i>			\$ 145.00 ✓
		702.90	
SUB TOTAL			\$ 702.90
LESS 20% <i>26%</i>		527.17	\$ 140.58
DISCOUNTED TOTAL			\$ 562.32
<i>yan</i> <i>2kk Auto</i> <i>8</i> <i>10/07/2019</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012100/DTF3N2

Date: 19/08/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29087313
Claimant Vehicle No :	SHD7280X	Insured Vehicle No :	GBH5339A
Date of Loss:	05/07/2019	Nature of Claim:	TP
		Claim No:	599644

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD7280X	Engine No:	2ZR2B82264
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703077512
Reg. Date:	27/11/2018 (Man. Year: 2018)	Odometer:	51662 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,500.26	8,649.65	3,850.61	30.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	1,930.00	2,540.00	56.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,970.26</b>	<b>10,579.65</b>	<b>6,390.61</b>	<b>37.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,450.00</b>		
(S\$)	16,970.26	8,450.00	8,520.26	50.21
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,187.92</b>	<b>591.50</b>	<b>596.42</b>	<b>50.21</b>
<b>Nett Amount (S\$)</b>	<b>18,158.18</b>	<b>9,041.50</b>	<b>9,116.68</b>	<b>50.21</b>

## INSPECTION

Date of Assignment: 12/07/2019

Date Inspected: 09/07/2019 Inspected At:

CHUNNI MOTOR WORK PTE LTD  
BLK 10 ANG MO KIO IND. PARK 2A,  
#03-19 AMK AUTOPOINT  
SINGAPORE 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2019)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD7280X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Dented	1,126.60 FL	*1,126.60 FL
2	1		*REAR TRUNK LID LOCK	Not Necessary	447.70 FL	*- FL
3	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	216.50 FL	*- FL
4	1		*REAR TRUNK LID RUBBER	Necessary	357.00 FL	*357.00 FL
5	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Broken	733.50 FL	*733.50 FL
6	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Broken	889.70 FL	*889.70 FL
7	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
8	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
9	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	52.90 FL	*52.90 FL
10	1		*REAR BUMPER	Broken	458.60 FL	*458.60 FL
11	1		*REAR BUMPER RE-INFORCEMENT	Dented	318.80 FL	*318.80 FL
12	1		*REAR BUMPER UNDER COVER	Punctured	552.60 FL	*552.60 FL
13	1		*REAR BUMPER SIDE RETAINER,RH	Not Necessary	112.70 FL	*- FL
14	1		*REAR BUMPER UNDER SIDE COVER (RH)	Not Necessary	167.60 FL	*- FL
15	1		*REAR BUMPER TOWING COVER	Distorted/Broken	82.70 FL	*82.70 FL
16	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*ARM SUB-ASSY,REAR BUMPER,RH	Not Necessary	139.60 FL	*- FL
18	1		*SEAL,REAR BUMPER SIDE,RH	Cut	148.40 FL	*148.40 FL
19	1		*TAIL LAMP ASSY (UPPER)(RH)	Broken	557.90 FL	*557.90 FL
20	1		*TAIL LAMP ASSY (LOWER)(RH)	Broken	548.40 FL	*548.40 FL
21	1		*REAR END PANEL	Dented	602.10 FL	*602.10 FL
22	1		*REAR END PANEL GARNISH	Mounting Deformed	121.60 FL	*121.60 FL
23	1		*REAR SPARE TYRE PANEL	Repair	667.70 FL	*- FL
24	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Not Necessary	101.40 FL	*- FL
25	1		*REAR FIBER TOOLS BOX TRAY	Not Necessary	450.00 FL	*- FL
26	1		*REAR EXHAUST PIPE	Bent	1,163.40 FL	*1,163.40 FL
27	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
28	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
29	1		*REAR FENDER,RH	Dented	817.50 FL	*817.50 FL
30	1		*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
31	1		*REAR FENDER SIDE PANEL	Dented	165.00 FL	*165.00 FL
32	1		*REAR FENDER AIR DUCT	Not Necessary	165.10 FL	*- FL
33	1		*REAR WINDSCREEN GLASS	Necessary	1,555.80 FL	*1,555.80 FL
34	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	208.60 FL	*- FL
35	1		*SPOILER SUB-ASSY,REAR	Not Necessary	953.70 FL	*- FL
36	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
37	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
38	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
39	1		*REAR BUMPER METAL PLATE	Bent/Necessary	50.00 FS	*50.00 FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*TAIL LAMP ASSY (UPPER)(LH)	Cracked	557.90 FL	*557.90 FL
42	1		*TAIL LAMP SIDE COVER (RH)	Cut	145.00 FL	*145.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					15,542.40	11,422.30
- List Item Discount on L Items 20.00/25.00% (S\$)					3,042.14	2,772.65
Total Parts (S\$)					12,500.26	8,649.65

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,500.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	150.00	60.00
9	DIAGNOSIS & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
Gross Labour Cost (\$\$)			<b>4,470.00</b>	<b>1,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >