

K. Anwar

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHD 7280X (Supplementary)

DATE : 10.07.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
TAIL LAMP ASSY (UPPER) (LH) <i>crack</i>			\$ 557.90 ✓
TAIL LAMP SIDE COVER (RH) <i>Cwt</i>			\$ 145.00 ✓
		702.90	
SUB TOTAL		527.17	\$ 702.90
LESS 20% <i>25%</i>			\$ 140.58
DISCOUNTED TOTAL			\$ 562.32
<i>ryan</i> <i>2kk Auto</i> <i>10/07/2019</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.