

ASS. REC. BY: Wilson REF: CS3/MSG17019742/Dvt3-1 Special Instruction: range

From (Person): Pauline Thiam of MSIA Date/Time: 05/07/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: SJN 3049Z Insured: SDP 86664

at Workshop no: N-51 Automotive Tel: 6842 0051

of Blk 2 Kaki Bukit, #01-17/18 Autohub 417921

Policy No: B27024536 SMP Claim No: 532799

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 12/10/2017

(Client's Record): _____

CA / REV / REP. / REV 24 HRS: 16/10/2017

Date/Time: 13/10/17 @ 4:54pm Person Contacted: Subrina H.O.D. Endorsment: _____

Vehicle: IN OUT

Date/Time	Action/Instruction / X / Estimate
	SJN 3049Z - NA / INC17019642 / r3 - D.O.A: 12/10/17
	SDP 86664 - NA / INC17019642 / r3 - D.O.A: 12/10/17
	Dismantle Part: 17.10.2017
	After Repair: 24.10.2017

06/11/17 7:14pm Email to Catherine Thia thru Marmen

MV e time of loss ~~251k~~

20k 71k

LIA

NL

13 ~~18k~~

Do Not Finalise

RECEIVED 24 JUL 2019

24/07/2019 - To submit d/s 112001 - with 8 d/s of
 reg v. (Red 8000, 4210)
 PPS photos seen. Part prices checked.

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Tuesday, 9 July 2019 10:41 AM
To: assignments
Cc: SUR; Accounts (LKKAuto)
Subject: FW: Report Send Back Alerts - SJN3049Z (TP)

CS3/MSG17019742/WBE2

Hi all,
FYNA pls.

Pending for Survey Report									
Claim Type	Branch	Claimant	Adjuster	Manager	File Ref. No.	Insurer	Repairer	RI Date	Asg Days
TP	HQ	*SJN3049Z CHEE POH YUN [SDP8666U] [SIMON LAU YUN CHEW]	Teo Cheng Ming Wilson	CATHERINE CHONG KAI LING	CS3/MSG17019742/WBE2	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	N-51 Automotive Pte Ltd (HQ)		634
12	05 Jul 2019 11:44				Ins Send Back Adj Rpt				PLEASE CONDUCT PAPER SUI
13	05 Jul 2019 11:44				Adj Next Rpt Changed				Next Rpt:Final Rpt.Due Date:
14	05 Jul 2019 11:44				Adj Mandate Set				Maintained.

Thanks & regards,
SweePeng

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 5 July 2019 12:00 PM
To: account@lkkauto.com
Subject: Report Send Back Alerts - SJN3049Z (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2700F

Vehicle Details

Vehicle No.: SJN3049Z

Vehicle to be Exported: No

Intended De-registration Date: 02 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS E MANUAL

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: 1NZXB43102

Chassis No.: MR053HY9305092851

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$11,320.00

Original Registration Date: 11 Feb 2009

First Registration Date: 11 Feb 2009

Transfer Count: 0

Actual ARF Paid: \$11,320.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Feb 2019

PARF Rebate Amount: \$6,226.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$2,693.00

COE Rebate Amount: \$275.00

Total Rebate Amount: \$6,501.00

The information contained herein is correct as at 02 Feb 2018

OK

MARKET VALUE OF MOTOR CARS
PUBLISHED DURING THE MONTH OF OCTOBER 2017

MODEL YEAR	MODEL MONTH	ADVT. DATE	MAKE/MODEL	MODEL DESCRIPTIONS	S\$ '000
2011	SEP	20.10.17	TOYOTA PREVIA		73.0
2011	SEP	23.10.17	TOYOTA PREVIA		73.0
2011	SEP	24.10.17	TOYOTA PREVIA		73.0
2011	SEP	25.10.17	TOYOTA PREVIA		73.0
2011	SEP	26.10.17	TOYOTA PREVIA		73.0
2011	SEP	27.10.17	TOYOTA PREVIA		73.0
2008	DEC	11.10.17	TOYOTA RUSH 1.5A		20.8
2008	DEC	12.10.17	TOYOTA RUSH 1.5A		20.8
2009	JAN	16.10.17	TOYOTA RUSH 1.5A		21.0
2009	JAN	17.10.17	TOYOTA RUSH 1.5A		21.0
2009	JAN	18.10.17	TOYOTA RUSH 1.5A		21.0
2009	JAN	19.10.17	TOYOTA RUSH 1.5A		21.0
2009	JAN	20.10.17	TOYOTA RUSH 1.5A		21.0
2008		20.10.17	TOYOTA SIENTA		37.0
2008		23.10.17	TOYOTA SIENTA		37.0
2008		24.10.17	TOYOTA SIENTA		37.0
2008		25.10.17	TOYOTA SIENTA		37.0
2008		26.10.17	TOYOTA SIENTA		37.0
2008		27.10.17	TOYOTA SIENTA		37.0
2006	MAR	10.10.17	TOYOTA VIOS 1.5A		28.0
2006	MAR	11.10.17	TOYOTA VIOS 1.5A		28.0
2006	MAR	12.10.17	TOYOTA VIOS 1.5A		28.0
2006	MAR	13.10.17	TOYOTA VIOS 1.5A		28.0
2006	MAR	16.10.17	TOYOTA VIOS 1.5A		28.0
2009	NOV	16.10.17	TOYOTA VIOS 1.5A		33.9
2009	NOV	17.10.17	TOYOTA VIOS 1.5A		33.9
2009	NOV	18.10.17	TOYOTA VIOS 1.5A		33.9
2009	NOV	19.10.17	TOYOTA VIOS 1.5A		33.9
2009	NOV	20.10.17	TOYOTA VIOS 1.5A		33.9
2010	FEB	06.10.17	TOYOTA VIOS 1.5A		29.9
2010	FEB	09.10.17	TOYOTA VIOS 1.5A		29.9
2010	FEB	10.10.17	TOYOTA VIOS 1.5A		29.9
2010	FEB	11.10.17	TOYOTA VIOS 1.5A		29.9
2010	FEB	12.10.17	TOYOTA VIOS 1.5A		29.9
2010	MAY	02.10.17	TOYOTA VIOS 1.5A		34.8
2010	MAY	03.10.17	TOYOTA VIOS 1.5A		34.8
2010	MAY	04.10.17	TOYOTA VIOS 1.5A		34.8
2010	MAY	05.10.17	TOYOTA VIOS 1.5A		34.8

Note: Price quoted are as published in the classified section of local newspaper. Listed price are asking price of vehicles and discount have to be considered for the Market Value.

PAR Automotive Consultancy

Regn. No. 52986774L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0251-19-N51

06 May 2019

ACCIDENT VEHICLE SURVEY REPORT

Chiee Poh Yun
Blk 2010 Compassvale Drive #13-561
Singapore 544021

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJN3049Z	<i>Odometer:</i>	239949km
<i>Make & Model:</i>	Toyota Vios E	<i>Colour:</i>	Red
<i>Chassis number:</i>	MR053HY9305092851	<i>Date of accident:</i>	12/10/2017
<i>Year of Regn.:</i>	11/02/2009	<i>Date inspected:</i>	16/10/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	24/10/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Report No: 0251-19-N51

06 May 2019

ACCIDENT VEHICLE SURVEY REPORT

Chee Poh Yun
Blk 2010 Compassvale Drive #13-561
Singapore 544021

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SJN3049Z	<i>Odometer:</i>	239949km
<i>Make & Model:</i>	Toyota Vios E	<i>Colour:</i>	Red
<i>Chassis number:</i>	MR053HY9305092851	<i>Date of accident:</i>	12/10/2017
<i>Year of Regn.:</i>	11/02/2009	<i>Date inspected:</i>	16/10/2017
	N-51 Automotive Pte Ltd	<i>Date inspected (After Repair):</i>	24/10/2017
	2 Kaki Bukit Ave 2 #01-18		
	Kaki Bukit Auto Hub		
	Singapore 417921		

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Yokohama	5mm/Yokohama	185/60R15
<i>Rear:</i>	5mm/Yokohama	5mm/Yokohama	185/60R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR AXLE CARRIAGE	1	distorted	2,013.10	2,013.10 NH
REAR BOOTLID	1	buckled	720.60	720.60 ✓
REAR BOOTLID 'E' EMBLEM	1	necessary	51.10	51.10 ✓
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	53.90	53.90 ✓
REAR BOOTLID 'VIOS' EMBLEM	1	necessary	51.50	51.50 ✓
REAR BOOTLID HINGES L/R	2	bent	364.50	152.40 364.50 ✓
REAR BOOTLID HINGES TORSION SPRING L/R	2	reuse	512.00	0.00 NH
REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	1	deformed	374.45	374.45 ✓
REAR BOOTLID MECHANISM LOCK	1	bent	381.90	381.90 ✓
REAR BOOTLID MECHANISM LOCK CABLE	1	reuse	172.25	0.00 NH
REAR BOOTLID MECHANISM LOCK STRIKER	1	bent	43.55	43.55 ✓
REAR BOOTLID OUTER GARNISH	1	fractured	281.70	281.70 ✓
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	87.80	87.80 NH
REAR BOOTLID WEATHERSTRIP	1	deformed	185.10	185.10 ✓
REAR BUMPER	1	squashed	374.45	374.45 ✓
REAR BUMPER BRACKET L/R	2	bent	262.70	66.40 262.70 ✓
REAR BUMPER END SEAL COVER L/R	2	deformed	283.00	283.00 NH
REAR BUMPER REFLECTOR L/R	2	fractured	357.70	357.70 ✓
REAR BUMPER SIDE CORNER BRACKET L/R	2	bent	288.90	288.90 NH
REAR BUMPER SIDE RETAINER L/R	2	necessary	282.90	282.90 NH
REAR CHASSIS SUB FRAME L/R	2	R-bent	1,390.00	695.00 ✓
REAR END PANEL	1	buckled	781.90	781.90 ✓
REAR END PANEL INENR TOP GARNISH	1	fractured	374.20	245.50 374.20 ✓
REAR EXHAUST ALUMINIUM HEAT SHIELD	1	deformed	270.40	270.40 ✓
REAR EXHAUST CHROME TAIL PIPE	1	distorted	182.25	86.70 182.25 ✓
REAR EXHAUST GASKET	1	necessary	61.10	61.10 ✓
REAR EXHAUST RUBBER MOUNTING	3	distorted	191.70	191.70 NH
REAR EXHAUST SILENCER BOX	1	bent	771.10	771.10 ✓
REAR FENDER INNER PANEL L/R	2	buckled	1,304.00	1,304.00 R
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	763.80	763.80 ✓
REAR FENDER L/R	2	buckled	1,956.20	1,956.20 ✓
REAR FENDER OUTER PANEL L/R	2	R-buckled	1,556.00	778.00 R
REAR FLOOR PANEL CENTER TOP SPONGE	1	deformed	378.20	378.20 ✓
REAR LH FENDER AIR VENT	1	warped	189.20	189.20 ✓
REAR LH SPARE TYRE TOP SPONGE	1	deformed	377.25	377.25 ✓
REAR LH SPARE TYRE TOP SPONGE BOARD COVER	1	fractured	68.50	68.50 ✓
REAR NUMBER PLATE LAMP L/R	2	fractured	242.50	242.50 ✓
REAR RH DOOR	1	repair	978.00	0.00 R
REAR RH DOOR MECHANISM LOCK	1	bent	389.10	389.10 NH
REAR RH DOOR WEATHERSTRIP	1	deformed	196.70	196.70 NH
REAR RH SPARE TYRE TOP SPONGE	1	deformed	381.90	381.90 ✓
REAR RH SPARE TYRE TOP SPONGE BOARD COVER	1	fractured	68.50	68.50 ✓

PAR Automotive Consultancy

REAR SHOCK ABSORBER L/R	2	R-bent	523.40	261.70	NAH
REAR SPARE TYRE INNER TOP CARDBOARD COVER	1	fractured	172.10	172.10	✓
REAR SPARE TYRE PANEL	1	buckled	987.30	881.90	987.30 ✓
REAR SPARE TYRE PANEL WHEEL CLAMP	1	na	61.30	0.00	NAH
REAR SPARE TYRE RETAINER LOCK	1	bent	61.30	61.30	✓
REAR SPARE TYRE SIDE EXTENSION PANEL L/R	2	buckled	338.00	338.00	✓
REAR SPEAKER PANEL	1	repair	886.00	0.00	R
REAR TAILLAMP BACK RUBBER GASKET L/R	2	necessary	122.20	122.20	NAH
REAR TAILLAMP INNER PANEL L/R	2	buckled	462.40	462.40	✓
REAR TAILLAMP L/R	2	broken	760.00	760.00	✓
REAR WHEEL BEARING L/R	2	R-dislodged	1,496.00	748.00	NAH
REAR WINDSCREEN GLASS MOULDING	1	necessary	189.20	189.20	✓

13297.40
9973.05

Subtotal before discount S\$ 26,074.80 S\$ 20,982.55

Percentage discount 25% and 25% S\$ 6,518.70 S\$ 5,245.64

Sub-total 1 S\$ 19,556.10 S\$ 15,736.91

REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	50.00	20/-	50.00 ✓
REAR BOOTLID OUTER GARNISH CLIPS - SET	1	necessary	30.00	10/-	30.00 ✓
REAR BUMPER CLIPS - SET	1	necessary	50.00	20/-	50.00 ✓
REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	necessary	60.00		60.00 NAH
REAR BUMPER REVERSE SENSOR	1	shorted	350.00	230/-	350.00 ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	10/-	30.00 ✓
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	30/-	60.00 ✓
REAR NUMBER PLATE	1	bent	25.00		25.00 ✓
REAR NUMBER PLATE HOLDER	1	bent	50.00	45/-	50.00 ✓
REAR SPARE TYRE	1	reuse	280.00		0.00
REAR SPEAKER PANEL BOARD CLIPS - SET	1	necessary	50.00		50.00 NAH
REAR TAILLAMP CLIPS L/R - SET	2	necessary	60.00		40.00 NAH
REAR WINDSCREEN GLASS SEALANT	1	necessary	80.00	40/-	80.00 ✓

395.00

Subtotal before discount S\$ 1,175.00 S\$ 875.00

Sub-total 2 S\$ 1,175.00 S\$ 875.00

Parts-total S\$ 20,731.10 S\$ 16,611.91

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00	60.00 30/-
To remove, reinstall windscreen. (to FR)	120.00	120.00 30/-
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	500.00	400.00 150/-
To road test driving, check and resetting wheel alignments system.	180.00	180.00 60/-
To remove, reinstall petrol tank. (to FR)	80.00	80.00 40/-
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	120.00 80/-
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	100.00	80.00 40/-
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,000.00	1,760.00 1400/-
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	150.00	120.00 60/-
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,000.00	2,500.00 1600/-
To mount vehicle on to Car 'O' Liner.	400.00	400.00 150/-
To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00 40/-
	Labour Total	SS 6,870.00 SS 5,940.00
	Parts & Labour Total	SS 27,601.10 SS 22,551.91

3650/-

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 19,200.00 and the recommended number of working days for the repairs is within 13 day(s).



B J Loi (J Eng, MIMI, AIRTE)
Automotive Appraiser

14018-05

4/5 11200/-

8 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 2700F

Vehicle Details

Vehicle No.: SJN3049Z
 Vehicle to be Exported: No
 Intended De-registration Date: 02 Feb 2018
 Vehicle Make: TOYOTA
 Vehicle Model: VIOS E MANUAL
 Primary Colour: Red
 Manufacturing Year: 2008
 Engine No.: 1NZX843102
 Chassis No.: MR053HY9305092851
 Maximum Power Output: 80.0 kW (107 bhp)
 Open Market Value: \$11,320.00
 Original Registration Date: 11 Feb 2009
 First Registration Date: 11 Feb 2009
 Transfer Count: 0
 Actual ARF Paid: \$11,320.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 10 Feb 2019
 PARF Rebate Amount: \$6,226.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2019
 COE Category: A - Car (1600cc & below)
 COE Period(Years): 10
 QP Paid: \$2,693.00
 COE Rebate Amount: \$275.00
Total Rebate Amount: \$6,501.00

The information contained herein is correct as at 02 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/10/2017 15:38
Date Of Accident	12/10/2017 09:45
Exact Location Of Accident	PIE TWDS TUAS B4 ENG NEO EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN3049Z
Insured/Policyholder	
Name Of Registered Owner	CHEE POH YUN
NRIC No	S7372700F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93867812
Alternative Phone No	OTHERS-93867812

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5042093911-07
Cover Note Number	

Driver

Name of Driver	POH JOO ANN
NRIC No	S1748699C
Date Of Birth	01/05/1966
Occupation	OUTDOOR
Date Of Driving Pass	22/04/1988
Driving Experience	29 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97390448
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 201D COMPASSVALE DR #13-561
Postcode	544201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDP8666U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	POH JOO ANN
------	-------------

Approximate Age

Injuries Sustain

SLIGHT

Injured person in which vehicle?

SJN3049Z

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the Claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(if driver is not the policyholder)
Date & Time

Report Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

R10 toward town before they blew exit



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time I was driving along R10 toward town on the 3 lane of a 5 lanes expressway somewhere before you see exit, vehicle ahead of me slowed down and stopped due to heavy traffic flow. As such I applied brake and stopped accordingly. Out of the sudden, vehicle B (SDP 8000 U) came from the rear and collided directly into the rear portion of my vehicle.

A - SJN 3049 E

B - SDP 8000 U

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]
 Policyholder's signature
 Date & Time

[Signature]
 Driver's signature
 (if driver is not the policyholder)
 Date & Time

[Signature] 12/10/17
 Reporting Officer's signature
 Name
 SANCIN No

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/10/2017 12:30
Date Of Accident	12/10/2017 09:50
Exact Location Of Accident	BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDP8666U
Insured/Policyholder	
Name Of Registered Owner	SIMON LAU YUN CHEW
NRIC No	S1369415Z
Email Address	SIMON@TELAHIN.COM
Mobile Phone No	(LOCAL) +65-97923633
Alternative Phone No	Office-62703367

Vehicle Particulars

Manufacturer	BMW
Model	523
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27024536SMP
Cover Note Number	

Driver

Name of Driver	SIMON LAU YUN CHEW
NRIC No	S1369415Z
Date Of Birth	27/10/1959
Occupation	INDOOR
Date Of Driving Pass	11/07/1986
Driving Experience	31 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97923633

Fax Number	
Contact Number	OFFICE-62703367
Email Address	SIMON@TELAHIN.COM
Address	7 JERVOIS CLOSE#04-12
Postcode	249103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN3049Z
Vehicle Make/Model/Colour	TOYOTA VIOS RED COLOR
Details Of Properties	
Name of Driver	MR POH JOO ANN
NRIC/Passport Number	
Contact Number	97390448
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	1

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquires by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/parcel packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be based outside of Singapore, for one or more of the above Purposes.


12/10/2017

Policyholder's Signature / Date & Time
0950 AM


MERINA CHIA SAN SAN
Performance Motors Limited
303 Aljunied Road
Sime Darby Performance Centre
Singapore 439941

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

12 OCT 2017

Sketch Plan



BKE

Describe Circumstances of the Accident

While driving, there was an accident on the opposite side of the road.

Cars in front were taking a look on the right as usual.

Suddenly, the car in front jam brake.

I had to jam brake as well but it was too late as I could not brake hard enough to stop the vehicle as the road was wet, after a down-pour.

Declaration

I/we declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


Witnessed by Reporting Centre Personnel
12 OCT 2017

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2017		13 Oct 2017 16:26 Edit Adj Rpt	S\$11,200.00 Edit Estimates	S\$11,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SIMON LAU YUN CHEW , ID: S1369415Z, Tel: +6597923633, Email: SIMON@TELAHIN.COM								
Main Claimant:	CHEE POH YUN , ID: S7372700F								
Vehicle Reg. No.:	SJN3049Z	Date of Loss:	12/10/2017 09:00 - :59 [104 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 532799	Policy/Cover Note No.:	B27024536SMP (Comprehensive) Coverage: 29/12/2016 - 28/12/2017						
Vehicle Reg. No. (Insured):	SDP8666U	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 09/07/2019]								
Driver/Custodian (Insured):	SIMON LAU YUN CHEW (57 / Male) , NRIC: S1369415Z, Tel: +6597923633 Email: SIMON@TELAHIN.COM								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> MSIG_SG (05/07/2019): Report Send Back Alerts - SJN3049Z (TP) 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN3049Z (532799)
 [SDP8666U]
 TP
 CHEE POH YUN
 Oct 12 2017 9:00AM
 [SIMON LAU YUN CHEW]
 N-51 Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View	
						View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	13/10/17 16:25	Accident Statement From:DD - Reg. No: SDP8666U, Claimant: SIMON LAU YUN CHEW			Load HTM	<input type="checkbox"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	06/11/17 19:12	Odometer Reading			Load JPG	<input checked="" type="checkbox"/>	
2	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
3	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
4	06/11/17 19:12	Chassis Number			Load JPG	<input checked="" type="checkbox"/>	
5	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
6	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
7	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
8	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
9	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
10	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
11	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
12	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
13	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
14	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
15	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
16	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
17	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
18	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
19	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
20	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
21	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
22	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
23	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
24	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
25	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
26	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
27	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
28	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
29	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
30	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
31	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
32	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	
33	06/11/17 19:12	General View			Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
35	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
36	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
37	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
38	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
39	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
40	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
41	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
42	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
43	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
44	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
45	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
46	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
47	06/11/17 19:12	General View		<input checked="" type="checkbox"/>
48	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
72	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
73	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
74	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
75	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
77	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	06/11/17 19:12	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	06/11/17 19:13	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	06/11/17 19:13	Photo After Spray		<input checked="" type="checkbox"/>
98	06/11/17 19:13	Photo After Spray		<input checked="" type="checkbox"/>
99	06/11/17 19:13	Photo After Spray		<input checked="" type="checkbox"/>
100	06/11/17 19:13	Photo After Spray		<input checked="" type="checkbox"/>
101	06/11/17 19:13	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/10/17 14:38	TPD SJN3049Z GIA REPORT		<input type="checkbox"/>
2	13/10/17 14:38	EMAIL TP FOR 10 SURYVEORS -SJN3049Z		<input type="checkbox"/>
3	13/10/17 14:38	PRI - SJN3049Z		<input type="checkbox"/>
4	13/10/17 16:26	Survey Disagreement email from TP -SJN3049Z.		<input type="checkbox"/>
5	13/10/17 16:26	PRI SJE REJECT EMAIL-SJN3049Z		<input type="checkbox"/>
6	13/10/17 16:38	workshop details -SJN3049Z		<input type="checkbox"/>
7	05/07/19 11:44	LOD - SURVEY REPORT		<input type="checkbox"/>
8	05/07/19 11:44	LOD - SURVEY PHOTOS 1		<input type="checkbox"/>
9	05/07/19 11:44	LOD - SURVEY PHOTOS 2		<input type="checkbox"/>
10	05/07/19 11:44	LOD - SURVEY PHOTOS 3		<input type="checkbox"/>
11	05/07/19 11:44	LOD - SURVEY PHOTOS 4		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 08:49	Colour Photo		<input type="checkbox"/>
2	25/07/19 08:49	PRS Invoice		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17019742/DVF3E2-1
Date: 25/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27024536SMP
Claimant Vehicle No : SJN3049Z	Insured Vehicle No :	SDP8666U
Date of Loss: 12/10/2017	Nature of Claim:	TP Claim No: 532799

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3049Z	Engine No:	1NZX843102
Make & Model:	TOYOTA VIOS EA, 1.5 (A)	Chassis No:	MR053HY9305092851
Reg. Date:	11/02/2009 (Man. Year: 2008)	Odometer:	239949 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Bluearth 3 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Bluearth 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,731.10	10,368.05	10,363.05	49.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	3,650.00	3,220.00	46.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,601.10	14,018.05	13,583.05	49.21
Approved Total (Overridden) (S\$)		11,200.00		
(S\$)	27,601.10	11,200.00	16,401.10	59.42
+ GST 7.00/7.00% (S\$)	1,932.08	784.00	1,148.08	59.42
Nett Amount (S\$)	29,533.18	11,984.00	17,549.18	59.42

INSPECTION

Date of Assignment:	13/10/2017	
Date Inspected:	16/10/2017 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	8.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2019)
Parts: 143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN3049Z)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR AXLE CARRIAGE	Not Necessary	2,013.10 FL	*- FL
2	1		*REAR BOOTLID	Buckled	720.60 FL	*720.60 FL
3	1		*REAR BOOTLID E EMBLEM	Necessary	51.10 FL	*51.10 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	53.90 FL	*53.90 FL
5	1		*REAR BOOTLID VIOS EMBLEM	Necessary	51.50 FL	*51.50 FL
6	2		*REAR BOOTLID HINGES L/R	Bent	364.50 FL	*152.40 FL
7	2		*REAR BOOTLID HINGES TORSION SPRING L/R	Not Necessary	512.00 FL	*- FL
8	1		*REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	Deformed	374.45 FL	*374.45 FL
9	1		*REAR BOOTLID MECHANISM LOCK	Bent	381.90 FL	*381.90 FL
10	1		*REAR BOOTLID MECHANISM LOCK CABLE	Not Necessary	172.25 FL	*- FL
11	1		*REAR BOOTLID MECHANISM LOCK STRIKER	Bent	43.55 FL	*43.55 FL
12	1		*REAR BOOTLID OUTER GARNISH	Fractured	281.70 FL	*281.70 FL
13	2		*REAR BOOTLID RUBBER GUIDE STOPPER L/R	Not Necessary	87.80 FL	*- FL
14	1		*REAR BOOTLID WEATHERSTRIP	Deformed	185.10 FL	*185.10 FL
15	1		*REAR BUMPER	Squashed	374.45 FL	*374.45 FL
16	2		*REAR BUMPER BRACKET L/R	Bent	262.70 FL	*66.40 FL
17	2		*REAR BUMPER END SEAL COVER L/R	Not Necessary	283.00 FL	*- FL
18	2		*REAR BUMPER REFLECTOR L/R	Fractured	357.70 FL	*357.70 FL
19	2		*REAR BUMPER SIDE CORNER BRACKET L/R	Not Necessary	288.90 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	282.90 FL	*- FL
21	1		*REAR CHASSIS SUB FRAME L/R	N/S Repair / O/S Bent	1,390.00 FL	*695.00 FL
22	1		*REAR END PANEL	Buckled	781.90 FL	*781.90 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Fractured	374.20 FL	*245.50 FL
24	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Deformed	270.40 FL	*270.40 FL
25	1		*REAR EXHAUST CHROME TAIL PIPE	Distorted	182.25 FL	*86.70 FL
26	1		*REAR EXHAUST GASKET	Necessary	61.10 FL	*61.10 FL
27	3		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	191.70 FL	*- FL
28	1		*REAR EXHAUST SILENCER BOX	Bent	771.10 FL	*771.10 FL
29	2		*REAR FENDER INNER PANEL L/R	Repair	1,304.00 FL	*- FL
30	2		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Deformed	763.80 FL	*763.80 FL
31	2		*REAR FENDER L/R	Buckled	1,956.20 FL	*1,956.20 FL
32	2		*REAR FENDER OUTER PANEL L/R	Repair	1,556.00 FL	*- FL
33	1		*REAR FLOOR PANEL CENTER TOP SPONGE	Deformed	378.20 FL	*378.20 FL
34	1		*REAR LH FENDER AIR VENT	Warped	189.20 FL	*189.20 FL
35	1		*REAR LH SPARE TYRE TOP SPONGE	Deformed	377.25 FL	*377.25 FL
36	1		*REAR LH SPARE TYRE TOP SPONGE BOARD COVER	Fractured	68.50 FL	*68.50 FL
37	2		*REAR NUMBER PLATE LAMP L/R	Fractured	242.50 FL	*242.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR RH DOOR	Repair	978.00 FL	*- FL
39	1		*REAR RH DOOR MECHANISM LOCK	Not Necessary	389.10 FL	*- FL
40	1		*REAR RH DOOR WEATHERSTRIP	Not Necessary	196.70 FL	*- FL
41	1		*REAR RH SPARE TYRE TOP SPONGE	Deformed	381.90 FL	*381.90 FL
42	1		*REAR RH SPARE TYRE TOP SPONGE BOARD COVER	Fractured	68.50 FL	*68.50 FL
43	2		*REAR SHOCK ABSORBER L/R	Not Necessary	523.40 FL	*- FL
44	1		*REAR SPARE TYRE INNER TOP CARDBOARD COVER	Fractured	172.10 FL	*172.10 FL
45	1		*REAR SPARE TYRE PANEL	Buckled	987.30 FL	*881.90 FL
46	1		*REAR SPARE TYRE PANEL WHEEL CLAMP	Not Necessary	61.30 FL	*- FL
47	1		*REAR SPARE TYRE RETAINER LOCK	Bent	61.30 FL	*61.30 FL
48	2		*REAR SPARE TYRE SIDE EXTENSION PANEL L/R	Buckled	338.00 FL	*338.00 FL
49	1		*REAR SPEAKER PANEL	Repair	886.00 FL	*- FL
50	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Not Necessary	122.20 FL	*- FL
51	2		*REAR TAILLAMP INNER PANEL L/R	Buckled	462.40 FL	*462.40 FL
52	2		*REAR TAILLAMP L/R	Broken	760.00 FL	*760.00 FL
53	2		*REAR WHEEL BEARING L/R	Not Necessary	1,496.00 FL	*- FL
54	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	189.20 FL	*189.20 FL
55	1		*SET REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
56	1		*SET REAR BOOTLID OUTER GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
57	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
58	2		*SET REAR BUMPER END SEAL COVER CLIPS L/R	Not Necessary	60.00 FS	*- FS
59	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*220.00 FS
60	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
61	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Necessary	60.00 FS	*30.00 FS
62	1		*REAR NUMBER PLATE HOLDER }	Bent	50.00 FS	*45.00 FS
63	1		*REAR NUMBER PLATE }		25.00 FS	*- FS
64	1		*REAR SPARE TYRE	Reuse	280.00 FS	*- FS
65	1		*SET REAR SPEAKER PANEL BOARD CLIPS	Not Necessary	50.00 FS	*- FS
66	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*- FS
67	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 27,249.80 13,692.40
 - List Item Discount on L Items 25.00/25.00% (\$\$) 6,518.70 3,324.35

Total Parts (\$\$) 20,731.10 10,368.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	80.00	30.00
2	TO REMOVE, REINSTALL WINDSCREEN (TO FR)	New	120.00	80.00
3	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	500.00	150.00
4	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00
5	TO REMOVE, REINSTALL PETROL TANK (TO FR)	New	80.00	0.00
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	80.00
7	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	100.00	0.00
8	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	2,000.00	1,400.00
9	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	150.00	60.00
10	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	3,000.00	1,600.00
11	TO MOUNT VEHICLE ON TO CAR O LINER	New	400.00	150.00
12	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
Gross Labour Cost (S\$)			6,870.00	3,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >