

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

07/07/2019

Owner: LE MOTOR CAR RENTAL PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLM1555Z

1pc	rear tailgate	Pr	\$ 1,100.90	✓
1pc	rear tailgate"HONDA" logo	Pr	\$ 27.00	X
1pc	rear tailgate"VEZEL" emble	Pr	\$ 55.10	✓
1set	rear tailgate windscreen moulding	Pr	\$ 120.00	✓
1pc	rear tailgate outer garnish	Pr	\$ 220.30	X
2pcs	rear tailgate reflector @\$350.80	o/s Pr	\$ 701.60	X
1pc	rear tailgate inner lock	Pr	\$ 198.40	✓
1pc	rear tailgate inner rubber	Pr	\$ 135.20	✓
1pc	rear tailgate inner garnish		\$ 252.70	?
1pc	rear tailgate inner handle garnish	Pr	\$ 20.70	✓
2pcs	rear taillamp @\$460.60	o/s Pr	\$ 921.20	X
1pc	rear bumper	Pr	\$ 986.30	✓
2pcs	rear bumper side bumper @\$195.20		\$ 390.40	?
2pcs	rear bumper side retainer @\$24.80		\$ 49.60	?
2pcs	rear bumper reflector @\$151.50	Pr	\$ 303.00	X
1pc	rear end panel		\$ 530.90	?
1pc	rear end panel inner garnish	Pr	\$ 285.50	✓
1pc	rear end panel inner sensor		\$ 195.50	?
1pc	rear end panel outer sensor		\$ 180.25	?
1pc	rear spare trye panel	Pr	\$ 1,130.60	✓
1pc	rear spare trye inner sponge	Pr	\$ 485.50	✓
			\$ 8,290.65	
	less 20%		\$ 1,658.13	
	balance c/f		\$ 6,632.52	
1set	rear reverse sensor	Pr	\$ 280.00	200.00
1set	rear number plate & casing	Pr	\$ 50.00	X
	remove & refix rear windscreen glass		\$ 120.00	✓
	wiring		\$ 150.00	200
	tuffkote		\$ 180.00	600
	sealant	Pr	\$ 100.00	400.00
	spray painting		\$ 1,200.00	600
	labour charges		\$ 1,200.00	600
	Total		\$ 9,912.52	

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

