

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G****AAD1907-050***Not Authorized  
61 Sng @ 3100*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

08 JUL 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC 5774G**

VF1ABL15AUC281616

RENAULT

LATITUDE

3.7.19

**CHINA TAIPING**

10/7/2015

| PART |                                 | LIST |                      |
|------|---------------------------------|------|----------------------|
| 1    | BUMPER COVER FRT                | \$   | <i>Bu</i> 1,259.42 ✓ |
| 1    | BUMPER SPOILER FRT              | \$   | <i>SL</i> 181.75     |
| 1    | BUMPER ABSORBER FRT             | \$   | <i>SL</i> 394.68     |
| 1    | BUMPER RETAINER FRT LH          | \$   | <i>SL</i> 151.41     |
| 1    | BUMPER SUPPORT FRT              | \$   | <i>SL</i> 123.88     |
| 1    | BUMPER UNDERTRAY FRT            | \$   | <i>SL</i> 472.83     |
| 1    | BUMPER GRILLE LOWER FRT         | \$   | <i>SL</i> 266.80     |
| 1    | BUMPER FOG LAMP GRILLE LH       | \$   | <i>SL</i> 207.21     |
| 1    | BUMPER BEAM FRT                 | \$   | <i>N</i> 914.08      |
| 1    | HEADLAMP LH                     | \$   | <i>ng</i> 1,184.43 ✓ |
| 1    | HEADLAMP PANEL FRT LH           | \$   | <i>N</i> 152.15 X    |
| 1    | FENDER PANEL FRT LH             | \$   | <i>B</i> 783.83 ✓    |
| 1    | WHEELARCH FRT LH                | \$   | <i>SL</i> 278.84     |
| 1    | FENDER BRACKET LOWER LH         | \$   | <i>SL</i> 15.79      |
| 1    | FENDER INSULATOR LH             | \$   | <i>SL</i> 130.84     |
| 1    | FRONT BRACE PANEL               | \$   | <i>N</i> 177.22      |
| 1    | RADIATOR GRILLE                 | \$   | <i>SL</i> 1,707.78   |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | <i>SL</i> 225.36     |
| 1    | RADIATOR GRILLE FRAME           | \$   | <i>SL</i> 1,353.75   |
| 1    | FRAME FULL SUPPORT PANEL        | \$   | <i>SL</i> 615.90     |
| 1    | FRAME FULL SUPPORT BRACKET      | \$   | <i>N</i> 89.79       |
| 1    | BONNET                          | \$   | <i>N</i> 1,941.63    |
| 1    | BONNET INSULATOR                | \$   | <i>SL</i> 405.73     |
| 1    | BONNET STRUT LH                 | \$   | <i>SL</i> 88.61      |
| 1    | BONNET STRUT RH                 | \$   | <i>SL</i> 88.61      |
| 1    | BONNET HINGE LH                 | \$   | <i>N</i> 348.31      |
| 1    | BONNET HINGE RH                 | \$   | <i>N</i> 348.31      |
| 1    | BONNET LOCK                     | \$   | <i>N</i> 305.48      |
| 1    | BONNET CABLE                    | \$   | <i>SL</i> 119.19     |

**Trans-cab Auto Services Pte Ltd**

AAD1907-050

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

|       |                               |    |                |           |   |   |  |
|-------|-------------------------------|----|----------------|-----------|---|---|--|
| 1     | BONNET CABLE COVER            | \$ | S <sub>L</sub> | 161.03    | } | X |  |
| 1     | BONNET SEAL OUTER             | \$ | S <sub>L</sub> | 92.36     |   |   |  |
| 1     | BONNET SEAL INNER             | \$ | S <sub>L</sub> | 157.28    |   |   |  |
| 1     | AIR CLEANER BOX               | \$ | S <sub>L</sub> | 464.20    |   |   |  |
| 1     | AIR CLEANER HOSE              | \$ | S <sub>L</sub> | 175.85    |   |   |  |
| 1     | AIR CLEANER LOWER             | \$ | S <sub>L</sub> | 271.26    |   |   |  |
| 1     | DOOR PANEL FRT LH             | \$ | H              | 2,844.66  |   |   |  |
| 1     | DOOR MIRROR ASSY LH           | \$ | S <sub>L</sub> | 1,483.40  |   |   |  |
| 1     | DOOR HARNESS WIRE LH          | \$ | S <sub>L</sub> | 2,670.00  |   |   |  |
| 1     | ROCKER PANEL INNER GARNISH LH | \$ | S <sub>L</sub> | 466.51    |   |   |  |
| 1     | ROCKER PANEL INNER LH         | \$ | H              | 1,024.79  |   |   |  |
| 1     | ROCKER PANEL OUTER LH         | \$ | H              | 1,184.99  |   |   |  |
| 1     | ROCKER PANEL CENTER LH        | \$ | H              | 990.25    |   |   |  |
| TOTAL |                               | \$ |                | 26,320.18 |   |   |  |
| 10%   |                               | \$ |                | 2,632.02  |   |   |  |
|       |                               | \$ |                | 23,688.16 |   |   |  |

**Special Nett**

|      |                                    |    |                |        |   |   |
|------|------------------------------------|----|----------------|--------|---|---|
| 1    | BUMPER CLIP FRT                    | \$ | na             | 66.00  | } | X |
| 1    | BUMPER BRACKET CLIP FRT LH         | \$ | na             | 12.00  |   |   |
| 1    | BUMPER SUPPORT CLIP FRT LH         | \$ | na             | 10.50  |   |   |
| 1    | BUMPER GRILLE LOWER CLIP           | \$ | na             | 69.00  |   |   |
| 1SET | FRAME FULL SUPPORT PANEL CLIP      | \$ | na             | 70.00  |   |   |
| 2    | FRAME FULL SUPPORT PANEL NUT       | \$ | na             | 20.00  |   |   |
| 2    | FRAME FULL SUPPORT PANEL STUD      | \$ | na             | 30.00  |   |   |
| 1    | WHEELARCH CLIP FRT LH              | \$ | na             | 30.50  |   |   |
| 1    | FRONT LEFT TYRE                    | \$ | S <sub>h</sub> | 300.00 |   |   |
| 1    | FRONT LEFT TYRE RIM                | \$ | S <sub>h</sub> | 380.00 |   |   |
| 1SET | Front licence plate with holder    | \$ | S <sub>h</sub> | 80.00  |   |   |
| 1    | WINDSCREEN SEALANT                 | \$ | na             | 253.80 |   |   |
| 1    | FRONT WINDSCREEN MOULDING          | \$ | na             | 120.00 |   |   |
| 1    | FRONT WINDSCREEN INNER SPONGE SEAL | \$ | na             | 100.00 |   |   |
| 6    | BONNET INSULATOR CLIP L70Y         | \$ | na             | 7.30   |   |   |
| 2    | BONNET STRUT L70Y                  | \$ | na             | 88.61  |   |   |
| 2    | BONNET CABLE CLIP L70Y             | \$ | na             | 6.31   |   |   |
| 2    | BONNET CABLE COVER SCREW L70Y      | \$ | na             | 10.85  |   |   |
| 1SET | RADIATOR GRILLE FRAME CLIP         | \$ | na             | 52.00  |   |   |
| 1SET | RADIATOR GRILLE SCREW              | \$ | na             | 16.00  |   |   |

**Trans-cab Auto Services Pte Ltd****AAD1907-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

|   |                                |    |                   |
|---|--------------------------------|----|-------------------|
| 1 | FRONT DOOR STICKER 'Trans-Cab' | \$ | <i>nn</i> 80.00 X |
| 1 | FRONT DOOR STICKER 'Classic'   | \$ | <i>nn</i> 80.00 X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,882.88</b> |
|--------------|-----------|-----------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>25,571.04</b> |
|--------------------|-----------|------------------|

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ *4000* 6,000.00

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of front windscreen fittings and conduct water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *4000*

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

**Trans-cab Auto Services Pte Ltd****AAD1907-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

To transfer of front door fittings, attachment and  
perform water seepage test.

\$

*nn* 380.00 *X*

To apply paint protection system (PPS) maintain  
and enhancement

\$

*nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$

170.00 *2cl*

To rust-proofing of the affected areas.

\$

170.00 *3cl***TOTAL \$ 15,560.00****Over All Total \$ 41,131.04****LUMP SUM (REPAIR DAY)**~~20 days~~*2 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: