

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHC 5774G**

AAD1907-050

*Not Authorized  
 61 Sing @ 31001*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model: 08 JUL 2019  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration:

**SHC 5774G**  
 VF1ABL15AUC281616  
 RENAULT  
 LATITUDE  
 3.7.19  
**CHINA TAIPING**  
 10/7/2015

| PART |                                 |    | LIST                   |     |   |
|------|---------------------------------|----|------------------------|-----|---|
| 1    | BUMPER COVER FRT                | \$ | <i>Buolna</i> 1,259.42 | ✓   |   |
| 1    | BUMPER SPOILER FRT              | \$ | <i>Sn</i> 181.75       | } X |   |
| 1    | BUMPER ABSORBER FRT             | \$ | <i>Sn</i> 394.68       |     |   |
| 1    | BUMPER RETAINER FRT LH          | \$ | <i>Sn</i> 151.41       |     |   |
| 1    | BUMPER SUPPORT FRT              | \$ | <i>Sn</i> 123.88       |     |   |
| 1    | BUMPER UNDERTRAY FRT            | \$ | <i>Sn</i> 472.83       |     |   |
| 1    | BUMPER GRILLE LOWER FRT         | \$ | <i>Sn</i> 266.80       |     |   |
| 1    | BUMPER FOG LAMP GRILLE LH       | \$ | <i>Sn</i> 207.21       |     |   |
| 1    | BUMPER BEAM FRT                 | \$ | <i>N</i> 914.08        |     |   |
| 1    | HEADLAMP LH                     | \$ | <i>mgen</i> 1,184.43   |     | ✓ |
| 1    | HEADLAMP PANEL FRT LH           | \$ | <i>N</i> 152.15        |     | X |
| 1    | FENDER PANEL FRT LH             | \$ | <i>Rn</i> 783.83       | ✓   |   |
| 1    | WHEELARCH FRT LH                | \$ | <i>Sn</i> 278.84       | } X |   |
| 1    | FENDER BRACKET LOWER LH         | \$ | <i>Sn</i> 15.79        |     |   |
| 1    | FENDER INSULATOR LH             | \$ | <i>Sn</i> 130.84       |     |   |
| 1    | FRONT BRACE PANEL               | \$ | <i>N</i> 177.22        |     |   |
| 1    | RADIATOR GRILLE                 | \$ | <i>Sn</i> 1,707.78     |     |   |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$ | <i>Sn</i> 225.36       |     |   |
| 1    | RADIATOR GRILLE FRAME           | \$ | <i>Sn</i> 1,353.75     |     |   |
| 1    | FRAME FULL SUPPORT PANEL        | \$ | <i>Sn</i> 615.90       |     |   |
| 1    | FRAME FULL SUPPORT BRACKET      | \$ | <i>N</i> 89.79         |     |   |
| 1    | BONNET                          | \$ | <i>N</i> 1,941.63      |     |   |
| 1    | BONNET INSULATOR                | \$ | <i>Sn</i> 405.73       |     |   |
| 1    | BONNET STRUT LH                 | \$ | <i>Sn</i> 88.61        |     |   |
| 1    | BONNET STRUT RH                 | \$ | <i>Sn</i> 88.61        |     |   |
| 1    | BONNET HINGE LH                 | \$ | <i>N</i> 348.31        |     |   |
| 1    | BONNET HINGE RH                 | \$ | <i>N</i> 348.31        |     |   |
| 1    | BONNET LOCK                     | \$ | <i>N</i> 305.48        |     |   |
| 1    | BONNET CABLE                    | \$ | <i>Sn</i> 119.19       |     |   |

**Trans-cab Auto Services Pte Ltd**

AAD1907-050

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

|              |                               |           |                |                  |   |
|--------------|-------------------------------|-----------|----------------|------------------|---|
| 1            | BONNET CABLE COVER            | \$        | S <sub>h</sub> | 161.03           | } |
| 1            | BONNET SEAL OUTER             | \$        | S <sub>h</sub> | 92.36            |   |
| 1            | BONNET SEAL INNER             | \$        | S <sub>h</sub> | 157.28           |   |
| 1            | AIR CLEANER BOX               | \$        | S <sub>h</sub> | 464.20           |   |
| 1            | AIR CLEANER HOSE              | \$        | S <sub>h</sub> | 175.85           |   |
| 1            | AIR CLEANER LOWER             | \$        | S <sub>h</sub> | 271.26           |   |
| 1            | DOOR PANEL FRT LH             | \$        | H              | 2,844.66         |   |
| 1            | DOOR MIRROR ASSY LH           | \$        | S <sub>h</sub> | 1,483.40         |   |
| 1            | DOOR HARNESS WIRE LH          | \$        | S <sub>h</sub> | 2,670.00         |   |
| 1            | ROCKER PANEL INNER GARNISH LH | \$        | S <sub>h</sub> | 466.51           |   |
| 1            | ROCKER PANEL INNER LH         | \$        | H              | 1,024.79         |   |
| 1            | ROCKER PANEL OUTER LH         | \$        | H              | 1,184.99         |   |
| 1            | ROCKER PANEL CENTER LH        | \$        | H              | 990.25           |   |
| <b>TOTAL</b> |                               | <b>\$</b> |                | <b>26,320.18</b> |   |
| <b>10%</b>   |                               | <b>\$</b> |                | <b>2,632.02</b>  |   |
|              |                               | <b>\$</b> |                | <b>23,688.16</b> |   |

**Special Nett**

|      |                                    |    |                |        |   |
|------|------------------------------------|----|----------------|--------|---|
| 1    | BUMPER CLIP FRT                    | \$ | na             | 66.00  | } |
| 1    | BUMPER BRACKET CLIP FRT LH         | \$ | na             | 12.00  |   |
| 1    | BUMPER SUPPORT CLIP FRT LH         | \$ | na             | 10.50  |   |
| 1    | BUMPER GRILLE LOWER CLIP           | \$ | na             | 69.00  |   |
| 1SET | FRAME FULL SUPPORT PANEL CLIP      | \$ | na             | 70.00  |   |
| 2    | FRAME FULL SUPPORT PANEL NUT       | \$ | na             | 20.00  |   |
| 2    | FRAME FULL SUPPORT PANEL STUD      | \$ | na             | 30.00  |   |
| 1    | WHEELARCH CLIP FRT LH              | \$ | na             | 30.50  |   |
| 1    | FRONT LEFT TYRE                    | \$ | S <sub>h</sub> | 300.00 |   |
| 1    | FRONT LEFT TYRE RIM                | \$ | S <sub>h</sub> | 380.00 |   |
| 1SET | Front licence plate with holder    | \$ | S <sub>h</sub> | 80.00  |   |
| 1    | WINDSCREEN SEALANT                 | \$ | na             | 253.80 |   |
| 1    | FRONT WINDSCREEN MOULDING          | \$ | na             | 120.00 |   |
| 1    | FRONT WINDSCREEN INNER SPONGE SEAL | \$ | na             | 100.00 |   |
| 6    | BONNET INSULATOR CLIP L70Y         | \$ | na             | 7.30   |   |
| 2    | BONNET STRUT L70Y                  | \$ | na             | 88.61  |   |
| 2    | BONNET CABLE CLIP L70Y             | \$ | na             | 6.31   |   |
| 2    | BONNET CABLE COVER SCREW L70Y      | \$ | na             | 10.85  |   |
| 1SET | RADIATOR GRILLE FRAME CLIP         | \$ | na             | 52.00  |   |
| 1SET | RADIATOR GRILLE SCREW              | \$ | na             | 16.00  |   |

**Trans-cab Auto Services Pte Ltd**

AAD1907-050

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

|   |                                |    |                   |
|---|--------------------------------|----|-------------------|
| 1 | FRONT DOOR STICKER 'Trans-Cab' | \$ | <i>nn</i> 80.00 X |
| 1 | FRONT DOOR STICKER 'Classic'   | \$ | <i>nn</i> 80.00 X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,882.88</b> |
|--------------|-----------|-----------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>25,571.04</b> |
|--------------------|-----------|------------------|

**LABOUR**

|   |    |                      |
|---|----|----------------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | <i>4000</i> 6,000.00 |
| To transfer of front bumper fittings, attachment and perform water seepage test.  | \$ | <i>nn</i> 380.00 X   |
| To transfer of front fender fittings, attachment and perform water seepage test.  | \$ | <i>↪</i> 380.00 X    |
| To transfer of front windscreen fittings and conduct water seepage test.  | \$ | <i>↪</i> 170.00 X    |
| To check steering geometry and computer wheel alignment   | \$ | <i>↪</i> 220.00 X    |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | <i>↪</i> 380.00 X    |
| To transfer of tire, rim and on wheel balancing.  | \$ | <i>↪</i> 170.00 X    |
| Putty and spray painting of the affected portion.   | \$ | 6,000.00 <i>4000</i> |
| To transfer of bonnet fittings, attachment and perform water seepage test.  | \$ | <i>nn</i> 380.00 X   |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.   | \$ | <i>nn</i> 380.00 X   |

**Trans-cab Auto Services Pte Ltd**

**AAD1907-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5774G**

|  |           |                           |
|--|-----------|---------------------------|
| To transfer of front door fittings, attachment and perform water seepage test. | \$        | <i>nn</i> 380.00 <i>X</i> |
| To apply paint protection system (PPS) maintain and enhancement                | \$        | <i>nn</i> 380.00 <i>X</i> |
| To Check Electrical Lighting Concerned.  | \$        | 170.00 <i>2cl</i>         |
| To rust-proofing of the affected areas.  | \$        | 170.00 <i>3cl</i>         |
| <b>TOTAL</b>   | <b>\$</b> | <b>15,560.00</b>          |
| <b>Over All Total</b>  | <b>\$</b> | <b>41,131.04</b>          |

**LUMP SUM (REPAIR DAY)**

~~20 days~~

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: