

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMD 1019R
TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 06/07/2019

TP Veh Reg No: SLQ8025U

Estimate No: ES1991720/YISHUN

Date: 08 Jul 2019

Policy No: 5099609903-01

Veh Reg No: SMD1019R

Make/Model: BMW BMW 528I 2.0L AT
D/AB 2WD 4DR

Chassis No: WBAXG32070C593411

Engine No: A0960055N20B20A

Reg. Date: 01/11/2011

Estimate Repair Cost to Vehicle No :SMD1019R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	1,285.00	1 PC	CM 1,285.00	✓
2 FRONT BUMPER REINFORCEMENT	715.00	1 PC	B 715.00	✓
3 FRONT BUMPER LH FOG LAMP	276.00	1 PC	Sn 276.00	✓
4 FRONT BUMPER LH FOG LAMP GARNISH	72.00	1 PC	Mri 72.00	✓
5 FRONT BUMPER LH PARKING SENSOR	265.00	1 PC	Shan 265.00	✓
6 FRONT BUMPER CENTRE PARKING SENSORS	265.00	2 PCS	Sn 530.00	✓
7 FRT BUMPER LOGO	69.00	1 PC	na 69.00	✓
8 FRONT BUMPER TOP RUBBER	39.00	1 PC	na 39.00	✓
9 FRONT BUMPER SPONGE	49.00	1 PC	CM 49.00	✓
10 LH HEADLAMP	2,645.00	1 PC	na 2,645.00	✓
11 HEADLAMP ECU	840.00	1 PC	Sn 840.00	✓
12 LH HEADLAMP WIPER NOZZLE	180.00	1 PC	CM 180.00	✓
13 LH HEADLAMP WIPER NOZZLE COVER	48.00	1 PC	na 48.00	✓
14 FRONT GRILLES	125.00	2 PCS	na 250.00	✓
15 FRONT LH FENDER	885.00	1 PC	na 885.00	✓
16 FRONT LH SPORT RIM	1,580.00	1 PC	na 1,580.00	✓
17 REAR BUMPER	1,570.00	1 PC	na 1,570.00	✓
18 REAR BUMPER REINFORCEMENT	772.00	1 PC	na 772.00	✓
19 REAR BUMPER LH SIDE RETAINER	145.00	1 PC	CM 145.00	✓
20 REAR BUMPER LH REVERSE SENSOR	328.00	1 PC	Shan 328.00	✓
21 REAR BUMPER CENTRE REVERSE SENSORS	328.00	2 PC	Shan 656.00	✓
22 REAR BUMPER INNER CENTRE GARNISH	75.00	1 PC	CM 75.00	✓ #185 ✓
23 REAR BUMPER LH REFLECTOR	36.00	1 PC	Sn 36.00	✓
24 REAR BUMPER TOW COVER	17.00	1 PC	na 17.00	✓
25 REAR BOOT	1,702.00	1 PC	na 1,702.00	✓
26 REAR BOOT EMBLEM (523I)	88.00	1 PC	na 88.00	✓
27 REAR BOOT LOGO	69.00	1 PC	na 69.00	✓
28 REAR BOOT INNER LOCK	295.00	1 PC	na 295.00	✓
29 REAR BOOT SMART KEY SENSOR	90.00	1 PC	CM 90.00	✓
30 REAR BOOT INNER RUBBER	85.00	1 PC	na 85.00	✓
31 REAR BOOT HINGES	135.00	2 PCS	na 270.00	✓
32 REAR BOOT REFLECTORS	395.00	2 PCS	Sn 790.00	✓
33 REAR PANEL	812.00	1 PC	na 812.00	✓
34 REAR PANEL INNER TOP GARNISH	117.00	1 PC	na 117.00	✓
35 REAR SPARE TYRE PANEL UNDER COVER	87.00	1 PC	Sn 87.00	✓
36 REAR SPARE TYRE PANEL UNDER COVER CLIPS	4.50	8 PCS	na 36.00	✓
37 REAR EXHAUST PIPE	1,475.00	1 PC	na 1,475.00	✓

Not Authorized

1/10/19 8:36,000

Resuming After Paint

10 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 06/07/2019
 TP Veh Reg No: SLQ8025U

Estimate No: ES1991720/YISHUN
 Date: 08 Jul 2019
 Policy No: 5099609903-01
 Veh Reg No: SMD1019R
 Make/Model: BMW BMW 528I 2.0L AT
 D/AB 2WD 4DR
 Chassis No: WBAXG32070C593411
 Engine No: A0960055N20B20A
 Reg. Date: 01/11/2011

Estimate Repair Cost to Vehicle No :SMD1019R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			19,243.00	
		Less 5%	962.15	18,280.85
Labour				
38 TOWING	60.00	1 LA	60.00	✓
39 PANEL BEATING ON FRT PORTION	700.00	1 LA	700.00	500
40 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	2✓
41 REMOVE & REFIX FRT LH UNDER CARRIAGE	150.00	1 LA	150.00	un ✓ X
42 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
43 PUTTY & RESPRAY ON BONNET,FRT BUMPER,FRT LH FENDER	780.00	1 LA	780.00	720
44 PANEL BEATING ON REAR PORTION	1,200.00	1 LA	1,200.00	900
45 PUTTY & RESPRAY ON REAR PANEL,REAR SPARE TYRE COMPARTMENT,REAR BOTH FENDERS,BOOT,HINGES,REAR BUMPER	1,100.00	1 LA	1,100.00	960
46 REMOV E& REFIX REAR EXHAUST AND CHECH SYSTEM	100.00	1 LA	100.00	80
47 RUSTPROOFING	80.00	1 LA	80.00	60
48 REMOVE & REFIX REVERSE CAMERA,SENSOR AND CHECK SYSTEM	80.00	1 LA	80.00	✓
			4,410.00	4,410.00

Total S\$ 22,690.85

Add GST @ 7% 1,588.36

Total Amount Payable S\$ 24,279.21

parts — 15,097

Supp — 2,061

17,158.00

less 5% 857.90

16,300.10

add lab 3520 + 280

\$ 20,100.10

L/S = \$ 16,100.00 15,920.00

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMD1019R

supp1

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY

#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 06/07/2019

TP Veh Reg No: SLQ8025U

Estimate No: ES1991720/YISHUN

Date: 16 Jul 2019

Policy No: 5099609903-01

Veh Reg No: SMD1019R

Make/Model: BMW BMW 528I 2.0L AT
D/AB 2WD 4DR

Chassis No: WBAXG32070C593411

Engine No: A0960055N20B20A

Reg. Date: 01/11/2011

Estimate Repair Cost to Vehicle No :SMD1019R

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
<i>1 Active / Jan</i>				
List Price				
1 HEADREST REPAIR KIT	335.00	2 SETS	670.00	✓
2 REAR BUMPER ADAPTOR	135.00	1 PC	CM 135.00	✓
3 REAR COMPARTMENT TOP CUSHION/BOARD	499.00	1 PC	CM 499.00	✓
4 REAR EXHAUST TOP HEAT SEAL	129.00	1 PC	R 129.00	✓
5 FRT BUMPER LOWER BEAM	164.00	1 PC	R 164.00	✓
6 FRT SUPPORT AIR DUCT GUILD	240.00	1 PC	CM 240.00	✓
7 LH HEADLAMP LOWER BRACKET	195.00	1 PC	P 195.00	✓
8 LH HEADLAMP SIDE GARNISH	29.00	1 PC	CM 29.00	✓
			2,061.00	
		Less 5%	103.05	1,957.95
Labour				
9 REMOVE & REFIX HEADRESTS,REPAIR AIR-BAG REPAIR KIT,RESET & REPROGRAMME SYSTEM	280.00	1 LA	280.00	220/
			280.00	280.00
			Total	S\$ 2,237.95
			GST Amount	S\$ 156.66
			Total Amount Payable	S\$ 2,394.61

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: