

15/02/10

INS. CASE OWNER:

CC 6 /AIG1901

2134, Ueb3⁵²

LKK:

IDAC:

Surveyor:

MARLUS

DOI:

ASSIGNMENT

A 7/19

Date / Time:

7/7/19

Registered in Merimen:

7/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUR 82770

Name of Insured:

BLUE STAR CONCIERGE PTE LTD

Insured Tel No.:

HP:

8/7/19

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SCR 6133E

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fastech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	7/7/19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Cks

Repair Cost:

SS 18,000

(10 days) Reduction:

71 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 22.11.19

Confirm with: Jason

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

38

If NO or B 28, Ass. Lia: 100

Repair Cost:

SS 19,260

3 YEN CL. QID. 1951

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 60.00

(S 60 x 4 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4330

Total:

SS 19,921.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 22.11.19

Confirm with: Jason

Email ☒ Call ☐

Payee 1:

SS 19,921.45

Name 1:

FASTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

TOTAL

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

VEHICLE NO. SCR 6133E

QTY	PARTICULAR
1 PCS	BOOTLID 1812.32
1 PCS	BOOTLID REAR LOGO
1 PCS	BOOTLID '1160' EMBLEM
2 PCS	BOOTLID HINGES @\$166.00
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID INNER TRIM
1 SET	BOOTLID INNER TRIM CLIPS
2 PCS	BOOTLID REFLECTORS @\$420.00
1 PCS	BOOTLID WEATHERSTRIP
1 PCS	REAR BUMPER 1010.35
1 PCS	REAR BUMPER LOWER DIFFUSER
1 PCS	REAR BUMPER REINFORCEMENT 615.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$305.00
1 PCS	REAR BUMPER TOWING COVER
4 PCS	REAR BUMPER PDC SENSORS @\$305.00 260x4=1040
1 PCS	REAR BUMPER PDC SENSORS WIRE
1 PCS	REAR BUMPER TOP GUIDE
1 PCS	REAR BUMPER LOWER GUIDE
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER reflectors @\$115.00
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR FLOOR PANEL
1PCS	REAR FLOOR PANEL TOP BOARD
1 PCS	REAR FLOOR PANEL CENTRE WELL (FIBRE)
2 PCS	REAR FENDERS @\$2150.00
2 PCS	REAR FENDER INNER trim @\$320.00
2 PCS	TAILLAMPS @\$680.00
1 PCS	REAR EXHAUST MUFFLER
1 PCS	REAR EXHAUST HEAT SHIELD
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00
1 PCS	CENTRE EXHAUST PIPE
1 PCS	BONNET
1 PCS	front LOGO
2 PCS	BONNET DAMPERS @\$170.00
2 PCS	BONNET HINGES @\$140.00

Not Authorized
L/S # 18.000
9/7/19
10 day.

Body	\$2,118.30
ru	\$68.00
ru	\$65.00
11	\$332.00 X
twi	\$299.08
rel/tw	\$295.43
ru	\$50.00
119	\$840.00
twi	\$312.00
115	\$1,850.00
NS	\$640.00 X
3rd	\$720.00
11	\$420.00 X
70-11	\$30.00
shubs	\$1,220.00
su	\$313.54 X
cu	\$205.00
NS	\$202.00 X
ru	\$50.00
119	\$230.00
Body	\$1,068.00
twi	\$290.50
11	\$1,120.20 X
su	\$650.00 X
11	\$882.00 X
11	\$4,300.00 X
11	\$640.00 X
cu	\$1,360.00
20/ 3rd	\$1,480.00
3rd	\$311.30
ru	\$90.00
11	\$1,880.00 X
11	\$2,135.00 X
ru	\$80.00
11	\$340.00 X
11	\$280.00 X

5%

1 PCS	BONNET INNER HANDLE W/CABLE	11	\$92.00	X
1 PCS	BONNET INSULATOR	11	\$193.00	X
1 SET	BONNET INSULATOR CLIPS	11	\$50.00	X
1 PCS	BONNET LOCK LEVEL	11	\$190.00	X
2 PCS	BONNET LOCK CATCHES @\$25.00	11	\$50.00	X
2 PCS	BONNET MECHANISM LOCK L/R @\$266.00	11	\$532.00	X
2 PCS	BONNET RUBBER GUIDE STOPPERS @\$15.00	11	\$30.00	X
1 PCS	BONNET WEATHERSTRIP	11	\$92.00	X
1 PCS	FRONT BUMPER 1015.00	20/22	\$1,615.00	
1 PCS	FRONT BUMPER INNER SPONGE	20/22	\$98.00	
1 PCS	FRONT BUMPER REINFORCEMENT	11	\$712.00	X
1 PCS	FRONT BUMPER NUMBER PLATE GARNISH	11	\$110.00	X
1 PCS	FRONT BUMPER TOW COVER N/S	11	\$35.00	X
2 PCS	FRONT BUMPER FOG LAMPS @\$280.00	11	\$560.00	X
2 PCS	FRONT BUMPER SIDE HOLDERS @\$115.00	11	\$230.00	X
1 SET	FRONT BUMPER CLIPS	11	\$50.00	
1 PCS	FRONT BUMPER CENTRE GRILLE 015	11	\$56.00	
2 PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$105.00	11	\$210.00	X
1 PCS	FRONT BUMPER TOP RUBBER SEAL	11	\$45.00	
2 PCS	FRONT GRILLES @\$180.00	11	\$360.00	
2 PCS	HEADLAMPS @\$2800.00 3105	11	\$5,600.00	
2 PCS	HEADLAMP LOWER BRACKETS @\$185.00	11	\$370.00	X
1 PCS	HEADLAMP NOZZLE N/S	11	\$180.00	X
1 PCS	HEADLAMP TOP BRACKET N/S	11	\$166.00	X
1 PCS	FRONT SUPPORT PANEL	11	\$627.00	X
1 PCS	ENGINE TOP COVER	11	\$289.30	X
1 PCS	AIR CLEANER BOX	11	\$766.50	X
2 PCS	ENGINE MOUNTINGS L/R @\$350.00	11	\$700.00	X
1 PCS	FRONT AIR CON CONDENSER AIR GUIDE ASSY	11	\$199.20	X
1 PCS	AIR CON CONDENSER	11	\$1,220.00	X
1 PCS	AIR CON SUCTION HOSE	11	\$295.00	X
1 PCS	AIR CON DISCHARGE HOSE	11	\$298.00	X
1 PCS	AIR CON TEMPERATURE SENSOR	11	\$155.00	X
1 PCS	RADIATOR	11	\$922.00	X
1 PCS	RADIATOR AUXILLIARY FAN ASSY	11	\$1,550.00	X
1 PCS	RADIATOR BY PASS HOSE	11	\$92.00	X
1 PCS	RADIATOR LOWER HOSE	11	\$122.50	X
1 PCS	RADIATOR TOP HOSE	11	\$133.50	X
2 PCS	FRONT FENDERS @\$919.00	11	\$1,838.00	X
2 PCS	FRONT FENDER INNER SHIELDS @\$211.30	11	\$422.60	X
1 PCS	FRONT OIL COOLING PIPE	11	\$266.30	X
2 PCS	FRONT HEADRESTS @\$650.00	11	\$1,300.00	X
2 PCS	FRONT SAFETY BELT BUCKLES @\$290.00	11	\$580.00	
2 PCS	FRONT HEADREST REPAIR KITS @\$155.00	11	\$310.00	X
1 PCS	Battery terminal 355	11	\$955.00	

15760.88
8772.97

	S.NETT		\$51,835.25
1 PCS	REAR LICENCE PLATE W/HOLDER	Set	\$100.00 40
1 PCS	REAR END PANEL SEALANT	re	\$80.00 50
1 PCS	REAR EXHAUST CHROME	11	\$200.00 X
1 PCS	REAR FLOOR PANEL CENTRE WELL SEALANT	11	\$100.00 X
1 PCS	FRONT LICENCE PLATE W/HOLDER	Set	\$100.00 40
1 BOT	RADIATOR COOLANT	11	\$80.00 X
LABOUR CHARGES:			
	TO CHECK WIRING		\$100.00 30
	TO DISMENTLE & REPLACING PDC SENSOR		\$100.00 50
	TO DISMENTLE & REFIX BOOTLID MECHANISM		\$180.00 80
	TO DISMENTLE & REPLACING REAR EXHAUST		\$380.00 100
	TOWING CHARGE KING ROLLER	11	\$180.00 X
	TO REPROGRAMME & CLEAR FAULT CODE		\$200.00 180
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00 X
	TO DISMENTLE AIR CON ASSY,VACUUM AND CHARGE IN GAS	11	\$150.00 X
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY		\$180.00 100
	TO SPRAY RUST PROOFING		\$180.00 80
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$3,800.00 1500
	& REPLACING PARTS		
	TO PUTTY & SPRAY PAINTING		\$2,800.00 1500
	TOTAL		\$61,125.25

LKY Auto Care Centre hereby notify
the Repairer of the following:

- To carry out repair for spray painting
- To carry out repair for (3) during resurvey
- Part of the repair is subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No other work is allowed
- Repairs are subject to approval and
is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2252.93

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6143I

Vehicle Details

Vehicle No.:	SCR6133E
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	32459373B37D15A
Chassis No.:	WBA1V720X0V250048
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,855.00
Original Registration Date:	27 Nov 2015
First Registration Date:	27 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$10,397.00 5798

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2025
PARF Rebate Amount:	\$7,797.00

Intended COE Rebate Details

COE Expiry Date:	26 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,200.00
COE Rebate Amount:	\$37,772.00
Total Rebate Amount:	\$45,569.00

The information contained herein is correct as at 09 Jul 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Wish 1.8A.



3.18% P.A \$0 Admin Fees At GV
Finance, 2 Years Warranty.
Monthly From \$788.
GV Credit Pte Ltd StarAd

• Free VICOM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

bmw 116

Advanced Search Submit

Search Selection

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

bmw 116

Any

Any

2015

Any

Any

Any

Available

BMW 1 Series 116i

\$67,000

\$10,380 /yr

13-Apr-2015

1,598 cc

85,000 km

Hatchback

Available

PML Maintain From Day 1, Superb Beautiful Condition, 100% Accident-Free. Well Maintained By 1 Owner. Own This Stylish And Reliable...

Posted: 07-Jul-2019

Tags: 2015 BMW 116i, 2015 bmw 116i, BMW 116i, bmw 116i, BMW, 116i, Used BMW

BMW 1 Series 116d

\$75,800

\$11,240 /yr

28-Sep-2015

1,496 cc

51,339 km

Hatchback

Available

Graded B by

STA

Fuel Type: Diesel (Euro 5 Engine and Above)

Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident Free Quality Pre Owned...

Cosmo Automobiles

Posted: 05-Jul-2019

Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW

BMW 1 Series 116d

\$75,800

\$11,110 /yr

27-Nov-2015

1,496 cc

70,688 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Please Call For Availability, High Loan Discussion Or Viewin...

Benefit Auto Enterprise Pte Ltd

Posted: 04-Jul-2019

Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW

BMW 1 Series 116d

\$67,800

\$9,810 /yr

28-Oct-2015

1,496 cc

81,000 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

5 Yrs/200,000Km Warranty And 5 Yrs/100,000Km Free Servicing From Agent PML! Attractive Financing Available. Gorgeous Mineral Grey...

Supreme Cars Pte Ltd

Posted: 04-Jul-2019

Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW

New Citroen C5 Aircross lands in Singapore

The new Citroen C5 Aircross promises to be the most modular and the most comfortable model in its segment, thanks to a progressive hydraulic suspension system.

Find out more!

BMW 1 Series 116d

\$75,800

\$10,990 /yr

22-Dec-2015

1,496 cc

44,100 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

(100% Loan Available) Promo Bank Interest Rate From 1.98%. Low Mileage And Fully Maintained By PML. Free 1 Year Warranty With C...

Dynamic Motoring

Posted: 23-Jun-2019

Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW

BMW 1 Series 116d

\$74,800

\$11,310 /yr

14-Sep-2015

1,496 cc

54,000 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Lady Owner. PML Maintained And Accident Free. Mileage 54,000 And Recent Change Runflat Tyres. Paint Protection By CSII Ceramic Co...

Compare

Posted: 22-Jun-2019

Tags: 2015 BMW 116d, 2015 bmw 116d, BMW 116d, bmw 116d, BMW, 116d, Used BMW

CONFIRMATION

Compare

COMING SOON

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 23 July 2019 10:09 AM
To: jason@fastechauto.com.sg; 'Nancy Lam'
Subject: Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us **(LKK)** to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Jul 2019 17:04	Clim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	09 Jul 2019 17:04	Clim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	09 Jul 2019 17:04	Clim Created	Reg No: SCR6133R. Acct Date: 2019/07/08. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Fastech Auto Pte Ltd (HQ)	[A] Lau Shu Pei
4	09 Jul 2019 17:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	09 Jul 2019 17:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/18	[A] Lau Shu Pei
6	09 Jul 2019 17:04	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	09 Jul 2019 17:04	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	09 Jul 2019 17:04	Label Added	(19):Fastlane.	[A] Lau Shu Pei
9	09 Jul 2019 17:04	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
10	10 Jul 2019 15:14	Clim Veh Model Changed	(206086) -> (206261) BMW 116D 1.5 D 5DR HATCH LED (A).	[A] Lau Shu Pei
11	10 Jul 2019 15:14	Clim Registration Modified	Reg No:SCR6133R->SCR6133E.	[A] Lau Shu Pei
12	23 Oct 2019 12:07	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
13	23 Oct 2019 12:07	Clim Dtl Modified	JPJ Reg. Date: -> 2015/11/27.	[A] NUR SHAQILAH BTE ABDOL WAHAB
14	23 Oct 2019 12:07	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
15	23 Oct 2019 15:52	Adj Mandate Request	Cur.Req:19927.45:LIABILITY: 100% B:28 3VEH CC OID LAST	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2206593	10 Jul 2019 08:48:34	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SCR6133R	SLR8277D	11.77
2322423	23 Oct 2019 12:07:46	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCR6133E	SLR8277D	11.77

11/20/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SCR6133E (4399713285SG)**

[SLR8277D]

TP

NG CHWEE CHENG

Jul 8 2019 12:00AM

[BLUE STAR CONCIERGE PTE LTD]

Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/11/2019 14:54 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$19927.45) - SCR6133E - Claim Handler: Foo, Chit Yan

Approved:19927.45.

Asher Sng (LKKAUTO)

From: Jason <Jason@fastechauto.com.sg>
Sent: Wednesday, 20 November 2019 3:55 PM
To: Asher Sng (LKKAUTO)
Subject: RE: Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

Follow Up Flag: Follow up
Flag Status: Flagged

Without Prejudice

Dear Asher,

We are pleased to accept your offer of \$ 19,927.45 for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Wednesday, November 20, 2019 2:32 PM
To: Jason <Jason@fastechauto.com.sg>
Subject: RE: Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 19,260.00
2. Loss of Use (11 days x \$60)	\$ 660.00
3. LTA/GIA search fee	\$ 7.45
TOTAL	<u>\$ 19,927.45</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)

Sent: Tuesday, 23 July 2019 10:09 AM

To: jason@fastechauto.com.sg; 'Nancy Lam' <nancy.lam@fastechauto.com.sg>

Subject: Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir/Madam,

Accident Involving SCR 6133E & SLR 8277D on 08/07/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2019 Edit Reg		09 Jul 2019 00:00 Edit Adj Rpt	S\$18,000.00 Edit Estimates	S\$18,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: NA			
Main Claimant:	NG CHWEE CHENG, ID: S06361431			
Vehicle Reg. No.:	SCR6133E	Date of Loss:	08/07/2019 00:00 - :59 [43 Months and 11 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 4399713285SG	Policy/Cover Note No.:	0999994449 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLR8277D	Policy No. (Claimant):	MPMVP000001457-02-000	
		Excess:		
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com			
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/07/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (15/11/2019): Alert - Adj Mandate Approved (S\$19927.45) - SCR6133E - Claim Handler: Foo, Chit ...
- AIG_SG (10/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCR6133E (4399713285SG)**
[SLR8277D]
TP
NG CHWEE CHENG
Jul 8 2019 12:00AM
[BLUE STAR CONCIERGE PTE LTD]
Fastech Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Thumbnail Edit
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/07/19 18:55	Chassis Number		Load JPG ☒
2	09/07/19 18:55	Odometer Reading		Load JPG ☒
3	09/07/19 18:56	General View		Load JPG ☒
4	09/07/19 18:56	General View		Load JPG ☒
5	09/07/19 18:56	General View		Load JPG ☒
6	09/07/19 18:56	General View		Load JPG ☒
7	09/07/19 18:56	General View		Load JPG ☒
8	09/07/19 18:56	General View		Load JPG ☒
9	09/07/19 18:56	General View		Load JPG ☒
10	09/07/19 18:56	General View		Load JPG ☒
11	09/07/19 18:56	General View		Load JPG ☒
12	09/07/19 18:56	General View		Load JPG ☒
13	09/07/19 18:56	General View		Load JPG ☒
14	09/07/19 18:56	General View		Load JPG ☒
15	09/07/19 18:56	General View		Load JPG ☒
16	09/07/19 18:56	General View		Load JPG ☒
17	09/07/19 18:56	General View		Load JPG ☒
18	09/07/19 18:56	General View		Load JPG ☒
19	09/07/19 18:56	General View		Load JPG ☒
20	09/07/19 18:56	General View		Load JPG ☒
21	09/07/19 18:56	General View		Load JPG ☒
22	09/07/19 18:56	General View		Load JPG ☒
23	09/07/19 18:56	General View		Load JPG ☒
24	09/07/19 18:56	General View		Load JPG ☒
25	09/07/19 18:56	General View		Load JPG ☒
26	09/07/19 18:56	General View		Load JPG ☒
27	09/07/19 18:56	General View		Load JPG ☒
28	09/07/19 18:56	General View		Load JPG ☒
29	09/07/19 18:56	General View		Load JPG ☒
30	09/07/19 18:56	General View		Load JPG ☒
31	09/07/19 18:56	General View		Load JPG ☒
32	09/07/19 18:56	General View		Load JPG ☒
33	09/07/19 18:56	General View		Load JPG ☒
34	09/07/19 18:56	General View		Load JPG ☒
35	09/07/19 18:56	General View		Load JPG ☒
36	09/07/19 18:56	General View		Load JPG ☒
37	09/07/19 18:56	General View		Load JPG ☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/07/19 18:56	General View	 Load JPG	☒
39	09/07/19 18:56	General View	 Load JPG	☒
40	09/07/19 18:56	General View	 Load JPG	☒
41	09/07/19 18:56	General View	 Load JPG	☒
42	09/07/19 18:56	General View	 Load JPG	☒
43	09/07/19 18:56	General View	 Load JPG	☒
44	09/07/19 18:56	General View	 Load JPG	☒
45	09/07/19 18:56	General View	 Load JPG	☒
46	09/07/19 18:56	General View	 Load JPG	☒
47	09/07/19 18:56	General View	 Load JPG	☒
48	09/07/19 18:56	General View	 Load JPG	☒
49	09/07/19 18:56	General View	 Load JPG	☒
50	09/07/19 18:56	General View	 Load JPG	☒
51	09/07/19 18:56	General View	 Load JPG	☒
52	09/07/19 18:56	General View	 Load JPG	☒
53	09/07/19 18:56	General View	 Load JPG	☒
54	09/07/19 18:56	General View	 Load JPG	☒
55	09/07/19 18:56	General View	 Load JPG	☒
56	09/07/19 18:56	General View	 Load JPG	☒
57	09/07/19 18:56	General View	 Load JPG	☒
58	09/07/19 18:56	General View	 Load JPG	☒
59	09/07/19 18:56	General View	 Load JPG	☒
60	09/07/19 18:56	General View	 Load JPG	☒
61	09/07/19 18:56	General View	 Load JPG	☒
62	09/07/19 18:56	General View	 Load JPG	☒
63	09/07/19 18:56	General View	 Load JPG	☒
64	09/07/19 18:56	General View	 Load JPG	☒
65	09/07/19 18:56	General View	 Load JPG	☒
66	09/07/19 18:56	General View	 Load JPG	☒
67	09/07/19 18:56	General View	 Load JPG	☒
68	09/07/19 18:56	General View	 Load JPG	☒
69	09/07/19 18:56	General View	 Load JPG	☒
70	09/07/19 18:56	General View	 Load JPG	☒
71	09/07/19 18:56	General View	 Load JPG	☒
72	09/07/19 18:56	General View	 Load JPG	☒
73	09/07/19 18:56	General View	 Load JPG	☒
74	09/07/19 18:56	General View	 Load JPG	☒
75	09/07/19 18:56	General View	 Load JPG	☒
76	09/07/19 18:56	General View	 Load JPG	☒
77	09/07/19 18:56	General View	 Load JPG	☒
78	09/07/19 18:56	General View	 Load JPG	☒
79	09/07/19 18:56	General View	 Load JPG	☒
80	09/07/19 18:56	General View	 Load JPG	☒
81	09/07/19 18:56	General View	 Load JPG	☒
82	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
83	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
84	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
85	09/07/19 18:57	Reinspection Photo	Load JPG	☒
86	09/07/19 18:57	Reinspection Photo	Load JPG	☒
87	09/07/19 18:57	Reinspection Photo	Load JPG	☒
88	09/07/19 18:57	Reinspection Photo	Load JPG	☒
89	09/07/19 18:57	Reinspection Photo	Load JPG	☒
90	09/07/19 18:57	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▾	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
92	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
93	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
94	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
95	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
96	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
97	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
98	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
99	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
100	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
101	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
102	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
103	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
104	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
105	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
106	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
107	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
108	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
109	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
110	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
111	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
112	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
113	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
114	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
115	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
116	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
117	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
118	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
119	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
120	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
121	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
122	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
123	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
124	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
125	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
126	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
127	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
128	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
129	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
130	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
131	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
132	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
133	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
134	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
135	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
136	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
137	09/07/19 18:57	Reinspection Photo	 Load JPG	✓
138	09/07/19 18:57	Reinspection Photo	Load JPG	✓
139	09/07/19 18:57	Reinspection Photo	Load JPG	✓
140	09/07/19 18:57	Reinspection Photo	Load JPG	✓
141	09/07/19 18:57	Reinspection Photo	Load JPG	✓
142	09/07/19 18:57	Reinspection Photo	Load JPG	✓
143	09/07/19 18:57	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
144	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
145	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
146	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
147	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
148	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
149	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
150	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
151	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
152	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
153	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
154	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
155	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
156	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
157	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
158	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
159	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
160	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
161	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
162	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
163	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
164	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
165	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
166	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
167	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
168	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
169	09/07/19 18:57	Reinspection Photo	 Load JPG	☒
170	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
171	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
172	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
173	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
174	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
175	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
176	10/07/19 18:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/07/19 09:32	TP GIA REPORT	 Load PDF	
2	23/07/19 10:07	LETTER TO OI	 Load PDF	
3	23/10/19 13:37	LOD	 Load PDF	
4	23/10/19 13:37	LTA SEARCH	 Load PDF	
5	06/12/19 10:44	AUTHORISATION TO ACT	 Load PDF	
6	06/12/19 10:44	RELEASE VOUCHER	 Load PDF	
7	06/12/19 10:44	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/07/19 08:44	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR8277D (Insd veh)	Model:	BMW 116D 1.5 D 5DR HATCH
	SCR6133E (TP veh)		LED (A)
Date of Accident:	08/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	: \$	65,404.02	
Final Repair Cost	: \$	19,260.00	
Loss of Use	: \$	660.00	11.00 days at \$60.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	19,927.45	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	: \$	19,927.45
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

06 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
 Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19012134/UEB3S2
Date: 06/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994449
Claimant Vehicle No : SCR6133E **Insured Vehicle No :** SLR8277D
 Date of Loss: 08/07/2019 Nature of Claim: TP Claim No: 4399713285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCR6133E**
 Make & Model: BMW 116D, 1.5 D 5DR HATCH LED (A) Engine No: 32459373B37D15A
 Reg. Date: 27/11/2015 (Man. Year: 2015) Chassis No: WBA1V720X0V250048
 Colour: Blue Odometer: 17024 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,495.25	18,902.93	33,592.32	63.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,630.00	3,620.00	5,010.00	58.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	61,125.25	22,522.93	38,602.32	63.15
Approved Total (Overridden) (\$\$)		18,000.00		
(\$\$)	61,125.25	18,000.00	43,125.25	70.55
+ GST 7.00/7.00% (\$\$)	4,278.77	1,260.00	3,018.77	70.55
Nett Amount (\$\$)	65,404.02	19,260.00	46,144.02	70.55
+ Loss of Use (11.0 x S\$60.00/day) (\$\$)		660.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		19,927.45		

INSPECTION

Date of Assignment: 09/07/2019
 Date Inspected: 09/07/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	2,118.30 F	*1,812.32 FL
2	1		*BOOTLID REAR LOGO	Necessary	68.00 F	*68.00 FL
3	1		*BOOTLID 116D EMBLEM	Necessary	65.00 F	*65.00 FL
4	2		*BOOTLID HINGES	Not Necessary	332.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Twisted	299.08 F	*299.08 FL
6	1		*BOOTLID INNER TRIM	Deformed / Twisted	295.43 F	*295.43 FL
7	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
8	2		*BOOTLID REFLECTORS	Cracked	840.00 F	*840.00 FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	312.00 F	*312.00 FL
10	1		*REAR BUMPER	Distorted	1,850.00 F	*1,010.35 FL
11	1		*REAR BUMPER LOWER DIFFUSER	No such part	640.00 F	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	720.00 F	*615.00 FL
13	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	420.00 F	*- FL
14	1		*REAR BUMPER TOWING COVER	Torn	30.00 F	*30.00 FL
15	4		*REAR BUMPER PDC SENSORS	Shorted	1,220.00 F	*1,040.00 FL
16	1		*REAR BUMPER PDC SENSORS WIRE	Serviceable	313.54 F	*- FL
17	1		*REAR BUMPER TOP GUIDE	Cracked	205.00 F	*205.00 FL
18	1		*REAR BUMPER LOWER GUIDE	No such part	202.00 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	2		*REAR BUMPER REFLECTORS	Cracked	230.00 F	*230.00 FL
21	1		*REAR END PANEL	Badly Dented	1,068.00 F	*1,068.00 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	290.50 F	*290.50 FL
23	1		*REAR FLOOR PANEL	Repair	1,120.20 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	650.00 F	*- FL
25	1		*REAR FLOOR PANEL CENTRE WELL (FIBRE)	Not Necessary	882.00 F	*- FL
26	2		*REAR FENDERS	Repair	4,300.00 F	*- FL
27	2		*REAR FENDER INNER TRIM	Not Necessary	640.00 F	*- FL
28	2		*TAILLAMPS	Cracked	1,360.00 F	*1,360.00 FL
29	1		*REAR EXHAUST MUFFLER	Dented / Bent	1,480.00 F	*1,480.00 FL
30	1		*REAR EXHAUST HEAT SHIELD	Bent	311.30 F	*311.30 FL
31	2		*REAR EXHAUST MOUNTINGS	Necessary	90.00 F	*90.00 FL
32	1		*CENTRE EXHAUST PIPE	Repair	1,880.00 F	*- FL
33	1		*BONNET	Repair	2,135.00 F	*- FL
34	1		*FRONT LOGO	Necessary	80.00 F	*80.00 FL
35	2		*BONNET DAMPERS	Not Necessary	340.00 F	*- FL
36	2		*BONNET HINGES	Not Necessary	280.00 F	*- FL
37	1		*BONNET INNER HANDLE W/CABLE	Not Necessary	92.00 F	*- FL
38	1		*BONNET INSULATOR	Not Necessary	193.00 F	*- FL
39	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
40	1		*BONNET LOCK LEVEL	Not Necessary	190.00 F	*- FL
41	2		*BONNET LOCK CATCHES	Not Necessary	50.00 F	*- FL
42	2		*BONNET MECHANISM LOCK L/R	Not Necessary	532.00 F	*- FL
43	2		*BONNET RUBBER GUIDE STOPPERS	Not Necessary	30.00 F	*- FL
44	1		*BONNET WEATHERSTRIP	Not Necessary	92.00 F	*- FL
45	1		*FRONT BUMPER	Dented / Deformed	1,615.00 F	*1,015.00 FL
46	1		*FRONT BUMPER INNER SPONGE	Torn	98.00 F	*98.00 FL
47	1		*FRONT BUMPER REINFORCEMENT	Repair	712.00 F	*- FL
48	1		*FRONT BUMPER NUMBER PLATE GARNISH	Serviceable	110.00 F	*- FL
49	1		*FRONT BUMPER TOW COVER N/S	Not Necessary	35.00 F	*- FL
50	2		*FRONT BUMPER FOG LAMPS	Not Necessary	560.00 F	*- FL
51	2		*FRONT BUMPER SIDE HOLDERS	Not Necessary	230.00 F	*- FL
52	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
53	1		*FRONT BUMPER GRILLE O/S	Scratched	56.00 F	*56.00 FL
54	2		*FRONT BUMPER REINFORCEMENT BRACKETS	Not Necessary	210.00 F	*- FL
55	1		*FRONT BUMPER TOP RUBBER SEAL	Necessary	45.00 F	*45.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*FRONT GRILLES	Scratched	360.00 F	*360.00 FL
57	2		*HEADLAMPS	Cracked	5,600.00 F	*5,600.00 FL
58	2		*HEADLAMP LOWER BRACKETS	Not Necessary	370.00 F	*- FL
59	1		*HEADLAMP NOZZLE N/S	Not Necessary	180.00 F	*- FL
60	1		*HEADLAMP TOP BRACKET N/S	Not Necessary	166.00 F	*- FL
61	1		*FRONT SUPPORT PANEL	Repair	627.00 F	*- FL
62	1		*ENGINE TOP COVER	Not Necessary	289.30 F	*- FL
63	1		*AIR CLEANER BOX	Not Necessary	766.50 F	*- FL
64	2		*ENGINE MOUNTINGS L/R	Not Necessary	700.00 F	*- FL
65	1		*FRONT AIR CON CONDENSER AIR GUIDE ASSY	Not Necessary	199.20 F	*- FL
66	1		*AIR CON CONDENSER	Not Necessary	1,220.00 F	*- FL
67	1		*AIR CON SUCTION HOSE	Not Necessary	295.00 F	*- FL
68	1		*AIR CON DISCHARGE HOSE	Not Necessary	298.00 F	*- FL
69	1		*AIR CON TEMPERATURE SENSOR	Not Necessary	155.00 F	*- FL
70	1		*RADIATOR	Not Necessary	922.00 F	*- FL
71	1		*RADIATOR AUXILLIARY FAN ASSY	Not Necessary	1,550.00 F	*- FL
72	1		*RADIATOR BY PASS HOSE	Not Necessary	92.00 F	*- FL
73	1		*RADIATOR LOWER HOSE	Not Necessary	122.50 F	*- FL
74	1		*RADIATOR TOP HOSE	Not Necessary	133.50 F	*- FL
75	2		*FRONT FENDERS	Not Necessary	1,838.00 F	*- FL
76	2		*FRONT FENDER INNER SHIELDS	Not Necessary	422.60 F	*- FL
77	1		*FRONT OIL COOLING PIPE	Not Necessary	266.30 F	*- FL
78	2		*FRONT HEADRESTS	Not Necessary	1,300.00 F	*- FL
79	2		*FRONT SAFETY BELT BUCKLES	Activated	580.00 F	*580.00 FL
80	2		*FRONT HEADREST REPAIR KITS	Not Necessary	310.00 F	*- FL
81	1		*BATTERY TERMINAL	Activated	955.00 F	*355.00 FL
82	1		*REAR LICENCE PLATE W/HOLDER	Bent	100.00 FS	*40.00 FS
83	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
84	1		*REAR EXHAUST CHROME	Not Necessary	200.00 FS	*- FS
85	1		*REAR FLOOR PANEL CENTRE WELL SEALANT	Not Necessary	100.00 FS	*- FS
86	1		*FRONT LICENCE PLATE W/HOLDER	Bent	100.00 FS	*40.00 FS
87	1		*BOT RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	52,495.25	19,890.98
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	988.05

Total Parts (S\$)	52,495.25	18,902.93
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	100.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR.	New	100.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM.	New	180.00	80.00
4	TO DISMANTLE & REPLACING REAR EXHAUST.	New	380.00	100.00
5	TOWING CHARGE KING ROLLER.	New	180.00	0.00
6	TO REPROGRAMMING & CLEAR FAULT CODE.	New	200.00	180.00
7	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
8	TO DISMANTLE AIR CON ASSY, VACUUM AND CHARGE IN GAS.	New	150.00	0.00
9	TO DISMANTLE & REFIX SEAT, CUSHION, UPHOLSTERY.	New	180.00	100.00
10	TO SPRAY RUST PROOFING.	New	180.00	80.00
11	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS.	New	3,800.00	1,500.00
12	TO PUTTY & SPRAY PAINTING.	New	2,800.00	1,500.00
Gross Labour Cost (\$\$)			8,630.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >