Asia motispot

Vehicle No	SIM	8025 R
A CHILCIE 140	. SLIVI	0023 h

M	ER	CE	DES	BE	NZ

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMEN
	PARTS (LIST ITEMS)			1515/
1	Front Bumper / AR		2065.00	1212
1	Front Bumper lower grille X		284.00	X
1	Front Bumper reinforcement X		560.00	X
1	Front Rumner under cover V M/		345.00	X
1	RHS Front bumper fog lamp cover X		136.00	X
1	Front bumper lower chrome moulding /	10	302.00	232/
1	RHS Front headlamp washer assy X M/I	and a	480.00	X
1	RHS Front headlamp washer pipeline assy X	NA	280.00	X
1	Front RHS under cover X ////		410.00	
1	Front bonnet / 00		2120.00	1665
1	Front grille / NR			4851
1	RHS Headlamp / BR		3120.00	:001 - 1
1	RHS Headlamp ballast X M/II		950.00	
1	RHS Headlamp panel X N/		550.00	
1	RHS Front door X		2150.00	X
1	RHS Front doot lower hinges X MI		185.00	X
1	RHS Front Fender / PD		980.00	915-32
1	RHS Front Fender emblem / 11/C		56.00	
1	211	no coluberto		
1	RHS Front Fender rear Inner Shield / CFV RHS Wing mirror cover w/lamp * / CFV	IX CENTER IT CO	215.00	/
1	RHS Wing mirror motor assy / (47		580.00	1
1	RHS rocker panel X MM		780.00	X
1	RHS Front shock absorber   Impact ×	NII	692.00	,
1	RHS Front lower arm on outer S	( 1/11)	378.00	
1	RHS Front tie rod side wall	1 MM	178.00	
1	RHS Front knuckle arm of tyre	11/11)	492.00	
1	RHS Front wheel bearing & rim ×	[V/V]	242.00	///
			19350.00	6752
		less	10% 1935.00	10%
	SPECIAL NETT ITEMS		17415.00	
1	RHS Front sports rim		1450.00	9501
set	RHS Front fender inner shield clips / 1/4		20/60.00	
set	Front bumper clips / //		70/80.00	
		TOTAL PARTS	19005.00	

MERCEDES BENZ Vehicle No. SIM 8025 R

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00 508	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 800	
3	To check wiring and focus headlamp beam	200.00 31	
4	To remove & replace RHS front undercarriage parts & suspension system	400.00 30	
5	To conduct computerised wheel alignment test	150.00 60	
6	To perform anti-rust treatment on affected areas	300.00 30	
7	To clear fault code with diagnostic computer and reset to specification	350.00 X	1550
	Labour Total :	3800.00	1202
	TOTAL (PARTS & LABOUR):	22805.00	

. No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## Steve Chen (LKK Auto)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>

Sent: Monday, July 29, 2019 4:35 PM

To: Steve Chen (LKK Auto)
Subject: Re: SLM 8025 Finalize

PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)

Hi Mr Steve,

We are pleased to inform you that we are agreeable to your proposed lump sum repair of \$7,600.00 at 5 working days for SLM 8025 R.

In the meantime, please note that with effect from 1<sup>st</sup> June 2019, we have shifted to and are now operating from the following address:

37A Everitt Road Singapore 428586

Please update your records accordingly and send all future correspondence to the new address above.

Thank you and we hope to hear from you soon.

Regards, Asia Motorsports Solution Pte Ltd 6745 3811 6746 5110 (fax) asiamotorsports@hotmail.com

From: Steve Chen (LKK Auto) < SteveChen@lkkauto.com >

Sent: Wednesday, July 24, 2019 7:36 PM

To: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>

Subject: SLM 8025 Finalize

Dear Sir,

We have come out with the finalize \$7600 (L/S, before GST). 5 repair days.

Kindly comfirm