

Vehicle No. SLM 8025 R

MERCEDES BENZ

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Bumper / NR		2065.00	
1	Front Bumper lower grille X		284.00	
1	Front Bumper reinforcement X		560.00	
1	Front Bumper under cover X		345.00	
1	RHS Front bumper fog lamp cover X		136.00	
1	Front bumper lower chrome moulding / NR		302.00	
1	RHS Front headlamp washer assy X		480.00	
1	RHS Front headlamp washer pipeline assy X		280.00	
1	Front RHS under cover X		410.00	
1	Front bonnet / OD		2120.00	
1	Front grille / NR		580.00	
1	RHS Headlamp / NR		3120.00	
1	RHS Headlamp ballast X		950.00	
1	RHS Headlamp panel X		550.00	
1	RHS Front door X R		2150.00	
1	RHS Front door lower hinges X		185.00	
1	RHS Front Fender / PD		980.00	
1	RHS Front Fender emblem / NR		56.00	
1	RHS Front Fender rear Inner Shield / CRW		240.00	
1	RHS Wing mirror cover w/lamp X / CRW	NR (check if comp complete)	215.00	
1	RHS Wing mirror motor assy / CRW		580.00	
1	RHS rocker panel X		780.00	
1	RHS Front shock absorber	Impact X	692.00	
1	RHS Front lower arm	on outer X	378.00	
1	RHS Front tie rod	side wall X	178.00	
1	RHS Front knuckle arm	of tyre X	492.00	
1	RHS Front wheel bearing	& rim X	242.00	
			less	
			10%	
			19350.00	
			1935.00	
			17415.00	
			1450.00	
1	RHS Front sports rim / CRW		20 60.00	
1set	RHS Front fender inner shield clips / NR		30 80.00	
1set	Front bumper clips / NR			
TOTAL PARTS			19005.00	
SPECIAL NETT ITEMS				

Vehicle No. SLM 8025 R MERCEDES BENZ

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00 500 600	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 800	
3	To check wiring and focus headlamp beam	200.00 30	
4	To remove & replace RHS front undercarriage parts & suspension system	400.00 30	
5	To conduct computerised wheel alignment test	150.00 60	
6	To perform anti-rust treatment on affected areas	300.00 30	
7	To clear fault code with diagnostic computer and reset to specification	350.00 X	
	Labour Total :	3800.00	
	TOTAL (PARTS & LABOUR):	22805.00	

Steve (LKK) will provide 8/7/19, 5-00pm
5 days
L/S
Reg AL spy

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: