

Surveyor:

REF: CSI/SPF19012158/Hg f352

Special Instruction:

From (Person): Frankie they of 8PF Date/Time: 27/6/19
Estimated Cost: Bill to:

Part by part: \$2853.78

Third Parties:

Claimant:

Surveyor: Automobile Inspection

Workshop: Kah Motor

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SDM 44H
at Workshop m/s Kah Motor
of 15 Ubi Rd 4

Insured: GBB7902S

Tel:

Policy No:

Claim No: AEMD/105/009/2018/188

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/12/2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 4 days)
Date/Time: 16/9/19 Submit Final Fig 2853.78, 4 days (Red \$ 0 / 0 %; Original days)

Date/Time	Action/Instruction
	SDM 44H-X
	GBB 7902S-X
	Frankie said this is the only documents available and ask us to do paper survey base on this.
10/7/19 @	1.73m request print & labour adjustment report from Frankie.
18/8/19 @	2.41m called Frankie, & he will go on check with Liberty.
12/9/19 @	10.10m Frankie said that they still awaiting the lot from U-Bent.
16/9/19	* Below case marking is base on handker give point out as picture see do paper survey, paint out picture is dark, no more photographs see if.

Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

* FAIR & REASONABLE.

(LOR range: \$2853.78 - \$2853.78)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Weekend : 2 days.

Total repair days: 6 days.

Lower knee and upper knee is the

same as there is no reduction

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

200

1) Date/Time 18/9/19 File Pass to typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Thursday, 27 June 2019 11:57 AM
To: Veron Chen (LKKAuto); assignments
Cc: Hafizul Farhan RAHMAT (SPF)
Subject: RE : Post survey for vehicle SDM44H
Attachments: 2018-188 Thid party survey report.pdf; 2018-188 GIA.pdf

Your reference: SDM 44H

Our reference: AEMD/105/009/2018/188

Veron,

Please conduct a Post survey for vehicle SDM 44H base on the GIA report and third party survey with photos.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/12/2018 17:27
Date Of Accident	11/12/2018 21:15
Exact Location Of Accident	CARPARK OF BLK 527UBI AVE 1 LOT 377
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDM44H
Insured/Policyholder	
Name Of Registered Owner	TAY YI SHENG TRAVIS
NRIC No	S8819655D
Email Address	TRAVISTAYYS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97373044
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	STATIONARY PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	.YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V08587 / VPC / R00 / E00
Cover Note Number	
Driver	
Name of Driver	TAY YI SHENG TRAVIS
NRIC No	S8819655D
Date Of Birth	01/06/1988
Occupation	INDOOR
Date Of Driving Pass	27/07/2010
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97373044
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	TRAVISTAYYS@GMAIL.COM

Address BLK 326 UBI AVE 1
#12-687
Postcode 400326
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TELOK BLANGAH NPP
Police Station Address ROAD: 51 TELOK BLANGAH DRIVE #01-116 , POSTCODE: 100055 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NUMBER: T/20181212/2061

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB7902S
Vehicle Make/Model/Colour POLICE VAN
Details Of Properties
Vehicle Category GOVERNMENT
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

TELOK BLANGAH NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

Report No: T/20181212/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2018 13:41	Vide Report No.: G/20181211/0243	Station Diary No.: 15
Informant's Particulars		
Name of Informant: TAY YI SHENG, TRAVIS	Address: APT BLK 326 UBI AVENUE 1 #12-687 SINGAPORE 400326	
ID Type / ID No.: NRIC NO / S8819655D	Contact No.: Home/Office:	Mobile: 97373044
Nationality: SINGAPORE CITIZEN	Email:	



SINGAPORE
POLICE FORCE



T/20181212/2061

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

2 of 3

Report No. T/20181212/2061

CONTINUATION OF REPORT

Brief Details.

On the 12/12/2018, I was informed by my mother at about 1200hrs that my car that I parked at my house's carpark had been damaged by a police van. The front right bumper had been damaged, and she informed me that there are 2 police memo attached on the windscreen. I was told to head to the nearest police station immediately to make a police report with vide report number G/20181211/0243 under IO Dylan.



Liberty Insurance
Member of Liberty Mutual Group

Liberty Insurance Pte Ltd
51 Club Street #03-00
Liberty House
Singapore 069428
Tel: (65) 6221 8611
Fax: (65) 6224 1047

AUTOMOBILE INSPECTION REPORT (IN-HOUSE SURVEY)

Type of Survey:	Type of claim and Assignment:		Type of Report:	Claim No	
Paper	OD	Survey	Finalized*	AVS18/3612	CMMN
Vehicle Inspected:	SDM44H		Date of Accident:	11/12/2018	
Insured Vehicle:	SDM44H		Date of Inspection:	13/12/2018	
Survey held at:	15 UBI RD 4			Attd. by: KAH MOTOR	

2. Vehicle Particulars & Condition (static test only)

Make & Model:	HONDA CIVIC 1.6 VTI CVT		Year:	15/08/2018
Excess / Loading:	EXCESS: \$600		Colour:	Maroon
Brakes:	In order / NA	Steering: Power	In order / NA	
Modifications:	NA			

3. Adjustment of cost of repairs

\$2,853.78

W/Shop estimation:

\$4,041.69

Lump

NA

Sum:

? Items:

Estimated repair period:

4 Working days.

Adjusted: →

Item	Unit*	\$/Unit	Amount
Panel Beat.	2	\$360.00	\$720.00
Spray Paint.	2	\$320.00	\$640.00
Mechanic	1	\$304.00	\$304.00
Others*	1	\$20.00	\$20.00
Parts	See attached list		\$1,169.78
Total (PBP)	-	-	\$2,853.78

Authorised Repairs: Yes

(This inspection is conducted on a "Without Prejudice Basis")

* Units: Days - Hours - Panels (Labour + Mat) *Others: Aircon gas - Wheel align. - Electronic diagnostic -
Tow - Glasses - Head-light align. - ...

4. Remarks

Market value : SGD 85,000.00 Supplementary expected : YES
LTA Rebate : SGD 41,740.00
Economical repair value : SGD 43,260.00 Recommended for repair : YES

Description of Damages:

Mainly At the FRONT RIGHT

Damages Consistent:

Yes


Inspection conducted by:

Andy Seah

Date & Signature:

25/12/2018

ANDY





SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

ATTN: Andy Seah (Liberty)

4 days

Customer: WP007 / LIBERTY INSURANCE
Chassis No: MRHFC5650JT001340
License No: SDM44H
Mileage: 9064
Engine No: R16B25501519

Document No: SVO18075058
Printed By: CSLIM
Order Date: 17. December 2018
Order Time: 9:30:00 AM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	OWN DAMAGE CLAIMS-J/NO: 71836 POLICY/CLAIMS NO: SD18V08587 / VPC / R00 OWNER: TAY YI SHENG TRAVIS ACC DATE: 11/12/18 SURVEYED BY: ANDY SEAH (LIBERTY) DATE: 13/12/2018 @ 15:35PM AUTHORIZED ON : 13/12/2018 @ 15:35PM EXCESS \$600 REF NO : AVS18/3612-OD-MN						
54206	EXTERNAL LABOUR SALES - INS. EXCESS	-1	600.00		-600.00	-42.00	-642.00
	SUM EXCESS:				-600.00	-42.00	-642.00
60213-TBA-A00ZZ	BRACKET AR.FR.FENDER ✓ BT	1	29.40	35	19.11	1.34	20.45
91505-TM8-003	CLIP,BUMPER ✓ nec	20	2.30	35	29.90	2.09	31.99
91501-TR0-003	CLIP,INNER FENDER ✓ nec	11	2.80	35	20.02	1.40	21.42
71101-TEA-T00ZZ	FACEFR.BUMPER ✓ car	1	579.90	35	376.93	26.39	403.32
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE ✓ SCR	1	18.00	35	11.70	0.82	12.52
71140-TEA-T00	BEAMR.FR.BUMPER UPPER ✓ car	1	26.70	35	17.35	1.21	18.56
71193-TEA-T01	SPACERR.FR.BUMPER SIDE ✓ car	1	10.40	35	6.76	0.47	7.23
71121-TEA-T01	BASE,FR.GRILLE CHROME ✓ car	1	73.80	35	47.97	3.36	51.33
75700-TBA-A00	EMBLEM ✓ nec	1	15.00	35	9.75	0.68	10.43
90301-ST0-003	NUTPUSH 3MM ✓ nec	2	2.10	35	2.73	0.19	2.92
33100-TEC-306	HEADLIGHT ASSY,R. ✓ sun	1	585.70	35	380.70	26.65	407.35
34300-TET-H01	LIGHT ASSYR.SIDE TURN ✓ sun	1	33.10	35	21.51	1.51	23.02
60211-TBA-A00ZZ	PANELR.FENDER ✓ BT	1	248.90	35	161.78	11.32	173.10
77930-TEA-B11	SENSOR ASSYFR.CRASH ✓ cut	1	71.40	35	46.41	3.25	49.66
76841-TEA-T01	TANKWASHER ✓ car	1	26.40	35	17.16	1.20	18.36
	SUM PARTS:				1,169.78	81.88	1,251.66
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES ✓ nec						
BML011	EXT-YJ	1	80.00	20	64.00	4.48	68.48
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BKBH01S	EXT-YJ	1	900.00	20	720.00	50.40	770.40
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						
BP03R	EXT-YBH	1	800.00	20	640.00	44.80	684.80
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)						
BMS00R	EXT-YJ	1	300.00	20	240.00	16.80	256.80
	RENEW FR R CRASH SENSORS & RESET SRS SYSTEM.(N)						
	SUM LABOUR:				1,684.00	117.88	1,801.88
	TOTAL SGD				2,853.78	157.76	2,411.54

Total Payable (SGD)

2853.78

2,411.54

RESURVEY ESTIMATE

22/12/2018

Page 1/2



C

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Attn: Andy Seah (Liberty)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

4 days

Customer: WP007 / LIBERTY INSURANCE
 Chassis No: MRHFC5650JT001340
 License No: SDM44H
 Mileage: 9064
 Engine No: R16B25501519

Document No: SVO18075058
 Printed By: CSLIM
 Order Date: 17. December 2018
 Order Time: 9:30:00 AM
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	OWN DAMAGE CLAIMS-J/NO: 71836 POLICY/CLAIMS NO: SD18V08587 / VPC / R00 OWNER: TAY YI SHENG TRAVIS ACC DATE: 11/12/18 SURVEYED BY: ANDY SEAH (LIBERTY) DATE: 13/12/2018 @ 15:35PM AUTHORIZED ON : 13/12/2018 @ 15:35PM EXCESS \$600 REF NO : AVS18/3612-OD-MN EXTERNAL LABOUR SALES - INS. EXCESS	-1	600.00		-600.00	-42.00	-642.00
	SUM EXCESS:				-600.00	-42.00	-642.00
54206	BRACKET AR.FR.FENDER ✓ BEND	1	29.40	35	19.11	1.34	20.45
60213-TBA-A00ZZ	CLIP,BUMPER ✓	20	2.30	35	29.90	2.09	31.99
91505-TM8-003	CLIP,INNER FENDER ✓	11	2.80	35	20.02	1.40	21.42
91501-TR0-003	FACEFR.BUMPER ✓	1	579.90	35	376.93	26.39	403.32
71101-TEA-T00ZZ	GARNISHR.FR.BUMPER SIDE ✓	1	18.00	35	11.70	0.82	12.52
71103-TEA-T00	BEAMR.FR.BUMPER UPPER ✓ CRACKED	1	26.70	35	17.35	1.21	18.56
71140-TEA-T00	SPACERR.FR.BUMPER SIDE ✓	1	10.40	35	6.76	0.47	7.23
71193-TEA-T01	BASE,FR.GRILLE CHROME ✓ HOLDER TORN	1	73.80	35	47.97	3.36	51.33
71121-TEA-T01	EMBLEM ✓ NEC	1	15.00	35	9.75	0.68	10.43
75700-TBA-A00	NUTPUSH 3MM ✓ NEC	2	2.10	35	2.73	0.19	2.92
90301-ST0-003	HEADLIGHT ASSY,R. ✓ CRACKED	1	585.70	35	380.70	26.65	407.35
33100-TEC-306	LIGHT ASSY, SIDE TURN ✓ GRAZED	1	33.10	35	21.51	1.51	23.02
34300-TET-H01	PANELR.FENDER ✓ DENTED	1	248.90	35	161.78	11.32	173.10
60211-TBA-A00ZZ	SENSOR ASSYFR.CRASH ✓ SENSOR CUT	1	71.40	35	46.41	3.25	49.66
77930-TEA-B11	TANKWASHER ✓ DEFORM	1	26.40	35	17.16	1.20	18.36
76841-TEA-T01	SUM PARTS:				1,169.78	81.88	1,251.66
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES ✓						
BML011	EXT-YJ	1	80.00	20	64.00	4.48	68.48
	INSPECT FR LIGHTING MECHANISMS & ✓ FOCUS HEADLIGHTS.(N)						
BKBH01S	EXT-YJ	1	900.00	20	720.00	50.40	770.40
	STRAGHTEN ALIGN BULKHEAD & ✓ RENEW DAMAGE PARTS.						
BP03R	EXT-YBH	1	800.00	20	640.00	44.80	684.80
	SPRAY PAINTING ON REPAIRED OR ✓ REPLACED AREAS.(3P)						
BMS00R	EXT-YJ	1	450.00	300	240.00	25.20	385.20
	RENEW FR R CRASH SENSORS & ✓ RESET SRS SYSTEM.(N)						
	SUM LABOUR:				1684		
	TOTAL SGD				2,539.78	166.16	2,539.94
	Total Payable (SGD)						2,539.94

GST Amount is calculated from individual line(s)

QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LIBERTY INSURANCE PTE LTD
51 CLUB STREET #03-00
LIBERTY HOUSE
SINGAPORE 069428

Registration No : SDM44H

Chassis No : MRHFC5650JT001340

Model : CIVIC 1.6 VTI YM2018

Owner's Name : TAY YI SHENG, TRAVIS

Ins Policy No. : SD18V08587 / VPC / R

Date of Accident : 11/12/2018

Document No.	: SQT18005434	Page	1
Date	: 20. Dec 2018		
Customer No.	: WP007		
Svc Advisor	: LIM CHOU SIONG		
Engine No	: R16B25501519		
Date Time	: 20. Dec 2018 10:17:42 AM		
Surveyor Name	: ANDY SEAH (LIBERTY)		
Survey Date	: 13/12/2018		
Authorisation Date	: 13/12/2018		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: 71836 POLICY/CLAIMS NO: SD18V08587 / VPC / R00 OWNER: TAY YI SHENG, TRAVIS ACC DATE: 11/12/2018 SURVEYED BY: ANDY SEAH (LIBERTY) DATE: 13/12/2018 @ 15:35PM AUTHORIZED ON : 13/12/2018 @ 15:35PM EXCESS \$600 REF NO : AVS18/3612-OD-MN SUPPLEMENTARY LABOUR & PARTS						
BMS00R	RENEW FR R CRASH SENNSOR & RESET SRS SYSTEM. (N)	1	450.00		450.00	31.50	481.50
				Sum Labor	<u>450.00</u>	<u>31.50</u>	<u>481.50</u>
60211-TBA-A00ZZ	PANELR.FENDER	1	248.90	35	161.78	11.32	173.10
77930-TEA-B11	SENSOR ASSYFR.CRASH	1	71.40	35	46.41	3.25	49.66
76841-TEA-T01	TANKWASHER	1	26.40	35	17.16	1.20	18.36
				Sum Item	<u>225.35</u>	<u>15.77</u>	<u>241.12</u>

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount	675.35	47.27	722.62
Total (Inclusive of GST)			722.62

Printed on 20/12/2018 10:34:26 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SDM 44H

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	BRACKET AR.FR.FENDER (SN)	BENT	19.11
20	CLIP, BUMPER (SN)	NECESSARY	29.90
11	CLIP, INNER FENDER (SN)	NECESSARY	20.02
1	FACEFR.BUMPER (SN)	CRUSHED	376.93
1	GARNISHR.FR.BUMPER SIDE (SN)	SCRATCHED	11.70
1	BEAMR.FR.BUMPER UPPER (SN)	CRUSHED	17.35
1	SPACERR.FR.BUMPER SIDE (SN)	CRUSHED	6.76
1	BASE,FR.GRILLE CHROME (SN)	CRUSHED	47.97
1	EMBLEM (SN)	NECESSARY	9.75
2	NUTPUSH 3MM (SN)	NECESSARY	2.73
1	HEADLIGHT ASSY,R. (SN)	SMASHED	380.70
1	LIGHT ASSYR.SIDE TURN (SN)	SMASHED	21.51
1	PANELR.FENDER (SN)	BENT	161.78
1	SENSOR ASSYFR.CRASH (SN)	CUT	46.41
1	TANKWASHER (SN)	CRUSHED	17.16
1	SUNDRIES (SN)	NECESSARY	20.00
			1,189.78
LABOUR			
INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.			64.00
STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.			720.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			640.00
RENEW FR R CRASH SENNSOR & RESET SRS SYSTEM.			240.00
			1,664.00
GRAND TOTAL			2,853.78
RECOMMENDED COST OF REPAIRS			2,853.78

Report Ref No. CS1/SPF19012158/Hqf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,853.78 - \$2,853.78

RECOMMENDED REPAIR DAYS : 4

WEEKENDS : 2

TOTAL DAYS : 6

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.