

7/2/2010

ASS. REC. BY:

REF:

CSINC190121621A2f302

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person):

Cynthia Ang

of

INC

Date/Time:

9/7/19 @ 10:09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SME 1876C

Insured:

FBP 8126K

at Workshop m/s

SK Automobile

Tel:

6702/555.

of

8 Kalci Bulciq Ave 4# 08-46

Policy No.:

Claim No.:

MT/1052137-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:17am @ 9/7/19

Person Contacted:

Chris

Vehicle IN / OUT

Date/Time

Action/Instruction

Johnnie ✓

FBP 8126K : X

SME 1876C : X

US \$4000, 4 days (led to 11983.68, 75%)

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 9 July 2019 3:44 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

IN with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 9 July 2019 10:09 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Clarence Richard Anthony <clarence.anthony@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eng Huey Huey	MT/1052486-001	SLU1663C	TEAM AUTOPRO PTE LTD	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	Peach Ang / 6258 1955		SGS3819C	06/07/2019	
2	Chryllis Quah	MT/1052455-001	SJJ6715	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGK2950D	06/07/2019	
3		Pending advice	SML1145S	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				
4	Eric Tang	MT/1049590-002	SLE2735G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLW1005S	31/05/2019	
5	Eng Huey Huey	MT/1052137-002	SME1876C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Chris / 6702 1555		FBP8126K	05/07/2019	
6	Jared Liu	MT/1052296-002	SJT8373Y	TORQUE 5 PTE LTD	8 KAKI BUKIT AVE 4 #01-50 PREMIER @ KAKI BUKIT	Lucas / 8131 6318		WC5674J	06/07/2019	
7	Chryllis Quah	MT/1052398-002	SBM131M	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 6341 6789		SJF4431M	06/07/2019	
8	Azhari	MT/1033901-001	FBL7115U	HOME ADDRESS	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY @ KB SINGAPORE 417800	Li Tian / 90054320		SKM1972P	17/02/2019	WORKSHOP NAME IS TUCK LIFE
9	Muhammad Airwan	MT/1050613-002	SJB9855L	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		FBM4589A	24/06/2019	
10	Chryllis Quah	MT/1034631-002	FBK8414E	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SJW8544E	01/03/2019	
11		Pending advice	GP3838M	SM AUTOMOTIVE	BLOCK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883	Sukyi Chong / 6747 9241				

12.	Pending advice	SK07188B	ZOOM AUTOWERKS PTE LTD	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53	Elin Cai / 9450 7920				
-----	----------------	----------	------------------------	--	----------------------	--	--	--	--

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
 Admin Assistant
 Motor Insurance
 T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

MVA31906514 / VAC - Kaki Bukit
 ENTRY DATE & TIME: 08/07/2019 10:46
 SUBMITTED BY: SITI FADHLON BTE ABUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 10:46
Date Of Accident	05/07/2019 17:30
Exact Location Of Accident	PASIR RIS DRIVE 1 TWRDS PASIR RIS STRET 52
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME1676C
Insured/Policyholder	
Name Of Registered Owner	LIM HUAN CHEE
NRIC No	S1187778H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82822805
Alternative Phone No	OTHERS-82822805
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT (AMS)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103965792
Cover Note Number	DRIVO PREMIUM
Driver	
Name of Driver	LIM HUAN CHEE
NRIC No	S1187778H
Date Of Birth	25/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	29/07/1976
Driving Experience	42 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82822805
Fax Number	
Contact Number	OTHERS-82822805
Email Address	NOEMAIL

Address BLK 20 #14-47 WOODLANDS CRESCENT
 Postcode 738081
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBP8126K
 Vehicle Make/Model/Colour YAMAHA / AEROX GDR155R CVT
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver ALIAS MAS AMAT
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have Insured vehicle(s) involved in this accident (all Insurer(s) who have Insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 8 JUL 2019

IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4

Reporting Centre, Singapore
Signature


Name: Tel: 67416697

NRIC/EN No.: Fax: 67492305

Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 05 JUL 2019 @ 1730HRS I WAS DRIVING ALONG PASIR RIS DRIVE. I
 WHEN THE VEHICLE B SUDDENLY COLLIDED INTO MY VEHICLE REAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 8 JUL 2019
IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre *[Signature]*
Name: P. S. S. S. S.
Fax: 67492305
NRIC/FIN Email: vaackb@singnet.com.sg

19	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 338.00	\$ 338.00	+
20	REAR FLOOR TOOLS BOX SPONGE	1	\$ 210.00	\$ 210.00	+
21	REAR UNDER COVER RH	1	\$ 98.00	\$ 98.00	+
22	REAR UNDER COVER LH	1	\$ 189.00	\$ 189.00	+
23	REAR EXHAUST PIPE	1	\$ 962.00	\$ 962.00	+
24	REAR EXHAUST INSULATOR	1	\$ 210.00	\$ 210.00	+
25	REAR EXHAUST PIPE MOULTING	2	\$ 45.00	\$ 90.00	+

3776.40

3021.12

TOTAL PRICE \$ 10,652.10
 LESS 20% \$ 2,130.42
 SUB TOTAL PRICE \$ 8,521.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	30
2	REAR BUMPER LOWER <i>Delud</i>	1	\$ 1,800.00	\$ 1,800.00	680.
3	BOOT LID SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	BOOT LID INSULATOR CLIP <i>new</i>	10	\$ 6.50	\$ 65.00	+
5	TAIL LAMP CLIP <i>new</i>	4	\$ 8.00	\$ 32.00	+
6	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
7	REAR FENDER INNER COWLING CLIP	18	\$ 6.50	\$ 117.00	+
8	REAR FENDER INNER TRIM CLIPS	18	\$ 6.50	\$ 117.00	+
9	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	4	\$ 6.50	\$ 26.00	+
10	REAR END PANEL SEALANT	1	\$ 120.00	\$ 120.00	+
11	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00	+
12	REVERSE SENSOR <i>Eng d</i>	1	\$ 220.00	\$ 220.00	200

910

TOTAL \$ 3,102.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600	
3	TUFF COAT	\$ 250.00	+	
4	WIRING CHECK	\$ 60.00	30	
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 180.00	30	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
7	TRANFER BOOTLID MECHANISM	\$ 80.00	X.	

8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
9	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$350.00	X	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X	

TOTAL

\$4,260.00

1130

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,623.68
TOTAL LABOUR COST : \$ 4,260.00
TOTAL REPAIR COST : \$ 15,883.68

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj
L/S 09/07/19

04 Days

Total: 5061.12

L/S: HK.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012162/Aqf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 17-02-2020



ATTN: ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 8126K	Veh. Inspected	SME 1876C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1052137-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	09/07/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU737983	Colour	SILVER
Odometer	54574 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	6 mm
L/H Front Tyre	195/65 R15	NEXEN	6 mm
R/H Rear Tyre	195/65 R15	NEXEN	6 mm
L/H Rear Tyre	195/65 R15	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2019	Inspect Date / Time	09/07/2019 (01:00 PM)
Survey held at	8 KAKI BUKIT AVE 4 #08-46		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1876C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	498.00	498.00
2	REAR BUMPER RETAINER @\$54.50	NECESSARY	109.00	109.00
5	REAR BUMPER BRACKET @\$19.80	CRACKED (2PCS ONLY)	99.00	39.60
2	REAR BUMPER REFLECTOR @\$198.00	NOT NECESSARY	396.00	-
1	REAR BUMPER REINFORCEMENT	BENT	345.00	345.00
1	BOOTLID	DENTED	1,728.00	1,728.00
2	BOOTLID REFLECTOR @\$298.00	NOT NECESSARY	596.00	-
2	BOOT LID LOCK DETECTOR @\$315.50	DAMAGED	631.00	182.00
1	BOOT LID EMBLEM 'ELANTRA'	NECESSARY	68.60	68.60
1	BOOT LID EMBLEM 'S'	NECESSARY	38.00	38.00
1	BOOTLID LOGO	NECESSARY	48.20	48.20
1	BOOTLID TOP LOCK	DAMAGED	298.00	298.00
1	BOOTLID WEATHER STRIP	CUT	198.00	198.00
2	TAILLAMP @\$896.00	NOT NECESSARY	1,792.00	-
2	REAR FENDER INNER COWLING @\$98.70	NOT NECESSARY	197.40	-
2	REAR FENDER INNER TRIM @\$354.00	NOT NECESSARY	708.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	580.90	-
1	REAR END PANEL TOP GARNISH	DEFORMED	224.00	224.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	338.00	-
1	REAR FLOOR TOOLS BOX SPONGE	NOT NECESSARY	210.00	-
1	REAR UNDER COVER RH	NOT NECESSARY	98.00	-
1	REAR UNDER COVER LH	NOT NECESSARY	189.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	962.00	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	210.00	-
2	REAR EXHAUST PIPE MOULTING @\$45.00	NOT NECESSARY	90.00	-
	LESS 20% DISCOUNT		-2,130.42	-755.28
			8,521.68	3,021.12
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/INC19012162/Aqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIP @\$6.50 (SN)	NECESSARY	65.00	30.00
1	REAR BUMPER LOWER (SN)	DEFORMED	1,800.00	680.00
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
10	BOOT LID INSULATOR CLIP @\$6.50 (SN)	NOT NECESSARY	65.00	-
4	TAIL LAMP CLIP @\$8.00 (SN)	NOT NECESSARY	32.00	-
2	TAIL LAMP PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
18	REAR FENDER INNER COWLING CLIP @\$6.50 (SN)	NOT NECESSARY	117.00	-
18	REAR FENDER INNER TRIM CLIPS @\$6.50 (SN)	NOT NECESSARY	117.00	-
4	REAR END PANEL TOP GARNISH CLIPS @\$6.50 (SN)	NOT NECESSARY	26.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	250.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			3,102.00	910.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL. TO SPRAY PAINT AFFECTED AREA.		1,600.00	400.00
	TUFF COAT.	NOT NECESSARY	1,400.00	600.00
	WIRING CHECK.		250.00	-
	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		60.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		180.00	50.00
	TRANFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	50.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	350.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	180.00	-
			-	-
			-	-
			4,260.00	1,130.00
GRAND TOTAL			15,883.68	5,061.12

Report Ref No. CS/INC19012162/Aqf3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,000.00
---	--	--	----------

Report Ref No. CS/INC19012162/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.