

ASS. REC. BY:

REF: CS/INC19012168/ATF302

Special Instruction:

Survey: Admcm

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of INC

Date/Time: 9/7/19 @ 10:09am

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBM131M

Insured:

SJF 4431M

at Workshop m/s

Vision Autowork

Tel:

6341 6789

of

Elcelei Bulut Ave 4 # 08-09

Policy No:

Claim No:

M7/1052398-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:31am @ 9/7/19

Person Contacted:

Michelle

Vehicle IN OUT

Date/Time

Action/Instruction

Johnny /

SJF 4431M : X

SBM 131M : X

lump sum \$5500 (Red: 11427.20 : 67%)

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

6 days

Res: Yes or No

Lum Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SBM131M Yr Regn: 2917 JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonatac.c. 1999Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading 53449

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHE341CMHA320944Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06

mm

R/Bal. 06

mm

L/Bal. 06

mm

L/Bal. 06

mm

D.O.A. _____

D.O.I. 09/07/15Survey held at Vision

5:08pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / INC.

RECEIVED 15 OCT 2019

mv:

pv:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 15/10 TUPST

3)

5)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 9 July 2019 3:44 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 9 July 2019 10:09 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Clarence Richard Anthony <clarence.anthony@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 09/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	Workshop Name	Workshop Address	Workshop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eng Huey Huey	MT/1052486-001	SLU1663C	TEAM AUTOPRO PTE LTD	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	Peach Ang / 6258 1955		SGS3819C	06/07/2019	
2	Chryllis Quah	MT/1052455-001	SJ6715	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGK2950D	06/07/2019	
3		Pending advice	SM11455	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				
4	Eric Tang	MT/1049590-002	SLE2735G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLW10055	31/05/2019	
5	Eng Huey Huey	MT/1052137-002	SME1876C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Chris / 6702 1555		FBP8126K	05/07/2019	
6	Jared Liu	MT/1052296-002	SJT8373Y	TORQUE 5 PTE LTD	8 KAKI BUKIT AVE 4 #01-50 PREMIER @ KAKI BUKIT	Lucas / 8131 6318		WC5674J	06/07/2019	
7	Chryllis Quah	MT/1052398-002	SBM131M	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	Michelle / 6341 6789		SJF4431M	06/07/2019	
8	Azhari	MT/1033901-001	FB1711SU	HOME ADDRESS	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY @ KB SINGAPORE 417800	Li Tian / 90054320		SKM1972P	17/02/2019	WORKSHOP NAME IS TUCK LIFE
9	Muhammad Airwan	MT/1050613-002	SJB9855L	PRO-JEX VZD MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		FBM4589A	24/06/2019	
10	Chryllis Quah	MT/1034631-002	FBK8414E	PRO-JEX VZD MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SJW8544E	01/03/2019	
11		Pending advice	GP3838M	SM AUTOMOTIVE	BLOCK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883	Sukyi Chong / 6747 9241				

12	Pending advice	SKQ7188B	ZOOM AUTOWERKS PTE LTD	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53	Elin Cai / 9450 7920				
----	----------------	----------	------------------------	--	----------------------	--	--	--	--

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 13:43
Date Of Accident	06/07/2019 21:45
Exact Location Of Accident	SLIP ROAD TPE EXIT 3C TO PASIR RIS DRIVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBM131M
Insured/Policyholder	
Name Of Registered Owner	MOHAMMED RUHUL ISLAM S/O MOHAMED NOORUL ISLAM
NRIC No	S7932620H
Email Address	RUHUL_ISLAM@MSN.COM
Mobile Phone No	(LOCAL) +65-97719291
Alternative Phone No	OFFICE-97719291

Vehicle Particulars

Manufacturer	HYUNDAI
Model	LF SONATA 2.0 GLS A/T
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29069191 QMY (COMP)
Cover Note Number	

Driver

Name of Driver	MOHAMMED RUHUL ISLAM S/O MOHAMED NOORUL ISLAM
NRIC No	S7932620H
Date Of Birth	24/10/1979
Occupation	INDOOR
Date Of Driving Pass	25/05/1999
Driving Experience	20 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97719291
Fax Number	
Contact Number	OFFICE-97719291
Email Address	RUHUL_ISLAM@MSN.COM

Address	BLK 527A PASIR RIS STREET 51 #07-743
Postcode	511527
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RAOUSHAN SHAHIR RUHUL GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF4431M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMMED RUHUL ISLAM S/O MOHAMED NOORUL ISLAM
Approximate Age	
Injuries Sustain	BODY PAIN
Injured person in which vehicle?	SBM131M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Name: _____
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg
NRIC/PR No: _____

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

On 06.07.19 at about 21:45 hours along Slip Road of TPE Exit 3C towards Pasir Ris Drive 8. I was stationary along the above mentioned slip road, waiting for the oncoming traffic to clear. Suddenly I heard a loud bang from behind. When I alighted I realise it was vehicle (B) collided onto rear portion of my vehicle (A). I wish to state that I have 1 passenger inside my vehicle (A).

Vehicle (A): SBM 131M

Vehicle (B): SJF 4431M



Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 08.07.19

TO : NTUC MOTOR CLAIMS DEPTS
VEHICLE NO : SBM131M
MODEL : HYUNDAI SONATA
DATE OF ACCIDENT : 06.07.19
TIME OF ACCIDENT : 21:45HRS

KM14 E341CMHA 320944

Denise

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 599.00	\$ 599.00
2	REAR BUMPER REFLECTOR <i>LH canld</i>	2	\$ 47.00	\$ 94.00
3	REAR BUMPER CENTER LAMP <i>canld</i>	1	\$ 356.00	\$ 356.00
4	REAR BUMPER BRACKET <i>3 pieces DM</i>	6	\$ 27.00	\$ 162.00
5	REAR BUMPER LOWER LIP <i>Rehd</i>	1	\$ 199.00	\$ 199.00
6	REAR BUMPER RETAINER <i>re</i>	2	\$ 37.00	\$ 74.00
7	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 489.00	\$ 489.00
8	REAR BUMPER REINFORCEMENT BRACKET <i>LH Best</i>	2	\$ 131.00	\$ 262.00
9	REAR BUMPER INNER GRANISH <i>canld 120</i>	2	\$ 49.00	\$ 98.00
10	REAR BUMPER LOWER CENTER GARNISH <i>canld</i>	1	\$ 74.00	\$ 74.00
11	BOOTLID <i>Dented</i>	1	\$ 1,199.00	\$ 1,199.00
12	BOOTLID LAMP <i>new</i>	2	\$ 868.00	\$ 1,736.00
13	BOOTLID NUMBER PLATE GARNISH <i>Rehd</i>	1	\$ 436.00	\$ 436.00
14	BOOTLID LOGO <i>2</i>	1	\$ 34.00	\$ 34.00
15	BOOTLID EMBLEM 'SONATA' <i>new</i>	1	\$ 36.00	\$ 36.00
16	BOOTLID EMBLEM 'VIII'	1	\$ 48.00	\$ 48.00
17	BOOTLID DETECTOR (OUTER) <i>canld</i>	1	\$ 379.00	\$ 379.00
18	BOOTLID DETECTOR (INNER) <i>canld</i>	1	\$ 384.00	\$ 384.00
19	BOOTLID DETECTOR WIRE HARNESS <i>new</i>	1	\$ 658.00	\$ 658.00
20	BOOTLID HINGE <i>new</i>	2	\$ 79.00	\$ 158.00
21	BOOTLID TOP LOCK <i>new</i>	1	\$ 139.00	\$ 139.00
22	BOOTLID LOWER LOCK <i>new</i>	1	\$ 29.00	\$ 29.00
23	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 109.00	\$ 109.00
24	TAILLAMP <i>LH canld</i>	2	\$ 794.00	\$ 1,588.00
25	REAR FENDER INNER COWLING <i>3 new</i>	2	\$ 142.00	\$ 284.00
26	REAR FENDER INNER TRIM <i>new</i>	2	\$ 269.00	\$ 538.00
27	REAR END PANEL <i>Dented</i>	1	\$ 426.00	\$ 426.00

195

81

131

49

95

105

794

TO : NTUC MOTOR CLAIMS DEPTS
 VEHICLE NO : SBM131M
 MODEL : HYUNDAI SONATA
 DATE OF ACCIDENT : 06.07.19
 TIME OF ACCIDENT : 21:45HRS

28	REAR END PANEL TOP GARNISH <i>Relnd</i>	1	\$ 84.00	\$ 84.00	✓
29	REAR FLOOR PANEL TOP BOARD <i>Relnd</i>	1	\$ 291.00	\$ 291.00	✓
30	REAR EXHAUST PIPE <i>Relnd</i>	1	\$ 1,499.00	\$ 1,499.00	+
31	REAR EXHAUST INSULATOR <i>2</i>	1	\$ 169.00	\$ 169.00	+
32	REAR EXHAUST GASKET (SET) <i>1/2</i>	1	\$ 16.00	\$ 16.00	+
33	REAR EXHAUST MOUNTING <i>1/2</i>	2	\$ 31.00	\$ 62.00	+

34 Rear Exhaust Tail Pipe. *305*
Bent *120.*
5901
A720.80

TOTAL PRICE \$ 12,709.00
 LESS 20% \$ 2,541.80
 SUB TOTAL PRICE \$ 10,167.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Relnd</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	30
3	REAR BUMPER INNER GRANISH <i>Relnd</i>	1	\$ 50.00	\$ 50.00	+
4	REAR BUMPER LOWER CENTER GARNISH CLIP (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	10
5	BOOTLID SEALANT <i>Relnd</i>	1	\$ 150.00	\$ 150.00	+
6	BOOT LID INSULATOR CLIP (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	+
7	TAIL LAMP CLIP (SET) <i>Relnd</i>	1	\$ 30.00	\$ 30.00	10
8	REAR FENDER INNER COWLING CLIP (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	+
9	REAR FENDER INNER TRIM CLIPS (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	+
10	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Relnd</i>	1	\$ 50.00	\$ 50.00	10
11	REAR END PANEL SEALANT <i>Relnd</i>	1	\$ 150.00	\$ 150.00	60
12	REAR FLOOR PANEL INSULATION SEAL <i>Relnd</i>	1	\$ 350.00	\$ 350.00	+
13	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
14	REVERSE CAMERA <i>Relnd</i>	1	\$ 450.00	\$ 450.00	+

TOTAL \$ 1,750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	80
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	80
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30

TO : **NTUC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SBM131M**
 MODEL : **HYUNDAI SONATA**
 DATE OF ACCIDENT : 06.07.19
 TIME OF ACCIDENT : 21:45HRS

5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	+
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	+
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

1850

TOTAL

5010

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,917.20
 TOTAL LABOUR COST : \$ 5,010.00
 TOTAL REPAIR COST : \$ 16,927.20 17167.20

Adrian Lim
 L/S 09/07/19.
 06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

total: 6890.80
 L/S: 551C

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012168/Atf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 15-10-2019



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 4431M	Veh. Inspected	SBM 131M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1052398-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	09/07/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHE341CMHA320944	Colour	SILVER
Odometer	53449 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/07/2019	Inspect Date / Time	09/07/2019 (05:08 PM)
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBM 131M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	599.00	599.00
2	REAR BUMPER REFLECTOR @\$47.00	N/S CRACKED	94.00	47.00
1	REAR BUMPER CENTER LAMP	CRACKED	356.00	195.00
6	REAR BUMPER BRACKET @\$27.00	DAMAGED (3 PCS ONLY)	162.00	81.00
1	REAR BUMPER LOWER LIP	DEFORMED	199.00	199.00
2	REAR BUMPER RETAINER @\$37.00	NECESSARY	74.00	74.00
1	REAR BUMPER REINFORCEMENT	BENT	489.00	489.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$131.00	N/S BENT	262.00	131.00
2	REAR BUMPER INNER GARNISH @\$49.00	CRACKED (1 PC ONLY)	98.00	49.00
1	REAR BUMPER LOWER CENTER GARNISH	CRACKED	74.00	74.00
1	BOOTLID	DENTED	1,199.00	1,199.00
2	BOOTLID LAMP @\$868.00	NOT NECESSARY	1,736.00	-
1	BOOTLID NUMBER PLATE GARNISH	DEFORMED	436.00	436.00
1	BOOTLID LOGO	NECESSARY	34.00	34.00
1	BOOTLID EMBLEM "SONATA"	NECESSARY	36.00	36.00
1	BOOTLID EMBLEM "VIII"	NECESSARY	48.00	48.00
1	BOOTLID DETECTOR (OUTER)	CRACKED	379.00	95.00
1	BOOTLID DETECTOR (INNER)	CRACKED	384.00	105.00
1	BOOTLID DETECTOR WIRE HARNESS	NOT NECESSARY	658.00	-
2	BOOTLID HINGE @\$79.00	NOT NECESSARY	158.00	-
1	BOOTLID TOP LOCK	DAMAGED	139.00	139.00
1	BOOTLID LOWER LOCK	NOT NECESSARY	29.00	-
1	BOOTLID WEATHER STRIP	CUT	109.00	109.00
2	TAILLAMP @\$794.00	N/S CRACKED	1,588.00	794.00
2	REAR FENDER INNER COWLING @\$142.00	NOT NECESSARY	284.00	-
2	REAR FENDER INNER TRIM @\$269.00	NOT NECESSARY	538.00	-
1	REAR END PANEL	DENTED	426.00	426.00
1	REAR END PANEL TOP GARNISH	DEFORMED	84.00	84.00
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	291.00	291.00

Report Ref No. CS/INC19012168/Atf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE	NOT NECESSARY	1,499.00	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	169.00	-
1	SET REAR EXHAUST GASKET	NOT NECESSARY	16.00	-
2	REAR EXHAUST MOUNTING @\$31.00	NOT NECESSARY	62.00	-
1	REAR EXHAUST TAIL PIPE	BENT	300.00	120.00
	LESS 20% DISCOUNT		-2,601.80	-1,170.80
			10,407.20	4,683.20
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER INNER GARNISH (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER LOWER CENTER GARNISH CLIP (SN)	NECESSARY	50.00	10.00
1	BOOTLID SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET BOOT LID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAIL LAMP CLIP (SN)	NECESSARY	30.00	10.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	350.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
			1,750.00	320.00
	LABOUR			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.		1,800.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	800.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK.		180.00	30.00
	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		250.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00

Report Ref No. CS/INC19012168/Atf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE.		80.00	50.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	180.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			5,010.00	1,850.00
	GRAND TOTAL		17,167.20	6,853.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,500.00

Report Ref No. CS/INC19012168/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.