SSS. REC. BY: STEVE REF: NTUK	4C19012172 E+F3DV
The same of the sa	GNMENT
From: Date:917_119	Veh No: SHS 9410 Yr Regn: 7/2/14
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi / Prime Mover /
OD I(TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SHB 941D	Make: Toyota filus c.c 1798
at Workshop m/s SMPT	Colour Margin A/C: Insured / Std / NI / NA
of woodlends Depot	Sp.Reading 6053)/ T/Radio: Insured / Std / NI / NA
Insured: GBF 8406E	Eng/No:
Policy No. 508870626802 (23/63/2019-22/03/2020)	C/No: JTOKN36UX95722908
Claims No. WT/1052532-002	Gen. Cond: Good / Fair/ Poor / Burnt
Sum Insured: Excess:	Steering(Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder) Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim) STD A/Rim or
	Tyre Size: F: 195/65R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSI
repair at the time of inspection.	TOYO/YOKO or West fall
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. S mm L/Bal. S mm
Est. Repairs: days Res.: Yes or No	D.O.A. 7/7/19 D.O.I. 9/7/19
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS (Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	07/19/1978
GBF 8406E:X	07/11/228
24/7/19 Finalize Comfin 52350, 3 Mays	(Red: 5339.65 :6970)
	COVACE I R CH 2019
TEV	ZETYLDE
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
1 - 1 - 1	Resurvey No. of Trip: Survey Fee: 160
1) 29 7 (MST : Final Report Date/Time, File Return to?	Transportation:
Add Ea	
<u>2)</u>	:Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Spin / LEJ: (\$ 2350)	: Weekend (\$
2 / 3 / 1 / 1 / 2 / 3 / 2 / 3 / 2 / 3 / 2 / 3 / 3 / 3	TOTAL 160

eBaoTech		10000								Genera	lClaim
Hello, NAC_PAYA_UBI_BO	0601						• Change Li	anguage	• Change	Password	· Log Out
My Desktop	Polic	cy Query									
Notice of Loss	Policy N	lo.				Date (of Accident	07/	07/2019 09	:44	
	Vehicle	No.(For Motor)	GBF840	6E		Certifi	cate Number				
					18	Search					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5088706268- 02		KIM KOON GAS SERVICES	20332300M	GCV	Comprehensive	GBF8406E	GBF8406E	23/03/2019	22/03/2020
					C	Continue	l				

Denise Tay (LKKAuto)

From:

MTCL@income.com.sg

Sent:

Monday, 29 July 2019 12:04 PM

To:

Denise Tay (LKKAuto)

Subject:

FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia

Senior Admin Assistant, Motor Insurance www.income.com.sg











At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Monday, 29 July 2019 10:47 AM

To: MTCL@income.com.sg

Subject: RE: REQUEST CLAIM NUMBER

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1052532- 002	SMRT	SHB 941D	<u>GBF</u> 8406E	7/7/2019	23:55	7,709.65	2350

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	
Owner ID:	Company
Vehicle Details	5369K
Vehicle No.:	SHB941D
Vehicle to be Exported:	No.
Intended Deregistration Date:	10 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR6130375
Chassis No.:	JTDKN36UX05722908
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	07 Feb 2014
First Registration Date:	07 Feb 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	\$0,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Feb 2022
PARF Rebate Amount:	\$5,857.00
ntended COE Rebate Details	
COE Expiry Date:	06 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$58,590.00
COE Rebate Amount:	\$18,853.00
otal Rebate Amount: Message	\$24,710.00
lease note that the 8-year COE for this vehicle of OE expiry or when the vehicle reaches its status	cannot be further renewed. The vehicle must be de-registered upon tory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

年为李洁师师共进一个大学的	ACCIDENT STATEMENT
Date Of Report	08/07/2019 14:41
Date Of Accident	07/07/2019 23:55
Exact Location Of Accident	KJE TOWARDS PIE (TUAS)
Country/State of Loss	SINGAPORE
AMERICAN DOMESTICATION OF THE	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB941D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	QUANG KOK KIONG
NRIC No	S7410743E
Date Of Birth	03/04/1974
Occupation	OUTDOOR

OUTDOOR Date Of Driving Pass 09/03/1998

Driving Experience 21 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-80000000

Fax Number Contact Number

EMail Address NOEMAIL Address

11

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

3

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

10

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ON THE EXTREME RIGHT LANE ALONG KJE TOWARDS PIE (TUAS) WITH 2 PASSENGERS (MALE INDIAN) ON BOARD. SUDDENLY A VEHICLE GBF8406E WHICH WAS TRAVELLING ON MY LEFT CUT TOWARDS MY LANE ABRUPTLY, I SOUNDED MY HORN TO ALERT THIRD PARTY BUT THIRD CONTINUED AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF8406E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ZHAO LINGXIAO

NRIC/Passport Number

Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN	KJE towards PIE (Tuas)
	A-9HB941D B-GBF8406E
DESCRIBE CIRCUMSTANCE	ES OF THE ACCIDENT
(200)	ticulars are true in every respect.
olicyholder's signature ate & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)
Date & Time: | | | | | | | | | | | |

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Scrylees Pie Ltd
60 Woodclands Industrial Paik E4, Engapare 757705
FAX Number 63685592
Estimator Telephone Number 58082023
Accident Reporting Number 58662672

Date Generaled : 24/07/2012 User ID : PohSuan

	Section C - Quota	tion and Accident Involce Details	N 1 + 52 Q
Quotation Number	QN-1907-0343	Invoice Number	
Quotation Date	21.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D	- Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, It applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200,00
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
RESPRAY MIRROR COVER LH	\$180,00	\$80.00
Total Spray Painting & Panel Beating	\$1,116.00	\$480.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TOWING CHARGE	\$56.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60,00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$596.66)
Total Other Costs	\$484.44	(\$388.22)

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87945- 74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	25.00	\$80.55	Replace	Replace /
		87940- 47310	MIRROR ASSY, LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace /
		81740- 52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given >
		87961- 47150	MIRROR GLASS LH	0.00	\$142.50	0.00	\$0.00	Replace	Not Given X
		52119- 47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair /2
		52115- 47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
1,		53876- 47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		52161- 16010	BUMPER CLIPS	10.00	\$1.61	25,00	\$12.08	Replace	Replace
		52116- 47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace /
		53852- 47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0,00	Replace	Not Given X
		53802- 47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair A
		75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Ptc Ltd 60 Woodlands Industrial Perk E4, Singapore 757765 FAX Number - 65465592 Extensior Telephone Number - 68652623 Accident Reporting Number - 66652672

Date Generated: 24/07/2019

User ID ; PohSuan

	1 1	42611 47140 (Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given X	NV
	1 1	81170- 47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace /	
Total					\$5,602.21		\$1,958.22			ant
	<u> </u>]
	are Parts / Ma	terial Usag	ge After Surveyor Signed o	u -]
	Portion		ge After Surveyor Signed o	Quantity	List Price \$	Discount (%)	Final Price	ARC Check	Surveyor Check	

1956.22 +300.00 +688.44 -207 -207 -357.33 -357.33

7774.14



AUTOMOTIVE

Case Reference Number: TAX/07/19/2028

Type of Repair : Accident Repair Vehicle Registration Number : SHB941D Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7610-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name: NTUC Income

Insurance Co-operative Ltd

Accident Date and Time: 07/07/2019 03:55 PM Vehicle Age(In Months): 65

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

				SMRT R	ecomm	endation							Surveyor Approval	
Туре	10 To	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace *	MIS /
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	1	918.68	Replace •	SR/
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0.00	Not Give •	X NM
One Time Key In	Main			MIRROR GLASS LH	1	142.50	142,50	25,00	106.88	Replace	0	0.00	Not Give •	Y NINI
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0.00	Repair •	RX
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0.00	Not Give *	X JIMI
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0.00	Not Give *	X MAIN
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace *	1990
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace *	/ BR
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0.00	Not Give *	X MM
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0.00	Repair +	R X
One Time Key In	Main			NAME PLATE (HYBRID)	t i	51.90	51.90	25.00	38.92	Replace	1	38.93	Replace *	(PC
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0.00	Not Give •	X ////

ВОМ Туре	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	0.00	Replace *	/ CUT
						Т	otal Spare P	art Cost	4,364.10		9	Surveyor Total	1,058.61 190	8.22
						Lum	p Sum Disc	ount (%)	20.00		Lum	p Sum Dis (%)	20.00	
						Fi	nal Spare P	art Cost	3,491.28		0	Final Sur Total	854.89	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	300.00 /	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
2	Main	TO RESPRAY RIM	180.00	0.00	
3	Main	TO REPSRAY FRONT BUMPER	378.00	200.00	
4	Main	RESPRAY MIRROR COVER LH	180.00	80.00	
Total:			1,116.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148,44	nec
2	Main	TOWING CHARGE	56.00	0.00	
3	Main	TO REMOVE AND REFIX WING MIRROR	120.00	60.00	Labour
4	Main	TO WASH AND VACUUM	60.00	0.00	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
otal:			484.44	208.44	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,491.28	854.89
Total Labour Cost	507.00	300.00
Total Spray Painting	1,116.00	480.00
Other	484.44	208.44
Overall Total	5,598,72	1,843.33

Ψ.		
	Lump Sum Total	5,600.00
	Surveyor Approved Amount	
	No of Repair Days*	4
	Remarks	
	Surveyor Name	
	Signature	
	Survey Date	09/07/2019

Lump Sum Repair Option

1,850.00

1,850.00

03

L/S repair, take after spray. Finalize sent to stevechen @likkauto.com.

STEVE CHEN

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting

- * To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

nowledged by Repairer

ature:





SMRT Accident Vehicle Repair Estimates

SMRT Automative Services Pte Ltd 50 Woodlands Industrial Park E4. Singapore 757705 FAX Number 63685592 Estimator Telephone Number 68652072 Accident Reporting Number 68662072

Date Generated : 24/07/2019 : PehSuan User ID

Registration Number	SHB941D
Case Reference Number	TAX/07/19/2028
Registration Date	7/2/2014
Company Type	SMRT Taxis Ple Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	QUANG KOK KIONG
Type of Accident	Side Swipe
Accident Date and Time	7П/2019 11:55 PM
Accident Reported Date and Time	8/7/2019 2:51 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	8/7/2019 2:50 AM
Replacement Vehicle issued?	No
Job Card Number	24102320
Special Instruction to ARC, if any	TOWED \$40/TP
Prepared Date and Time	8/7/2019 7:15 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and	





lytins

Section B - Summary of Repair Estimates								
Summary of Repair Estimates								
CENTRAL PROPERTY OF THE PROPERTY OF	Quotation from ARC	Adjusted by Surveyor, if applicable						
Total Labour Cost	\$507.00	\$300.00						
Total Spray Cost	\$1,116.00	\$480.00						
Total Spare Part Cost	\$4,364.10	\$1,958.22						
Total Other Cost	\$484.44	(\$386.22)						
TOTAL COST	\$6,471.54 7709.65	\$2,350.00 (L/S)						
Lump Sum Total	\$0.00	\$0.00						
Number of Repair Days	4.0	3.0						
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / NTUC						
ARC / Surveyor Sign Off Date	09/07/2019 4:14 PM	09/07/2019 3:10 PM						
Signature	3							
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.						



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTU	C INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1901217	2/Etf3e2
		D UNION HOUSESINGAPORE	Date:	05-08-2019 INC4	
1.		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	GBF 8406E	Veh. I	nspected	SHB 941D
	Policy No.	5088706268-02	Cover	age (\$)	0.00
	Claim No.	MT/1052532-002	Exces	s (\$)	0.00
	Assign From		Assig	n Date	09/07/2019
2.		Vehicle Parti	culars &	& Condition	
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	Year o	of Reg.	2014
	Chassis No.	JTDKN36UX05722908	Colou	r	MAROON
	Odometer	605311	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modif	ication	SPORTS RIM
	General	FAIR			
3.		Conditi	ons of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm
4.		Descripti	on of D	amages	
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.		Genera	Inform	nation	
	Accident Date	07/07/2019	Inspe	ction Date	09/07/2019
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 7577	705
5a.		R	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate	Days o	f Repair	TO THE REAL PROPERTY.
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		3 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 941D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, OUTER MIRROR, LH (DISC 25%)	MISSING	107.40	80.55
1	MIRROR ASSY, LH (DISC 25%)	BROKEN	1,224.90	918.68
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/LH (DISC 25%)	BROKEN	76.40	57.30
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	HEAD LAMP LH (DISC 10%)	сит	945.20	850.68
1	MIRROR LAMP LH	NOT NECESSARY	65.30	:-
1	MIRROR GLASS LH	NOT NECESSARY	142.50	:-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	9
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	
1	FENDER LINER PAD, FR WHEEL.LH	NOT NECESSARY	49.30	
1	WHEEL DISC.FRONT	NOT NECESSARY	1,484.20	3
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	a d
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	9
			5,616.70	1,958.22
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT AND FENDER FRT / LH.		507.00	300.00
	SPRAY PAINT.		1,116.00	480.00
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		148.44	148.44
	TOWING CHARGE.		56.00	F.
	TO REMOVE AND REFIX WING MIRROR.		120.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	59
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	
			2,107.44	988.44
	GRAND TOTAL		7,724.14	2,946.66

RECOMMENDED COST OF LUMP SUM REPAIRS		2,350.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC19012172/Etf3e2





Report Ref No. NS/INC19012172/Etf3e2

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.