

ASS. REC. BY:

REF:

Tm1 / CC3/Tm2 19012173 / ksf3n2

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1-B1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 5595B Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Ruv

c.c

1798

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

100884

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU403074003

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / RIM or

Tyre Size:

F:

11

R:

G7

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

2 G7

mm

Rear

R/Bal.

2

mm

L/Bal.

G7

8

mm

L/Bal.

2

mm

D.O.A.

8/7/19

D.O.I.

9/7/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

SHD 3495D - X

SLR 84752 - X

86481-11 To Sumit

(5 20.312-38 Red - 76%)

RECEIVED 2 SEP 2019

Date/Time, File Pass to?

02/09/19

1) Typist

Date/Time, File Return to?



Prell. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

11

Fuel:

Others:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

TOTAL

261

Report Format:

Lump Sum (I.B.): (\$

6,481.11 p/p

**FW: TCS REF: AAD1907-093--Accident involving SHD 5595B & SLR 8475Z on 08/07/2019**

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Mon 2/9/2019 9:47 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

📎 5 attachments (3 MB)

image001.wmz; ESTIMATE MARKED.pdf; IMG\_0120.JPG; IMG\_0122.JPG; IMG\_0125.JPG;

Hi Shirley

Amount confirmed \$ 6,481.11 (before GST).

Thank You

Best Regards,

**Ng Wai Yin**

Finance Department

TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: [www.transcab.com.sg](http://www.transcab.com.sg)



This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

**Sent:** Friday, 30 August, 2019 12:02 PM

**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>

**Cc:** SUR <sur@lkkauto.com>

**Subject:** TCS REF: AAD1907-093--Accident involving SHD 5595B & SLR 8475Z on 08/07/2019

Dear Wai Yin,

Please confirm final fig \$ 6,481.11 @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AVG logo

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 10 July 2019 5:34 PM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 08/07/2019 , SHD 5595B (TP Vehicle), SLR 8475Z (OI Vehicle)  
**Attachments:** TP GIA REPORT.pdf; ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5595B at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 09/07/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHD5595B

Vehicle to be Exported: Yes

Intended Deregistration Date: 08 Jul 2019

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: 2ZR2B51479

Chassis No.: JTDKB3FU403074003

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,605.00

Original Registration Date: 26 Oct 2018

First Registration Date: 26 Oct 2018

Transfer Count: 0

Actual ARF Paid: \$14,247.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Oct 2026

PARF Rebate Amount: \$10,685.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Oct 2026

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$24,228.00

COE Rebate Amount: \$19,382.00

**Total Rebate Amount: \$30,067.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/07/2019 16:43
Date Of Accident	08/07/2019 14:40
Exact Location Of Accident	ANSON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5595B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	FOO CHEE SENG
NRIC No	S1161974F
Date Of Birth	04/09/1956
Occupation	OUTDOOR
Date Of Driving Pass	26/11/1977
Driving Experience	41 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91012600
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 209 BISHAN STREET 23 #13-367
Postcode	570209
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 08.07.2019 at about 1440Hours, I was travelling straight on the third lane along Anson Road. Suddenly I felt an impact. Vehicle B (SLR8475Z) which was travelling on my left swerved into my lane without checking for oncoming vehicle and hit onto my taxi's left side front portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8475Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FOO CHEE SENG
NRIC/Passport Number	S1161974F
Contact Number	91991567
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



# **SKETCH PLAN**

## **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

Anson Road

A = SHO 5595B  
B = SLR 847DZ

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GVA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

AAD1907-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5595B

*Not Authorized**Repair B4 paint**06481-11*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

09 JUL 2019

SHD 5595B

JTDKB3FU403074003

RENAULT

LATITUDE

8.7.19

TOKIO MARINE

26/10/2018

**PART****LIST**

1	1	FRONT BUMPER	\$	<i>BU</i>	509.10	✓
2	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>SL</i>	101.20	X
3	1	REINFORCEMENT, FRONT BUMPER	\$	<i>SL</i>	708.10	X
4	1	COVER, FRONT BUMPER HOLE, LH	\$	<i>SL</i>	29.00	X
5	1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>SL</i>	130.20	X
6	1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>SL</i>	78.10	X
7	1	FRONT BUMPER SIDE RETAINER LH	\$	<i>DIS</i>	112.70	✓
8	1	FRONT BUMPER SUPPORT	\$	<i>SL</i>	81.70	X
9	1	EXTENSION, FRONT BUMPER, RH	\$	<i>SL</i>	118.50	X
10	1	EXTENSION, FRONT BUMPER, LH	\$	<i>SL</i>	118.50	X
11	1	FRONT LED LAMP (LOWER) LH	\$	<i>NGC M SL</i>	907.75	X
12	1	FRONT HEADLAMP LH	\$	<i>NGC M</i>	2,909.04	✓
13	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	<i>SL</i>	492.30	X
14	1	MOTOR, HEADLAMP LEVELING, LH	\$	<i>SL</i>	413.10	X
15	1	FRONT FENDER LH	\$	<i>BU</i>	963.80	✓
16	1	EXTENSION, FRONT FENDER, LH	\$	<i>SL</i>	48.80	X
17	1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	<i>SL</i>	98.30	X
18	1	LINER, FRONT FENDER, LH	\$	<i>CM</i>	200.70	✓
19	1	FRONT FENDER EMBLEM LH	\$	<i>BU</i>	86.50	✓
20	1	SEAL, FENDER APRON MUDGUARD, LH	\$	<i>SL</i>	50.90	} X
21	1	FRONT BONNET	\$	<i>SL</i>	969.00	
22	1	HINGE ASSY, HOOD, LH	\$	<i>SL</i>	58.00	
23	1	GRILLE, RADIATOR, LOWER NO.1	\$	<i>SL</i>	167.90	
24	1	FRONT LOWER ARM	\$	<i>SL</i>	631.90	
25	1	FRONT SHOCK ABSORBER	\$	<i>SL</i>	401.80	
26	1	SHAFT ASSY, FRONT DRIVE, LH	\$	<i>SL</i>	1,186.20	
27	1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	<i>SL</i>	637.50	
28	1	KNUCKLE, STEERING, LH	\$	<i>SL</i>	562.30	
29	1	LINK ASSY, FRONT STABILIZER, LH	\$	<i>SL</i>	199.00	

**Trans-cab Auto Services Pte Ltd**

AAD1907-093

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5595B

30	1	BAR, STABILIZER, FRONT	\$	<i>Pl</i>	360.30	<i>X</i>
----	---	------------------------	----	-----------	--------	----------

<b>TOTAL</b>	<b>\$</b>	<b>13,332.19</b>
<b>25%</b>	<b>\$</b>	<b>3,333.05</b>
	<b>\$</b>	<b>9,999.14</b>

**Special-Nett**

1	1	FRONT WHEEL RIM	\$	<i>Net</i>	1,570.55	<i>✓</i>
2	1	FRONT WHEEL RIM COVER	\$	<i>Pl</i>	175.80	<i>X</i>
3	1	CLIP, FRONT FENDER LINER	\$	<i>nn</i>	22.00	<i>✓</i>
4	1	BUMPER CLIP FRT	\$	<i>nn</i>	66.00	<i>✓</i>
5	1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>Pl</i>	200.00	<i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>2,034.35</b>
--------------	-----------	-----------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>12,033.49</b>
--------------------	-----------	------------------

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>4401</i>
---	----	----------	-------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>4001</i>
---	----	----------	-------------

To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
---	----	--------	------------

To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
--	----	------------------	----------

To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
--	----	------------------	----------

To check steering geometry and computer wheel alignment	\$	220.00	<i>601</i>
--	----	--------	------------

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00	<i>X</i>
--	----	------------------	----------

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
---	----	--------	------------

**Trans-cab Auto Services Pte Ltd****AAD1907-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5595B**

To transfer of Bonnet fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *2cl*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ *4* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *4* 380.00 *X***TOTAL \$ 14,760.00****Over All Total \$ 26,793.49****(PART-BY-PART) Repair Days***20 days**2 day,*

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19012173/KSF3N2

Date: 02/09/2019

## REFERENCE

<b>Handling Insurer:</b>	Tokio Marine Insurance Singapore Ltd	<b>Policy No:</b>	MK000577
<b>Claimant Vehicle No :</b>	SHD5595B	<b>Insured Vehicle No :</b>	SLR8475Z
<b>Date of Loss:</b>	08/07/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	M1905135

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SHD5595B	<b>Engine No:</b>	2ZR2B51479
<b>Make &amp; Model:</b>	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	<b>Chassis No:</b>	JTDKB3FU403074003
<b>Reg. Date:</b>	26/10/2018 (Man. Year: 2018)	<b>Odometer:</b>	100864 km
<b>Colour:</b>	Metallic White/Red		
<b>Engine Capacity:</b>	1798 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	195/65R15	<b>Rear Tyre Size:</b>	195/65R15
<b>Front Left Side:</b>	Giti 8 mm	<b>Rear Left Side:</b>	Goodyear 2 mm
<b>Front Right Side:</b>	Goodyear 2 mm	<b>Rear Right Side:</b>	Goodyear 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,033.49	5,511.10	6,522.39	54.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,760.00	970.00	13,790.00	93.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,793.49</b>	<b>6,481.10</b>	<b>20,312.39</b>	<b>75.81</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,875.54</b>	<b>453.68</b>	<b>1,421.86</b>	<b>75.81</b>
<b>Nett Amount (S\$)</b>	<b>28,669.03</b>	<b>6,934.78</b>	<b>21,734.25</b>	<b>75.81</b>

## INSPECTION

<b>Date of Assignment:</b>	11/07/2019	
<b>Date Inspected:</b>	09/07/2019	<b>Inspected At:</b>
		Trans Cab Auto Services Pte Ltd - Amk (HQ)
		No 2 Ang Mo Kio St 63
		Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$6481.11

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2019)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5595B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	509.10 FL	*509.10 FL
2	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTING	Serviceable	101.20 FL	*- FL
3	1		*REINFORCEMENT,FRONT BUMPER	Repair	708.10 FL	*- FL
4	1		*COVER,FRONT BUMPER HOLE,LH	Serviceable	29.00 FL	*- FL
5	1		*ABSORBER,FRONT BUMPER,LOWER	Serviceable	130.20 FL	*- FL
6	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	78.10 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	112.70 FL	*112.70 FL
8	1		*FRONT BUMPER SUPPORT	Serviceable	81.70 FL	*- FL
9	1		*EXTENSION,FRONT BUMPER,RH	Serviceable	118.50 FL	*- FL
10	1		*EXTENSION,FRONT BUMPER,LH	Serviceable	118.50 FL	*- FL
11	1		*FRONT LED LAMP (LOWER) LH	Mtg Cracked	907.75 FL	*907.75 FL
12	1		*FRONT HEADLAMP LH	Mtg Cracked	2,909.04 FL	*2,909.04 FL
13	1		*COMPUTER SUB-ASSY,HEADLAMP,LH NO,1	Serviceable	492.30 FL	*- FL
14	1		*MOTOR,HEADLAMP LEVELING,LH	Serviceable	413.10 FL	*- FL
15	1		*FRONT FENDER LH	Bent	963.80 FL	*963.80 FL
16	1		*EXTENSION,FRONT FENDER,LH	Serviceable	48.80 FL	*- FL
17	1		*COVER SUB-ASSY,FRONT PILLAR,UPR LH	Serviceable	98.30 FL	*- FL
18	1		*LINER,FRONT FENDER,LH	Cracked	200.70 FL	*200.70 FL
19	1		*FRONT FENDER EMBLEM LH	Necessary	86.50 FL	*86.50 FL
20	1		*SEAL,FENDER APRON MUDGUARD,LH	Serviceable	50.90 FL	*- FL
21	1		*FRONT BONNET	Repair	969.00 FL	*- FL
22	1		*HINGE ASSY,HOOD,LH	Repair	58.00 FL	*- FL
23	1		*GRILLE RADIATOR LOWER NO,1	Serviceable	167.90 FL	*- FL
24	1		*FRONT LOWER ARM	Serviceable	631.90 FL	*- FL
25	1		*FRONT SHOCK ABSORBER	Serviceable	401.80 FL	*- FL
26	1		*SHAFT ASSY,FRONT DRIVE,LH	Serviceable	1,186.20 FL	*- FL
27	1		*ARM SUB-ASSY,FRONT SUSPENSION,LOWER NO,1 LH	Serviceable	637.50 FL	*- FL
28	1		*KNUCKLE,STEERING,LH	Serviceable	562.30 FL	*- FL
29	1		*LINK ASSY,FRONT STABILIZER,LH	Serviceable	199.00 FL	*- FL
30	1		*BAR,STABILIZER,FRONT	Serviceable	360.30 FL	*- FL
31	1		*FRONT WHEEL RIM	Dented	1,570.55 F	*1,570.55 FN
32	1		*FRONT WHEEL RIM COVER	Serviceable	175.80 F	*- FN
33	1		*CLIP,FRONT FENDER LINER	Necessary	22.00 F	*22.00 FN
34	1		*BUMPER CLIP FRT	Necessary	66.00 F	*66.00 FN
35	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 F	*- FN

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,366.54</b>	<b>7,348.14</b>
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,333.05	1,422.40
- Nett Item Discount on N Items 0.00/25.00% (\$\$)	0.00	414.64

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>12,033.49</b>
						<b>5,511.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
12	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,760.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >