

12/03/2002

ASS. REC. BY:

REF: CS/MSG19012176 / Ksf3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tan Gek Ing of MSIGDate/Time: 09/07/2019 17:12

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 3423HInsured: GBB 6692Dat Workshop m/s Cheng Hoe Motor Pte LtdTel: 6755 6142of Blk 1019 #01-374 Yishun Ind Park APolicy No: 28607323Claim No: 598809

Sum Insured:

Excess:

Make of Veh:

D.O.A. 03/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10-7-19 9:42 AM

Person Contacted:

JimVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBB 6692D : X</u>
	<u>GBG 3423H : X</u>
<u>19/07/19 @ 8:13pm</u>	<u>Wong said they still awaiting liability issued</u>
<u>27/08/19 @ 11:10 am</u>	<u>received PA to Irene Tan via messenger.</u>

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4-8 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBG 34234

Yr Regn: _____

07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy Itaca

c.c

2982

Colour: _____

Multi Colour

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

66289

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

*K01120**10219815*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

*195/80R15*BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. _____

6 mm

R/Bal. _____

6 mm

L/Bal. _____

6 mm

L/Bal. _____

6 mm

D.O.A. _____

3/7/19

D.O.I. _____

21/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*1 File pass to**83641.68**cf 500/- led - 12%**8/11/2019*

RECEIVED 21 NOV 2019

Date/Time, File Pass to?

21/11/19

: Prel. Report



: Final Report

1) Typist

Date/Time, File Return to?

2) _____

Days Of Repair: _____

4

Resurvey No. of Trlp: _____

*1*Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

150

S - RS. SI

11

Furnish

Others

TOTAL

161

Report Format:

Lump Sum (I.B.): (\$

3,641.68 r/p

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 27 Aug 2019

Preliminary Advice

Insured Vehicle No	: GBB6692D	Accident Date	: 03/07/2019
TP Vehicle No	: GBG3423H	Assignment Date	: 09/07/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 4 - 5 days
Date of Inspection	: 21/08/2019		
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,141.68
Revised Amount	:S\$	3,341.68
Check Items (Estimated)	:S\$	480.00
Total	:S\$	3,821.68

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jul 2019		09 Jul 2019 17:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	HONG SEAFOOD PTE LTD, Co. Reg. No.: 199203129W		[Created by insurer]
Main Claimant:	KOUFU GOURMET PTE LTD, Co. Reg. No.: 200209727R		
Vehicle Reg. No.:	GBG3423H	Date of Loss:	03/07/2019 09:00 - :59 [23 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 598809	Policy/Cover Note No.:	28607323 (Comprehensive) Coverage: 29/09/2018 - 28/09/2019
Vehicle Reg. No. (Insured):	GBB6692D	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/07/2019]		
Driver/Custodian (Insured):	TOH SOO ANN (), NRIC: S1294002E, Tel: +6596446541 Email:		
Adj Asg. Remarks:	on WP. Liab: 100%. TP agree on SJE- assign Kenneth Kong from LKK Auto Consultants. Contact: June @ 67556142		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	9727R

Vehicle Details

Vehicle No.:	GBG3423H
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2698857
Chassis No.:	KDH2010219815
Maximum Power Output:	-
Open Market Value:	\$33,389.00
Original Registration Date:	20 Jul 2017
First Registration Date:	20 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$1,670.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$29,661.00
Total Rebate Amount:	\$29,661.00

The information contained herein is correct as at 03 Jul 2019

OK

Shirley Hiew (LKK Auto)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Wednesday, 20 November 2019 4:14 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: GBG 3423H DOA - 03/07/2019 FINALIZE

Hi,

Confirmed as below.

Thank you

Rgds
Efeeda
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Shirley Hiew (LKK Auto)
Sent: Monday, November 11, 2019 8:43 AM
To: chmotor@singnet.com.sg
Cc: SUR
Subject: GBG 3423H DOA - 03/07/2019 FINALIZE

Hi June,

Please confirm final fig of \$ 3,641.68 @ 4 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBG 3423H
 TP / MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No:

ES1991907

Date:

21 Aug 2019

Policy No:

5101586917

Veh Reg No:

GBG3423H

Make/Model:

TOYOTA HIACE DX 3.0
 AUTO

Chassis No:

KDH2010219815

Engine No:

1KD2698857

Reg. Date:

20/07/2017

WS Ref:

TP-MSIG

Claim Type:

Third Party

Accident Date:

03/07/2019

TP Veh Reg No:

GBB6692D

Estimate Repair Cost to Vehicle No :GBG3423H

PAGE:1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	396.40	1 PC	396.40	✓
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
3 TAILGATE	1,672.70	1 PC	1,672.70	✓
4 TAILGATE LOGO	59.60	1 PC	59.60	✓
5 TAILGATE INNER RUBBER	391.20	1 PC	391.20	✓
			2,540.90	
	Less 25%		635.23	1,905.68
Special Net				
6 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
7 70KM/H STICKER	10.00	1 PC	10.00	✓
8 REVERSE SENSOR	200.00	1 PC	200.00	✓
9 TAILGATE INNER STEEL BOARD RIVETS	36.00	1 PC	36.00	✓
10 TAILGATE INNER STEEL BOARD GUM	20.00	2 ROLLS	40.00	✓
			326.00	326.00
Labour				
11 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
12 REMOVE AND REFIX REAR BUMPER ASSY, TAILGATE ASSY, REAR WIPER, THIRD BRAKE LIGHT, REAR VIEW MIRROR, LOCK ASSY. TO KNOCK AND REPAIR REAR END PANEL AND REALIGN THE SAME	700.00	1 LA	700.00	500
13 PUTTY AND RESPRAY ON TAILGATE, REAR END PANEL AND REAR AFFECTED AREA	500.00	1 LA	500.00	400
14 REMOVE AND REFIX TAILGATE INNER STEEL PROTECTOR	80.00	1 LA	80.00	60
15 RUSTPROOFING	30.00	1 LA	30.00	✓
16 TO REWRITE ADVERTISEMENT	480.00	1 LA	480.00	300
			1,910.00	1,910.00
			Total	SS 4,141.68
			Add GST @ 7%	289.92
			Total Amount Payable	SS 4,431.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012176/KSF3N2

Date: 22/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28607323
Claimant Vehicle No :	GBG3423H	Insured Vehicle No :	GBB6692D
Date of Loss:	03/07/2019	Nature of Claim:	TP
		Claim No:	598809

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3423H	Engine No:	1KD2698857
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Chassis No:	KDH2010219815
Reg. Date:	20/07/2017 (Man. Year: 2017)	Odometer:	66289 km
Colour:	Multi-colour		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80R15	Rear Tyre Size:	195/80R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,231.67	2,231.67	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,410.00	500.00	26.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,141.67	3,641.67	500.00	12.07
+ GST 7.00/7.00% (S\$)	289.92	254.92	35.00	12.07
Nett Amount (S\$)	4,431.59	3,896.59	535.00	12.07

INSPECTION

Date of Assignment:	09/07/2019	
Date Inspected:	21/08/2019	Inspected At:
		Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial
		Park A
		Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$3,641.68

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2019)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3423H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	396.40 FL	*396.40 FL
2	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
3	1		*TAILGATE	Bent	1,672.70 FL	*1,672.70 FL
4	1		*TAILGATE LOGO	Necessary	59.60 FL	*59.60 FL
5	1		*TAILGATE INNER RUBBER	Cut	391.20 FL	*391.20 FL
6	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
7	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
8	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
9	1		*TAILGATE INNER STEEL BOARD RIVETS	Necessary	36.00 FS	*36.00 FS
10	2		*ROLLS TAILGATE INNER STEEL BOARD GUM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,866.90	2,866.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	635.23	635.23
Total Parts (\$\$)	2,231.67	2,231.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE AND REFIX REAR BUMPER ASSY, TAILGATE ASSY, REAR WIPER, THIRD BRAKE LIGHT, REAR VIEW MIRROR, LOCK ASSY. TO KNOCK AND REPAIR REAR END PANEL AND REALIGN THE SAME	New	700.00	500.00
3	PUTTY AND RESPRAY ON TAILGATE, REAR END PANEL AND REAR AFFECTED AREA	New	500.00	400.00
4	REMOVE AND REFIX TAILGATE INNER STEEL PROTECTOR	New	80.00	60.00
5	RUSTPROOFING	New	30.00	30.00
6	TO REWRITE ADVERTISEMENT	New	480.00	300.00
Gross Labour Cost (\$\$)			1,910.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >